


Universal Tube Weldment

Assembly instructions

August 2025

Contents

- [1] Tube Weldment
- [1] Reversible Shock Brkt
- [5] 3/8-16 Hex bolts & Hardware
- [1] Shock Pin Bolt



Assembly

Orient the tube weldment for the correct machine ODD or EVEN

Use the supplied Hardware to bolt the Reversible shock Bracket to tube weldment. Shock bracket will point rearward closest to shock assembly. Assemble cushion plank and pieces accordingly and then install in your machine.

Note* Longer leg of tube weldment will always be towards the shock assembly side for ODD and EVEN Machines. This will also be the side that the Reversible Shock Bracket bolts to.

