








SAURYAJYOTI RENEWABLES PVT LTD

Doc. No.: SRPL/SOP/004
SAFETY STANDARD PROCEDURE

Safety Guidelines				
Sr. No	Activity	Precautions	IMAGE1	IMAGE2
1	Climbing on roof	Safety Harness is must while climbing on monkey ladder. Harness need to hook on every step. Person should always face the ladder while climbing up and down.		
2	Temporary life line arrangements on roof	Need to do temporary arrangements of life ropes while moment till Safety line installation. Person should ensure that safety harness is properly connected with the safety line.		
3	lifting material from roof edge	While lifting material manually on edge of roof it is mandatory to hook safety harness in safety lifeline. Person should ensure that safety harness is properly connected with		



SAURYAJYOTI RENEWABLES PVT LTD

		the safety line. Lifting area should be clear and barricaded while the activity. Material should be properly bound while lifting.		
4	Material movement on roof	While material movement on roof pre installation of Walkway and lifeline is mandatory on roof. While movement, workers need to use walkway & hook safety harness with lifeline. Skylight area need to be barricaded. Ensure distance between people & material stacking to avoid unnecessary loading on roof. Any material should be properly placed and away from the movement area and the edges.		
5	Welding	PPE while welding is important as mentioned in Image to avoid any physical		

Sunil Vila, 39B, Ibrahimpur Road, Jadavpur, Kolkata 700032

Phone: 9717088074/ 8902550652

E-mail: solar@ganapatiproducs.com/ganapatiproducs@gmail.com

Website:www.ganapatiproducs.com





		<p>damage to worker. Fire resistance cloths & apron are must. Fire Extinguisher & Fire blanket should be there while welding to avoid fire incident. Surrounding area should be cleared and barricaded.</p>		
6	Grinding	<p>PPE while Grinding is important as mentioned in Image to avoid any physical damage to worker. Fire resistance cloths & apron are must. Fire Extinguisher & Fire blanket should be there while Grinding to avoid fire incident. Surrounding area should be cleared and barricaded.</p>	<p>PPE!!</p> <ul style="list-style-type: none"> - Face shield - Gloves - Fire resistant clothing - Hearing protection 	
	Drilling	<p>PPE while drilling is important as mentioned in Image to avoid any physical damage to worker.</p>		



7		<p>Fire resistance cloths & apron are must. Fire Extinguisher & Fire blanket should be there while Drilling to avoid fire incident.</p> <p>Surrounding area should be cleared and barricaded</p>		
8	Manual Material movement	<p>All manual work to be carried out in a safe and ergonomical stature.</p> <p>Movement are should be safe for movement of material.</p>		
9	Industrial electrical Switch socket board	<p>Industrial electrical board should use for powered equipment's & tools. Electrical power Board should be having ELCB protection in it. Single power cable should be use instead of multiple joint cables. Powderd type fire extinguisher should be there to avoid any electrical fire incidence</p>		



SAURYAJYOTI RENEWABLES PVT LTD

10	LOTO	<p>Mandatory to use LOTO for the MMCB which are not in use.</p> <p>1. Caution board should be provided</p>	 
----	------	------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------

We have read and understood the all the safety protocols. If any incidence happens due to negligence by our team we will be responsible for the Incidence

Engineer/Supervisor Name:-

Acceptance :-

GANAPATI PRODUCTS

Sunil Vila, 39B, Ibrahimpur Road, Jadavpur, Kolkata 700032

Phone: 9717088074/ 8902550652

E-mail: solar@ganapatiproductions.com/ganapatiproductions@gmail.com

Website: www.ganapatiproductions.com