

WILDER 2024 SHEET METAL SLITTER BASIC SAFETY

- The maximum is 20-gauge mild steel SHEET METAL ONLY. The maximum width is 24 inches to slit.
- Ensure cut-area is clear. Always use some type of support for materials being slit (on the feed and output sides).
- Check guards and guide. Adjust settings before plugging in.
- Watch for catch hazards – No loose clothing, lanyards, anything.
- Never place hands or fingers near blades when operating.
- Turn on and listen, note abnormal noises or vibration.
- Gloves are advised to feed the material – Keep away from the blades.
- Keep metal pressed against the guide – allow machine to pull the metal through.
- If two-person operation is necessary, communication and responsibilities must be clear. The helper must signal the operator to cycle / The operator should announce “clear” before feeding material.
- Never leave machine running unattended.
- Unplug. Place scraps and trimmings in metal waste containers. Clean the work area before leaving the area.
- Notify a Monitor if guards are missing or the machine is damaged.

