

HACIENDA LA PUENTE UNIFIED SCHOOL DISTRICT PURCHASING DEPARTMENT

15959 E. GALE AVENUE • CITY OF INDUSTRY, CA 91745 (626) 933-3930

Joel Duarte, Director Purchasing & Warehouse

BID NO. 2024-25.10 WILSON HIGH SCHOOL: MEDIA CENTER UPGRADE February 11, 2025

ADDENDUM NO.01

The following changes, additions, deletions, or corrections shall become a part of the Contract Documents for the project named above and all other conditions shall remain the same. The bidders shall be responsible for transmitting this information to all affected subcontractors and suppliers prior to the closing of bids. Acknowledge receipt of this Addendum in spaces provided on the Bid Form. Failure to acknowledge may subject Bidder to disqualification.

BID FORMS REPLACED

• None

REVISIONS TO BIDDING REQUIREMENTS

• The day and time for which Bids are due and will be opened is hereby changed, any and all references in the original bid shall be revised to reflect the new <u>DUE DATE OF</u>:

FEBRUARY 18, 2025 at 3:00 PM

REVISIONS TO SPECIFICATIONS

None

REVISIONS TO DRAWINGS

• See attached included in ADDENDUM 01 Details

RESPONSES TO BID RFI

• See attached, Wilson HS Media_Pre-bid RFI's Responses

CLARIFICATIONS

Bid Alternate No.1 should ONLY include the amount necessary for that portion of work associated for the
work called out in the Bid and Addenda, it is NOT CUMULATIVE OF THE ENTIRE SCOPE INCLUDING
THAT WHICH IS CALLED OUT IN THE ALTERNATE.

ATTACHMENTS

- ADDENDUM 01 Details (which includes new attached Drawings: A-0, A-7, A-9, A-13, E-0.1, E-2.0, E-2.1, E-3.1)
- Wilson HS Media Pre-bid RFI's Responses
- 2025 Wilson HS Media Center-Library Asbestos and Lead Survey Rpt

END OF ADDENDUM NO.1

Date: February 11, 2025

ADDENDUM 01 Details

RE: Project Bidding Documents for:

WILSON HIGH SCHOOL
MEDIA CENTER REMODEL
HACIENDA LA PUENTE UNIFIED SCHOOL DISTRICT

tBP Project No. 21211.00

tBP/ARCHITECTURE 4611 Teller Avenue Newport Beach, CA 92660 949-673-0300

TO: PROSPECTIVE BIDDERS

This Addendum forms a part of the Contract Documents and modifies the original approved Bidding Drawings and Specifications dated November 21, 2024. Acknowledge receipt of this Addendum in space provided on the Bid Form. Failure to acknowledge may subject Bidder to disqualification.

CHANGES TO DRAWINGS

Architectural

1. SHEET A-0 SITE DEMO AND REMODEL PLAN

- a. Site Demo Plan Revised demolition Keynote #7 to add the height of the existing brick wall for Bid Alt # 1.
- b. Site Demo Plan Revised Keynotes #6 and #7 have been labeled as "Typical" on the Site Demo Plan.
- c. Site Plan Keynotes # 9 and #11 have been labeled as "Typical" on the Stie Plan.
- d. Replace Sheet A-0 Site Demo and Remodel plan in its entirety issued with this addendum.

2. SHEET A-7 INTERIOR ELEVATIONS

- a. Remodel Keynote # 10 was modified to include a projection screen mounting detail 20/A-9 and revise mounting height to
- b. Replace Sheet A-7 Interior Elevation sheet in its entirety issued with this addendum.

3. SHEET A-9 INTERIOR DETAILS

- a. Added Detail 20 /A-9 for the mounting of the motorized projection screen.
- b. Replace Sheet A-9 Interior Detail sheet in its entirely issued with this addendum.

WILSON HIGH SCHOOL
MEDIA CENTER REMODEL
HACIENDA LA PUENTE UNIFIED SCHOOL DISTRICT

4. SHEET A-13 FURNITURE SCHEDULE

- a. Added a note: "ALL FURNISHINGS ARE TO BE OWNER FURNISHED AND CONTRACTOR INSTALLED."
- b. Replace Sheet A-13 Furniture Schedule sheet in its entirely issued with this addendum.

5. SHEET E-0.1 GENERAL NOTES, SYMBOLS & SCHEDULES

- a. Revise Panel Schedule KLB to include (N) AV Rack.
- b. Replace Sheet E-01 General Notes, Symbols & Schedules in its entirety issued with this addendum.

6. SHEET E2.0 REMODEL POWER PLAN

- a. Added location of new AV Cabinet and power to Panel KLB.
- b. Replace Sheet E-2.0 Remodel Power Plan in its entirety issued with this addendum.

7. SHEET E-2.1 REMODEL SIGNAL PLAN

- a. Added location of new AV cabinet.
- b. Replace Sheet E-2.1 Remodel Signal Plan in its entirety issued with this addendum.

8. SHEET E3.1 ELECTRICAL DETAILS

- a. Revise Details 8, 9, 13, 14, & 15.
- b. Replace Sheet E-3.1 Electrical Details in its entirety issued with this addendum.

ATTACHMENTS

The following attachments are a part of Addendum 01:

1. Full Size Documents (30" x 42") Drawings: (Total 8)

A-0

A-7

A-9

A-13

E-0.1

E-2.0

E-2.1

E-3.1

Date: February 11, 2025

WILSON HIGH SCHOOL MEDIA CENTER REMODEL HACIENDA LA PUENTE UNIFIED SCHOOL DISTRICT

tBP Proj. No. 21211.00

tBP/ARCHITECTURE 4611 Teller Avenue Newport Beach, CA 92660 949-673-0300

TO: PROSPECTIVE BIDDERS

RESPONSES TO PRE-BID RFI'S

1. Sheet A-13

The furniture schedule on Sheet A-13 is for reference only. Please confirm all interior and exterior furnishings are not part of this project.

Response – The district will have the furnishings indicated on sheet A-13 to be "Owner Furnished and Contractor Installed." Plan is attached to this addendum.

2. General

Is there an Engineer's Estimate for this project?

Response – \$650,000

3. General

Are there any prequalification requirements? GC? MEP subcontractors?

Response – There is no prequalification requirement for the GC or subcontractors.

4. General

Are there any DBE/DVBE requirements?

Response – See Information for Bidders #23.

General

Are there estimated start and completion dates?

Response – The estimated start date is April 1, 2025. The estimated completion date is May 30, 2025.

6. General

Is this project subject to Davis-Bacon? If this project is subject to Davis-Bacon, please provide Federal wage determination.

Response – This project is not subject to Davis-Bacon.

7. General

Part A: Is there a statute or regulation that would impose STW requirements as an enforceable commitment for this project, in accordance with Public Contract Code Sections 2600 - 2603?

Part B: If the answer to question #1 is "yes," which specific statute or regulation mandates STW as an enforceable commitment for this project?

Response – STW are not applicable to this project.

8 Sheet A-0

Is the entire brick wall around the outdoor area to be removed (as an alt) or only the south wall with the rest remaining? Is the fence alt to replace the North, South, and West walls with fence, terminating at the building along the East perimeter?

Response – Bid Alternate No.1 indicates the removal the entire masonry wall and foundation and replace it with new foundation and fencing and shall be excluded from the base bid and listed separately. Demolition keynote #7 "Bid Alt No.1" has been modified to indicate the wall height and is noted as typical for all sides of the masonry wall, and keynote #6 is noted as typical for all sides of the masonry wall. Site Plan keynote #11 "Bid Alt No. 1" and keynote #9 is typical for all sides of the masonry wall. Plan A-0 is attached to this addendum.

9. General

As discussed verbally during the job walk, contractors should account for PLA wages in their pricing. Please confirm, is this project submit to PLA (project labor agreement), While as per Bid documents the project is submit to PW (Prevailing Wages)?

Response – This Project is subject to the District's Continuity of Work Agreement (CWA) included in the bid documents. The CWA does not negate or supplant the Prevailing Wage requirement.

10. Sheet A-7

Please clarify the mounting details for the projection screens. Keynote #10 on sheet A-7 says to use 8/A-9 however that detail is for a motorized window shade. Please clarify and provide an updated detail.

Response – New projection screen mounting detail 20/A9 is provided for mounting of the screen. Plan A-7 and A-9 are attached to this addendum.

11. Specification Section 11 52 13

Please provide a model for the projection screens that should be provided under section 115213. This was not included in the specs and not shown on the plans.

Response – Basis of Design: Dal-Lite Tension Contour Electrol -16:10 Wide Format, 123" diagonal, model #29928LS, Parallax Stratos 1.0, or equal. Mount the bottom of the screen case at 10'-0" above floor and align projector lens to minimize parallax and image distortion.

12. Specification Section 11 52 16

Please provide a model number for the flat panel displays that should be provided under section 115216. This display was mentioned in the specs, but no model number was provided. Also not provided on the plans.

Response – Basis of Design: Sony Model #KDL70R550A, 70-inch, 1080P, LED, HDTV monitor, or equal.

13. AV Wiring Diagram

Please provide the missing AV wiring diagram that shows how the AV systems should be connected.

Response – Refer to sheet E3.1, detail #13 for A/V wiring diagram. (A&F Engineering Group, Inc.)

14. Sheet E-2.1

Sheet E-2.1 is showing (2) projectors and (5) flat panel displays but there is no indication if this is all one system or multiple. Please clarify.

Response – Refer to sheet E3.1, A/V Outlet Diagrams and A/V Wiring Diagrams for system requirements. Projectors shall be interconnected and all flat panel displays are to be individually controlled. Projectors are to be mounted at a suitable height for the lenses to be aligned correctly to minimize parallax and image distortion.

15. Specification Section 27 13 46

The AV equipment called out in the 271346 specs are not reflected on the plans. Please clarify what spaces this section applies to and provide updated drawings that match.

Response – Refer to sheet E3.1, A/V Outlet Diagrams and A/V Wiring Diagrams for system requirements. (A&F Engineering Group, Inc.)

16. Sheet E-2.1

Plan note #7 on sheet E2.1 calls out for an assistive listening system to be provided however it is not clear if each AV system should be provided with their own separate assistive listening systems. Please clarify how many ALS should be provided.

Response – Note #7 indicates to provide quantities equal to 4% of the seating capacity, but in no case less than two receivers are to be provided. Refer to Architectural seating capacity to obtain quantities to be provided with a minimum of two receivers to be provided. Assistive listening devices shall be integrated into ceiling speakers. (A&F Engineering Group, Inc.)

17. Specification Section 27 13 46

The Teach Logic #CS-2 speakers are no longer available. Please provide an alternate.

Response – The Teach Logic #CS-2 is package of two (2) #SP-628 speakers with wire. Individual speaker model number is #SP-628. (A&F Engineering Group, Inc.)

18. Sheet -E2.2

Plans call to remove and reinstall fire pathways and devices. What is current manufacturer of the existing fire system?

Response – Existing fire alarm system is Silent Knight. (A&F Engineering Group, Inc.)

19. Information for Bidders

Per the "information for Bidders" Page 1, The District may receive requests for the Contract Documents from plan rooms. Please note: Prospective Bidders who choose to review the Contract Documents at a plan room must contact the District to obtain the required Contract Documents. We obtained our documents from ARC Costa Mesa's plan room. Do we need anything else directly from the District?

Response –The District has used ARC/Planwell for all project bid documents: https://customer.e-arc.com/arcEOC/PWELL Main.asp?mem=29 with District

20. General

Please confirm whether the Project Labor Agreement (PLA) is mandatory for this bid or if Prevailing Wage alone will be acceptable per the bid documents. Given the project's small scope and budget, enforcing PLA provisions is anticipated to increase the costs by 40% to 60% and significantly limit the pool of subcontractors suited for a project of this size. Clarification on this matter will help ensure accurate and competitive bidding.

Response – See response for RFI #9.

21. Sheet ED2.0

Where is the nearest IDF located for the network cabling?

Response – Refer to sheet ED2.0, plan #2 for location of nearest existing IDF.

22. General

Please advise where ethe laydown area will be for both material and parking, as the project develops.

Response – The laydown area will be determined after the contract is awarded. Its location will be selected in coordination with the needs of the awarded contractor, as well as the limitations and requirements of the school and the District's Facilities Department.

23. General

Has a hazardous material survey been completed for the area of work, if so, please provide the report?

Response – Attached as part of this Addendum No.1.

24. General

The abatement of any material identified in the District's Asbestos & Lead Based Paint Inspection Report will be done by the District.

25. Detail 13/E3.1

In the attached drawing, please clarify the intent of the following items:

- a. Priority page senor, is this provided by the customer and we are just proving the #22 cable to the amplifies and terminating to our amplifier?
- b. Internet TV, is this provided by the customer? If not, what are the specs and requirements needed?
- c. Microphone antenna, what are the specs and requirements needed?
- d. Splitter, what is the purpose of having two splitters on the same wire?

Response- a. Priority page sensor to be provided by Contractor.

- b. Not required.
- c. Not required
- d. Refer to the revised wiring diagram on Sheet E3.1 attached to the addendum.

Refer to clouded areas on revised sheets E-0.1 General Notes, Symbols & schedules, E2.0 Remodel Power Plan, E-2.1 Remodel Signal Plan and E3.1 Electrical Details, for additional revised AV system information.

26. What is the objective of the audio system? Knowing the intent of the system will help our team develop and design the proper system that will adhere to the request.

Response - Audio system shall integrate with projectors and 3rd party connections to projectors. Individual TV stations shall utilize the speaker of the TV. Contractor to confirm with the District their requirements and provide a complete and operable

system upon completion.

- 27. Please advise on the speaker symbol icons in the print. What is the difference between the circle speaker icon and the square speaker icon?
 - **Response** Disregard speaker symbol enclosed in a circle as that would have been part of the PA system, but the PA system is remaining as existing for this area. Provide the speaker enclosed in a square and that speaker will be for the projector screen interface.
- 28. Please provide all applicable information available for the existing fire alarm system, including equipment location.
 - **Response-** Fire alarm scope is limited to lifting existing wire-mold and sliding new material behind the fire alarm elements with the re-installation of the existing wire-mold on the new surface. All fire alarm equipment affected within the scope of work is indicated on the demolition sheet ED-2.0, plan #2 and sheet E-2.2, plan #1. The existing fire alarm system is a VEVAC system manufactured by Silent Knight.
- 29. During the job walk, it was noted that a DSA inspector will oversee the project. However, there is no DSA case number, permit, or approval process under Title 24 Standards, and the Bid documents don't specify the inspector's role. Please advise will a specific DSA permit be issued to allow the supervising inspector to enforce compliance with the approved plans? If no DSA permit will be issued, please advise how the DSA inspector's supervisory role will be managed, particularly in the absence of DSA standards specified in the plans.
 - **Response** No DSA permit will be issued. The inspector's responsibility will be to ensure that the work is being carried out in accordance with the project plans and specifications. The inspector will also monitor the quality of the contractor's workmanship and provide regular reports to the District.
- 30. Is there a minimum self-performance threshold for prime contractors? **Response** There is no minimum threshold.



ASBESTOS & LEAD-BASED PAINT INSPECTION REPORT

For

WILSON HIGH SCHOOL MEDIA CENTER-LIBRARY

16455 Wedgeworth Drive Hacienda Heights, California 91745

Prepared For



HACIENDA LA PUENTE UNIFIED SCHOOL DISTRICT

15959 E. Gale Avenue City of Industry, California 91745

Prepared By



16700 Valley View Avenue, Suite 100, La Mirada, California 90638 (714) 523-9811 • Fax (714) 523-9810 <u>www.encorp.net</u>

January 21, 2025 ENCORP PROJECT NUMBER P25033.H21



TABLE OF CONTENTS

I.	ASBESTOS & LEAD-BASED PAINT INSPECTION REPORT

- II. SAMPLE ANALYSIS
 - IIA. SAMPLE ANALYSIS ASBESTOS
 - IIB. SAMPLE ANALYSIS LEAD
- III. CERTIFICATIONS
- IV. FIELD INSPECTION DATA
- V. LIMITATIONS

I. ASBESTOS & LEAD-BASED PAINT INSPECTION REPORT

ASBESTOS & LEAD-BASED PAINT INSPECTION REPORT

FACILITIES:WILSON HIGH SCHOOL MEDIA CENTER-LIBRARY

16455 Wedgeworth Drive Hacienda Heights, California 91745

INSPECTION DATE:.....January 21, 2025

INTRODUCTION

The HACIENDA LA PUENTE UNIFIED SCHOOL DISTRICT retained ENCORP to conduct an asbestos and lead-based paint inspection of the MEDIA CENTER-LIBRARY at WILSON HIGH SCHOOL located at 16455 Wedgeworth Drive, Hacienda Heights, California 91745. The inspection scope of work was to perform a complete inspection for suspect Asbestos Containing Materials (ACM's) and Lead-Based Painted Materials (LBPM's) of the exterior and interior of the building. The inspection results that follow summarize the components tested and the results.

Asbestos is a general term applied to a group of naturally occurring minerals which separate into fibers. This fibrous material (e.g., Amosite, Chrysotile, Crocidolite, Tremolite, Anthophyllite, and Actinolite) are composed of silicates of aluminum, magnesium and other metals which are incombustible and very difficult to destroy or degrade. Asbestos has a tendency to break into a dust of tiny fibers which can float in the air and be inhaled or swallowed. Asbestos inhalation exposure has been shown to increase the risk of developing lung cancer, mesothelioma (cancer of the lining of the lung and/or abdomen.) and asbestosis (chronic lung disease), as well as other damage to the lungs. Exposure occurs by breathing asbestos fibers produced as a fine dust when asbestos is handled during fabrication, installation or removal. By definition Asbestos Containing Materials (ACM) are any materials or products which contain greater than 1 percent (1%) asbestos. CAL/OSHA further regulates the content of asbestos in materials or products that contain greater than 1 tenth of a percent (0.1%) of asbestos requiring work to be performed by a licensed abatement contractor, and asbestos containing material containing 0.1% or less of asbestos requiring notification and training for the purpose of worker protection.

ENCORP's Certified Site Surveillance Technician and Lead Sampling Technician, Mr. Angel Jimenez (CSST No. 15-5431, LRC-00002763) completed the site inspections. Sampling was performed under the direction of Certified Asbestos Consultant and Lead Inspector/Assessor, Mr. Howard Baba (CAC No. 95-1791, LRC-00003404). Prior to sample collection, ENCORP's representative conducted a visual investigation of the property to identify and quantify all suspect asbestos containing and lead painted building materials. Upon completion of the visual investigation, building materials were grouped into homogeneous categories and samples were collected from the suspect ACM's previously identified.

SAMPLING METHODOLOGY - ASBESTOS

ENCORP used a modified random sampling protocol to collect the samples of the suspect ACM's. Each of the suspect samples collected for this report were given a unique sample identification number and sealed inside leak proof containers for shipment to the laboratory for analysis.

Asbestos bulk samples collected during this inspection were analyzed by ENCORP Environmental Laboratory. ENCORP Environmental Laboratory is accredited by NIST/NVLAP for analysis of asbestos fibers in bulk. PLM Bulk samples were analyzed by Polarized Light Microscopy (PLM)/Dispersion Staining (EPA/600/R-93/116). ENCORP NVLAP Lab Code 200878-0, 16700 Valley View Ave, Suite 100, La Mirada, CA 90638, 714-523-9811.

Because fibers with a diameter less than one micron will not be seen using PLM, a possibility exists that the asbestos content of materials with low asbestos percentages (such as floor tiles and soils) could actually be higher when analyzed by TEM, SEM, or X-ray diffraction.

INSPECTION RESULTS -- ASBESTOS

The following contains the summary of the suspect asbestos containing materials sampled during this inspection, including the location and laboratory analysis. Positive ACM's are distinguished in "**bold**". Samples collected and found not to contain asbestos are classified as being None Detected "ND". The complete sampling results can be found in the attachment section of this report.

		SUMMARY OF SUSPEC	T MATERI	ALS TES	TED	
Sample No.	Building Component	Location of Material	Condition	Friability	Estimated Quantity	% and type of Asbestos
1 2 3	6" Black Cove Base / Mastic / Glue	Building B Media Center/Library Throughout Interior	G	NF	180 sq ft	Cove base = ND Mastic = <0.1% Tremolite by 1000 point count analysis
4 5 6	Carpet Glue	Building B Media Center/Library Throughout Interior	G	NF	4000 sq ft	ND
7 8 9	Carpet Mastic	Building B Media Center/Library Interior Sporadic Under Carpet	G	NF	1500 sq ft	
10 11 12	Vinyl Floor Tile / Mastic	Building B Media Center/Library Interior Sporadic Under Carpet	G	NF	500 sq ft	Tile = ND Mastic = ND
13 14 15	Leveling Compound	Building B Media Center/Library Interior Sporadic Under Carpet	G	NF	200 sq ft	ND
16 17 18	Walk-On Mat Adhesive	Building B Media Center/Library Interior Entryways	G	NF	100 sq ft	ND
19 20 21	12"x12" Grey Floor Tile / Mastic	Building B Media Center/Library Conference/Storage Room	G	NF	300 sq ft	Tile = ND Mastic = ND
22 23 24	Carpet Pad / Adhesive	Building B Media Center/Library Below Older Perimeter Carpet	G	NF	60 sq ft	Pad = ND Adhesive = ND
25 26 27	Wall Panel Insulation	Building B Media Center/Library Wall Partitions	G	F	1600 sq ft	ND
28 29 30	Ceiling Panel Insulation	Building B Media Center/Library Throughout Interior	G	F	4000 sq ft	ND
31 32 33	Ceiling Space Roofing Debris	Building B Media Center/Library Above Suspended Ceiling	G	F	2000 sq ft	ND
34 35 36	Pipe Run Insulation	Building B Media Center/Library Above Suspended Ceiling	G	F	60 sq ft	ND
37 38 39	HVAC Insulation	Building B Media Center/Library Above Suspended Ceiling	G	F	40 sq ft	ND
40 41 42	Steel Beam Caulking	Building B Media Center/Library Interior / Exterior	G	NF	120 sq ft	ND
43 44 45	Brick / Mortar	Building B Media Center/Library Interior / Exterior	G	NF	5000 sq ft	Brick = ND Mortar = ND
46 47 48 49 50	Stucco Overhang	Building B Media Center/Library Exterior	G	NF	3000 sq ft	Skim Coat = ND Stucco = ND
51 52 53	Overhang Panel Insulation	Building B Media Center/Library Exterior	G	F	1300 sq ft	ND

Conditions of materials are identified as follows: Good (G), Damaged (D), or Significantly Damaged (SD), Friable (F), Non-friable (NF). The quantities listed are for budgetary purposes only. Contractors completing proposals for the removal of asbestos containing materials are responsible for verifying the location, quantity, degree of difficulty and necessity for removing the identified materials.

DISCUSSIONS AND RECOMMENDATIONS (ASBESTOS)

A trace amount (<0.1%) of asbestos was identified in the cove base adhesive of this scope of work.

Materials found to be below 0.1% require disturbance by asbestos trained personnel in accordance with CAL/OSHA 1529 and 5208. A notification for rule 1403 is not required and asbestos abatement license registration is also not required by the California Department of Occupational Safety and health (CAL DOSH). OSHA training requirements apply to all asbestos related work regardless of the asbestos content of impacted materials.

ENCORP also recommends that a California Certified Asbestos Consultant/Site Surveillance Technician oversee the project to ensure that proper methods are being utilized.

Additional asbestos-containing may be present at this site. Care should be taken when demolishing materials that will open wall cavities or sealed ceiling areas. Any additional suspect asbestos material encountered during demolition that is not shown in this report should be sampled and analyzed prior to disturbance. Asbestos containing materials (ACM) should be removed by a California trained and licensed abatement contractor in accordance with all governing regulations. If any additional known, assumed, or suspected asbestos-containing materials are discovered during renovation, remodeling or demolition activities, contact an environmental consultant to determine the proper course of action.

INSPECTION RESULTS -- LEAD (XRF Analysis)

The Niton XRF Spectrum Analyzer was utilized for the analysis of suspect lead-based painted materials. In this method of analysis, the material is exposed to X-Rays or other high-energy radiation (such as gamma rays), which causes lead to emit X-Rays with a characteristic frequency. The intensity of this radiation is measured by the instrument's detector and is then converted into a number that represents the amount of lead in the material per unit area, usually milligrams per square centimeter (mg/cm²).

The HUD and OSHA have set a lead level of 1.0 mg/cm² as being a regulated lead-containing material. All components with results of >0.7 mg/cm² are considered lead-based paint based on the location of the subject property in Los Angeles County, the "abatement" level" (threshold) setting of 0.7 mg/cm² was chosen for the inspection. Analytical sensitivity of the XRF measurement methodology reports positive lead-based content results at or above 0.7 mg/cm², presence of lead content result between 0.1 and 0.6 mg/cm², and results below the detection limit at less than 0.1 mg/cm². CAL/OSHA considers all lead surface levels to be of concern.

Listed below is a summary of the materials sampled. Items found positive for lead-based paint using XRF analyses at these buildings are highlighted in **BOLD RED**, along with the location and estimated quantity. A complete listing of all components tested can be found in Section IIB of this report. Results are reported as Below Level of Detection = BLD, Lead Containing Paint = LCP, Lead-Based Paint = LBP.

		SUMMARY	OF LEAD-CON	TAINING COMPONE	NTS TEST	TED .	
Sample No	Color	Substrate	Component	Location	Results	Mg/cm2	QTY
4	Tan	Stucco	Overhang Trim	Media Center Exterior	BLD	0.0	-
5	Tan	Stucco	Overhang Trim	Media Center Exterior	BLD	0.0	-
6	Tan	Metal	Overhang Panel	Media Center Exterior	BLD	0.0	-
7	Tan	Metal	Overhang Panel	Media Center Exterior	BLD	0.0	-
8	Red	Metal	Door	Media Center Exterior	BLD	0.0	-
9	Black	Metal	Door Frame	Media Center Exterior	BLD	0.0	-
10	Black	Metal	Window Frame	Media Center Exterior	BLD	0.0	-
11	Red	Metal	Window Panel	Media Center Exterior	BLD	0.0	-
12	Red	Metal	Door	Media Center Interior	BLD	0.0	-
13	Black	Metal	Door Frame	Media Center Interior	BLD	0.0	-
14	White	Metal	Wall Panel	Media Center Interior	BLD	0.0	-
15	White	Metal	Wall Panel	Media Center Interior	BLD	0.0	-
16	White	Metal	Wall Panel	Media Center Interior	BLD	0.0	-
17	White	Metal	Wall Panel	Media Center Interior	BLD	0.0	-
18	Black	Steel	Beam	Media Center Interior	BLD	0.0	-
19	White	Wood	Door	Media Center Interior	BLD	0.0	-
20	Black	Metal	Door Frame	Media Center Interior	BLD	0.0	-
21	Tan	Metal	Wall Panel	Media Center Interior	BLD	0.0	-
22	Grey	Wood	Door	Media Center Interior	BLD	0.0	-
23	Red	Brick	Wall	Media Center Interior	BLD	0.0	-
24	Red	Brick	Wall	Media Center Interior	BLD	0.0	-
25	Red	Brick	Wall	Media Center Exterior	BLD	0.0	-
26	Red	Brick	Wall	Media Center Exterior	BLD	0.0	-

Note: The quantities listed are for budgetary purposes only. Contractors completing proposals for the removal of lead containing materials are responsible for verifying the location, quantity, degree of difficulty and necessity for removing the identified materials.

Results are reported as Below Level of Detection = BLD, Lead Containing Paint = LCP, Lead-Based Paint = LPB.

DISCUSSIONS AND RECOMMENDATIONS (LEAD)

Lead-Based Paint was NOT identified in this scope of work.

All components with results of ≥0.7 mg/cm² are considered lead-based paint in Los Angeles County. A trained lead-based paint contractor should perform the paint film stabilization, loose and flaky paint, and any preparations of lead bearing levels of surfaces for repainting.

Minor disturbance to lead-based painted components such as coring or drilling can be performed by a certified trained contractor with a minimum OSHA Lead Awareness Operations and Maintenance Training, and EPA Lead Renovators (EPA Renovate, Repair and Painting Rule training). This work classification is used as an adequate alternative for trade work involving electrical, lighting, plumbing, painting and miscellaneous disturbances where work is likely to disturb lead containing components as part of construction activities other than lead abatement purposes.

Any material containing any detectable level of lead is subject to the OSHA's Lead Exposure in Construction Rule, 29 Code of Federal Regulation (CFR) 1926. All removal of lead-based painted (LBP) should be performed by a state-licensed contractor, using CDPH-certified workers with at least one CDPH-certified Supervisor.

CONCLUSION

A trace amount (<0.1%) of asbestos was identified in the cove base adhesive of this scope of work.

Materials found to be below 0.1% require disturbance by asbestos trained personnel in accordance with CAL/OSHA 1529 and 5208. A notification for rule 1403 is not required and asbestos abatement license registration is also not required by the California Department of Occupational Safety and health (CAL DOSH). OSHA training requirements apply to all asbestos related work regardless of the asbestos content of impacted materials.

ENCORP also recommends that a California Certified Asbestos Consultant/Site Surveillance Technician oversee the project to ensure that proper methods are being utilized. Sampling was limited to only areas and materials indicated as being impacted.

Any suspect asbestos material encountered during demolition that is not shown in this report should be sampled and analyzed prior to disturbance.

Lead-Based Paint was NOT identified in this scope of work.

All components with results of ≥0.7 mg/cm² are considered lead-based paint in Los Angeles County. A trained lead-based paint contractor should perform the paint film stabilization, loose and flaky paint, and any preparations of lead bearing levels of surfaces for renovation/repair/repainting.

Minor disturbance to lead-based painted components such as coring or drilling can be performed by a certified trained contractor with a minimum OSHA Lead Awareness Operations and Maintenance Training, and EPA Lead Renovators (EPA Renovate, Repair and Painting Rule training). This work classification is used as an adequate alternative for trade work involving electrical, lighting, plumbing, painting and miscellaneous disturbances where work is likely to disturb lead containing components as part of construction activities other than lead abatement purposes.

Any material containing any detectable level of lead is subject to the OSHA's Lead Exposure in Construction Rule, 29 Code of Federal Regulation (CFR) 1926. All removal of lead-based painted (LBP) should be performed by a state-licensed contractor, using CDPH-certified workers with at least one CDPH-certified Supervisor.

Additional asbestos-containing and lead-based painted materials may be present at this site. Care should be taken when demolishing materials that will open wall cavities or sealed ceiling areas. If any additional known, assumed, or suspected asbestos-containing materials or lead-based painted components are discovered during renovation, remodeling or demolition activities, contact an environmental consultant to determine the proper course of action.

Should you have any questions concerning this report, please contact me at (714) 523-9811. Thank you.

Respectfully submitted,

Howard Baba

Operations Manager, ENCORP

Certified Asbestos Consultant No. 95-1791

Lead Inspector/Risk Assessor No. LRC-00003404





Reference Batch Number: 064174 Sampled Date: Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002

Facility Name: Wilson HS Media Center-Library Hacienda Heights, CA 91745 Facility Address: 16455 Wedgeworth Drive

ANGEL JIMENEZ 1/21/2025 Sampled By:

Date Analyzed: 1/31/2025 Date Received: 1/21/2025

H21

Project Number: P25033

KRISTINA MARTINEZ

Analyzed By:

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

of the second		SAMPLE DESCRIPTION				EV.	
Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-	Asbestos	Non Asbestos (%)
822931A	001A	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) 6" BLACK COVE BASE	N.	NONE DETECTED	100% MATRIX
822931B	001B	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) MASTIC	₽ E	<1% TREMOLITE	100% MATRIX
822931C	001C	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) GLUE	Ä	NONE DETECTED	100% MATRIX
822931P	001P	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) MASTIC	뿔	<0.1%CHRYSOTILE	99.9%MATRIX
822932A	002A	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOMGENEOUS) 6" BLACK COVE BASE	Ŗ	NONE DETECTED	100% MATRIX
822932B	002B	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) MASTIC	Ŗ	<1% TREMOLITE	100% MATRIX
822932C	002C	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) GLUE	Ä	NONE DETECTED	100% MATRIX
822932P	002P	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) MASTIC	Ē.	<0.1 TREMOLITE	99.9%MATRIX

Page 1 of 12 were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples. the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable.

Reference Batch Number: 064174 Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002

Facility Name: Wilson HS Media Center-Library Facility Address: 16455 Wedgeworth Drive

Hacienda Heights, CA 91745

Sampled By: ANGEL JIMENEZ Sampled Date: 1/21/2025

Date Received: 1/21/2025

H21

Project Number: P25033

Date Analyzed: 1/31/2025

Analyzed By: KRISTINA MARTINEZ

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

damo		SAMPLE DESCRIPTION				TV.	
Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-	Asbestos	Non Asbestos (%)
822933A	003A	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) 6" BLACK COVE BASE	Ľ.	NONE DETECTED	100% MATRIX
822933B	003B	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) MASTIC	Ę	<1% TREMOLITE	100% MATRIX
822933C	003C	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) GLUE	분	NONE DETECTED	100% MATRIX
822933P	003P	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) MASTIC	Ę	<0.1%TREMOLITE	99.9%MATRIX
822934	004	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) CARPET GLUE	ĸ	NONE DETECTED	100% MATRIX
822935	005	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) CARPET GLUE	분	NONE DETECTED	100% MATRIX
822936	900	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) CARPET GLUE	분	NONE DETECTED	100% MATRIX
822937	200	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) CARPET MASTIC	E Z	NONE DETECTED	100% MATRIX

Page 2 of 12 the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples.

Page 2 of were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or purposes without prior written authorization is Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the

714) 523-9811 · FAX (714) 523-9810 · MAIN@ENCORP.NET · WWW.ENCORP.NET 16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638 ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002 Facility Name: Wilson HS Media Center-Library

Sampled By: Sampled Date: Reference Batch Number:

Date Analyzed: 1/31/2025 Date Received: 1/21/2025

H21

Project Number: P25033

KRISTINA MARTINEZ

ANGEL JIMENEZ

Analyzed By:

1/21/2025 064174

Hacienda Heights, CA 91745

Facility Address: 16455 Wedgeworth Drive

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

		NOLEGIC DESCRIPTION					
Sample	Ciple! Olions	SAMPLE DESCRIPTION				CVE	
Number	Number	Sample Location/Activity	Color	Material	Friable or Non-	Asbestos	Non Asbestos (%)
822938	800	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) CARPET MASTIC	Ľ	NONE DETECTED	100% MATRIX
822939	600	BLDG. B - MEDIA CENTER INT.	BROWN	(HOMOGENEOUS) CARPET MASTIC	E Z	NONE DETECTED	100% MATRIX
822940A	010A	BLDG. B - MEDIA CENTER INT.	WHITE	(HOMGOENEOUS) VINYL FLOOR TILE	E Z	NONE DETECTED	100% MATRIX
822940B	0108	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) MASTIC	L Z	NONE DETECTED	100% MATRIX
822941A	011A	BLDG. B - MEDIA CENTER INT.	WHITE	(HOMOGENEOUS) VINYL FLOORI TILE	L Z	NONE DETECTED	100% MATRIX
822941B	0118	BLDG. B - MEDIA CENTER INT.	вгаск	(HOMOGENEOUS) MASTIC	F.	NONE DETECTED	100% MATRIX
822942A	012A	BLDG. B - MEDIA CENTER INT.	WHITE	(HOMOGENEOUS) VINYL FLOOR TILE	Ä	NONE DETECTED	100% MATRIX
822942B	012B	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) MASTIC	E C	NONE DETECTED	100% MATRIX

Page 3 of 12 were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples.

Page 3 of 1 the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable.

Reference Batch Number: Sampled Date: Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002 Facility Name: Wilson HS Media Center-Library

Facility Address: 16455 Wedgeworth Drive

Hacienda Heights, CA 91745

ANGEL JIMENEZ 1/21/2025 Sampled By:

064174

Date Received: 1/21/2025 Project Number: P25033

H21

Date Analyzed: 1/31/2025

Analyzed By: KRISTINA MARTINEZ

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

	Non Asbestos (%)	ED 100% MATRIX	ED 100% MATRIX	ED 100% MATRIX	ED 100% MATRIX	ED 100% MATRIX	ED 100% MATRIX	ED 100% MATRIX	ED 100% MATRIX
CVF	As	NONE DETECTED	NONE DETECTED	NONE DETECTED	NONE DETECTED	NONE DETECTED	NONE DETECTED	NONE DETECTED	NONE DETECTED
	Friable or Non-	Ë	Z L	Ľ.	E E	E Z	Ę	L Z	¥.
	Material	(HOMOGENEOUS) LEVELING COMPOUND	(HOMOGENEOUS) LEVELING COMPOUND	(HOMOGENEOUS) LEVELING COMPOUND	(HOMOGENEOUS) WALK ON MAT ADHESIVE	(HOMOGENEOUS) WALK ON MAT ADHESIVE	(HOMOGENEOUS) WALK ON MAT ADHESIVE	(HOMOGENEOUS) 12X12 GRAY VFT	(HOMOGENEOUS) MASTIC
SAMPLE DESCRIPTION	rity Color	YELLOW	YELLOW	YELLOW	YELLOW	YELLOW	YELLOW	GRAY	BLACK
SAMPLE	Sample Location/Activity	BLDG. B - MEDIA CENTER INT.	BLDG. B - MEDIA CENTER INT.	BLDG. B - MEDIA CENTER INT.	BLDG. B - MEDIA CENTER INT.	BLDG. B - MEDIA CENTER INT.	BLDG. B - MEDIA CENTER INT.	BLDG. B - MEDIA CENTER INT.	BLDG. B - MEDIA CENTER INT.
	Field/ Client Number	013	910	015	910	017	018	019A	019B
Common	Number	822943	822944	822945	822946	822947	822948	822949A	822949B

Page 4 of 12 the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples.

Page 4 of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or pubpicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable.

Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002

Facility Name: Wilson HS Media Center-Library

Facility Address: 16455 Wedgeworth Drive

Hacienda Heights, CA 91745

1/21/2025 Reference Batch Number: 064174 Sampled By: Sampled Date:

Date Received: 1/21/2025

Project Number: P25033

Analyzed By: KRISTINA MARTINEZ ANGEL JIMENEZ

Date Analyzed: 1/31/2025

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

		SAMPLE DESCRIPTION					
Sample Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or	CVE Asbestos	Non Asbestos (%)
822950A	020A	BLDG. B - MEDIA CENTER INT.	GRAY	(HOMOGENEOUS) 12X12 GRAY VFT	Ľ.	NONE DETECTED	100% MATRIX
822950B	020B	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) MASTIC	L Z	NONE DETECTED	100% MATRIX
822951A	021A	BLDG. B - MEDIA CENTER INT.	GRAY	(HOMOGENEOUS) 12X12 GRAY VFT	E C	NONE DETECTED	100% MATRIX
822951B	0218	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) MASTIC	Ę	NONE DETECTED	100% MATRIX
822952A	022A	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) CARPET PAD	L Z	NONE DETECTED	95% SYNTHETIC FIBER 5% MATRIX
822952B	022B	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) ADHESIVE	보	NONE DETECTED	100% MATRIX
822953A	023A	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) CARPET PAD	Ľ	NONE DETECTED	95% SYNTHETIC FIBER 5% MATRIX
822953B	023B	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) ADHESIVE	Ľ	NONE DETECTED	100% MATRIX

Page 5 of 12 were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples.

Page 5 of 1 the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable.

1/21/2025 Reference Batch Number: 064174 Sampled Date: Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002 Facility Name: Wilson HS Media Center-Library

Hacienda Heights, CA 91745 Facility Address: 16455 Wedgeworth Drive

ANGEL JIMENEZ Sampled By:

Date Received: 1/21/2025 Project Number: P25033

Date Analyzed: 1/31/2025

Analyzed By: KRISTINA MARTINEZ

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

o de mario		SAMPLE DESCRIPTION				EV.	
Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-	Asbestos	Non Asbestos (%)
822954A	024A	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) CARPET PAD	ĽZ	NONE DETECTED	95% SYNTHETIC FIBER 5% MATRIX
822954B	024B	BLDG. B - MEDIA CENTER INT.	BEIGE	(HOMOGENEOUS) ADHESIVE	R E	NONE DETECTED	100% MATRIX
822955	025	BLDG. B - MEDIA CENTER INT.	WHITE	(FIBROUS) WALL PANEL INSULATION	Æ	NONE DETECTED	2% CELLULOSE 98% MATRIX
822956	026	BLDG. B - MEDIA CENTER INT.	WHITE	(FIBROUS) WALL PANEL INSULATION	Æ	NONE DETECTED	2% CELLULOSE 98% MATRIX
822957	027	BLDG. B - MEDIA CENTER INT.	WHITE	(FIBROUS) WALL PANEL INSULATION	æ	NONE DETECTED	2% CELLULOSE 98% MATRIX
822958	028	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) CEILING PANEL INSULATION	쯌	NONE DETECTED	25% CELLULOSE 65% FIBROUS GLASS 10% MATRIX
822959	029	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) CEILING PANEL INSULATION	쯌	NONE DETECTED	25% CELLULOSE 65% FIBROUS GLASS 10% MATRIX
822960	030	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) CEILING PANEL INSULATION	፳	NONE DETECTED	25% CELLULOSE 65% FIBROUS GLASS 10% MATRIX

the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples.

Page 6 of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable.

Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002

Facility Name: Wilson HS Media Center-Library Facility Address: 16455 Wedgeworth Drive

Hacienda Heights, CA 91745

ANGEL JIMENEZ 1/21/2025 Reference Batch Number: 064174 Sampled Date: Sampled By:

Date Received: 1/21/2025

H21

Project Number: P25033

Date Analyzed: 1/31/2025

Analyzed By: KRISTINA MARTINEZ

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

Clame		SAMPLE DESCRIPTION				EVS	
Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-	Asbestos	Non Asbestos (%)
822961A	031A	BLDG. B - MEDIA CENTER INT.	BLACK	(FIBROUS) CEILING SPACE ROOFING DEBRIS	R	NONE DETECTED	10% FIBROUS GLASS 90% MATRIX
822961B	031B	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) MASTIC	L Z	NONE DETECTED	100% MATRIX
822961C	031C	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) INSULATION	Æ	NONE DETECTED	75% CELLULOSE 25% MATRIX
822961D	031D	BLDG. B - MEDIA CENTER INT.	YELLOW	(HOMOGENEOUS) FOAM	N-	NONE DETECTED	100% MATRIX
822962A	032A	BLDG. B - MEDIA CENTER INT.	BLACK	(FIBROUS) CEILING SPACE ROOFING DEBRIS	N.	NONE DETECTED	10% FIBROUS GLASS 90% MATRIX
822962B	032B	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) MASTIC	Ä	NONE DETECTED	100% MATRIX
822962C	032C	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) INSULATION	Æ	NONE DETECTED	75% CELLULOSE 25% MATRIX
822962D	032D	BLDG. B - MEDIA CENTER INT.	YELLOW	(HOMOGENEOUS) FOAM	Ą	NONE DETECTED	100% MATRIX

Page 7 of 12 the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or pubpicity purposes without prior written authorization is -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the

Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002 Facility Name: Wilson HS Media Center-Library

Facility Address: 16455 Wedgeworth Drive

Hacienda Heights, CA 91745

1/21/2025 064174 Reference Batch Number: Sampled Date:

Date Received: 1/21/2025

Project Number: P25033

Date Analyzed: 1/31/2025

Analyzed By: KRISTINA MARTINEZ Sampled By: ANGEL JIMENEZ

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

Samula		SAMPLE DESCRIPTION				EV.S	
Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-	Asbestos	Non Asbestos (%)
822963A	033A	BLDG. B - MEDIA CENTER INT.	BLACK	(FIBROUS) CEILING	I Z	NONE DETECTED	10% FIBROUS GLASS
				SPACE ROOFING DEBRIS			90% MATRIX
822963B	033B	BLDG. B - MEDIA CENTER INT.	BLACK	(HOMOGENEOUS) MASTIC	E.	NONE DETECTED	100% MATRIX
822963C	033C	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) INSULATION	Æ	NONE DETECTED	75% CELLULOSE 25% MATRIX
822963D	033D	BLDG. B - MEDIA CENTER INT.	YELLOW	(HOMOGENEOUS) FOAM	F	NONE DETECTED	100% MATRIX
822964	034	BLDG. B - MEDIA CENTER INT.	YELLOW/BROWN	(FIBROUS) PIPE RUN INSULATION	Ā	NONE DETECTED	30% CELLULOSE 65% FIBROUS GLASS 5% MATRIX
822965	035	BLDG. B - MEDIA CENTER INT.	YELLOW/BROWN	(FIBROUS) PIPE RUN INSULATION	Ŗ	NONE DETECTED	30% CELLULOSE 65% FIBROUS GLASS 5% MATRIX
822966	036	BLDG. B - MEDIA CENTER INT.	YELLOW/BROWN	(FIBROUS) PIPE RUN INSULATION	Ŗ	NONE DETECTED	30% CELLULOSE 65% FIBROUS GLASS 5% MATRIX
822967	037	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) HVAC INSULATION	Æ	NONE DETECTED	100% FIBROUS GLASS

the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or pubpicity purposes without prior written authorization is composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples.

Page 8 of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples. -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the

Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002

Facility Name: Wilson HS Media Center-Library Facility Address: 16455 Wedgeworth Drive

Hacienda Heights, CA 91745

1/21/2025 064174 Reference Batch Number: Sampled Date:

ANGEL JIMENEZ Sampled By: Analyzed By: KRISTINA MARTINEZ

Date Received: 1/21/2025 Project Number: P25033

H21

Date Analyzed: 1/31/2025

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

		SAMPLE DESCRIPTION				í	
Sample	Field/ Client				Friable or	CVE	
Number	Number	Sample Location/Activity	Color	Material	Non-	Asbestos	Non Asbestos (%)
822968	038	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) HVAC INSULATION	A.	NONE DETECTED	100% FIBROUS GLASS
822969	039	BLDG. B - MEDIA CENTER INT.	BROWN	(FIBROUS) HVAC INSULATION	Æ	NONE DETECTED	100% FIBROUS GLASS
822970	040	BLDG. B - MEDIA CENTER INT.	GRAY	(HOMOGENEOUS) STEEL BEM CAULKING	¥	NONE DETECTED	100% MATRIX
822971	041	BLDG. B - MEDIA CENTER INT.	GRAY	(HOMOGENEOUS) STEEL BEM CAULKING	E Z	NONE DETECTED	100% MATRIX
822972	042	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) STEEL BEM CAULKING	Ę	NONE DETECTED	100% MATRIX
822973A	043A	BLDG. B - MEDIA CENTER EXT	RED	(HOMOGENEOUS) BRICK	R.	NONE DETECTED	100% MATRIX
822973B	043B	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) MORTAR	Ę.	NONE DETECTED	100% MATRIX
822974A	044A	BLDG. B - MEDIA CENTER EXT	RED	(HOMOGENEOUS) BRICK	Ŗ	NONE DETECTED	100% MATRIX

Page 9 of 12 were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos she represents the composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples. the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable.

Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

Reference Batch Number: 064174

CITY OF INDUSTRY, CA 91716-0002 Facility Name: Wilson HS Media Center-Library

Hacienda Heights, CA 91745 Facility Address: 16455 Wedgeworth Drive

Analyzed By: KRISTINA MARTINEZ Sampled By: ANGEL JIMENEZ Sampled Date: 1/21/2025

Date Received: 1/21/2025

H21

Project Number: P25033

Date Analyzed: 1/31/2025

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

Comple		SAMPLE DESCRIPTION				EV.	
Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-	Asbestos	Non Asbestos (%)
822974B	044B	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) MORTAR	E N	NONE DETECTED	100% MATRIX
822975A	045A	BLDG. B - MEDIA CENTER EXT	RED	(HOMOGENEOUS) BRICK	L Z	NONE DETECTED	100% MATRIX
822975B	045B	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) MORTAR	Ŗ	NONE DETECTED	100% MATRIX
822976A	046A	BLDG. B - MEDIA CENTER EXT	BEIGE	(HOMOGENEOUS) SKIM COAT	L Z	NONE DETECTED	100% MATRIX
822976B	046B	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) STUCCO OVERHANG	¥	NONE DETECTED	100% MATRIX
822977A	047A	BLDG. B - MEDIA CENTER EXT	BEIGE	(HOMOGENEOUS) SKIM COAT	Ľ.	NONE DETECTED	100% MATRIX
822977B	047B	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) STUCCO OVERHANG	Ĩ.	NONE DETECTED	100% MATRIX
822978A	048A	BLDG. B - MEDIA CENTER EXT	BEIGE	(HOMOGENEOUS) SKIM COAT	E N	NONE DETECTED	100% MATRIX

Page 10 of 12 the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples.

Radiding Materials, EPA - 40 CFR Appendix E to Subpart E of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable.

Reference Batch Number: 064174 Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002 Facility Name: Wilson HS Media Center-Library

Hacienda Heights, CA 91745 Facility Address: 16455 Wedgeworth Drive

ANGEL JIMENEZ 1/21/2025 Sampled Date: Sampled By:

Analyzed By: KRISTINA MARTINEZ

Date Analyzed: 1/31/2025

H21

Date Received: 1/21/2025 Project Number: P25033

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

		SAMPLE DESCRIPTION				1,10	
Sample	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-	Asbestos	Non Asbestos (%)
822978B	048B	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) STUCCO OVERHANG	Ä	NONE DETECTED	100% MATRIX
822979A	049A	BLDG. B - MEDIA CENTER EXT	BEIGE	(HOMOGENEOUS) SKIM COAT	Ľ.	NONE DETECTED	100% MATRIX
822979B	049B	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) STUCCO OVERHANG	F.	NONE DETECTED	100% MATRIX
822980A	050A	BLDG. B - MEDIA CENTER EXT	BEIGE	(HOMOGENEOUS) SKIM COAT	L N	NONE DETECTED	100% MATRIX
822980B	0508	BLDG. B - MEDIA CENTER EXT	GRAY	(HOMOGENEOUS) STUCCO OVERHANG	Ę	NONE DETECTED	100% MATRIX
822981	051	BLDG. B - MEDIA CENTER EXT	BROWN	(FIBROUS) OVERHANG PANEL INSULATION	R.	NONE DETECTED	100% FIBROUS GLASS
822982	052	BLDG. B - MEDIA CENTER EXT	BROWN	(FIBROUS) OVERHANG PANEL INSULATION	R	NONE DETECTED	100% FIBROUS GLASS
822983	053	BLDG. B - MEDIA CENTER EXT	BROWN	(FIBROUS) OVERHANG PANEL INSULATION	Æ	NONE DETECTED	100% FIBROUS GLASS

Page 11 of 12 the specific scope of accreditation under NVLAP Lab Code 200878-0. This report applies only to the items as received. Results are representative of the samples submitted and may not represent the entire materials from which the samples composite percentage of all sample layers. These samples were quantified using a calibrated visual estimate. Bulk sample(s) submitted were analyzed in accordance with the procedures EPA 600/R-93/116: Method for the Determination of Asbestos in Bulk Insulation Samples.

Page 11 of Part 763, Interim Method of the Determination of Asbestos in Bulk Insulation Samples. were collected. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or pubpicity purposes without prior written authorization is Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for -NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the

Reference Batch Number: 064174 Client Address: 350 N. HACIENDA BLVD. Client Name: HACIENDA LA PUENTE

CITY OF INDUSTRY, CA 91716-0002

Facility Name: Wilson HS Media Center-Library

Facility Address: 16455 Wedgeworth Drive

Hacienda Heights, CA 91745

ANGEL JIMENEZ 1/21/2025 Sampled By: Sampled Date:

Analyzed By: KRISTINA MARTINEZ

Date Received: <u>1/21/2025</u>

H21

Project Number: P25033

Date Analyzed: 1/31/2025

olumb.		SAMPLE DESCRIPTION	N			EVE.	
Calliple	Field/ Client				Friable or	1	
lumber	Nimber	Sample Location/Activity	Color	Material	No.	Aspestos	Non Aspestos (%)

LABORATORY TEST REPORT FOR BULK ASBESTOS FIBER ANALYSIS (PLM)

Notes: P-1000 POINT COUNT



ENCORP 174 CHAIN OF CUSTODY FORM Asbestos Bulk Analysis: Z PLM Bulk | 1000 Poi

Asbestos Bulk Analysis: ☐ PLM Bulk ☐ 1000 Point Count Turn-around Time: ☐ RUSH ☐ 24 HRS ☐ 48 HRS ☐ 72 HRS ☐ Standard

16700 Valley View Avenue, Suite 100	La Mirada, California 90638	Tel. (714) 523-9811	Fax: (714) 523-9810
valley View Ar	La Mirada, (Tel	Fax
16/00			

CLIENT:	Haciena (Turn-around Time: RUSH 12 24 1 LS 12 INSPECTORS:	Furn-around Time: RUSH Z 24 HRS	0	www.encorp.net
OCATION		Wilson Its They're Confer			

SAMPLE NO.	LAB ID#	SAMPLE LOCATION	MATERIA	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
-	18677	26231 BLDG B - CENTER INT	6. Black	6. Bluck Coverage/ Vostre/614		:	
2.	2332						
က	12233						
4.	75734		(arpe	Carpet 6 lue			
જ	722335						
ဖွဲ	.22a3 6						
7.	922937		Corpe	Carpet Mastic			
ၹၴ	. 22338						
6	52339		_				
0.	× 522340		Limp! Fi	Umyl Floor Tile			
	The state of the s						

			Sampled by Relinquished: Date/Time:
TYPES OF MATERIALS:	CONDITION:	OTHER	Aree Truesas and
S = Surface Material	G = Good	S.F. = Square Feet	Reinspektion of By S. M. of S. M. of S. M. of S. A. S. M. o. S. C.
M = Miscellaneous Material	SD = Significantly Damaged	L.r Linear rest	Relinquished/Received By:
Comments/special Instructions:			
ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 - La Mirada - California 90638	ey View Avenue, Suite 100 · La Mirada	-California 90638	Office (714) 523-9811 . Fax (714) 523-981

7 VablickFORMVield Forms/Current Field Forms/Bulk Sample Forms

ENCORP Engineering our Environment

06 4 1 7 4 CHAIN OF CUSTODY FORM

Asbestos Bulk Analysis: ☐ PLM Bulk ☐ 1000 Point Count Turn-around Time: ☐ RUSH ☐ 24 HRS ☐ 48 HRS ☐ 72 HRS ☐ Standard

16700 Valley View Avenue, Suite 100 La Mirada, California 90638 Tel: (714) 523-9811 Fax: (714) 523-9810 www.encorp.net

	•
Fax: (714) 523-98	
Tel: (714) 523-98	
La Mirada, California 906	
10100 tales attended of the	

CLIENT:	CLIENT: Havierda La Prente USD	Preste USD	DATE: 1/21/25 PAGE:) 0 F	9
JOB NO:	JOB NO: 825033.421	INSPECTORS:	Argel Somener		
LOCATION:	L.	Wison Its wedin conter			
	: !				

SAMPLE NO.	LABID#	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	176228				(90)	
2.	258228					
3.	\$22543		leading compound			
4.	7587					
(5.	25070					
. 6.	822346		ualk on mot Adhes NE			
(7.	75:77					
8.	22.48					
.6	67:72		126 12 6 my UFT / 125 AZ			
7 0.	.52.50					

	ABBREVIATIONS:		CHAIN OF CUSTODY
TYPES OF MATERIALS	CONDITION:	OTHED	Sampled by/Relinquished:
			Aree Truesas and 1/21/25 1300
S = Surface Material	9 = Good	S.F. = Square Feet	Saller Baller
N = Miscellaneous Material	SD = Significantly Damaged	L.r. = Linear reet	Relinquished/Received By:
Comments/special Instructions:			
ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 - La Mirada - California 90638	lley View Avenue, Suite 100 · La Mirada ·	California 90638	Office (714) \$23-9811 - Fax (714) \$23-9810

Z. Public/FORM/Field Forms/Current Field Forms/Bulk Sample Forms

E ENCORP **Engineering our Environment**

06 4 1 7 4 CHAIN OF CUSTODY FORM

16700 Valley View Avenue, Suite 100 La Mirada, California 90638 Tel: (714) 523-9811 Fax: (714) 523-9810 www.encorp.net

Asbestos Bulk Analysis: ☐ PLM Bulk ☐ 1000 Point Count Turn-around Time: ☐ RUSH ☐ 24 HRS ☐ 48 HRS ☐ 72 HRS ☐ Standard La Prente

INSPECTORS:

Carter

nedia

£

1, 15on

LOCATION:

127

Hacierda 850574

CLIENT: JOB NO:

500

PAGE: Umerer 12/12 Je je DATE:

Q

о Г

SAMPLE NO.	LAB ID#	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
2 1.	.2.51					9
2 2.	2.52		compating fact palses in			
2 3.	53					
.4 2	\$22324					
2 5.	25.77		bod Bonel			
26.	12.56					**************************************
2 7.	12 57					
2 8.	12.58		cei (ing papel)			
6 2	.2.59					
٧ 0.	72 60					

			COSTO OF COSTO
			Sampled by/Relatiquishod: Date/Time:
TYPES OF MATERIALS:	CONDITION:	OTHER:	Arcel Smara2 and 121/25 1500
S = Surface Material	9 = 600d	S.F. = Square Feet	Soller Allen
M = Miscellaneous Material	SD = Significantly Damaged	L.r. = Linear reet	Relinquished/Recerved By:
Comments/special Instructions:			
ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 . Le Mireda . Ceiliomia 90638	sy View Avenue, Suite 100 . La Mirada · (California 90638	Office (714) 523-9611 - Fax (714) 523-9810

Z. Public/FORM/Field Forms/Current Field Forms/Bulk Sample Forms

ENCORP Engineering our Environment

06 4 1 7 4 CHAIN OF CUSTODY FORM

PLM Bulk Asbestos Bulk Analysis:

16700 Valley View Avenue, Suite 100 La Mirada, California 90638	Tel: (714) 523-9811	Fax: (714) 523-9810	www.encorp.net

☐ 1000 Point Count Turn-around Time:

RUSH

X	٨	
tandard	PAGE:	ڵ ا
☐ RUSH ☑ 24 HRS ☐ 48 HRS ☐ 72 HRS ☐ Standard	DATE: 1/2//25	Ared Smeyer
RUSH - 12 24 HRS	ľ	INSPECTORS:

Carter

nedia

£

Wilson

JOB NO: 825033.421 CLIENT: Hacienda

LOCATION:

C S D

la Prente

SAMPLE NO.	LAB ID#	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
3 1.	1977.		Leilng sport			
3 2.	. 22. 62					
7 3.	77 63					
3 4.	17.77		pipe pun Irsulahir		(45)	
ψ,	. 2.2.65					
W.	99:77:					
3 7.	75.22		that Disciption			
3 8.	89 77					
% %	69.77					
رد ٥.	70 70		steel Beard Courting			

11 1 12 22 1 1 1 1 1 1 1 1 1 1 1 1 1	ABBREVIATIONS:		CHAIN OF CUSTODY
TYPES OF MATERIALS:	CONDITION:	отнек:	Sampled by Relinquished: Angel Struerae 2 A 1/21/25 (520)
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	S.F. = Square Feet L.F. = Linear Feet	Control By, Baller Holl
Comments/special Instructions:			
ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 · La Mirada · California 90638	ley View Avenue, Suite 100 · La Mirada	California 90638	Office (7.4) \$23-9911 Fax (7.14) \$23-9910

Z.NPublickFORMVField Forms/Current Field Forms/Bulk Sample Forms



06 4 1 7 4 CHAIN OF CUSTODY FORM

Asbestos Bulk Analysis: ☐ PLM Bulk ☐ 1000 Point Count Turn-around Time: ☐ RUSH ☐ 24 HRS ☐ 48 HRS ☐ 72 HRS ☐ Standard

					i.		
LIENT:	LIENT: Havierda La Puente USD	Prende USD	DATE: 1/21/25	PAGE:	7	0 F	9
OB NO:	825033.421	INSPECTORS:	Agel Smeyer	۱			
OCATION:		utilson Its weather conter					

SAMPLE NO.	LABID#	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
η 1.	11.8728					
ι(2.	622572	predia Center				
ý 3.	87873		sick/ horter			
ý 4.	71.6723					
ψ 5.	822375			,		
y 6.	92072		Stacco overheary			
γ.	11.77					
٧ 8.	22:73					
·6)·	52.79					
≥ 0.	2.2 80					
	ABBREVIATIONS	No.	VACTOR OF MALE	3		

THE PERSON NAMED IN COLUMN 1	ABBREVIATIONS:		CHAIN OF CUSTODY
			Sampled by/Relinquished: Date Time:
TYPES OF MATERIALS:	CONDITION:	OTHER:	Area Smenez and 1/21/25,500
S = Surface Material	poo5 = 5	S.F. = Square Feet	A Bollox Aller
(15) = Thermal Systems Insulation M = Miscellaneous Material	U = Damaged SD = Significantly Damaged	L.r. = Linear reet	Relinquished/Received By:
Comments/special Instructions:			
ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 . La Mirada - California 90638	y View Avenue, Suite 100 · La Mirada · C	California 90638	Office (714) 593-4841 - Fee (714) 593-4841
			Desire (c. 1) for a constitution of

ENCORP Engineering our Environment

06 4 1 7 4 CHAIN OF CUSTODY FORM

Asbestos Bulk Analysis: ☐ PLM Bulk ☐ 1000 Point Count Turn-around Time: ☐ RUSH ☐ 24 HRS ☐ 48 HRS ☐ 72 HRS ☐ Standard

JOB NO:	LOCATION:	SAMPLE NO.	ζ 1.	\$ 2.	53.	4.	ιċ	ဖ	7.	œί	6	·o
JOB NO: 825033.421	U; (LABID#	18.77	\$22082	827783							
	Wilson Its media carter	SAMPLE LOCATION										
Ared Smerer		MATERIAL DESCRIPTION	wereng novel									
erer		CONDITION QUANTITY										
		% ASBESTOS										

TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled by Relinquished: Anop () True as 2
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	S.F. = Square Feet L.F. = Linear Feet	and By 3 church Affiles
Comments/special Instructions: ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 - La Mirada - California 90638	ley Vrew Avenue, Suite 100 · La Mirada ·	California 90638	Office (714) 523-9811 · Fax (714) 523-9810

7. Public/FORMField Forms/Current Field Forms/Bulk Sample Forms



ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: Itaciendor la Prente	- 450	ADDRESS:	Wilson	Hs	
SCOPE OF PROJECT:					DATE: 1/21/25
INSPECTOR: Area Jimener	XRF SERIAL #:			PRC	DJECT NUMBER: P25033. HZ

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDITION	roc	ATION	QUANTITY	COMMENTS
1.	1.10	Red	Test	Pant Sheet		Confirme	tron		
2.	1.00								
3-	1.00	((
4.	0.00	tan	Stucco	Dervarg		Media Cente	1 - Ext		
5.	0.00	Ŋ	1	(.)			
6.	0.00		medal	parel					
7.	0.00								
8.	00.0	Ked		Door					
9.	0,00	Black		Doorbrane					
10.	0.00	1		unden					
\ 1.	0.00	Red		in morow panel			+		
1 2.	0.00			D001			- Irl		
1 3.	0.60	Black		burtrane					
1 4.	0.00	white		hall pane					
1 5.	0.00			1					
/ 6.	0.00								
1 7.	0.60	(1						
ſ 8.	0.00	Black	Steel	Beam					
/ 9.	0.00	white	wood	Door					
2 0.	0.00	3 (ack	Netal	boorfane					
2 1.	0.00	tan	l	hall Parel					
2 2.	0.00	Grego	Wood	DOOR					
2 3.	0.00	Red	Brick	inter (Inte		
24.	00.00						= /		
25.	0.00						-Ext		
2.6.	0.00		(
2 7.	1.10	Red	Test	Pant Sheet		Conti	mation		
Z 8.	1.10								
Z 9.	1.00								
3 0.	•		4	***************************************					

Ву:	Title:
	Page / of /









STATE OF CALIFORNIA DEPARTMENT OF PUBLIC HEALTH



LEAD-RELATED CONSTRUCTION CERTIFICATE

INDIVIDUAL:

CERTIFICATE TYPE:

NUMBER:

EXPIRATION DATE:

Lead Sampling Technician

LRC-00002763

9/15/2025

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD



16700 Valley View Avenue Suite 100 La Mirada, California 90638 p: 714.523.9811 f: 714.523.9810





Howard M Baba

Certification No. _

Expires on_

08/29/25

This certification was issued by the Division of Occupational Safety and Health as authorized by Sections 7180 et seq. of the Business and Professions Code



STATE OF CALIFORNIA DEPARTMENT OF PUBLIC HEALTH



LEAD-RELATED CONSTRUCTION CERTIFICATE

INDIVIDUAL:

CERTIFICATE TYPE:

NUMBER:

EXPIRATION DATE:

Lead Inspector/Assessor

LRC-00003404

10/3/2025

Lead Supervisor

LRC-00011254

5/25/2025

Howard Baba

Disclaimer: This document alone should not be relied upon to confirm certification status. Compare the individual's photo and name to another valid form of government issued photo identification. Verify the individual's certification status by searching for Lead-Related Construction Professionals at www.cdph.ca.gov/programs/clppb or calling (800) 597-LEAD



HOMOGENEOUS MATERIALS INSPECTION FORM

Date: 1/21/25	Project Name:	Acm	Project #	P250	33.HZ
Project Address:	Wilson	48h School			·
Inspector(s):	Argel Jimen	ez	Page:	of	3
Building:	time to the second second		Building Code:		

Material Description	Locations	Individual Sq Ft	Total Sq Ft	Condition	Qty of Samples	Sample #'s
6" Black Corebase/ mostre/ Glue	BLDG B Media Center Througha Interior		180\$	6	3	1-3
Carpet Glue			4000cp			4-6
Carpet Mastic	- Duknov Sporadic Undercarpet		15006			7-9
Vmy1 Eloor Tile/Mastic			2004			10-12
Leveling			2000			13-15
halk on Most Adhesive	- Enterror Entry ways		1000			16-18
12x12 Grey Unyl Floor Tile/Mostic	-conterence/ Storage P-oom		300%		=	19-21


HOMOGENEOUS MATERIALS INSPECTION FORM

Date: 1/2/125P	roject Name:	A	cm	Project #	# P25033.H		
Project Address:	Wilson	Hosh	School	- 1 Champan San			
Inspector(s):	Angel Jimen	er		Page: _	2	of	3
Building:	-			Building Code:			

Material Description	Locations	Individual Sq Ft	Total Sq Ft	Condition	Qty of Samples	Sample #'s	
Corpet Pad/ Adhesive	- Below older permeter compa		ЬОФ	6	3	22-24	
parel production	- wall Parts trons		1600ф			75-27	
Ceiling panel Disclation	-Throughout Difertor		4000%			28-30	19
Ceiling Space Roofing Debnis	-Above Drap Ceiling		roved	5 D		31-33	
pipe for Disolation			600	6		34-36	Elbow, 100 F Observi 114 Scop area
the Drew ation			40\$			37-38	
Steel Beam Caulking	-Int/Ext		120\$			40-42	

HOMOGENEOUS MATERIALS INSPECTION FORM

Date: 1/2/1251		eny		_ Project :	# P250	33.142
	Wilson Hosh	School			3/3/	
Inspector(s):	Angel Jimenez			_ Page: _	3 of	_3_
Building:			Buil	ding Code:	*	
Material Description	Locations	Individual Sq Ft	Total Sq Ft	Condition	Qty of Samples	Sample #'s
Brick/ Mortar	-In+/Ex+		5000B	G	3	43-45
Stucco Overhang	- Ex+		3000 B		5	46-50
overhang Parel Disclation			1300¢		3	51-53
			3		9	



NT DEPLIN

DESCRIPTION: Wilson HS

JOB NAME: Acm/Lead Survey

JOB NUMBER: \$25033. H21

DRAWN BY: Aregi Jimenez


DATE: 1/21/25

DATE: 1/21/25

PENCORP
Engineering our Environment

16700 Valley View Ave., Suite 100
La Mirada, CA 90638
(714) 523-9811

FAX(714) 523-9810



LIMITATIONS

Conditions described in this report are as found at the time of investigation, unless otherwise stated.

ENCORP analyzed only the substances, conditions, and locations described in this report at the time indicated. No inferences regarding other substances, conditions, location or time can be made unless specifically stated in this report. ENCORP's inspection was limited to accessible materials only for the purpose of this survey.

This report is intended for the use listed in the section of this report titled "INTRODUCTION." The use of this report in any manner other than that listed in the Introduction requires the written consent of ENCORP and the TORRANCE UNIFIED SCHOOL DISTRICT. This report must be presented in its entirety.

The conclusions and recommendations presented are based on the agreed upon scope of work outlined in this report. ENCORP makes no warranties or guarantees as to the accuracy or completeness of information obtained from information provided or compiled by others. Note that information exists beyond the scope of this investigation. Additional information, which was outside this scope of work, not found, or available to ENCORP at the time of writing this report, may result in a modification of the conclusions and recommendations presented. This report is not a legal opinion. The services performed by ENCORP have been conducted in a manner consistent with a level of care ordinarily exercised by members of our profession currently practicing under similar conditions. No other warranty, expressed or implied, is made.