



March 3, 2022

Dr. Andrew Stewart
146 Balmoral Place
Ottawa, On

As per site visit on March 3rd, 2022 I inspected supporting concrete block wall which is behind the furnace and the finding was that the wall is structurally sound, there is no danger or concerns for structural failure. The visual cracks that are seen is parging which has no structural integrity and is only cosmetic, which over time has a tendency to spall.

Regards,

Carmelo Lagana

Buildama Construction
1092 Lena Ave.
Manotick, On
K4M 1E7

(613) 797-5966