


Plant Service Record



Date: 24/VII/2023		Fitter's name: DOM	
Plant Item: DANDO 3060		Plant no.: CT-62	
Hour reading: 417.2			
Description of work carried out	Time taken (hours)	Initials	
REPLACE BRAKE CABLE 2nd part → → CHAINWHEEL SIDE			
REPLACE BRAKE SHOES ON RIGHT SIDE (CHAINWHEEL SIDE) DUE TO CRACKS ON FRICTION MATERIAL			
INSTALL NEW BRAKE CONNECTOR BAR			
Parts/materials used		Quantity	
BRAKE CABLE		1	
BRAKE BAR		1	
NEW BRAKE PINS		3	
Fitter's comments: OUR BRAKE SHOES HAVE TOO THICK FRICTION MATERIAL. HAD TO CUT OFF ~ 1,5 mm from each			
Fitter's Signature (work complete)		 25/VII/2023	