Separate Lifting Accessories Report



Regular Thorough Examination

Name of User: SOCOTEC UK HOLDING LTD AND/OR SOCOTEC UK LIMITED

AND/OR ANY

Policy Number: NV10405624

Allianz (II)

Contract

Number:

Location: SOCOTEC CENTRAL, LEOFRIC BUSINESS PARK, PROGRESS

CLOSE, COVENTRY, CV3 2TF

Report Number: E26407034284

The following items were thoroughly examined and were found to contain NO defects which could become a danger to persons.

Last Examination Date: 25-Apr-2024 Next Examination Date: 25-Oct-2024 Examination Scheme No. None

Item No.	Description	Serial No.	Safe Working Load(s)	Location
MTC12270	Chain Sling, 4 Leg	CS14771	8 t at 45 deg	Truck

The above items were seen at: (If blank, refer to the Location details)

Visit made on behalf of:

Client Name SOCOTEC UK HOLDING LTD AND/OR SOCOTEC UK LIMITED AND/OR ANY

Address SOCOTEC CENTRAL

LEOFRIC BUSINESS PARK

PROGRESS CLOSE

COVENTRY CV3 2TF

This notification shall not be reproduced except in full without the approval of Allianz Engineering and the client for whom it was produced.

Client's Report Notes [These notes DO NOT form part of the Allianz Inspection Report]

Date of commencement of examination and tests

25-Apr-2024

Competent Person Allianz Engineering

Date of Report

25-Apr-2024

UK Tel: +44 (0) 1428 722407 ROI Tel: +00353 (0) 1 613 4081

Engineer Surveyor

W. Halliday

Allianz Engineering Inspection Services Ltd, 57 Ladymead, Guildford, Surrey, GU1 1DB
Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840. Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.

Allianz Engineering Inspection Services Ltd. Registered in England Number: 5441840, Registered Office: 57 Ladymead, Guildford, Surrey, GU1 1DB, United Kingdom.

Allianz plc, Allianz House, Elmpark, Merrion Road, Dublin 4, Republic of Ireland. Allianz plc trading as Allianz is regulated by the Irish Financial Regulator. Registered in Ireland number 143108.

www.allianzengineering.co.uk





This is an electronically produced copy of an original report held on the Allianz Engineering computer database called FACE

Print

Close

Print/email friendly page

Attachments

Type

Comments

No Attachments