

Plant Service Record

Date: 11 May 2020	Fitter's name: Phil Clements			
Plant Item: Dando 2000 Explorer	Plant no: CT52			
Hour reading: N/a	Last Service			
Description of work carried out		Time taken (hours)	Initials	
Travel to site (Durham) & Return		4	PC	
Diagnose snapped actuator cable Removed Clutch and found new cable to of its swage. Appeared to be an manufacturin the cable. Replaced with different model of cable and Op (K Price) tested and we adjusted clutch OP happy and tested satis.	re-built.	2	PC	
Parts/materials used			Quantity	
Actuator cable			1	
Fitter's comments:				
Fitter's Signature (work complete)	the	Phil Clements		
Managers signature (uploaded)				