



Date: 18. IX. 2024		Fitter's name: DOM	
Plant Item: COMACCHIO - 205		Plant no.: R-70	
Hour reading: 3045,8			
Description of work carried out		Time taken (hours)	Initials
REPAIR WATER JET WASH LEAK			
Parts/materials used		Quantity	
Fitter's comments: ATTEND TO SITE IN CORBY N17			
REPAIR LEAK FROM JET WASH HOSE by REPLACING AN			
O-RING.			
FOUND OIL LEAK ON DYNASET PUMP → TIGHTEN			
PLUG AND ADVISE DRILLER TO OBSERVE IT			
FOUND HARD WORKING LEVER FOR AUD/JET WASH			
PUMP → NEW LEVER REQUIRED			

18-IX-MMXXIV