



All the wires Connected with screws 1 through 8 should be soldered to solder pads with the same number.