## **Infrared Thermographic Report**

July 30, 2014

Location: Building 5 Component: Buss Fault Area: Investigate Rating / T-Rise: Minor 9.3F

Rating /Temp Rise F	
Minor	: 1-18
Alert	:19-36
Serious	:37-54
Critical	:>55



Notes: Open and investigate, see page 5.




18026 Saratoga Tr., Strongsville, OH 44136 t - 440-554-3620 e - jeff@visioninfrared.com w - www.visioninfrared.com

## **Infrared Thermographic Report**

July 30, 2014

Location: Building 5 Component: Buss Main Fault Area: C-phase Rating / T-Rise: Critical 71.1F

Rating /Temp Rise F	
Minor	: 1-18
Alert	:19-36
Serious	:37-54
Critical	:>55



Notes: Replace lug and trim back conductors.



18026 Saratoga Tr., Strongsville, OH 44136 t - 440-554-3620 e - jeff@visioninfrared.com w - www.visioninfrared.com