

OWNER: CBR AVIATION LLC		OPERATOR: CBR AVIATION LLC	
ADDRESS: 101 JEGS PLACE		ADDRESS: 101 JEGS PLACE	
DELAWARE OH 43015		DELAWARE OH 43015	
OFFICE: 614 579 5573		OFFICE: 614 579 5573	
FAX:		FAX:	
ANALYST: JAKE SALINAS		+1-316-928-7883 (DIRECT)	800-787-9749 (EFAX-CARDS)
EMAIL: JSALINAS@CAMPSYSTEMS.COM		+1-631-588-3200 (MAIN)	631-980-4222 (EFAX-CARDS)
		WWW.CAMPSYSTEMS.COM	
PLEASE REACH OUT TO YOUR ANALYST TO RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY).			

FILTER CRITERIA : Mode:WITH COMPLIANCE OR NEXT DUE; Group by Profile or Bulletin:PROFILE TYPE;

AIRCRAFT	SERIAL/REGNO: 45-134/N751JC	MODEL: LEARJET 45	MANUFACTURER: BOMBARDIER AVIATION
----------	-----------------------------	-------------------	-----------------------------------

CERTIFICATION DATE: 13-JAN-2001	LAST ACTUALS:
	9832.1 A/C HRS as of 31-MAY-2026
	7527 AFL as of 31-MAY-2026
	2676.1 ACH as of 01-MAY-2019

ENGINE NO. 1	SERIAL/PART: P-116262/3060084-2	MODEL: TFE731-20BR-1B	MANUFACTURER: HONEYWELL
--------------	---------------------------------	-----------------------	-------------------------

INSTALLED ON: 01-JUN-2001	LAST ACTUALS:
0 ENG. HRS 0 A/C HRS	9768.2 ENG. HRS as of 31-MAY-2026
0 ENC	7475 ENC as of 31-MAY-2026

ENGINE NO. 2	SERIAL/PART: P-116261/3060084-2	MODEL: TFE731-20BR-1B	MANUFACTURER: HONEYWELL
--------------	---------------------------------	-----------------------	-------------------------

INSTALLED ON: 11-SEP-2015	LAST ACTUALS:
7653.4 ENG. HRS 8202.7 A/C HRS	9282.8 ENG. HRS as of 31-MAY-2026
5888 ENC	7118 ENC as of 31-MAY-2026

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
AIRCRAFT - AD - LEARJET 45 45-134/N751JC							
FAA 1974-08-09	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R01)	MOS HRS/MSC AFL	-	31-OCT-2012 7416 5646	-	SUPERSEDED	Complied With
FAA 1974-08-09 R02	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION (SUPERSEDED BY FAA AD 1974-08-09 R03)	MOS HRS/MSC AFL	-	28-JAN-2008 6362.3 4817	-		Complied With
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION	MOS HRS/MSC AFL	1000	03-APR-2023 9282.3 7144	10282.3	MANDATORY RECURRING	Complied With
FAA 2003-16-09	REPLACEMENT OF THE MAIN LANDING GEAR TRUNNION SHEAR PINS	MOS HRS/MSC AFL	A/R	17-JUL-2008 6762.92 5122	-	MANDATORY	Complied With
FAA 2003-16-09 PART (A)	ACCOMPLISH REPLACEMENT OF THE MAIN LANDING GEAR TRUNNION SHEAR PINS -REVISE THE AIRWORTHINESS LIMITATIONS (AWL) SECTION OF THE INSTRUCTIONS FOR CONTINUED AIRWORTHINESS	MOS HRS/MSC AFL	-	17-JUL-2008 6762.92 5122	-	MANDATORY	Complied With
FAA 2003-16-09 PART (B)	ACCOMPLISH REPLACEMENT OF THE MAIN LANDING GEAR TRUNNION SHEAR PINS REPLACE THE SHEAR PINS	MOS HRS/MSC AFL	-	17-JUL-2008 6762.92 5122	-	MANDATORY	Complied With
FAA 2007-17-17	INSPECT FOR UNSEALED GAPS ON THE PYLON SIDE OF THE ENGINE FIREWALL	MOS HRS/MSC AFL	-	27-FEB-2009 6768.5 5125	-	MANDATORY	Complied With
FAA 2008-01-03	REVISION OF THE AIRWORTHINESS LIMITATIONS SECTION OF THE AIRPLANE MAINTENANCE MANUAL TO INCORPORATE CERTAIN INSPECTIONS AND COMPLIANCE TIMES TO DETECT FATIGUE CRACKING OF CERTAIN PRINCIPAL STRUCTURAL ELEMENTS (PSES).	DAYS HRS/MSC AFL	-	10-MAR-2008 6492.57 4909	-	AIRWORTHINESS	Complied With
FAA 2009-05-08	UPGRADE THE SYSTEM SOFTWARE OF ANY TRIMBLE OR FREEFLIGHT SYSTEMS 2101 I/O APPROACH PLUSGPS NAVIGATION SYSTEM	DAYS HRS/MSC	N/A	20-APR-2009			Complied With
FAA 2009-11-13	CHAFED HYDRAULIC TUBES IN THE LEFT-HAND ENGINE. (SUPERSEDED BY AD 2011-13-10)	MOS HRS/MSC AFL	-	23-JUL-2012 7326.6 5563	-	MANDATORY	Complied With

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2009-11-13 PARAGRAPH (G)	DETAILED INSPECTION CHAFED HYDRAULIC TUBES IN THE LEFT-HAND ENGINE. (SUPERSEDED BY AD 2011-13-10) CASE DRAIN TUBE						Complied With
		MOS		23-JUL-2012			
		HRS/MSC	-	7326.6	-		
		AFL		5563			
FAA 2009-11-13 PARAGRAPH (H)	DETAILED INSPECTION CHAFED HYDRAULIC TUBES IN THE LEFT-HAND ENGINE. (SUPERSEDED BY AD 2011-13-10) NACELLE TUBING						Complied With
		MOS		23-JUL-2012			
		HRS/MSC	-	7326.6	-		
		AFL		5563			
FAA 2009-11-13 PARAGRAPH (I)	DETAILED INSPECTION CHAFED HYDRAULIC TUBES IN THE LEFT-HAND ENGINE. (SUPERSEDED BY AD 2011-13-10) FOR FLUID LEAKAGE AND INADEQUATE CLEARANCE (REMOVE CLAMP)						Complied With
		MOS		23-JUL-2012			
		HRS/MSC	-	7326.6	-		
		AFL		5563			
FAA 2009-11-13 PARAGRAPH (J)	REPLACE CHAFED HYDRAULIC TUBES IN THE LEFT-HAND ENGINE. (SUPERSEDED BY AD 2011-13-10) CLAMP					MANDATORY	Complied With
Eff. Date: 17-JUN-2009		MOS		23-JUL-2012			
		HRS/MSC	-	7326.6	-		
		AFL		5563			
FAA 2009-24-22	TO PREVENT THE USE OF DOOR SEALS AND SEALANT THAT DO NOT MEET FLAMMABILITY REQUIREMENTS					MANDATORY	Not Applicable
Eff. Date: 08-JAN-2010		MOS		30-JUN-2011			
		HRS/MSC	-	7028.6	-		
		AFL		5302			
FAA 2009-24-22 PARA (G)	INSPECT/REPLACE TO PREVENT THE USE OF DOOR SEALS AND SEALANT THAT DO NOT MEET FLAMMABILITY REQUIREMENTS THE RED ROOM TEMPERATURE VULCANIZING (RTV) SEALANT IN AFT BAGGAGE BAY					MANDATORY	Not Applicable
Eff. Date: 08-JAN-2010		MOS		30-JUN-2011			
		HRS/MSC	-	7028.6	-		
		AFL		5302			
FAA 2009-24-22 PARA (H)	INSPECTION TO PREVENT THE USE OF DOOR SEALS AND SEALANT THAT DO NOT MEET FLAMMABILITY REQUIREMENTS OF BAGGAGE BAY DOOR FIRE BARRIER SEAL					MANDATORY	Not Applicable
Eff. Date: 08-JAN-2010		MOS		30-JUN-2011			
		HRS/MSC	-	7028.6	-		
		AFL		5302			
FAA 2010-06-13	TO DETECT AND CORRECT CRACKED AND MISSING BALLSCREW ASSEMBLY SLEEVES					MANDATORY	Complied With
Eff. Date: 01-APR-2010		MOS		05-NOV-2014			
		HRS/MSC	-	7967.9	-		
		AFL		6117			
FAA 2010-06-13 PARA (G)	GENERAL VISUAL INSPECTION TO DETECT AND CORRECT CRACKED AND MISSING BALLSCREW ASSEMBLY SLEEVES					MANDATORY	Complied With
Eff. Date: 01-APR-2010		DAYS		21-MAY-2014			
		HRS/MSC	-	7830.7	-		
		AFL		5995			

MASTER AD/SI REPORT

AIRCRAFT
All Bulletins With Compliance or Due
Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026
29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2010-06-13 PARA (H)	NON DESTRUCTIVE INSPECT TO DETECT AND CORRECT CRACKED AND MISSING BALLSCREW ASSEMBLY SLEEVES	MOS HRS/MSC AFL	-	19-DEC-2019 8761 6753	-	N/A BY SERIAL NUMBER	Complied With
FAA 2010-06-13 PARA (I)	REPLACE TO DETECT AND CORRECT CRACKED AND MISSING BALLSCREW ASSEMBLY SLEEVES	MOS HRS/MSC AFL	A/R	13-DEC-2013 7712.2 5907	-	MANDATORY	Declined
Eff. Date: 01-APR-2010							
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)	MOS HRS/MSC AFL	-	23-AUG-2010 6817.77 5152	-	MANDATORY	Not Applicable - SER# NOT COVERED UNDER AD
Eff. Date: 03-MAY-2010							
FAA 2010-21-19	REPLACEMENT, CHECK, INSPECTION OF THE ALUMINUM FIRE EXTINGUISHER DISCHARGE TUBES	MOS HRS/MSC AFL	-	02-DEC-2011 7169.3 5413	-	MANDATORY	Complied With
Eff. Date: 18-NOV-2010							
FAA 2011-04-08	VISUAL INSPECTION FOR DAMAGE OF WIRING (INCLUDING CHAFING, PINCHED WIRES, AND EXPOSED WIRES) AND CORRECT ROUTING OF WIRES IN THE LEFT AND RIGHT CIRCUIT BREAKER PANELS	MOS HRS/MSC AFL	-	02-APR-2011 6972.5 5250	-	MANDATORY	Complied With
Eff. Date: 31-MAR-2011							
A45-24-16							
FAA 2011-04-09	VARIOUS TRANSPORT CATEGORY AIRPLANES EQUIPPED WITH CHEMICAL OXYGEN GENERATORS INSTALLED IN A LAVATORY	DAYS HRS/MSC AFL	-	02-APR-2011 6972.5 5250	-	MANDATORY	Not Applicable
Eff. Date: 14-MAR-2011							
FAA 2011-13-10	CHAFED HYDRAULIC TUBES IN THE LEFT-HAND ENGINE	MOS HRS/MSC AFL	-	23-JUL-2012 7326.6 5563	-	MANDATORY	Complied With
Eff. Date: 01-AUG-2011							
FAA 2011-13-10 PARA (L)	REPLACE CHAFED HYDRAULIC TUBES IN THE LEFT-HAND ENGINE LEFT ENGINE FUEL AND HYDRAULIC TUBING AND INSTALL A TUBING SUPPORT CHANNEL USING NEW PARTS AND PREFORM INSPECTIONS	MOS HRS/MSC AFL	-	23-JUL-2012 7326.6 5563	-	MANDATORY	Complied With
Eff. Date: 01-AUG-2011							
FAA 2011-13-10 PARA (M)	CHANGE CHAFED HYDRAULIC TUBES IN THE LEFT-HAND ENGINE THE ROUTING AND CLAMPING CONFIGURATION OF THE ENGINE AND ALTERNATOR WIRE HARNESSSES AND THE STARTER/GENERATOR WIRE BUNDLES AND PERFORM INSPECTIONS	MOS HRS/MSC AFL	-	23-JUL-2012 7326.6 5563	-	MANDATORY	Complied With
Eff. Date: 01-AUG-2011							
FAA 2011-25-03	FATIGUE CRACKING OF THE END CAP OF THE MAIN LANDING GEAR	MOS HRS/MSC AFL	-	29-FEB-2012 7217.6 5456	-		Complied With
Eff. Date: 23-JAN-2012							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2011-25-03 PARA (G)(1)	REVISE FATIGUE CRACKING OF THE END CAP OF THE MAIN LANDING GEAR MAINTENANCE PROGRAM						Complied With
Eff. Date: 23-JAN-2012		DAYS		29-FEB-2012			
		HRS/MSC	-	7217.6	-		
		AFL		5456			
FAA 2012-02-08	AVIATION COMMUNICATION & SURVEILLANCE SYSTEMS (ACSS) TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM (TCAS) UNITS					MANDATORY	Not Applicable - TO THE EQUIPMENT INSTALLED
Eff. Date: 13-MAR-2012		MOS		10-FEB-2015			
		HRS/MSC	-	8031	-		
		AFL		6156			
FAA 2012-08-08	PERIODIC INSPECTION - REVISE THE MAINTENANCE PROGRAM BY INCORPORATING THE APPLICABLE INSPECTION REFERENCE NUMBER (IRN) TASKS					MANDATORY	Complied With
Eff. Date: 29-MAY-2012		DAYS	90	27-SEP-2012			
		HRS/MSC	-	7362.9	-		
		AFL		5599			
FAA 2012-26-15 R01	AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)					MANDATORY	
Eff. Date: 03-DEC-2014		MOS					
		HRS/MSC	-				
FAA 2013-14-07	EQUIPMENT/FURNISHINGS - FIRE BARRIER SEAL ON THE EXTERNAL BAGGAGE DOOR - MODIFY					MANDATORY	Complied With
Eff. Date: 26-AUG-2013		MOS		05-AUG-2014			
		HRS/MSC	-	7865	-		
		AFL		6031			
45-25-35 R03							
FAA 2014-13-06	INSPECT THRUST REVERSER FLANGE FOR ANY CORROSION, AND DAMAGE TO THE SEALANT; INSTALL SEALANTS AND GASKETS; AND RELATED INVESTIGATIVE AND CORRECTIVE ACTIONS					MANDATORY	Not Applicable - N/A AIRCRAFT ENGINE DO NOT HAVE COMPOSITE AFTERBODIES
Eff. Date: 19-AUG-2014		MOS		06-JUN-2018			
		HRS/MSC	-	8570.5	-		
		AFL		6600			
FAA 2014-13-06 PARA (G)(1)	DO A DETAILED INSPECTION OF THE THRUST REVERSER FLANGE FOR DAMAGE TO THE SEALANT, AS APPLICABLE, AND INSTALL SEALANTS AND GASKETS					MANDATORY	Not Applicable - N/A AIRCRAFT ENGINE DO NOT HAVE COMPOSITE AFTERBODIES
Eff. Date: 19-AUG-2014		MOS		06-JUN-2018			
		HRS/MSC	-	8570.5	-		
		AFL		6600			
FAA 2014-13-06 PARA (G)(2)	DO A FLUORESCENT PENETRANT INSPECTION FOR CORROSION OF THE METALLIC COMPONENTS OF THE THRUST REVERSER'S ATTACH FLANGE FOR ANY CORROSION, AND ALL APPLICABLE RELATED INVESTIGATIVE AND CORRECTIVE ACTIONS					MANDATORY	Not Applicable - N/A AIRCRAFT ENGINE DO NOT HAVE COMPOSITE AFTERBODIES
Eff. Date: 19-AUG-2014		MOS		06-JUN-2018			
		HRS/MSC	-	8570.5	-		
		AFL		6600			
FAA 2015-12-06 PARA (G)	ACCOMPLISH GVI OF THE COUPE RAILS / ULTRASOUND INSPECTION TO MEASURE THE DIMENSIONS OF THE LOWER COUPE RAILS; AN ECI TO DETECT CRACKS OF THE L/H AND R/H LOWER COUPE RAILS					MANDATORY	Complied With
Eff. Date: 21-JUL-2015		MOS		06-JUN-2018			
		HRS/MSC	-	8570.5	-		
		AFL		6600			

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2015-12-06 PARA (H)	REVISE THE MAINTENANCE OR INSPECTION PROGRAM (AS APPLICABLE) TO INCORPORATE TASKS FOR INSPECTIONS OF THE LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH AND REPLACEMENT OF THE COUPE RAILS					MANDATORY	Complied With
Eff. Date: 21-JUL-2015		DAYS HRS/MSC AFL	-	03-AUG-2015 8179.1 6266	-		
FAA 2015-23-09	OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS					MANDATORY	Not Applicable - CHECK OF OXYGEN MASKS INSTALLED,PILOT SIDE MC10-15-166 SERIAL NO: 74061, CO-PILOT SIDE MC10-15-166 SERIAL NO: 89196, PER AD MASKS ARE NOT AFFECTED
Eff. Date: 28-DEC-2015		MOS HRS/MSC AFL	-	11-DEC-2015 8263.9 6339	-		
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER					MANDATORY	Not Applicable - CHECK OF OXYGEN MASKS INSTALLED,PILOT SIDE MC10-15-166 SERIAL NO: 74061, CO-PILOT SIDE MC10-15-166 SERIAL NO: 89196, PER AD MASKS ARE NOT AFFECTED
Eff. Date: 28-DEC-2015		DAYS HRS/MSC AFL	-	11-DEC-2015 8263.9 6339	-		
FAA 2015-23-09 PARA (H)(1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1) (I) OR (H)(1)(II).					MANDATORY	Not Applicable - CHECK OF OXYGEN MASKS INSTALLED,PILOT SIDE MC10-15-166 SERIAL NO: 74061, CO-PILOT SIDE MC10-15-166 SERIAL NO: 89196, PER AD MASKS ARE NOT AFFECTED
Eff. Date: 28-DEC-2015		DAYS HRS/MSC AFL	-	11-DEC-2015 8263.9 6339	-		
FAA 2015-23-09 PARA (H)(2)(I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1					MANDATORY	Not Applicable - CHECK OF OXYGEN MASKS INSTALLED,PILOT SIDE MC10-15-166 SERIAL NO: 74061, CO-PILOT SIDE MC10-15-166 SERIAL NO: 89196, PER AD MASKS ARE NOT AFFECTED
Eff. Date: 28-DEC-2015		DAYS HRS/MSC AFL	-	11-DEC-2015 8263.9 6339	-		
FAA 2015-23-09 PARA (H)(2)(II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."					MANDATORY	Not Applicable - CHECK OF OXYGEN MASKS INSTALLED,PILOT SIDE MC10-15-166 SERIAL NO: 74061, CO-PILOT SIDE MC10-15-166 SERIAL NO: 89196, PER AD MASKS ARE NOT AFFECTED
Eff. Date: 28-DEC-2015		DAYS HRS/MSC AFL	-	11-DEC-2015 8263.9 6339	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT					MANDATORY	Not Applicable - CHECK OF OXYGEN MASKS INSTALLED,PILOT SIDE MC10-15-166 SERIAL NO: 74061, CO-PILOT SIDE MC10-15-166 SERIAL NO: 89196, PER AD MASKS ARE NOT AFFECTED
Eff. Date: 28-DEC-2015		MOS HRS/MSC AFL	-	11-DEC-2015 8263.9 6339	-		
FAA 2017-04-06	CABIN SYSTEMS - REPLACEMENT OF UNITED INSTRUMENTS INC. 5934 SERIES ALTIMETERS MANUFACTURED BETWEEN JANUARY 2015 AND FEBRUARY 2016					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED - NO FURTHER ACTION REQUIRED
Eff. Date: 07-APR-2017		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2021-23-08	WING - REPETITIVELY INSPECTING THE CENTER WING AREA FOR CORROSION AND DETERIORATION OF PROTECTIVE TREATMENTS, REMOVING ANY CORROSION, AND TREATING ANY DETERIORATED AREAS					MANDATORY	Complied With - PREVIOUSLY IAW SB 45-57-13 ON 21 MAY 2020
Eff. Date: 10-JAN-2022		MOS HRS/MSC	-	10-FEB-2023			
FAA 2021-23-08 PARA (H)	INSPECT THE CENTER WING AREA FOR CORROSION AND DETERIORATION OF PROTECTIVE TREATMENTS AND PERFORM ALL RELATED CORRECTIVE ACTIONS					MANDATORY	Complied With - PREVIOUSLY IAW SB 45-57-13 ON 21 MAY 2020
Eff. Date: 10-JAN-2022		MOS	96	21-MAY-2020	21-MAY-2028	RECURRING	
FAA 2021-23-08 PARA (J)	SUBMIT A REPORT OF THE FINDINGS (BOTH POSITIVE AND NEGATIVE) OF THE INSPECTION					MANDATORY	Complied With - PREVIOUSLY IAW SB 45-57-13 ON 21 MAY 2020
Eff. Date: 10-JAN-2022		DAYS HRS/MSC	-	10-FEB-2023			
FAA 2021-23-11 PARA (G)	REPORT THE INFORMATION IN PARA (G)(1) TO (G)(9)					MANDATORY	Complied With - SUBMITTED DATA TO E-MAIL PER AD INSTRUCTIONS - JY
Eff. Date: 10-JAN-2022		DAYS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2021-23-11 PARA (H)	REPLACE THE ENGINE FUEL FLOW METER BRACKET					MANDATORY	Complied With - C/W ON 8-MAR-2022 BY SUBMISSION OF DATA TO EMAILPER AD INSTRUCTION - PREVIOUS COMPLIANCE WITH SERVICE BULLETINS VERIFIED - NO ADDITIONAL REQUIRED
Eff. Date: 10-JAN-2022		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2023-01-05	PNEUMATIC - MAINTENANCE/INSPECTION PROGRAM - REVISION					MANDATORY	Complied With
Eff. Date: 09-MAR-2023		DAYS HRS/MSC AFL	-	03-APR-2023 -	-		

APPLIANCE - LEARJET 45 45-134/N751JC

FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI					MANDATORY	Not Applicable - DUE TO EQUIPMENT NOT INSTALLED
Eff. Date: 08-MAR-2010		MOS HRS/MSC AFL	-	27-APR-2010 6815.8 5151	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2010-04-16 PARA (G)	APPLIANCE ADP - REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT					MANDATORY	Not Applicable - DUE TO EQUIPMENT NOT INSTALLED
Eff. Date: 08-MAR-2010		DAYS HRS/MS AFL	-	27-APR-2010 6815.8 5151	-		
FAA 2010-04-16 PARA (H)	APPLIANCE ADP - RETURN TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI THE AFFECTED FIRE EXTINGUISHER TO MANUFACTURER					MANDATORY	Not Applicable - DUE TO EQUIPMENT NOT INSTALLED
Eff. Date: 08-MAR-2010		DAYS HRS/MS AFL	-	27-APR-2010 6815.8 5151	-		
FAA 2011-01-09	APPLIANCE AD - B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) PART NUMBER 119003-11 INSTALLED ON VARIOUS TRANSPORT AIRPLANES					MANDATORY	Not Applicable
Eff. Date: 09-FEB-2011		DAYS HRS/MS AFL	-	02-APR-2011 6972.5 5250	-		
FAA 2012-26-15	APPLIANCE AD - IDENTIFY OUT OF SPEC ADC, ADM, ADAHRS, AND DADC. (RESCINDED BY FAA 2012-26-15 R1)					MANDATORY	Not Applicable
Eff. Date: 24-JAN-2013		MOS HRS/MS AFL	-	27-FEB-2013 7510.6 5712	-		
FAA 2012-26-15 PARA (G)(1)	APPLIANCE ADP - REMOVE IDENTIFY OUT OF SPEC ADC, ADM, ADAHRS, AND DADC. (RESCINDED BY FAA 2012-26-15 R1) AFFECTED ADC, ADM, ADAHRS, OR DADC					MANDATORY	Not Applicable
Eff. Date: 24-JAN-2013		DAYS HRS/MS AFL	-	27-FEB-2013 7510.6 5712	-		
FAA 2012-26-15 PARA (G)(2)	APPLIANCE ADP - PERFORM IDENTIFY OUT OF SPEC ADC, ADM, ADAHRS, AND DADC. (RESCINDED BY FAA 2012-26-15 R1) PITOT-STATIC CERTIFICATION TEST						Not Applicable
		DAYS HRS/MS AFL	-	27-FEB-2013 7510.6 5712	-		
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	
Eff. Date: 14-OCT-2014		MOS HRS/MS	-				
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSSES					MANDATORY	Not Applicable - N/A BY P/N OF OXYGEN MASK INSTALLED
Eff. Date: 16-JUN-2015		MOS HRS/MS AFL	-	31-MAY-2017 8437.9 6495	-		
FAA 2015-08-07 PARA (G)	APPLIANCE ADP - INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011(FOR ALL AIRPLANES OTHER THAN BOMBARDIER AIRPLANES); OR APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-241, REVISION 3, DATED JUNE 23, 2011 (FOR BOMBARDIER AIRPLANES)					MANDATORY	Not Applicable - N/A BY P/N OF OXYGEN MASK INSTALLED
Eff. Date: 16-JUN-2015		MOS HRS/MS AFL	-	31-MAY-2017 8437.9 6495	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2015-08-07 PARA (H)	APPLIANCE ADP - REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPRGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES					MANDATORY	Not Applicable - N/A BY P/N OF OXYGEN MASK INSTALLED
Eff. Date: 16-JUN-2015		MOS HRS/MSC AFL	-	31-MAY-2017 8437.9 6495	-		
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	Not Applicable - EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.
Eff. Date: 15-JUL-2016		MOS HRS/MSC AFL	-	22-DEC-2016 8384.7 6454	-		
FAA 2016-11-20 PARA (G)	APPLIANCE ADP - PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A..1 SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	Not Applicable - EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.
Eff. Date: 15-JUL-2016		MOS HRS/MSC AFL	-	22-DEC-2016 8384.7 6454	-		
FAA 2016-11-20 PARA (H.1)	APPLIANCE ADP - REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	Not Applicable - EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.
Eff. Date: 15-JUL-2016		MOS HRS/MSC AFL	-	22-DEC-2016 8384.7 6454	-		
FAA 2016-11-20 PARA (H.2)	APPLIANCE ADP - REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12					MANDATORY	Not Applicable - EQUIPMENT NOT INSTALLED. NO FURTHER ACTION REQUIRED.
Eff. Date: 15-JUL-2016		MOS HRS/MSC AFL	-	22-DEC-2016 8384.7 6454	-		
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS					MANDATORY	Not Applicable - N/A ARTEX ELT INSTALLED NO FURTHER ACTION REQUIRED
Eff. Date: 24-OCT-2017		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2017-16-01 PARA (G)	APPLIANCE ADP - PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS						Not Applicable - N/A ARTEX ELT INSTALLED NO FURTHER ACTION REQUIRED
		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2017-16-01 PARA (J)	APPLIANCE ADP - OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT					MANDATORY	Not Applicable - N/A ARTEX ELT INSTALLED NO FURTHER ACTION REQUIRED
Eff. Date: 24-OCT-2017		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES					MANDATORY	Not Applicable - N.A , NO PBE INSTALLED
Eff. Date: 16-OCT-2017		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2017-18-12 PARA (G)	APPLIANCE ADP - INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	Not Applicable - N.A , NO PBE INSTALLED
Eff. Date: 15-JUL-2016		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2017-18-12 PARA (H)	APPLIANCE ADP - REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED					MANDATORY	Not Applicable - N.A , NO PBE INSTALLED
Eff. Date: 15-JUL-2016		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2017-18-12 PARA (I) & (J)	APPLIANCE ADP - INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.					MANDATORY	Not Applicable - N.A , NO PBE INSTALLED
Eff. Date: 16-OCT-2017		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2018-03-04	APPLIANCE AD - NAVIGATION - REPLACEMENT OF ROSEMOUNT AEROSPACE INC. MODEL 851AK PITOT PROBES REPAIRED BY CSI AEROSPACE INC					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED - NO FURTHER ACTION REQUIRED
Eff. Date: 16-MAR-2018		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2018-03-04 PARA (G)	APPLIANCE ADP - DETERMINE NUMBER OF AFFECTED PITOT PROBES INSTALLED					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED - NO FURTHER ACTION REQUIRED
Eff. Date: 16-MAR-2018		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2018-03-04 PARA (H)(1)	APPLIANCE ADP - REPLACE AFFECTED PITOT PROBES					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED - NO FURTHER ACTION REQUIRED
Eff. Date: 16-MAR-2018		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2018-03-04 PARA (H)(2)	APPLIANCE ADP - DO NOT INSTALL ON ANY AIRPLANE A PITOT PROBE HAVING A SERIAL NUMBER LISTED IN PARA (C)(1) OF THIS AD, UNLESS IT HAS BEEN PROPERLY REPAIRED, AND IF REPAIRED BY CSI AEROSPACE, INC., HAS A REPAIR DATE OF AUGUST 1, 2014, OR LATER					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED - NO FURTHER ACTION REQUIRED
Eff. Date: 16-MAR-2018		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
FAA 2018-21-14	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR HARNESS INFLATION HOSES - INSPECTION / REPLACEMENT					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED
Eff. Date: 27-MAR-2019		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2018-21-14 PARA (G)	APPLIANCE ADP - REQUIRED ACTIONS					MANDATORY	Not Applicable - AD2018-21-14 PARA G - 36 MONTH FOLLOW ON ACTIONS PER ZODIAC SB MC10-35-274 - N/A BY PART NUMBER INSTALLED - NO FURTHER ACTION REQUIRED
Eff. Date: 27-MAR-2019		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2018-21-14 PARA (H)	APPLIANCE ADP - DO NOT INSTALL ON ANY AIRPLANE A FLIGHT CREW OXYGEN MASK REGULATOR WITH A P/N LISTED IN PLANNING INFORMATION, PARAGRAPH 1.A.(1), OF ZODIAC SB MC10-35-274 R02, DATED JUNE 25, 2014, UNLESS IT MEETS THE DEFINITION OF A PART ELIGIBLE FOR INSTALLATION IN PARA (I) OF THIS AD					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED
Eff. Date: 27-MAR-2019		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED
Eff. Date: 11-MAY-2021		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2021-07-13 PARA (E)(1)	APPLIANCE ADP - INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED
Eff. Date: 11-MAY-2021		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2021-07-13 PARA (E)(2)	APPLIANCE ADP - MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED
Eff. Date: 11-MAY-2021		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2021-07-13 PARA (E)(3)	APPLIANCE ADP - DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER					MANDATORY	Not Applicable - N/A BY PART NUMBER INSTALLED
Eff. Date: 11-MAY-2021		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS					MANDATORY	Complied With
Eff. Date: 09-DEC-2021		MOS HRS/MSC AFL	-	08-MAR-2022 9124.9 7029	-		
FAA 2023-10-02 PARA (I)	APPLIANCE ADP - REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)					MANDATORY	Complied With
Eff. Date: 26-MAY-2023		MOS HRS/MSC AFL	-	08-AUG-2023 9342.8 7199	-		

MASTER AD/SI REPORT

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2024-26-02 PARA (G)(1)	APPLIANCE ADP - INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	Complied With
Eff. Date: 07-MAR-2025		MOS HRS/MSC AFL	-	10-MAR-2025 9625.9 7387	-		
FAA 2024-26-02 PARA (G)(2)	APPLIANCE ADP - MEASURE THE THICKNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE					MANDATORY	Complied With - MEASUREMENT WAS LESS THAN 0.125"
Eff. Date: 07-MAR-2025		MOS HRS/MSC AFL	-	10-MAR-2025 9625.9 7387	-		
FAA 2025-16-09 PARA (G)(1)	APPLIANCE ADP - INSPECT EACH BUCKLE SCREW FOR CRACKED, LOOSE, AND MISSING SCREW HEADS BY FOLLOWING THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPHS B.(1) AND (2), OF PARKER MEGGITT SERVICE BULLETIN SB 1111475-25-001-2023, REVISION 002, DATED APRIL 1, 2024 (SB 1111475-25-001-2023 REV 002) - FOR AIRPLANES WITH BUCKLE P/N 1111475 (ALL DASH NUMBERS)					MANDATORY	
Eff. Date: 22-SEP-2025		MOS	12		22-SEP-2026		
FAA 2025-16-09 PARA (G)(2)	APPLIANCE ADP - INSPECT EACH BUCKLE SCREW FOR CRACKED, LOOSE, AND MISSING SCREW HEADS BY FOLLOWING THE ACCOMPLISHMENT INSTRUCTIONS, PARAGRAPH B.(1), OF PARKER MEGGITT SB 1111548-25-001-2023, REVISION 002, DATED APRIL 1, 2024 (SB 1111548-25-001-2023 REV 002) - AIRPLANES WITH BUCKLE P/N 1111548-01					MANDATORY	
Eff. Date: 22-SEP-2025		MOS	12		22-SEP-2026		
FAA 2025-16-09 PARA (G)(3)	APPLIANCE ADP - CREWMEMBER SEAT OR PASSENGER SEAT (AS AN OPTION FOR THE ACTIONS REQUIRED BY PARAGRAPH (G)(1) OR (2) OF THIS AD) - REMOVE MALE SIDE FROM THE LAP OF THE RESTRAINT SYSTEM AND FABRICATE A PLACARD STATING SEAT IS INOPERATIVE					MANDATORY	
Eff. Date: 22-SEP-2025		MOS	12		22-SEP-2026		
FAA 2025-25-02	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS					MANDATORY	
Eff. Date: 24-DEC-2025		DAYS HRS/MSC	-				
FAA 2025-26-06	APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT					MANDATORY	Not Applicable - N/A (EQUIPMENT NOT INSTALLED)
Eff. Date: 14-JAN-2026		DAYS HRS/MSC AFL	-	15-MAY-2026 9815.8 7514	-		
FAA 2026-03-09	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE					MANDATORY	Not Applicable - N/A (EQUIPMENT NOT INSTALLED)
Eff. Date: 12-MAR-2026		MOS HRS/MSC AFL	-	15-MAY-2026 9815.8 7514	-		
FAA 2026-03-09 PARA (G) EASA (	APPLIANCE ADP - REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD					MANDATORY	Not Applicable - N/A (EQUIPMENT NOT INSTALLED)
Eff. Date: 12-MAR-2026		DAYS HRS/MSC AFL	-	15-MAY-2026 9815.8 7514	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
FAA 2026-03-09 PARA (G) EASA (	APPLIANCE ADP - ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD					MANDATORY	Not Applicable - N/A (EQUIPMENT NOT INSTALLED)
Eff. Date: 12-MAR-2026		MOS HRS/MSC AFL	-	15-MAY-2026 9815.8 7514	-		
FAA 2026-03-09 PARA (G) EASA (	APPLIANCE ADP - PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT					MANDATORY	Not Applicable - N/A (EQUIPMENT NOT INSTALLED)
Eff. Date: 12-MAR-2026		DAYS HRS/MSC AFL	-	15-MAY-2026 9815.8 7514	-		
FAA 2026-03-09 PARA (G) EASA (	APPLIANCE ADP - LIFE LIMIT: REMOVE FROM SERVICE					MANDATORY	Not Applicable - N/A (EQUIPMENT NOT INSTALLED)
		MOS HRS/MSC AFL	-	15-MAY-2026 9815.8 7514	-		
AIRCRAFT - SB - LEARJET 45 45-134/N751JC							
AW 21-010	INSPECTION OF KEITH PRODUCTS AIR CONDITIONING POWER PANEL HARDWARE, ADVISORY WIRE					MANDATORY	Complied With
Eff. Date: 02-AUG-2013		MOS HRS/MSC AFL	-	10-DEC-2013 7712.2 5907	-		
SB 45-11-4	INCREASE MAXIMUM TAKE-OFF WEIGHT TO 21500 POUNDS. (EFFECTIVE: 45-005 THRU 45-2000), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 09-AUG-2002		MOS HRS/MSC AFL	A/R	22-JAN-2003 1594.4 1206	-		
SB 45-11-6 R02	PLACARDS AND MARKINGS - REPLACEMENT OF NOSE STRUT SERVICING PLACARDS (EFFECTIVE: LEARJET 45-005 THRU 45-367, 45-369 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 28-MAY-2013		MOS HRS/MSC	-				
SB 45-11-6 R03	PLACARDS AND MARKINGS - REPLACEMENT OF NOSE STRUT SERVICING PLACARDS (EFFECTIVE: 45-005 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 19-MAY-2014		MOS HRS/MSC	-				
SB 45-11-6 R04	PLACARDS AND MARKINGS - REPLACEMENT OF NOSE STRUT SERVICING PLACARDS (EFFECTIVE: 45-005 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 05-JAN-2015		MOS HRS/MSC	-				
SB 45-12-1 R02	INSTALLATION OF REMOTE OXYGEN SERVICING PROVISIONS, SERVICE BULLETIN					SUPERSEDED	Complied With
		MOS HRS/MSC AFL	A/R	22-SEP-2001 296.4 230	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-12-1 R03	INSTALLATION OF REMOTE OXYGEN SERVICING PROVISIONS, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-	SUPERSEDED	Complied With
SB 45-12-1 R04	INSTALLATION OF REMOTE OXYGEN SERVICING PROVISIONS, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-	SUPERSEDED	Complied With
SB 45-20-2 R01	STANDARD PRACTICES - INSPECTION/MODIFICATION OF WIRE CHAFE BEHIND CENTER SWITCH PANEL (P5) (EFFECTIVE: 45-005 THRU 45-367 AND 45-369 THRU 45-445, 45-447 THRU 45-455), SERVICE BULLETIN	MOS HRS/MSC	-	-	-	OPTIONAL	
SB 45-21-11	INSTALLATION OF CABIN PRESSURE CONTROLLER BONDING, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-	SUPERSEDED	Complied With
SB 45-21-11 R01	INSTALLATION OF CABIN PRESSURE CONTROLLER BONDING (EFFECTIVE: 45 005 THRU 45 155), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-	RECOMMENDED	Complied With
SB 45-21-13	UPGRADE OF THE CABIN PRESSURE CONTROLLER, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	06-NOV-2004 3180.1 2379	-	SUPERSEDED	Complied With
SB 45-21-16	INSTALLATION OF PNEUMATIC TUBE ASSEMBLY FILTERS (EFFECTIVE: 45 005 THRU 45 232), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	24-SEP-2003 2105.2 1585	-	RECOMMENDED	Complied With
SB 45-21-23	AIR CONDITIONING - MODIFICATION OF THE CABIN BLOWER CIRCUIT WIRING (EFFECTIVE: 45-005 THRU 45-231 WHEN KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM IS INSTALLED), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
SB 45-21-23 R01	AIR CONDITIONING - MODIFICATION OF THE CABIN BLOWER CIRCUIT WIRING.NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-231 WHEN KEITH PRODUCTS VAPOR CYCLE AIR CONDITIONING SYSTEM IS INSTALLED AND HAVE COMPLIED WITH STC ST01250LA-D, CONFIGURATION 4), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
SB 45-21-24 R02	REPLACEMENT OF KEITH PRODUCTS AIR CONDITIONING TERMINAL LUGS. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-291 WITH KEITH PRODUCTS R134A AIR CONDITIONING INSTALLED), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-21-24 R03	REPLACEMENT OF KEITH PRODUCTS AIR CONDITIONING TERMINAL LUGS. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-291 WITH KEITH PRODUCTS R134A AIR CONDITIONING INSTALLED. NO REWORK REQUIRED), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 01-DEC-2010		MOS HRS/MSC	-				
SB 45-21-25 R01	AIR CONDITIONING - MODIFICATION OF THE ENVIRONMENTAL CONTROL SYSTEM (ECS) PLENUM ASSEMBLY DUCT FLANGE. NO REWORK REQUIRED. EFFECTIVE 45-005 THRU 45-426., SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 30-JAN-2012		MOS HRS/MSC	-				
SB 45-21-26	AIR CONDITIONING - INSPECTION OF AIR CONDITIONING SYSTEM POWER DISTRIBUTION PANEL (EFFECTIVE: 45-005 THRU 45-367, 45-369 THRU 45-445, 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 25-NOV-2013		MOS HRS/MSC AFL	-	05-AUG-2014 7865 6031	-		
SB 45-21-28	AIR CONDITIONING - CABIN PRESSURE CONTROLLER INSPECTION/REPLACEMENT (EFFECTIVE: 45-245 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 29-SEP-2014		MOS HRS/MSC	-				
SB 45-21-6	INSTALLATION OF RESTRICTOR PLATE, SERVICE BULLETIN					OPTIONAL	Complied With
Eff. Date: 16-JUN-2000		MOS HRS/MSC	A/R	06-MAY-2001			
SB 45-21-6 R01	INSTALLATION OF RESTRICTOR PLATE, SERVICE BULLETIN					SUPERSEDED	Complied With
		MOS HRS/MSC	-	06-MAY-2001			
SB 45-21-6 R02	INSTALLATION OF RESTRICTOR PLATE, SERVICE BULLETIN					SUPERSEDED	Complied With
		MOS HRS/MSC	-	06-MAY-2001			
SB 45-22-10	AUTO FLIGHT - HONEYWELL PHASE VI AVIONICS UPGRADE (EFFECTIVE: 45-005 THRU 45-2000 WITH PHASE V AVIONICS INSTALLED), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 10-NOV-2008		MOS HRS/MSC	A/R				
SB 45-22-10 R01	AUTO FLIGHT - HONEYWELL PHASE VI AVIONICS UPGRADE. NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-2000 WITH PHASE V AVIONICS INSTALLED), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 02-FEB-2009		MOS HRS/MSC	A/R				
SB 45-22-10 R02	AUTO FLIGHT - HONEYWELL PHASE VI AVIONICS UPGRADE. NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-397 WITH PHASE V AVIONICS INSTALLED), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 20-APR-2009		MOS HRS/MSC	-				
SB 45-22-11	AUTO FLIGHT - INSPECTION/REPLACEMENT OF SAFETY WIRE OR CABLE ON THEAILERON SERVO CABLE LOWER QUADRANT (EFFECTIVE: 45-005 THRU 45-367, 45-369 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 17-MAR-2014		MOS HRS/MSC AFL	-	05-AUG-2014 7865 6031	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-22-4 R03	HONEYWELL PHASE III SOFTWARE UPGRADE (, SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 12-OCT-2001		MOS		17-MAY-2002			
		HRS/MSC	A/R	963.3	-		
		AFL		723			
SB 45-22-4 R04	HONEYWELL PHASE III SOFTWARE UPGRADE (EFFECTIVE: 45 005 THRU 45 169), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 24-APR-2002		MOS		17-MAY-2002			
		HRS/MSC	A/R	963.3	-		
		AFL		723			
SB 45-22-5 R02	HONEYWELL PHASE IV UPGRADE. (NO REWORK REQUIRED) (EFFECTIVE: 45-005 THRU 45-235), SERVICE BULLETIN					RECOMMENDED	Complied With - C/W PARA 2A, B, C, D, E, F, G
Eff. Date: 29-MAR-2005		MOS		14-AUG-2008			
		HRS/MSC	A/R	6762.9	-		
		AFL		5122			
SB 45-23-14	COMMUNICATIONS - GMA 36 AUDIO PROCESSING UNIT MOD 3 UPGRADE (EFFECTIVITY: 45-368), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 20-JUL-2015		MOS					
		HRS/MSC	-				
SB 45-23-14 R02	COMMUNICATIONS - GMA 36 AUDIO PROCESSING UNIT MOD 3 UPGRADE (EFFECTIVITY: 45-368), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 07-DEC-2015		MOS					
		HRS/MSC	-				
SB 45-24-10 R01	ELECTRICAL POW3ER - REPLACEMENT OF THE EMERGENCY BATTERY GROUNDING BRACKET. NO REWORK REQUIRED. (EFFECTIVE: 45-002 THRU 45-337), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 17-NOV-2008		MOS		14-AUG-2010			
		HRS/MSC	-	6817.77	-		
		AFL		5152			
SB 45-24-13	ELECTRICAL POWER - MODIFICATION OF THE TAILCONE ELECTRICAL CONNECTORS. (EFFECTIVE: 45-005 THRU 45-391.), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 04-MAY-2009		MOS					
		HRS/MSC	-				
SB 45-24-14 R01	INSPECTION/MODIFICATION OF THE OPTIONAL AFT CIRCUIT BREAKER PANEL WIRE HARNESS ROUTING. (EFFECTIVE: 45-005 THRU 45-371 WITH OPTIONAL AFT CIRCUIT BREAKER PANEL INSTALLED. NO REWORK REQUIRED), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 28-JUN-2010		MOS					
		HRS/MSC	-				
SB 45-24-15	REPLACEMENT OF THE PITCH TRIM ACTUATOR CIRCUIT BREAKER. (EFFECTIVE: 45-005 THRU 45-410), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 15-MAR-2010		MOS					
		HRS/MSC	-				
SB 45-24-15 R02	REPLACEMENT OF THE PITCH TRIM ACTUATOR CIRCUIT BREAKER (45-005 - 45-367, 45-369 - 45-412), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 11-FEB-2013		MOS					
		HRS/MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-24-19	ELECTRICAL POWER - INSTALLATION OF ADDITIONAL WIRING BUNDLE PROTECTION IN TAILCONE. (EFFECTIVE: 45-005 THRU 45-408, 45-410 THRU 45-420.), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 21-MAR-2011		MOS HRS/MSC	-				
SB 45-24-21	ELECTRICAL POWER - REPLACEMENT OF QUICK ATTACH AND DETACH (QAD) MOUNTING ADAPTER SEAL (EFFECTIVE: 45-429 THRU 45-446), SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 04-MAR-2013		MOS HRS/MSC AFL	-	10-DEC-2013 7712.2 5907	-		
SB 45-24-3	INCREASE FUSE AMPERAGE FOR AOA INDICATOR LIGHTING, SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 21-JUN-2001		MOS HRS/MSC AFL	A/R	25-APR-2002 912.5 686	-		
SB 45-24-3 R01	INCREASE FUSE AMPERAGE FOR ANGLE OF ATTACK (AOA) INDICATOR LIGHTING. (EFFECTIVE: 45-002 THRU 45-208.), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 22-APR-2002		MOS HRS/MSC AFL	A/R	25-APR-2002 912.5 686	-		
SB 45-24-4	FLIGHT GUIDANCE CONTROLLER BACK LIGHTING FUSES, SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 06-DEC-2002		MOS HRS/MSC AFL	A/R	13-MAY-2003 1869.6 1395	-		
SB 45-24-5	INSTALLATION OF A 115 VAC CABIN INVERTER OUTLET CURRENT LIMITER. (EFFECTIVE: 45-005 THRU 45-231), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 15-MAR-2005		MOS HRS/MSC AFL	A/R	05-NOV-2005 4224.6 3182	-		
SB 45-24-9 R01	INSTALLATION OF CONCORDE 38 AHR BATTERIES. (EFFECTIVE: LEARJET 45-005 THRU 45-296 WHEN EQUIPPED WITH CONCORDE 28 AHR BATTERIES.), SERVICE BULLETIN					REVISED	Not Applicable - 38 AHR BATTERIES INSTALLED
Eff. Date: 05-MAR-2012		MOS HRS/MSC	-				
SB 45-24-9 R02	ELECTRICAL POWER - INSTALLATION OF CONCORDE 38 AHR BATTERIES. EFFECTIVE LEARJET 45-005 THRU 45-296, WHEN EQUIPPED WITH CONCORDE 28 AHR BATTERIES., SERVICE BULLETIN					RECOMMENDED	Complied With - PREVIOUSLY COMPLIED WITH.
Eff. Date: 05-MAR-2012		MOS HRS/MSC	-				
SB 45-24-9 R03	ELECTRICAL POWER - INSTALLATION OF CONCORDE 38 AHR BATTERIES (EFFECTIVE: LEARJET 45-005 THRU 45-296, WHEN EQUIPPED WITH CONCORDE 28 AHR BATTERIES), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 29-APR-2008		MOS HRS/MSC	-	-	-		
SB 45-25-21 R01	EQUIPMENT/FURNISHINGS - INSPECT/REMOVE RED RTV SEALANT IN THE AFT BAGGAGE BAY., SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 16-JUN-2008		MOS HRS/MSC AFL	-	30-JUN-2011 7028.6 5302	-		

MASTER AD/SI REPORT

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-25-24 R01	EQUIPMENT AND FURNISHINGS - INSTALLATION OF THE CABIN POWER INVERTER COVER. (EFFECITVE: 45-005 THRU 45-370 WHEN EQUIPPED WITH OPTIONAL CABIN POWER INVERTER (P/N 2D1200-1A-1011 OR 3D1200-2A-1029)), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 10-NOV-2008		MOS HRS/MSC	-	-	-		
SB 45-25-28 R02	EQUIPMENT/FURNISHINGS - MODIFICATION OF THE EMTEQ AC POWER OUTLET(EFFECTIVE: LEARJET 45-289, 45-331 THRU 45-349, 45-351 THRU 45-357, 45-359 THRU 45-364, 45-366, 45-367, 45-369 THRU 45-381 AND 45-383), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 28-MAY-2013		MOS HRS/MSC	-				
SB 45-25-29 R02	MODIFICATION OF THE TOILET SHROUD FORWARD FACE (EFFECTIVE: LEARJET 45-232 THRU 45-367, 45-369 THRU 45-409 AND 45-412), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 11-MAR-2013		MOS HRS/MSC	-				
SB 45-25-3	INSTALLATION OF OXYGEN CUP STOWAGE BRACKET, SERVICE BULLETIN					SUPERSEDED	Complied With
		MOS HRS/MSC	A/R		06-MAY-2001		
SB 45-25-3 R01	INSTALLATION OF OXYGEN CUP STOWAGE BRACKET (EFFECTIVE: 45 005 THRU 45 057), SERVICE BULLETIN						Complied With
		MOS HRS/MSC	A/R		06-MAY-2001		
SB 45-25-35 R03	EQUIPMENT AND FURNISHINGS - BAGGAGE DOOR FIRE SEAL RELOCATION. NO REWORK REQUIRED. EFFECTIVE 45-002 THRU 45-380, 45-382 THRU 45-396, 45-398 THRU 45-405., SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 06-FEB-2012		MOS HRS/MSC AFL	-		05-AUG-2014 7865 6031	-	
SB 45-25-38 R02	EQUIPMENT/FURNISHINGS - REPOSITIONING OF CREW SEAT ARMRESTS. EFFECTIVITY: LEARJET 45-005 THRU 45-432 FOR AIRCRAFT WITH FISCHER+ENTWICKLUNGEN CREW SEATS INSTALLED. NO REWORK REQUIRED, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 15-OCT-2012		MOS HRS/MSC	-				
SB 45-25-40	EQUIPMENT/FURNISHINGS - RETRACTABLE CUP HOLDER WIRE CHAFING MODIFICATION [EFFECTIVE: 45-232 THRU 45-263], SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 05-MAY-2014		MOS HRS/MSC	-	-	-		
SB 45-25-41	EQUIPMENT/FURNISHINGS - GAS SPRING SUPPORT AND HEIGHT ADJUSTMENT LEVER - MODIFICATION (EFFECTIVE: LEARJET 45-005 THRU 45-412, 45-414, 45-415 AND 45-422 THRU 45-425 THAT HAVE INSTALLED LEARJET SERVICE BULLETIN 45-25-37, "REPLACEMENT OF THE CREW SEATS" LEARJET 45-413, 45-416 THRU 45-421, 45-426 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 02-MAR-2015		MOS HRS/MSC	-	-	-		
SB 45-25-6 R02	MODIFICATION OF TRIM CAPS ABOVE EMERGENCY EXIT, SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R		17-MAY-2002 963.3 723	-	

MASTER AD/SI REPORT

AIRCRAFT
All Bulletins With Compliance or Due
Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026
29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-26-10	INSPECTION/MODIFICATION OF THE APU FIRE EXTINGUISHER SQUIB WIRING (EFFECTIVE: 45-005 THRU 45-408, 45-410 THRU 45-412 AND 45-417 WITH APU INSTALLED), SERVICE BULLETIN	MOS HRS/MSC AFL	-	26-FEB-2012 7217.6 5456	-	RECOMMENDED	Not Applicable
SB 45-26-10 R01	FIRE PROTECTION - INSPECTION/MODIFICATION OF THE APU FIRE EXTINGUISHER SQUIB WIRING. EFFECTIVITY: 45-005 THRU 45-438 WITH APU INSTALLED. REWORK REQUIRED, SERVICE BULLETIN	MOS HRS/MSC AFL	-	19-OCT-2012 7396.1 5632	-	RECOMMENDED	Not Applicable - NO APU
SB 45-26-13	FIRE PROTECTION - ENGINE FIRE EXTINGUISHER CONTAINER LABEL INSTALLATION. EFFECTIVE 45-005 THRU 45-380, 45-382 THRU 45-396, 45-398 THRU 45-405, 45-407 THRU 45-412, 45-416 AND 45-421 THRU 45-423., SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	Declined - CUSTOMER DECLINED PER EMAIL 5 JULY 13
SB 45-26-7	FIRE PROTECTION - INSPECTION/REPLACEMENT OF BLEED LEAK DETECT UNITS. (EFFECTIVE: 45-005 THRU 45-283), SERVICE BULLETIN	MOS HRS/MSC AFL	-	15-APR-2008 6561 4958	-	RECOMMENDED	Complied With
SB 45-27-11 R01	REPLACEMENT OF THE RUDDER PEDAL ADJUSTMENT ACTUATOR ASSEMBLY (EFFECTIVE: 45 005 THRU 45 129, 45 131 THRU 45 142, 45 144 THRU 45 169, 45 171 THRU 45 181, 45 183 THRU 45 201, 45 203, 45 207, 45 210, 45 212 THRU 45 214, 45 216, 45 219 THRU 45 222, 45 225, AND 45 227), SERVICE BULLETIN	MOS HRS/MSC AFL	-	06-NOV-2004 3180.1 2379	-	SUPERSEDED	Complied With
SB 45-27-13	REPLACEMENT OF HORIZONTAL STABILIZER AND LOWER TORQUE LINK ASSEMBLIES, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	15-NOV-2005 4224.6 3182	-	RECOMMENDED	Complied With
SB 45-27-14	INSTALLATION OF CABLE RETAINER FOR PITCH DISCONNECT CABLE ASSEMBLY (EFFECTIVE: 45 005 THRU 45 236), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	06-NOV-2004 3180.1 2379	-		Complied With
SB 45-27-17	FLIGHT CONTROLS - REPAIR OF THE RUDDER TORQUE TUBE ASSEMBLY BONDING JUMPERS (EFFECTIVE: 45-005 THRU 45-232), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	15-NOV-2005 4224.6 3182	-	RECOMMENDED	Complied With
SB 45-27-17 R01	FLIGHT CONTROLS - REPAIR OF THE RUDDER TORQUE TUBE ASSEMBLY BONDING JUMPERS. (NO REWORK REQUIRED) (EFFECTIVE: 45-005 THRU 45-290), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	15-OCT-2008 6766.9 5123	-	RECOMMENDED	Complied With - PREVIOUSLY

MASTER AD/SI REPORT

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-27-24 R02	INSPECTION/REPAIR OF THE RUDDER TORQUE TUBE. NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-307), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 22-MAR-2010		MOS HRS/MSC	-				
SB 45-27-25 R01	FLIGHT CONTROLS - REPLACEMENT OF THE RUDDER TORQUE TUBE, NO REWORK REQUIRED (EFFECTIVE: 45 005 THRU 45 2000), SERVICE BULLETIN					SUPERSEDED	Complied With
Eff. Date: 04-SEP-2007		MOS HRS/MSC AFL	-	15-OCT-2008 6766.9 5123	-		
SB 45-27-26	INSPECTION/REPLACEMENT OF THE RUDDER CONTROL IMPEDANCE BUSHING (EFFECTIVE: 45-005 THRU 45-249), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 11-JUN-2007		MOS HRS/MSC	A/R	-	-		
SB 45-27-27 R01	FLIGHT CONTROLS - SPOILERON ESSENTIAL POWER INPUT CORRECTION. NO REWORK REQUIRED (EFFECTIVE: 45 002 THRU 45 285), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 20-OCT-2008		MOS HRS/MSC	A/R				
SB 45-27-31	FLIGHT CONTROLS - INSPECTION / REPLACEMENT OF THE FLAP ROLLERS AND CAM FOLLOWERS (EFFECTIVE: 45-005 THRU 45-407), SERVICE BULLETIN					SUPERSEDED	Complied With
Eff. Date: 03-NOV-2008		MOS HRS/MSC AFL	-	03-SEP-2009 6773.2 5131	-		
SB 45-27-33 R04	WEIGHT AND BALANCE CHANGE AFTER REPLACEMENT OF THE HORIZONTAL STABILIZER TRIM ACTUATOR. NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-375), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 05-APR-2010		MOS HRS/MSC	-				
SB 45-27-35 R01	FLIGHT CONTROLS - REPLACEMENT OF HORIZONTAL STABILIZER TRIM ACTUATOR. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-367 THAT HAVE THE 6627401000-009), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 11-AUG-2008		MOS HRS/MSC	A/R				
SB 45-27-47	FLIGHT CONTROLS - INSTALLATION OF IMPROVED FLAP ACTUATORS. EFFECTIVE 45-005 THRU 45-441, SERVICE BULLETIN					SUPERSEDED	Complied With
		MOS HRS/MSC	-	19-DEC-2019 -	-		
SB 45-27-49	FLIGHT CONTROLS - FLAP POWER UNIT HYDRAULIC MOTOR TORQUE INSPECTION. EFFECTIVE LEARJET 45-005 THRU 45-426 WITH FLAP POWER UNIT P/N C144483-1 INSTALLED, AND AIRCRAFT WITH FLAP POWER UNIT C144483-3 WITH A SERIAL NUMBER FROM S/N 1001 THRU S/N 1639. ON AIRCRAFT WITH A FLAP POWER UNIT INSTALLED WITH AN "X" SUFFIX SCRIBED TO THE UNIT SERIAL NUMBER, THESE INSTRUCTIONS DO NOT NEED TO BE PERFORMED., SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 27-FEB-2012		MOS HRS/MSC AFL	-	13-DEC-2013 7712.2 5907	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-27-49 R01	FLIGHT CONTROLS - FLAP POWER UNIT HYDRAULIC MOTOR TORQUE INSPECTION (EFFECTIVITY : LEARJET 45 -005 THRU 45-426 WITH FLAP POWER UNIT P/N C144483-1 INSTALLED, AND AIRCRAFT WITH FLAP POWER UNIT C144483-3 WITH A SERIAL NUMBER FROM S/N 1001 THRU S/N 1639. ON AIRCRAFT WITH A FLAP POWER UNIT INSTALLED WITH AN "X" SUFFIX SCRIBED TO THE UNIT SERIAL NUMBER, THESE INSTRUCTIONS DO NOT NEED TO BE PERFORMED.), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 27-FEB-2012		MOS HRS/MSC	-	-	-		
SB 45-27-5 R01	DUAL LOCKING CONTROL WHEEL MODIFICATION, SERVICE BULLETIN					SUPERSEDED	Complied With
		MOS HRS/MSC	-	06-MAY-2001			
SB 45-27-5 R02	DUAL LOCKING CONTROL WHEEL MODIFICATION, SERVICE BULLETIN					SUPERSEDED	Complied With
		MOS HRS/MSC	-	06-MAY-2001			
SB 45-27-5 R03	DUAL LOCKING CONTROL WHEEL MODIFICATION (EFFECTIVE: 45 002 THRU 45 208), SERVICE BULLETIN						Complied With
		MOS HRS/MSC	A/R	06-MAY-2001			
SB 45-27-51 R02	FLIGHT CONTROLS - PITCH TRIM BIAS WIRING MODIFICATION (EFFECTIVE: LEARJET 45-005 THRU 45-367, 45 -369 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 17-MAR-2014		MOS HRS/MSC AFL	-	11-MAY-2016 8317 6377	-		
SB 45-27-53	FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 17-JAN-2025		MOS HRS/MSC	-				
SB 45-27-53 R01	FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 04-AUG-2025		MOS HRS/MSC	-				
SB 45-27-53 R02	FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 08-SEP-2025		MOS HRS/MSC	-				
SB 45-27-53 R05	FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 17-JAN-2025		MOS HRS/MSC	6		22-JUL-2026		
SB 45-27-54	FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 04-AUG-2025		MOS HRS/MSC	-				
SB 45-27-54 R01	FLIGHT CONTROLS - INSPECTION/MODIFICATION OF THE AILERON, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 04-AUG-2025		MOS HRS/MSC	-				
SB 45-27-6	SPOILER SYSTEM, SERVICE BULLETIN					SUPERSEDED	Complied With
		MOS HRS/MSC	-	06-MAY-2001			

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-27-6 R01	SPOILER SYSTEM, SERVICE BULLETIN	MOS HRS/MSC	-	06-MAY-2001		SUPERSEDED	Complied With
SB 45-27-6 R02	SPOILER SYSTEM (EFFECTIVE: 45-001 THRU 45-152), SERVICE BULLETIN	MOS HRS/MSC	A/R	06-MAY-2001			Complied With
SB 45-27-8	SPOILERON COMPUTER, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	19-SEP-2002 1267.5 962	-		Complied With
SB 45-27-8 R01	REPLACEMENT OF THE SPOILERON COMPUTER (EFFECTIVE: 45 005 THRU 45 194), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	19-SEP-2002 1267.5 962	-		Complied With
SB 45-28-6	INSPECTION OF FUEL TUBES ADJACENT TO TOILET SERVICING PANEL (EFFECTIVE: 45 005 THRU 45 231), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	10-DEC-2003 2335.3 1752	-		Complied With
SB 45-28-6 R01	FUEL - INSPECTION OF FUEL TUBES ADJACENT TO THE TOILET SERVICING PANEL. NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-231), SERVICE BULLETIN	MOS HRS/MSC AFL	-	10-DEC-2003 2328.78 1747	-	RECOMMENDED	Complied With
SB 45-28-7	INSTALLATION OF CORROSION PROTECTED FUEL TUBES (EFFECTIVE: 45-005 THRU 45-237), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	06-NOV-2004 3180.1 2379	-	RECOMMENDED	Complied With
SB 45-28-8 R01	FUEL - MODIFICATION OF THE FUEL IMBALANCE CAS MESSAGE LOGIC. NO REWORK REQUIRED!!! (EFFECTIVE: 45-005 THRU 45-258 AND 45-260), SERVICE BULLETIN	MOS HRS/MSC	A/R			RECOMMENDED	
SB 45-29-10	INSPECTION AND REPLACEMENT OF HYDRAULIC LINE CHAFING (EFFECTIVE: 45 002 THRU 45 145), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-		Complied With
SB 45-29-11	INSPECTION / MODIFICATION OF HYDRAULIC LINE CHAFING (EFFECTIVE: 45 005 THRU 45 201), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	24-SEP-2003 2105.2 1585	-		Complied With

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-29-16	POWERPLANT - INSPECTION/REPLACEMENT OF THE LEFT ENGINE HYDRAULIC TUBES AT NACELLE STATION 183.77 (EFFECTIVE: 45-005 THRU 45-362), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 09-APR-2008		MOS HRS/MSC AFL	-	03-SEP-2009 6773.2 5131	-		
SB 45-29-17 R02	HYDRAULIC POWER - REPLACEMENT OF THE HYDRAULIC SYSTEM LOW PRESSURE SWITCH ASSEMBLIES (EFFECTIVE: 45-005 THRU 45-396, 45-398 THRU 45-404), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 28-JAN-2013		MOS HRS/MSC	-				
SB 45-29-18	HYDRAULIC POWER - EATON HYDRAULIC PUMP SEALING SCREW INSPECTION (EFFECTIVITY: LEARJET 45-005 THRU 45-367, 45-369 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 14-OCT-2019		MOS HRS/MSC AFL	-	19-DEC-2019 8761 6753	-		
SB 45-29-7	INSTALLATION OF HYDRAULIC BLEED VALVES (EFFECTIVE: 45-002 THRU 45-194), SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	24-JUL-2012 7326.6 5563	-		
SB 45-31-1 R02	MODIFICATION OF MCOS II MAINT CONNECTOR WIRING (EFFECTIVE: 45 003 AND 45 005 THRU 45 143), SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	22-SEP-2001 296.4 230	-		
SB 45-32-11 R01	MAIN LANDING GEAR FREE-FALL SYSTEM EXTENSION MODIFICATION (EFFECTIVE: 45 005 THRU 45 106), SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	22-MAY-2007 5645.1 4257	-		
SB 45-32-15	LANDING GEAR CONTROL SWITCH, SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-		
SB 45-32-15 R01	LANDING GEAR CONTROL SWITCH REPLACEMENT (EFFECTIVE: 45 005 THRU 45 149), SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-		
SB 45-32-16	INSTALL SPIRAL WRAP ON NOSE DOWNLOCK SWITCH, SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-		
SB 45-32-16 R01	INSTALLATION OF SPIRAL WRAP ON NOSE DOWNLOCK SWITCH WIRE BUNDLE (EFFECTIVE: 45 002 THRU 45 208), SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-32-17	MODIFICATION OF GROUND PLUG BRACKET (EFFECTIVE: 45-005 THRU 45-260), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	06-NOV-2004 3180.1 2379	-		Complied With
SB 45-32-19 R01	MAIN LANDING GEAR DOOR ACTUATOR IMPROVEMENT/SADDLE INSTALLATION. (NO REWORK REQUIRED), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	15-NOV-2005 4224.6 3182	-	RECOMMENDED	Complied With
SB 45-32-19 R02	MAIN LANDING GEAR DOOR ACTUATOR IMPROVEMENT/SADDLE INSTALLATION. (NO REWORK REQUIRED), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	14-AUG-2008 6762.9 5122	-	RECOMMENDED	Complied With - C/W PARA 2A THROUGH 2F
SB 45-32-20 R01	INSPECTION OF THE MAIN LANDING GEAR DOOR ACTUATOR GIMBAL. (NO REWORK REQUIRED) (EFFECTIVE: 45-005 THRU 45-2000), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	15-NOV-2005 4224.6 3182	-	RECOMMENDED	Complied With
SB 45-32-23 R02	LANDING GEAR - REPLACEMENT OF THE NOSE LANDING GEAR SEAL RETAINER (EFFECTIVE: 45-005 THRU 45-320), SERVICE BULLETIN	MOS HRS/MSC	-			REVISED	
SB 45-32-23 R03	LANDING GEAR - REPLACEMENT OF THE NOSE LANDING GEAR SEAL RETAINER (EFFECTIVE: 45-005 THRU 45-320), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
SB 45-32-25 R01	LANDING GEAR - REPLACEMENT OF THE MAIN LANDING GEAR INBOARD DOOR ACTUATOR GIMBAL. NO REWORK REQUIRED., SERVICE BULLETIN	MOS HRS/MSC AFL	-	14-AUG-2008 6762.9 5122	-	RECOMMENDED	Complied With - C/W PARA 2A THROUGH 2E
SB 45-32-28	LANDING GEAR - INSPECTION/REROUTE OF NOSE WHEEL STEERING WIRING HARNESS. (EFFECTIVE: 45-005 THRU 45-358), SERVICE BULLETIN	MOS HRS/MSC AFL	-	30-JUN-2011 7028.6 5302	-	RECOMMENDED	Complied With - PREVIOUSLY
SB 45-32-29	LANDING GEAR - INSTALLATION OF TEFLON OVERBRAID ON WHEEL SPEED TRANSDUCER WIRE CABLES. (EFFECTIVE: 45-005 THRU 45-385), SERVICE BULLETIN	MOS HRS/MSC	-	20-MAY-2010		SUPERSEDED	Complied With
SB 45-32-29 R01	LANDING GEAR - INSTALLATION OF TEFLON OVERBRAID ON WHEEL SPEED TRANSDUCER WIRE CABLES. NO REWORK REQUIRED., SERVICE BULLETIN	MOS HRS/MSC AFL	-	20-MAY-2010 6815.8 5151	-	SUPERSEDED	Complied With - PREVIOUSLY C/W REV 1

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-32-29 R02	INSTALLATION OF TEFLON OVERBRAID ON WHEEL SPEED TRANSDUCER WIRE CABLES. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-385), SERVICE BULLETIN	MOS HRS/MSC AFL	-	20-MAY-2010 6815.8 5151	-	SUPERSEDED	Complied With - PREVIOUSLY C/W REV 1
SB 45-32-29 R03	INSTALLATION OF TEFLON OVERBRAID ON WHEEL SPEED TRANSDUCER WIRE CABLES. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-385), SERVICE BULLETIN	MOS HRS/MSC AFL	-	20-MAY-2010 6815.8 5151	-	RECOMMENDED	Complied With - PREVIOUSLY C/W BASIC ISSUE
SB 45-32-30	LANDING GEAR - NONDESTRUCTIVE INSPECTION (NDI) OF THE MAIN LANDING GEAR SHOCK STRUT CYLINDERS. (EFFECTIVE: 45-005 THRU 45-373, 45-375 THRU 45-378 AND 45-380), SERVICE BULLETIN	MOS HRS/MSC AFL	-	27-SEP-2012 7362.9 5599	-	RECOMMENDED	Complied With
SB 45-32-30 R01	LANDING GEAR - NONDESTRUCTIVE INSPECTION (NDI) OF THE MAIN LANDING GEAR SHOCK STRUT CYLINDERS. NO REWORK REQUIRED. EFFECTIVE 45-005 THRU 45-373, 45-375 THRU 45-378 AND 45-380 THAT HAVE NOT PERFORMED THE INITIAL LANDING GEAR INSPECTION IN SPECIAL INSPECTIONS OF CHAPTER 5 OF THE MM., SERVICE BULLETIN	MOS HRS/MSC AFL	-	26-AUG-2012 7362.9 5599	-	RECOMMENDED	Complied With
SB 45-32-31	INSPECTION/REPLACEMENT OF THE NOSE GEAR WHEEL ASSEMBLY. (EFFECTIVE: 45-005 THRU 45-380.), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
SB 45-32-32	AFT LANDING GEAR CONTROL VALVE FREEFALL CABLE AND AFT EMERGENCY/ PARKING BRAKE CABLE CLAMP INSTALLATION. (EFFECTIVE: 45-005 THRU 45-396, 45-398 THRU 45-402 AND 45-404), SERVICE BULLETIN	MOS HRS/MSC	-	-	-	SUPERSEDED	
SB 45-32-32 R01	AFT LANDING GEAR CONTROL VALVE FREEFALL CABLE AND AFT EMERGENCY/ PARKING BRAKE CABLE CLAMP INSTALLATION. NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-396, 45-398 THRU 45-402 AND 45-404), SERVICE BULLETIN	MOS HRS/MSC AFL	-	11-APR-2012 7251.8 5483	-	RECOMMENDED	Complied With
SB 45-32-36	LANDING GEAR - LANDING GEAR RETRACTION BRAKE PRESSURE-PULSE TEST MODIFICATION (EFFECTIVITY : LEARJET 45-005 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
SB 45-32-36 R01	LANDING GEAR - LANDING GEAR EXTENSION BRAKE PRESSURE-PULSE TEST MODIFICATION (EFFECTIVITY: LEARJET 45-005 THRU 45-445 & 45-447 THRU 45-455), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-32-36 R02	LANDING GEAR - LANDING GEAR EXTENSION BRAKE PRESSURE-PULSE TEST MODIFICATION (EFFECTIVITY: LEARJET 45-005 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 07-DEC-2015		MOS HRS/MSC	-				
SB 45-32-43	LANDING GEAR - BRAKE SYSTEM TIMING CHANGE, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 27-DEC-2024		MOS AFL HRS/MSC	-				
SB 45-32-43 R01	LANDING GEAR - BRAKE SYSTEM TIMING CHANGE, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 27-DEC-2024		MOS AFL	36 900		27-DEC-2027 8256		
SB 45-32-46	LANDING GEAR - EATON SWIVEL FITTING INSPECTION, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 25-AUG-2025		MOS HRS/MSC	-	-	-		
SB 45-32-46 R01	LANDING GEAR - EATON SWIVEL FITTING INSPECTION, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 25-AUG-2025		MOS HRS/MSC	600	-	10326.43		
SB 45-32-8 R03	LANDING GEAR - REPLACEMENT OF NOSE LANDING GEAR SQUAT SWITCH CAMROD (EFFECTIVE: (1) LEARJET 45-005 THRU 45-071 WHICH HAVE BEEN MODIFIED BY LEARJET SERVICE BULLETIN 45-32-3, "NOSE WHEEL STEERING UPGRADE". (2) LEARJET 45-072 THRU 45-114.), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 18-OCT-2000		MOS HRS/MSC	-				
SB 45-33-3	LIGHTS - REPLACEMENT OF THE LANDING/RECOGNITION LIGHT LENS (EFFECTIVE: 45-005 THRU 45-2000), SERVICE BULLETIN					REVISED	Complied With
Eff. Date: 21-JAN-2013		MOS HRS/MSC AFL	-	16-NOV-2011 7151.5 5402	-		
SB 45-34-11	IDENTIFICATION/UPGRADE OF INTEGRATED NAV UNITS (EFFECTIVE: 45-005 THRU 45-235), SERVICE BULLETIN					RECOMMENDED	Complied With
		MOS HRS/MSC AFL	A/R	15-NOV-2005 4224.6 3182	-		
FAA 2003-04-06							
SB 45-34-20	NAVIGATION - INSTALLATION OF EGPWS COMPUTER SOFTWARE UPGRADE (965-0976-040-218-218), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 29-JUN-2009		MOS HRS/MSC	-				
SB 45-34-20 R03	NAVIGATION - INSTALLATION OF EGPWS COMPUTER SOFTWARE UPGRADE (965-0976-040-218-218). (EFFECTIVE 45-005 THRU 45-367, 45-369 THRU 45-379, AND 45-381 THRU 45-393.), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 25-MAR-2013		MOS HRS/MSC	-				
SB 45-34-29	802.7 SOFTWARE UPGRADE FOR THE FLIGHT MANAGEMENT SYSTEM (FMS) (EFFECTIVE: 45-005 THRU 45-392, 45-394 THRU 45-396, 45-398 THRU 45-401, 45-403, AND 45-404 WITH UNS-1 SOFTWARE INSTALLED), SERVICE BULLETIN					SUPERSEDED	
Eff. Date: 16-NOV-2009		MOS HRS/MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-34-29 R01	802.7 SOFTWARE UPGRADE FOR THE FLIGHT MANAGEMENT SYSTEM (FMS). NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-392, 45-394 THRU 45-396, 45-398 THRU 45-401, 45-403, AND 45-404 WITH UNS-1 () WITH 802.1, 802.2, 802.3 OR 802.4 SOFTWARE INSTALLED), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 23-NOV-2009		MOS HRS/MSC	-				
SB 45-34-29 R02	NAVIGATION - 802.7 SOFTWARE UPGRADE FOR THE FLIGHT MANAGEMENT SYSTEM (FMS) (EFFECTIVE: 45-005 THRU 45-367, 45-369 THRU 45-392, 45-394 THRU 45-396, 45-398 THRU 45-401, 45-403, AND 45-404 WITH UNS-1 () WITH 802.1, 802.2, 802.3 OR 802.4 SOFTWARE INSTALLED), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 09-DEC-2013		MOS HRS/MSC	-				
SB 45-34-31	NAVIGATION - TCAS INTERFERENCE LIMITING IMPROVEMENT. EFFECTIVE 45-005 THRU 45-367 AND 45-369 THRU 45-433 EQUIPPED WITH ACSS TCAS-2000., SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 13-MAR-2012		MOS HRS/MSC	-				
SB 45-34-36	NAVIGATION - UPGRADE TO AUTOMATIC DEPENDENT SURVEILLANCE - BROADCAST (ADS-B) OPERATION, SERVICE BULLETIN					OPTIONAL	Complied With
Eff. Date: 06-MAR-2014		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
SB 45-34-38	NAVIGATION - EGPWS FAIL ANNUNCIATION WITH SINGLE FMS (EFFECTIVE: LEARJET 45-005 THRU 45-367, 45-369 THRU 45-445 AND 45-447 THRU 45-455 WITH SINGLE FMS INSTALLED), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 28-JUL-2014		MOS HRS/MSC	-				
SB 45-34-40	NAVIGATION - FLIGHT MANAGEMENT SYSTEM (FMS) DUAL UNS-1EW SOFTWARE UPGRADE, SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 28-APR-2021		MOS HRS/MSC AFL	-	04-MAR-2022 9124.9 7029	-		
SB 45-34-40 R01	NAVIGATION - FLIGHT MANAGEMENT SYSTEM (FMS) DUAL UNS-1EW SOFTWARE UPGRADE, SERVICE BULLETIN						
		MOS HRS/MSC	-	-	-		
SB 45-34-40 R03	NAVIGATION - FLIGHT MANAGEMENT SYSTEM (FMS) DUAL UNS-1EW SOFTWARE UPGRADE (EFFECTIVITY: 45-227, 45-455, 45-451, 45-324), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 28-APR-2021		MOS HRS/MSC	-	-	-		
SB 45-34-40 R04	NAVIGATION - FLIGHT MANAGEMENT SYSTEM (FMS) DUAL UNS-1EW SOFTWARE UPGRADE (EFFECTIVITY: 45-227, 45-455, 45-451, 45-324, 45-134, 45-303, 45-044, 45-334, 45-362, 45-263), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 21-NOV-2022		MOS HRS/MSC	-	-	-		
SB 45-35-3	OXYGEN - REMOTE OXYGEN SWITCH REPLACEMENT (EFFECTIVITY (1) LEARJET 45-005 THRU 45-244), SERVICE BULLETIN					OPTIONAL	Complied With
Eff. Date: 30-JUL-2009		MOS HRS/MSC AFL	-	11-APR-2012 7251.8 5483	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-36-4	REPLACEMENT OF THE ENVIRONMENTAL CONTROL SYSTEM CONTROLLER (EFFECTIVE: 45 005 THRU 45 201), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	11-MAY-2003 1869.6 1395	-		Complied With
SB 45-36-5	REPLACEMENT OF THE PYLON HIGH PRESSURE BLEED AIR MANIFOLD SWITCH (EFFECTIVE: 45-005 THRU 45-332 WITH TFE731-20BR-1B ENGINES), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	14-AUG-2008 6762.9 5122	-	RECOMMENDED	Complied With - C/W PARA 2A THROUGH 2F
Eff. Date: 16-JUL-2007							
SB 45-36-6	INSTALLATION OF IN-LINE FILTER TO THE HIGH PRESSURE BLEED AIR SHUTOFF VALVE ASSEMBLY (EFFECTIVE: 45-005 THRU 45-417), SERVICE BULLETIN	MOS HRS/MSC AFL	-	05-AUG-2014 7865 6031	-	OPTIONAL	Complied With
Eff. Date: 12-APR-2010							
SB 45-49-13	AIRBORNE AUXILIARY POWER - INSPECTION / REPLACEMENT OF APU WIRING HARNESS CONNECTOR BACKSHELLS. EFFECTIVE 45-005 THRU 45-440 (WHEN EQUIPPED WITH APU)., SERVICE BULLETIN	MOS HRS/MSC	-	-	-	REVISED	
SB 45-49-13 R01	AIRBORNE AUXILIARY POWER - INSPECTION / REPLACEMENT OF APU WI CONNECTOR BACKSHELLS. EFFECTIVE 45-005 THRU 45-440 (WHEN EQUIPPED WITH APU)., SERVICE BULLETIN	MOS HRS/MSC AFL	-	30-JUN-2012 7313.9 5545	-	RECOMMENDED	Not Applicable - NO APU
Eff. Date: 21-MAY-2012							
SB 45-49-15	AIRBORNE AUXILIARY POWER - INSTALLATION OF AUXILIARY POWER UNIT (APU) GROUND BRACKET (EFFECTIVITY: LEARJET 45-233 THRU 45-240 AND 45-242 THRU 45-252 EQUIPPED WITH APU), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
Eff. Date: 09-MAR-2015							
SB 45-49-15 R01	AIRBORNE AUXILIARY POWER - INSTALLATION OF AUXILIARY POWER UNIT (APU) GROUND BRACKET (EFFECTIVITY: LEARJET 45-233 THRU 45-240 AND 45-242 THRU 45-252 AND 45-282 EQUIPPED WITH APU.), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
Eff. Date: 07-DEC-2015							
SB 45-49-16 R01	AIRBORNE AUXILIARY POWER - AUXILIARY POWER UNIT (APU) GROUND BRACKET INSPECTION (EFFECTIVITY: LEARJET 45-002 THRU 45-232 AND 45-241 THAT HAVE COMPLETED SB45-49-4 REV 2 OR EARLIER, 45-253 THRU 45-445 AND 45-447 THRU 45-455 WHEN EQUIPPED WITH APU), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
Eff. Date: 07-DEC-2015							
SB 45-49-17	AIRBORNE AUXILIARY POWER - AUXILIARY POWER UNIT (APU) ELECTRONIC CONTROL UNIT (ECU) UPGRADE (EFFECTIVITY: 45-002 THRU 45-367, AND 45-369 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN	MOS HRS/MSC	-			OPTIONAL	
Eff. Date: 08-OCT-2018							
SB 45-49-4 R03	AIRBORNE AUXILIARY POWER - INSTALLATION OF AUXILIARY POWER UNIT (APU) GROUND BRACKET (EFFECTIVE: LEARJET 45-002 THRU 45-232 AND 45-241 EQUIPPED WITH APU), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
Eff. Date: 09-MAR-2015							

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT
All Bulletins With Compliance or Due
29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-49-4 R04	AIRBORNE AUXILIARY POWER - INSTALLATION OF AUXILIARY POWER UNIT (APU) GROUND BRACKET (EFFECTIVITY: LEARJET 45-002 THRU 45-232 AND 45-241 EQUIPPED WITH APU.), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 07-DEC-2015		MOS HRS/MSC AFL	-				
SB 45-52-11	REPLACE EMERGENCY EXIT DOOR LATCH SPRINGS (EFFECTIVE: 45-005 THRU 45-217), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 30-JUL-2004		MOS HRS/MSC AFL	A/R	06-NOV-2004 3180.1 2379	-		
SB 45-52-12	DOORS - REPLACEMENT OF LOWER CABIN DOOR STRUT BRACKETS (EFFECTIVE: 45-005 THRU 45-362), SERVICE BULLETIN					OPTIONAL	Complied With - FORWARD BRACKET ONLY
Eff. Date: 02-MAR-2009		MOS HRS/MSC AFL	-	11-APR-2012 7251.8 5483	-		
SB 45-52-16 R01	DOORS - INSPECTION/REPLACEMENT OF THE BAGGAGE BAY DOOR FIRE BARRIER SEAL. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-321 AND 45-323 THRU 45-332), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 16-JUN-2008		MOS HRS/MSC AFL	-	03-SEP-2009 6773.2 5131	-		
SB 45-52-16 R02	DOORS - INSPECTION/REPLACEMENT OF THE BAGGAGE BAY DOOR FIRE BARRIER SEAL. EFFECTIVE 45-005 THRU 45-321, 45-323, 45-332. NO REWORK REQUIRED., SERVICE BULLETIN					RECOMMENDED	Complied With - REV 1
Eff. Date: 04-APR-2011		MOS HRS/MSC AFL	-	03-SEP-2009 6773.2 5131	-		
SB 45-52-18	REPLACEMENT OF THE MAIN ENTRY DOOR HANDLE RETAINING SCREWS (EFFECTIVE: 45-005 THRU 45-396, 45-398 THRU 45-401, 45-403, AND 45-404), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 16-NOV-2009		MOS HRS/MSC	-				
SB 45-52-20	DOORS - REPLACEMENT OF THE MAIN PASSENGER/CREW EXTERIOR DOOR HANDLE SUB-ASSEMBLY (EFFECTIVITY: LEARJET 45-005 THRU 45-367, 45-369 THRU 45-445, AND 45-447 THRU 45-455), SERVICE BULLETIN					OPTIONAL	Complied With
Eff. Date: 20-DEC-2017		MOS HRS/MSC AFL	-	01-JUL-2021 9002.4 6938	-		
SB 45-52-4 R02	INSTALLATION OF TAKE-UP REEL RUB BLOCK, SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	22-JAN-2003 1594.4 1208	-		
SB 45-52-4 R03	INSTALLATION OF TAKE-UP REEL RUB BLOCK, SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	22-JAN-2003 1594.4 1208	-		
SB 45-52-6 R01	LOWER ENTRY DOOR DAMPER, SERVICE BULLETIN					OPTIONAL	Complied With
Eff. Date: 17-AUG-2001		MOS HRS/MSC AFL	A/R	02-SEP-2004 3034.6 2258	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-52-6 R02	LOWER ENTRY DOOR DAMPER, SERVICE BULLETIN					OPTIONAL	Complied With
Eff. Date: 27-FEB-2004		MOS HRS/MSC AFL	A/R	02-SEP-2004 3034.6 2258	-		
SB 45-53-13	MODIFICATION OF ENGINE PYLON STARTER/GENERATOR GROUND STRAP (EFFECTIVE: 45-005 THRU 45-249), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 24-SEP-2004		MOS HRS/MSC AFL	A/R	15-NOV-2005 4224.6 3182	-		
SB 45-53-16	INSTALLATION OF DRAIN HOLES IN THE TAILCONE (EFFECTIVE: 45-005 THRU 45-287), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 13-SEP-2005		MOS HRS/MSC AFL	A/R	10-FEB-2006 4454.1 3349	-		
SB 45-53-30 R02	REPAIR OF CRACKING AND GAPS AT FRAME 2. NO REWORK REQUIRED (EFFECTIVE: 45-005 THRU 45-387), SERVICE BULLETIN					OPTIONAL	Complied With
Eff. Date: 22-MAR-2010		MOS HRS/MSC AFL	-	14-AUG-2010 6817.77 5152	-		
SB 45-53-32	SINGLE POINT PRESSURE REFUELING DOOR LATCH IMPROVEMENT. (EFFECTIVE: 45-005 THRU 45-393), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 26-APR-2010		MOS HRS/MSC	-				
SB 45-53-35	FUSELAGE - LH OVERWING FAIRING MODIFICATION (EFFECTIVITY: LEARJET 45-005 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 23-FEB-2015		MOS HRS/MSC AFL	-	11-MAY-2016 8317 6377	-		
SB 45-53-37	FUSELAGE - LOWER QUADRANT BULKHEAD FASTENER INSPECTION (EFFECTIVITY: LEARJET 45-005 - 45-367, 45-369 - 45-445, 45-447 - 45-455), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 19-MAR-2018		MOS HRS/MSC AFL	-	06-JUN-2018 8570.5 6600	-		
SB 45-53-4 R02	INSTALLATION OF ENTRY DOOR GUTTER, SERVICE BULLETIN						Complied With
		MOS HRS/MSC	A/R	06-MAY-2001			
SB 45-53-4 R03	INSTALLATION OF ENTRY DOOR GUTTER (EFFECTIVE: 45 001 THRU 45 167), SERVICE BULLETIN						Complied With
		MOS HRS/MSC	A/R	06-MAY-2001			
SB 45-53-5 R01	INSTALLATION OF IMPROVED SPFR DOOR, SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	22-SEP-2001 296.4 230	-		
SB 45-53-5 R02	INSTALLATION OF IMPROVED SPFR DOOR, SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	22-SEP-2001 296.4 230	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-53-5 R03	INSTALLATION OF IMPROVED SPDR DOOR (EFFECTIVE: 45 002 THRU 45 189), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	22-SEP-2001 296.4 230	-		Complied With
SB 45-53-8	MODIFICATION OF NOSE LANDING GEAR AFT ACCESS, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-		Complied With
SB 45-53-8 R01	MODIFICATION OF NOSE LANDING GEAR AFT ACCESS PANEL (EFFECTIVE: 45 002 THRU 45 169), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	17-MAY-2002 963.3 723	-		Complied With
SB 45-53-9 R02	INSTALLATION OF MOISTURE DRAINS IN FORWARD BELLY FAIRINGS (EFFECTIVE: 45 005 THRU 45 208), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	12-SEP-2002 1249.8 945	-		Complied With
SB 45-54-3 R02	FIREWALL SEALING MOD/APPLICATION OF PYLON TRAILING EDGE SEALANT, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	14-AUG-2008 6762.9 5122	-		Complied With - C/W PARA 2A, B, C, D, E
SB 45-54-4	INSTALL PROTECTIVE BOOTS ON START/GEN INLET SCOOPS, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	11-JAN-2004 2463.4 1841	-		Complied With
SB 45-54-5 R02	NACELLES/PYLONS - REPLACEMENT OF FORWARD ENGINE MOUNT FIREWALL SCREWS, SERVICE BULLETIN	MOS HRS/MSC	-	-	-	RECOMMENDED	
SB 45-54-5 R03	NACELLES/PYLONS - REPLACEMENT OF FORWARD ENGINE MOUNT FIREWALL SCREWS, SERVICE BULLETIN	MOS HRS/MSC	24 600	-	06-OCT-2027 10343.37	RECOMMENDED	
SB 45-55-16 R01	MODIFICATION OF THE VERTICAL STABILIZER BULLET FAIRING CENTER SKINS. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-333), SERVICE BULLETIN	MOS HRS/MSC	-			RECOMMENDED	
SB 45-55-3 R01	INSTALLATION OF DORSAL INLET DRAIN PAN, SERVICE BULLETIN	MOS HRS/MSC	A/R	06-MAY-2001		RECOMMENDED	Complied With
SB 45-55-3 R02	INSTALLATION OF DORSAL INLET DRAIN PAN (EFFECTIVE: 45 001 THRU 45 194), SERVICE BULLETIN	MOS HRS/MSC	-	06-MAY-2001		RECOMMENDED	Complied With
SB 45-55-4 R01	INSTALLATION OF BULLET FAIRING REINFORCEMENT, SERVICE BULLETIN	MOS HRS/MSC	A/R	06-MAY-2001		RECOMMENDED	Complied With

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-55-4 R02	INSTALLATION OF BULLET FAIRING REINFORCEMENT (EFFECTIVE: 45 005, 45 006 AND 45 008 THRU 45 214), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 25-MAR-2002		MOS HRS/MSC	A/R		06-MAY-2001		
SB 45-55-6 R01	MODIFICATION OF RUDDER AND RUDDER TRIM TAB. (NO REWORK REQUIRED) (EFFECTIVE: 45-005 THRU 45-225), SERVICE BULLETIN					RECOMMENDED	Complied With
		MOS HRS/MSC AFL	A/R		15-NOV-2005 4224.6 3182	-	
SB 45-55-8	INSPECTION OF HORIZONTAL STABILIZER ACTUATOR LOWER ATTACH FITTING. (EFFECTIVE: 45-005 THRU 45-241 AND 45-243), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 08-SEP-2004		MOS HRS/MSC AFL	A/R		15-NOV-2005 4224.6 3182	-	
SB 45-55-9 R02	STABILIZERS - IMPROVED MODIFICATION OF THE BULLET FAIRING AND VERTICAL STABILIZER. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-276, 45-278 THRU 45-280, 45-282, 45-283, AND 45-285), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 20-APR-2009		MOS HRS/MSC AFL	-		28-MAR-2008 6517.55 4927	-	
SB 45-56-2	MODIFICATION OF THE GKN WINDSHIELD HEAT TERMINAL LUG INSTALLATION (EFFECTIVE: LEARJET 45-005 THRU 45-418 WITH GKN WINDSHIELDS INSTALLED) (SUPERSEDED BY SB 45-56-5), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 21-JUN-2010		MOS HRS/MSC	-				
SB 45-56-3	WINDOWS- WINDSHIELD COUPE RAIL INSPECTION, SERVICE BULLETIN					REVISED	Complied With - R.H ONLY
Eff. Date: 15-OCT-2012		MOS HRS/MSC AFL	-		22-MAY-2013 7583.6 5775	-	
SB 45-56-5	WINDOWS - GKN WINDSHIELD HEAT TERMINAL LUG INSPECTION (EFFECTIVE: LEARJET 45-005 THRU 45-445 WITH PART NUMBER 6656100001-001 (VENDOR P/N P01400-5) AND 6656100001-002 (VENDOR P/N P01400-6) GKN WINDSHIELDS), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 16-JUN-2014		MOS HRS/MSC AFL	-		05-AUG-2014 7865 6031	-	
SB 45-56-5 R01	WINDOWS - GKN WINDSHIELD HEAT TERMINAL LUG INSPECTION (EFFECTIVE: LEARJET 45-005 THRU 45-445 AND 45-447 THRU 45-455 WITH PART NUMBER 6656100001-001 (VENDOR P/N P01400-5) AND 6656100001-002 (VENDOR P/N P01400-6) GKN WINDSHIELDS), SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 16-JUN-2014		MOS HRS/MSC	-	-	-		
SB 45-57-10	INSTALLATION OF LONGER BODY/WING RUB STRIPS (EFFECTIVE: 45-005 THRU 45-398, 45-400, 45-401, 45-403 AND 45-404.), SERVICE BULLETIN					SUPERSEDED	
Eff. Date: 08-SEP-2009		MOS HRS/MSC	-	-	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-57-11	INSTALLATION OF MAIN LANDING GEAR AFT TRUNNION FITTING UPPER SHEAR PIN SPACERS (EFFECTIVE: 45-005 THRU 45-425), SERVICE BULLETIN	MOS HRS/MSC AFL	-	10-FEB-2015 8031 6156	-	REVISED	Complied With - PREVIOUSLY - FOUND SPACERS INSTALLED
SB 45-57-11 R01	WINGS - INSTALLATION OF MAIN LANDING GEAR AFT TRUNNION FITTING UPPER SHEAR PIN SPACERS (EFFECTIVE: 45-005 THRU 45-425), SERVICE BULLETIN	MOS HRS/MSC	-	-	-	RECOMMENDED	
Eff. Date: 29-OCT-2012							
SB 45-57-11 R02	WINGS - INSTALLATION OF MAIN LANDING GEAR AFT TRUNNION FITTING UPPER SHEAR PIN SPACERS [45-005 THRU 45-208, 45-210 THRU 45-222, 45-224, 45-225, 45-229 AND 45-230 WHEN MODIFIEDBY LEARJET SERVICE BULLETIN 45-57-7, "MODIFICATION OF MAIN LANDING GEAR TRUNNION ASSEMBLIES." 45-209, 45-223, 45-226 THRU 45-228, 45-231 THRU 45-425], SERVICE BULLETIN	MOS HRS/MSC AFL	-	05-AUG-2014 7865 6031	-	RECOMMENDED	Complied With
Eff. Date: 07-JUL-2014							
SB 45-57-13	WINGS - WING SPAR INSPECTION (EFFECTIVITY: LEARJET 45-005 THRU 45-367, 45-369 THRU 45-445 AND 45-447 THRU 45-455), SERVICE BULLETIN	MOS HRS/MSC AFL	-	21-MAY-2020 8814.5 6789	-	RECOMMENDED	Complied With
Eff. Date: 25-FEB-2019							
SB 45-57-16	WINGS - WING TANK DRAIN VALVE CORROSION INSPECTION, SERVICE BULLETIN	MOS	12		31-MAR-2026	RECOMMENDED	
Eff. Date: 31-MAR-2025							
SB 45-57-5	INSPECT/REPLACE FLUX VALVE BRACKET, SERVICE BULLETIN	MOS HRS/MSC	A/R	06-MAY-2001			Complied With
SB 45-57-6	REPLACEMENT MAIN LANDING GEAR TRUNNION SHEAR PINS, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	24-SEP-2003 2105.2 1585	-	RECOMMENDED	Complied With
Eff. Date: 09-JUN-2003							
SB 45-57-6 R01	REPLACEMENT MAIN LANDING GEAR TRUNNION SHEAR PINS, SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	24-SEP-2003 2105.2 1585	-	RECOMMENDED	Complied With
Eff. Date: 19-SEP-2003							
SB 45-57-7 R01	MODIFICATION OF MAIN LANDING GEAR TRUNNION ASSEMBLY. (NO REWORK REQUIRED) (EFFECTIVE: 45-005 THRU 45-208, 45-210 THRU 45-222, 45-224, 45-225, 45-229 AND 45-230), SERVICE BULLETIN	MOS HRS/MSC AFL	A/R	06-NOV-2004 3180.1 2379	-	RECOMMENDED	Complied With
Eff. Date: 19-MAR-2004							
SB 45-57-7 R03	WINGS - MODIFICATION OF MAIN LANDING GEAR TRUNNION ASSEMBLIES (EFFECTIVE: 45-005 THRU 45-208, 45-210 THRU 45-222, 45-224, 45-225, 45-229 AND 45-230), SERVICE BULLETIN	MOS AFL HRS/MSC	-			RECOMMENDED	
Eff. Date: 02-SEP-2014							

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB 45-71-6 R01	POWERPLANT - INSTALLATION OF STARTER/GENERATOR EXHAUST SCUPPER. THRU 45-351 AND 45-353, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 19-SEP-2011		MOS HRS/MSC	-				
SB 45-71-7	REPLACEMENT OF THE LEFT ENGINE FUEL AND HYDRAULIC TUBING AND INSTALLATION OF TUBING SUPPORT CHANNEL. (EFFECTIVE: 45 005 THRU 45 405), SERVICE BULLETIN					RECOMMENDED	Deferred
Eff. Date: 07-DEC-2009		MOS HRS/MSC AFL	-	13-JAN-2001 -	-		
FAA 2009-11-13							
SB 45-72-1 R05	TFE731-20BR-1B ENGINE UPGRADE. (REWORK REQUIRED) BULLETIN					OPTIONAL	Complied With - C/W PARA 2A, B, C, D, E, F
Eff. Date: 16-JUL-2007		MOS HRS/MSC AFL	A/R	14-AUG-2008 6762.9 5122	-		
SB 45-73-1 R01	REPLACEMENT OF DUAL FUEL FLOW CONVERTER (EFFECTIVE: 45 002 THRU 45 194), SERVICE BULLETIN						Complied With
		MOS HRS/MSC AFL	A/R	20-OCT-2002 1367.8 1039	-		
SB 45-73-2	ENGINE FUEL AND CONTROL - ENGINE FUEL FLOW TRANSDUCER BRACKET REPLACEMENT (EFFECTIVITY: LEARJET 45-005 THRU 45-445 AND 45-447 THRU 45-455.), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 03-OCT-2016		MOS HRS/MSC AFL	-	08-FEB-2017 8396.2 6463	-		
SB 45-76-2 R01	THRUST REVERSER MAX THRUST CREDIT, SERVICE BULLETIN						Complied With
		MOS HRS/MSC	A/R	06-MAY-2001			
SB 45-76-2 R02	THRUST REVERSER MAX THRUST CREDIT (EFFECTIVE: 45 005 THRU 45 169), SERVICE BULLETIN						Complied With
		MOS HRS/MSC	A/R	06-MAY-2001			
SB 45-77-1 R01	INSPECTION OF THE DUAL FUEL FLOW CONVERTER WIRING. BULLETIN					RECOMMENDED	
Eff. Date: 15-MAR-2010		MOS HRS/MSC	-				
SB 45-78-5	IMPROVEMENT OF ENGINE BEAM FIREWALL SEAL (EFFECTIVE: 45 002 THRU 45 219), SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 27-JUN-2001		MOS HRS/MSC AFL	A/R	03-JUL-2004 2887.8 2148	-		
SB 45-78-9	POWERPLANT - INSTALLATION OF THE THRUST REVERSER AND SERVICE ISLAND MOUNTING FLANGE GASKETS. EFFECTIVE 45-005 THRU 45-436 WITH COMPOSITE FAN DUCT INSTALLED., SERVICE BULLETIN					REVISED	
Eff. Date: 05-NOV-2012		MOS HRS/MSC	-	-	-		
ASB A45-21-14	DEACTIVATION OF COCKPIT FOOT WARMERS (EFFECTIVE: 45-005 THRU 45-213), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 03-MAR-2002		MOS HRS/MSC AFL	A/R	27-MAY-2002 999.2 755	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ASB A45-21-9	DEACTIVATION OF AUXILIARY CABIN HEATER (EFFECTIVE: 45-001 AND SUBSEQUENT), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 27-FEB-2001		MOS HRS/MSC	A/R	16-MAY-2001			
ASB A45-21-9 R01	DEACTIVATION OF AUXILIARY CABIN HEATER. (NO REWORK REQUIRED) (EFFECTIVE: 45-005 THRU 45-208, AND 45-210 THRU 45-226), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 18-JUN-2003		MOS HRS/MSC AFL	A/R	17-JAN-2002 610.7 455	-		
ASB A45-24-16	INSPECTION OF THE CIRCUIT BREAKER PANEL WIRING. (EFFECTIVE: 45-005 THRU 45-380, 45-382 THRU 45-391, 45-393 THRU 45-396, 45-398, 45-400, 45-401 AND 45-403), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 16-NOV-2009		MOS HRS/MSC AFL	-	24-NOV-2009 6774.1 5132	-		
ASB A45-25-7	PASSENGER SEAT BELT (EFFECTIVE: 45-005 THRU 45-147), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 10-JUL-2001		MOS HRS/MSC AFL	A/R	15-JUL-2001 162.1 123	-		
ASB A45-25-7 R01	PASSENGER SEAT BELT. (REWORK REQUIRED) (EFFECTIVE: 45-005 THRU 45-147), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 23-AUG-2001		MOS HRS/MSC AFL	A/R	04-MAR-2002 748.8 557	-		
ASB A45-27-15	FLIGHT CONTROLS-REPLACEMENT OF THE HORIZONTAL STABILIZER ACTUATOR ASSEMBLY (EFFECTIVE: 45-001 THRU 45-232), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 20-MAR-2003		MOS HRS/MSC AFL	A/R	20-MAR-2003 1735.8 1299	-		
ASB A45-27-18	FLIGHT CONTROLS - REPLACEMENT OF THE HORIZONTAL STABILIZER ACTUATOR ASSEMBLY (EFFECTIVE: 45-001 THRU 45-233), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 08-SEP-2003		MOS HRS/MSC AFL	A/R	24-SEP-2003 2105.2 1585	-		
ASB A45-27-30 R03	REPLACEMENT OF FLAP ACTUATOR FORWARD ATTACH JOINTS. NO REWORK REQUIRED. (EFFECTIVE: 45-005 THRU 45-339), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With - NO REWORK REQUIRED
Eff. Date: 15-FEB-2010		MOS HRS/MSC AFL	-	29-MAR-2008 6517.5 4927	-		
ASB A45-27-34	FLIGHT CONTROLS - REPLACEMENT OF RUDDER TRIM TAB HINGE COTTER PINS (EFFECTIVE: 45-005 THRU 45-364), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 16-JUN-2008		MOS HRS/MSC AFL	-	27-SEP-2012 7362.9 5599	-		
ASB A45-27-40	INSPECTION OF THE FLAP ACTUATOR BALLSCREW ASSEMBLYSLEEVES (EFFECTIVE: 45-005 THRU 45-380), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 11-JAN-2010		DAYS HRS/MSC AFL	-	21-MAY-2014 7830.7 5995	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ASB A45-29-15	INSPECTION/REPLACEMENT OF THE LEFT HYDRAULIC PUMP CASE DRAIN TUBE (EFFECTIVE: 45-005 THRU 45-313), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 26-DEC-2006		MOS HRS/MSC AFL	-	03-SEP-2009 6773.2 5131	-		
ASB A45-30-10	ICE AND RAIN PROTECTION - NACELLE ANTI-ICE TUBE INSPECTION, ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 25-APR-2016		MOS HRS/MSC AFL	-	11-MAY-2016 8317 6377	-		
ASB A45-32-41	LANDING GEAR - MAIN LANDING GEAR ACTUATOR UPPER PIN INSPECTION (EFFECTIVITY: LEARJET 45-005 THRU 45-367, 45-369 THRU 45-445, AND 45-447 THRU 45-455), ALERT SERVICE BULLETIN					ALERT	Complied With - LH PN 200-0325-101 SN H-2968 RH PN 200-0325-101 SN H-2976
Eff. Date: 05-OCT-2021		MOS HRS/MSC AFL	-	06-DEC-2021 9115.4 7018	-		
ASB A45-34-7	UNS PERFORMANCE DATABASE RESTRICTION PLACARD (EFFECTIVE: 45-005 AND SUBSEQUENT), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 07-DEC-2001		MOS HRS/MSC AFL	A/R	25-JAN-2002 641.8 476	-		
ASB A45-35-6	OXYGEN-PROTECTIVE BREATHING EQUIPMENT INSPECTION(EFFECTIVITY: LEARJET 45-005 THRU 45-445 AND 45-447 THRU 45-455), ALERT SERVICE BULLETIN					RECOMMENDED	Not Applicable - NO PBE INSTALLED IN AIRCRAFT
Eff. Date: 14-MAR-2016		MOS HRS/MSC AFL	-	11-MAY-2016 8317 6377	-		
ASB A45-55-19	STABILIZERS - INSPECT THE HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY ATTACHING HARDWARE (EFFECTIVE: 45 005 THRU 45 342), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 15-OCT-2007		MOS HRS/MSC AFL	-	27-FEB-2009 6768.5 5125	-		
ASB A45-71-4	MODIFICATION OF THE LEFT ENGINE ALTERNATOR WIRE ROUTING. (EFFECTIVE: 45-005 THRU 45-273), ALERT SERVICE BULLETIN					RECOMMENDED	Complied With
Eff. Date: 29-SEP-2005		MOS HRS/MSC AFL	A/R	15-NOV-2005 4224.6 3182	-		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 1 - AD - TFE731-20BR-1B P-116262/3060084-2							
FAA 1998-10-15	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - MAIN PUMP FUEL PUMP FUEL LINE, P/N 3061191-1 - REPLACE	MOS			05-FEB-2004	AIRWORTHINESS	Not Applicable - PER ENGINE MODEL
Eff. Date: 19-MAY-1998		HRS/MSC	A/R				
FAA 1999-07-19	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - FUEL FLOW METER TUBE ASSEMBLY P/N 3061157-2 - INSPECT	MOS			05-FEB-2004	AIRWORTHINESS	Not Applicable - PER ENGINE MODEL
Eff. Date: 21-APR-1999		HRS/MSC	A/R				
FAA 2008-02-19	NO. 1 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INSPECT/REPLACE	MOS			06-MAR-2008	MANDATORY	Complied With
Eff. Date: 06-MAR-2008		HRS/MSC	-		4835.1		
		ENC			3660		
FAA 2012-16-14	NO. 1 ENGINE - ENGINE - LPT2 ROTOR BLADES - REMOVE/INSPECT	MOS			12-DEC-2017	MANDATORY	Not Applicable - BY PART NUMBER INSTALLED
Eff. Date: 01-OCT-2012		HRS/MSC	-		8448.1		- NO FURTHER ACTION REQUIRED
		ENC			6510		
FAA 2014-12-52	NO. 1 ENGINE - REVIEW ENGINE LOGBOOKS AND REPLACE LOW PRESSURE TURBINE 2 (LPT2) BLADE P/N 3075424-1, -2, OR -3	MOS			05-AUG-2014	MANDATORY	Complied With - COMPLIED WITH REVIEW OF LOGBOOKS AND DETERMINED AIRCRAFT HAS MORE THAN 250 HOURS FROM BLADE INSTALLATION
Eff. Date: 28-JUL-2014		HRS/MSC	-		7801.1		
		ENC			5979		
FAA 2019-05-07 PARA (G)	NO. 1 ENGINE - REMOVE THE AFFECTED FAN DISK	MOS			01-DEC-2000	MANDATORY	
Eff. Date: 25-APR-2019		HRS/MSC	-		-		
		ENC	9000			10835.1	
						9000	

MASTER AD/SI REPORT

AIRCRAFT
All Bulletins With Compliance or Due
29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ENGINE NO. 2 - AD - TFE731-20BR-1B P-116261/3060084-2							
FAA 2008-02-19	NO. 2 ENGINE - ENGINE - HIGH PRESSURE (HP) TURBINE ROTOR DISCS - INSPECT/REPLACE					MANDATORY	Not Applicable - DUE TO S/N OF ROTOR INSTALLED
Eff. Date: 06-MAR-2008		MOS		27-FEB-2009			
		HRS/MSC	-	6238.1	-		
		ENC		4737			
FAA 2012-16-14	NO. 2 ENGINE - ENGINE - LPT2 ROTOR BLADES - REMOVE/INSPECT					MANDATORY	Not Applicable - BY PART NUMBER INSTALLED - NO FURTHER ACTION REQUIRED
Eff. Date: 01-OCT-2012		MOS		12-DEC-2017			
		HRS/MSC	-	7962.7	-		
		ENC		6153			
FAA 2014-12-52	NO. 2 ENGINE - REVIEW ENGINE LOGBOOKS AND REPLACE LOW PRESSURE TURBINE 2 (LPT2) BLADE P/N 3075424-1, -2, OR -3					MANDATORY	Complied With - BY PREVIOUS COMPLIANCE WITH SB TFE731-71-A5246
Eff. Date: 28-JUL-2014		MOS		03-SEP-2015			
		HRS/MSC	-	7653.4	-		
		ENC		5888			
FAA 2019-05-07 PARA (G)	NO. 2 ENGINE - REMOVE THE AFFECTED FAN DISK					MANDATORY	
Eff. Date: 25-APR-2019		MOS		01-JUL-2000			
		HRS/MSC	-	-	11031.7		
		ENC	9000		9000		
ENGINE NO. 1 - SB - TFE731-20BR-1B P-116262/3060084-2							
SB TFE731-72-5159 R04	NO. 1 ENGINE - ENGINE - ACCESSORY DRIVES SECTION - INSTALL THE IMPROVED FILTER BY-PASS VALVE ASSEMBLY, PN, 3060782-2, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 20-SEP-2012		MOS					
		HRS/MSC	DUE	-	10801.1		
SB TFE731-72-5172 R05	NO. 1 ENGINE - TURBINE SECTION - HPT AND LPT BLADE HOUR TRACKING AND RECOMMENDED BLADE REPLACEMENT INTERVALS FOR TFE731-20, -40, -50, -60 SERIES ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 07-AUG-2015		MOS					
		HRS/MSC	MPI	-	10801.1		
SB TFE731-72-5197 R02	NO. 1 ENGINE - COMPRESSOR SECTION - INSTALL DESWIRL, PN 3060326-4, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 27-NOV-2019		MOS					
		HRS/MSC	CZI	-	10835.1		
SB TFE731-72-5209 R01	NO. 1 ENGINE - ENGINE - BY-PASS SECTION - INSTALL IMPROVED FAN BY-PASS DUCT, PN 3060798-2, -3, SERVICE BULLETIN					CATEGORY 3	
Eff. Date: 26-FEB-2013		MOS					
		HRS/MSC	-				
SB TFE731-72-5216	NO. 1 ENGINE - ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED PLAIN ENCASED SEAL, PN 3020052-25, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 07-JUN-2011		MOS					
		HRS/MSC	-				
SB TFE731-72-5216 R01	NO. 1 ENGINE - ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED PLAIN ENCASED SEAL, PN 3020052-26, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 28-OCT-2011		MOS					
		HRS/MSC	DUE	-	10801.1		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB TFE731-72-5221 R01	NO. 1 ENGINE - TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED LOW PRESSURE SECOND STAGE TURBINE (LPT2) ROTOR BLADES, PN 3075424-2, -3, SERVICE BULLETIN					CATEGORY 1	Not Applicable - BY PART NUMBER INSTALLED
Eff. Date: 02-NOV-2017		MOS HRS/MSC ENC	-	12-DEC-2017 8448.1 6510	-		
FAA 2012-16-14							
SB TFE731-72-5221 R01 PARA (3)	NO. 1 ENGINE - TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED LOW PRESSURE SECOND STAGE TURBINE (LPT2) ROTOR BLADES, PN 3075424-2, -3, SERVICE BULLETIN REVIEW ENGINE LOG BOOK (INCLUDING THE LIFE LIMITED PART LOG CARD FOR THE INSTALLED LPT2 ROTOR ASSEMBLY, PN 3060608-2, -3, -5), AND THIS SERVICE BULLETIN TO DETERMINE IF THE ENGINE IS EFFECTED					CATEGORY 1	Not Applicable - BY PART NUMBER INSTALLED
Eff. Date: 02-NOV-2017		MOS HRS/MSC ENC	-	12-DEC-2017 8448.1 6510	-		
SB TFE731-72-5221 R01 PARA (6)	NO. 1 ENGINE - TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED LOW PRESSURE SECOND STAGE TURBINE (LPT2) ROTOR BLADES, PN 3075424-2, -3, SERVICE BULLETIN REMOVE SUSPECT LPT2 ROTOR BLADE					CATEGORY 1	Not Applicable - BY PART NUMBER INSTALLED
Eff. Date: 02-NOV-2017		MOS HRS/MSC ENC	-	12-DEC-2017 8448.1 6510	-		
SB TFE731-72-5222 R02	NO. 1 ENGINE - COMPRESSOR SECTION - INSTALL FRONT FRAME ASSEMBLY THAT HAS ADDITIONAL CORROSION PROTECTION FEATURES, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 13-OCT-2021		MOS HRS/MSC	-	-	10835.1		
SB TFE731-72-5223 R01	NO. 1 ENGINE - BYPASS SECTION - APPLY PROTECTIVE COATING TO THE AFT FLANGE OF THE COMPOSITE BYPASS DUCT ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 20-APR-2018		MOS HRS/MSC	DUE	-	10801.1		
SB TFE731-72-5224 R01	NO. 1 ENGINE - BYPASS SECTION - INSPECT, REWORK, OR REPLACE COMPOSITE BYPASS DUCTS ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 19-APR-2018		MOS HRS/MSC	DUE	-	10835.1		
SB TFE731-72-5225 R01	NO. 1 ENGINE - ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED LOW PRESSURE COMPRESSOR SECOND STAGE (LPC2) SHROUD, PN 3072403-6, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 17-AUG-2012		MOS HRS/MSC	DUE	-	10835.1		
SB TFE731-72-5227 R01	NO. 1 ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY SECTION - INTRODUCTION OF ACCESSORY DRIVE GEARBOX ASSEMBLY WITH HYDRODYNAMIC CARBON FACE SEALS FOR TFE731-20, -40, -50, -60 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 24-JUL-2015		MOS HRS/MSC	DUE	-	10835.1		
SB TFE731-72-5236	NO. 1 ENGINE - FAN INLET HOUSING INSTALLATION - INSTALLATION OF NEW OR REWORKED FAN INLET HOUSING, SERVICE BULLETIN					CATEGORY 3	
Eff. Date: 25-NOV-2013		MOS HRS/MSC	-				

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB TFE731-72-5247	NO. 1 ENGINE - ENGINE - BYPASS SECTION - REPLACE FAN STATOR VANE ASSEMBLY, PN 3060163-3, -4, -5 WITH PN 70060130-1 FOR TFE731-20, -40 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 08-JUL-2015		MOS HRS/MSC	DUE	-	10835.1		
SB TFE731-72-5251	NO. 1 ENGINE - TURBINE SECTION - ACCOMPLISH EDDY CURRENT INSPECTION OF SPECIFIC SECOND STAGE LOW PRESSURE TURBINE (LPT2) BLADES, PN 3075424, ON TFE731-20, -40, -50, -60 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 25-MAR-2015		MOS HRS/MSC	DUE	-	10801.1		
SB TFE731-72-5251 R01	NO. 1 ENGINE - TURBINE SECTION - ACCOMPLISH EDDY CURRENT INSPECTION OF SPECIFIC SECOND STAGE LOW PRESSURE TURBINE (LPT2) BLADES, PN 3075424, ON TFE731-20, -40, -50, -60 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 16-FEB-2021		MOS HRS/MSC	MPI	-	10801.1		
SB TFE731-72-5256 R01	NO. 1 ENGINE - BYPASS SECTION - IDENTIFY AND REPLACE SPECIFIC FAN DISKS, PN 3060287-2, WITH SUSPECT SHOT PEENED ROLLED EDGES ON TFE731-20 AND -40 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 1	Not Applicable - REVIEWED - NO ACTION REQUIRED, N/A BY PART NUMBER INSTALLED
Eff. Date: 07-OCT-2016		MOS HRS/MSC ENC	-	08-MAR-2022 9061 6977	-		
ASB TFE731-72-A5240	NO. 1 ENGINE - TURBINE SECTION - INSPECT OR REPLACE SECOND STAGE LOW PRESSURE TURBINE ROTOR ASSEMBLIES WITH SUSPECT BLADES INSTALLED ON TFE731-20, -40, -50, AND -60 SERIES ENGINES, ALERT SERVICE BULLETIN					CATEGORY 1	Not Applicable
Eff. Date: 25-JUN-2014		MOS HRS/MSC ENC	-	05-AUG-2014 7801.1 5979	-		
ASB TFE731-72-A5242 R01	NO. 1 ENGINE - TURBINE SECTION - SECOND STAGE LOW PRESSURE TURBINE ROTOR ASSEMBLIES WITH SUSPECT BLADES INSTALLED ON TFE731-20, -40, -50, AND -60 SERIES ENGINES, ALERT SERVICE BULLETIN					CATEGORY 1	Complied With - COMPLIED WITH REVIEW OF LOGBOOKS AND DETERMINED AIRCRAFT HAS MORE THAN 250 HOURS FROM BLADE INSTALLATION
Eff. Date: 25-JUN-2014		MOS HRS/MSC ENC	-	05-AUG-2014 7801.1 5979	-		
ASB TFE731-72-A5242 R02	NO. 1 ENGINE - TURBINE SECTION - SECOND STAGE LOW PRESSURE TURBINE ROTOR ASSEMBLIES WITH SUSPECT BLADES INSTALLED ON TFE731-20, -40, -50, AND -60 SERIES ENGINES, ALERT SERVICE BULLETIN					CATEGORY 1	
Eff. Date: 29-AUG-2014		MOS HRS/MSC	BF/F				
ASB TFE731-72-A5246	NO. 1 ENGINE - TURBINE SECTION - EDDY CURRENT INSPECT SECOND STAGE LOW PRESSURE TURBINE ROTOR ASSEMBLIES WITH SUSPECT BLADES INSTALLED ON TFE731-20, -40, -50 AND -60 SERIES ENGINES (SERVICE BULLETIN IS EXPORT CONTROLLED. CONTACT HONEYWELL TO OBTAIN A COPY OF THE SERVICE BULLETIN), ALERT SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 25-JUN-2014		MOS HRS/MSC ENC	-	05-AUG-2014 7801.1 5979	-		

MASTER AD/SI REPORT

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB TFE731-73-5127	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - INSPECT/REPLACE (AS REQUIRED) FUEL PUMP TO MOTIVE FLOW PUMP TUBE ASSEMBLY, PART NO. 3061192-1/3061201-1, AND REPLACE CLAMP, PART NO. NAS1715C6K, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 10-NOV-2005		MOS HRS/MSC ENC	-	01-DEC-2000 -	-		
SB TFE731-73-5127 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE FUEL PUMP TO MOTIVE FLOW PUMP TUBE ASSEMBLY, PART NO. 3061192-1/3061201-1 WITH PART NO. 3061314-2, SERVICE BULLETIN					CATEGORY 2	Complied With
Eff. Date: 10-NOV-2005		MOS HRS/MSC ENC	A/R	30-JUN-2006 4789.5 3624	-		
SB TFE731-73-5145	NO. 1 ENGINE - ENGINE FUEL AND CONTROLLING - DISTRIBUTION - REPLACEMENT OF FUEL FLOW METER TUBE ASSEMBLIES, PN 3061157-1 AND PN 3061148-1, WITH IMPROVED FUEL HOSE ASSEMBLY, PN 3061288-1, AND FUEL TUBE ASSEMBLY, PN 70060172-1, ON TFE731-20, -40 MODEL ENGINES., SERVICE BULLETIN					CATEGORY 1	Complied With
Eff. Date: 05-OCT-2016		MOS HRS/MSC ENC	-	08-FEB-2017 8332.3 6411	-		
SB TFE731-73-5145 PARA (E)(2)	NO. 1 ENGINE - FCU TO FLOW METER TUBE ASSEMBLY INSPECTION					CATEGORY 1	Complied With
Eff. Date: 05-OCT-2016		MOS HRS/MSC ENC	-	08-FEB-2017 8332.3 6411	-		
SB TFE731-73-5145 PARA (E)(3)	NO. 1 ENGINE - REPLACEMENT OF THE EXISTING FUEL FLOW METER TO FLOW DIVIDER TUBE ASSEMBLY, PN 3061148-1, AND FCU TO FLOW METER TUBE ASSEMBLY, PN 3061157-1					CATEGORY 1	Complied With
Eff. Date: 05-OCT-2016		MOS HRS/MSC ENC	-	08-FEB-2017 8332.3 6411	-		
SB TFE731-73-5146	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-28, -30, -37, -47, -69, AND -79, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	Deferred - TO BE C/W AT ENGINE MPI/CZI INSPECTIONS
Eff. Date: 04-MAY-2017		MOS HRS/MSC	-				
SB TFE731-73-5146 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-28, -30, -37, -47, -69, AND -79, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 24-JAN-2018		MOS HRS/MSC	DUE	-	10801.1		
SB TFE731-73-SB13	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - MODEL CH-R1 FUEL CONTROL -CONVERT FUEL CONTROL ASSEMBLIES, PN 3070800-3X TO PN 3070800-4X, SERVICE BULLETIN						
Eff. Date: 14-MAR-2012		MOS HRS/MSC	-				
SB TFE731-79-5106 R07	NO. 1 ENGINE - INSTALL AN IMPROVED OIL DRAINBACK SYSTEM, SERVICE BULLETIN					CATEGORY 3	
Eff. Date: 06-FEB-2013		MOS HRS/MSC	-				

MASTER AD/SI REPORT

AIRCRAFT
All Bulletins With Compliance or Due
29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB TFE731-79-5125	NO. 1 ENGINE - ENGINE - OIL DISTRIBUTION - INSTALL NEW FORWARD NO. 6 BEARING OIL SUPPLY TUBE ASSEMBLY, PN 3060900-2, AND MID NO. 6 BEARING OIL SUPPLY TUBE ASSEMBLY, PN 3060901-6, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 25-JUL-2013		MOS HRS/MSC	-				
SB TFE731-79-5127	NO. 1 ENGINE - OIL - DISTRIBUTION - INSTALL TWO-PIECE AIR-OIL COOLER SUPPLY TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 14-MAR-2014		MOS HRS/MSC	-	-	10835.1		
SB TFE731-79-5129	NO. 1 ENGINE - OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-20, -40, -60 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 09-MAY-2018		MOS HRS/MSC	DUE	-	10801.1		
ASB TFE731-A72-5185	NO. 1 ENGINE - ENGINE - TURBINE SECTION - INSPECT/REPLACE (IF REQUIRED) SPECIFIC IDENTIFIED HIGH PRESSURE (HP) TURBINE ROTOR DISCS, PART NO. 3060841-1, ALERT SERVICE BULLETIN					CATEGORY 1	Complied With
Eff. Date: 05-JUL-2006		MOS HRS/MSC ENC	-	21-AUG-2006 4835.1 3660	-		
ASB TFE731-A73-5126 R01	NO. 1 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE FUEL PUMP TO MOTIVE FLOW PUMP TUBE ASSEMBLY, PART NO. 3061191-2 WITH PART NO. 3061314-2, ALERT SERVICE BULLETIN						
Eff. Date: 10-NOV-2005		MOS HRS/MSC ENC	-	01-DEC-2000 -	-		
ASB TFE731-A73-5133	NO. 1 ENGINE - REPLACE INLET FILTER SCREEN, PART NO. 765310, ON IDENTIFIED MOTIVE FLOW PUMPS, ALERT SERVICE BULLETIN						Complied With
Eff. Date: 16-AUG-2004		MOS HRS/MSC	A/R	06-NOV-2004 4378.1	-		
ENGINE NO. 2 - SB - TFE731-20BR-1B P-116261/3060084-2							
SB TFE731-72-5150	NO. 2 ENGINE - BYPASS SECTION - REPLACE THE HOISTING BRACKET ON THE FAN DUCT SET, PART NUMBER 3072420-13 (UPPER HALF), ON SPECIFIC IDENTIFIED ENGINES, SERVICE BULLETIN					CATEGORY 1	Complied With
Eff. Date: 29-JUN-2001		MOS HRS/MSC	A/R	17-MAY-2002 963.3	-		
SB TFE731-72-5159 R04	NO. 2 ENGINE - ENGINE - ACCESSORY DRIVES SECTION - INSTALL THE IMPROVED FILTER BY-PASS VALVE ASSEMBLY, PN, 3060782-2, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 20-SEP-2012		MOS HRS/MSC	DUE	-	10653.4		
SB TFE731-72-5172 R05	NO. 2 ENGINE - TURBINE SECTION - HPT AND LPT BLADE HOUR TRACKING AND RECOMMENDED BLADE REPLACEMENT INTERVALS FOR TFE731-20, -40, -50, -60 SERIES ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 07-AUG-2015		MOS HRS/MSC	MPI	-	10653.4		
SB TFE731-72-5197 R02	NO. 2 ENGINE - COMPRESSOR SECTION - INSTALL DESWIRL, PN 3060326-4, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 27-NOV-2019		MOS HRS/MSC	CZI	-	11031.7		

MASTER AD/SI REPORT

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB TFE731-72-5209 R01	NO. 2 ENGINE - ENGINE - BY-PASS SECTION - INSTALL IMPROVED FAN BY-PASS DUCT, PN 3060798-2, -3, SERVICE BULLETIN					CATEGORY 3	
Eff. Date: 26-FEB-2013		MOS HRS/MSC	-				
SB TFE731-72-5216	NO. 2 ENGINE - ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED PLAIN ENCASED SEAL, PN 3020052-25, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 07-JUN-2011		MOS HRS/MSC	-				
SB TFE731-72-5216 R01	NO. 2 ENGINE - ENGINE - ACCESSORY DRIVES SECTION - INSTALL IMPROVED PLAIN ENCASED SEAL, PN 3020052-26, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 28-OCT-2011		MOS HRS/MSC	DUE	-	10653.4		
SB TFE731-72-5221 R01	NO. 2 ENGINE - TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED LOW PRESSURE SECOND STAGE TURBINE (LPT2) ROTOR BLADES, PN 3075424-2, -3, SERVICE BULLETIN					CATEGORY 1	Not Applicable - BY PART NUMBER INSTALLED
Eff. Date: 02-NOV-2017		MOS HRS/MSC ENC	-	12-DEC-2017 7962.7 6153	-		
FAA 2012-16-14							
SB TFE731-72-5221 R01 PARA (3)	NO. 2 ENGINE - TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED LOW PRESSURE SECOND STAGE TURBINE (LPT2) ROTOR BLADES, PN 3075424-2, -3, SERVICE BULLETIN REVIEW ENGINE LOG BOOK (INCLUDING THE LIFE LIMITED PART LOG CARD FOR THE INSTALLED LPT2 ROTOR ASSEMBLY, PN 3060608-2, -3, -5), AND THIS SERVICE BULLETIN TO DETERMINE IF THE ENGINE IS EFFECTED					CATEGORY 1	Not Applicable - BY PART NUMBER INSTALLED
Eff. Date: 02-NOV-2017		MOS HRS/MSC ENC	-	12-DEC-2017 7962.7 6153	-		
SB TFE731-72-5221 R01 PARA (6)	NO. 2 ENGINE - TURBINE SECTION - REPLACE SPECIFIC IDENTIFIED LOW PRESSURE SECOND STAGE TURBINE (LPT2) ROTOR BLADES, PN 3075424-2, -3, SERVICE BULLETIN REMOVE SUSPECT LPT2 ROTOR BLADE					CATEGORY 1	Not Applicable - BY PART NUMBER INSTALLED
Eff. Date: 02-NOV-2017		MOS HRS/MSC ENC	-	12-DEC-2017 7962.7 6153	-		
SB TFE731-72-5222 R02	NO. 2 ENGINE - COMPRESSOR SECTION - INSTALL FRONT FRAME ASSEMBLY THAT HAS ADDITIONAL CORROSION PROTECTION FEATURES, SERVICE BULLETIN					RECOMMENDED	
Eff. Date: 13-OCT-2021		MOS HRS/MSC	-	-	11031.7		
SB TFE731-72-5223 R01	NO. 2 ENGINE - BYPASS SECTION - APPLY PROTECTIVE COATING TO THE AFT FLANGE OF THE COMPOSITE BYPASS DUCT ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 20-APR-2018		MOS HRS/MSC	DUE	-	10653.4		
SB TFE731-72-5224 R01	NO. 2 ENGINE - BYPASS SECTION - INSPECT, REWORK, OR REPLACE COMPOSITE BYPASS DUCTS ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 19-APR-2018		MOS HRS/MSC	DUE	-	11031.7		

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

29-Jun-2026 11:49 AM

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB TFE731-72-5225 R01	NO. 2 ENGINE - ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED LOW PRESSURE COMPRESSOR SECOND STAGE (LPC2) SHROUD, PN 3072403-6, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 17-AUG-2012		MOS HRS/MSC	DUE	-	11031.7		
SB TFE731-72-5227 R01	NO. 2 ENGINE - ACCESSORY DRIVE GEARBOX ASSEMBLY SECTION - INTRODUCTION OF ACCESSORY DRIVE GEARBOX ASSEMBLY WITH HYDRODYNAMIC CARBON FACE SEALS FOR TFE731-20, -40, -50, -60 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 24-JUL-2015		MOS HRS/MSC	DUE	-	11031.7		
SB TFE731-72-5236	NO. 2 ENGINE - FAN INLET HOUSING INSTALLATION - INSTALLATION OF NEW OR REWORKED FAN INLET HOUSING, SERVICE BULLETIN					CATEGORY 3	
Eff. Date: 25-NOV-2013		MOS HRS/MSC	-				
SB TFE731-72-5247	NO. 2 ENGINE - ENGINE - BYPASS SECTION - REPLACE FAN STATOR VANE ASSEMBLY, PN 3060163-3, -4, -5 WITH PN 70060130-1 FOR TFE731-20, -40 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 08-JUL-2015		MOS HRS/MSC	DUE	-	11031.7		
SB TFE731-72-5251	NO. 2 ENGINE - TURBINE SECTION - ACCOMPLISH EDDY CURRENT INSPECTION OF SPECIFIC SECOND STAGE LOW PRESSURE TURBINE (LPT2) BLADES, PN 3075424, ON TFE731-20, -40, -50, -60 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 25-MAR-2015		MOS HRS/MSC	DUE	-	10653.4		
SB TFE731-72-5251 R01	NO. 2 ENGINE - TURBINE SECTION - ACCOMPLISH EDDY CURRENT INSPECTION OF SPECIFIC SECOND STAGE LOW PRESSURE TURBINE (LPT2) BLADES, PN 3075424, ON TFE731-20, -40, -50, -60 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 16-FEB-2021		MOS HRS/MSC	MPI	-	10653.4		
SB TFE731-72-5256 R01	NO. 2 ENGINE - BYPASS SECTION - IDENTIFY AND REPLACE SPECIFIC FAN DISKS, PN 3060287-2, WITH SUSPECT SHOT PEENED ROLLED EDGES ON TFE731-20 AND -40 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 1	Not Applicable - REVIEWED - NO ACTION REQUIRED, N/A BY PART NUMBER INSTALLED
Eff. Date: 07-OCT-2016		MOS HRS/MSC ENC	-	08-MAR-2022 8575.6 6620	-		
ASB TFE731-72-A5240	NO. 2 ENGINE - TURBINE SECTION - INSPECT OR REPLACE SECOND STAGE LOW PRESSURE TURBINE ROTOR ASSEMBLIES WITH SUSPECT BLADES INSTALLED ON TFE731-20, -40, -50, AND -60 SERIES ENGINES, ALERT SERVICE BULLETIN					CATEGORY 1	Not Applicable
Eff. Date: 25-JUN-2014		MOS HRS/MSC ENC	-	05-AUG-2014 7335.1 5643	-		
ASB TFE731-72-A5242 R01	NO. 2 ENGINE - TURBINE SECTION - SECOND STAGE LOW PRESSURE TURBINE ROTOR ASSEMBLIES WITH SUSPECT BLADES INSTALLED ON TFE731-20, -40, -50, AND -60 SERIES ENGINES, ALERT SERVICE BULLETIN					CATEGORY 1	Not Applicable
Eff. Date: 25-JUN-2014		MOS HRS/MSC ENC	-	05-AUG-2014 7335.1 5643	-		

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
ASB TFE731-72-A5242 R02	NO. 2 ENGINE - TURBINE SECTION - SECOND STAGE LOW PRESSURE TURBINE ROTOR ASSEMBLIES WITH SUSPECT BLADES INSTALLED ON TFE731-20, -40, -50, AND -60 SERIES ENGINES, ALERT SERVICE BULLETIN					CATEGORY 1	
Eff. Date: 29-AUG-2014		MOS HRS/MSC	BF/F				
ASB TFE731-72-A5246	NO. 2 ENGINE - TURBINE SECTION - EDDY CURRENT INSPECT SECOND STAGE LOW PRESSURE TURBINE ROTOR ASSEMBLIES WITH SUSPECT BLADES INSTALLED ON TFE731-20, -40, -50 AND -60 SERIES ENGINES (SERVICE BULLETIN IS EXPORT CONTROLLED. CONTACT HONEYWELL TO OBTAIN A COPY OF THE SERVICE BULLETIN), ALERT SERVICE BULLETIN					RECOMMENDED	Not Applicable
Eff. Date: 25-JUN-2014		MOS HRS/MSC ENC	-	05-AUG-2014 7335.1 5643	-		
SB TFE731-73-5127	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - INSPECT/REPLACE (AS REQUIRED) FUEL PUMP TO MOTIVE FLOW PUMP TUBE ASSEMBLY, PART NO. 3061192-1/3061201-1, AND REPLACE CLAMP, PART NO. NAS1715C6K, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 10-NOV-2005		MOS HRS/MSC ENC	-	01-JUL-2000 -	-		
SB TFE731-73-5127 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE FUEL PUMP TO MOTIVE FLOW PUMP TUBE ASSEMBLY, PART NO. 3061192-1/3061201-1 WITH PART NO. 3061314-2, SERVICE BULLETIN					CATEGORY 2	Complied With
Eff. Date: 10-NOV-2005		MOS HRS/MSC ENC	A/R	30-JUN-2006 4378.7 3313	-		
SB TFE731-73-5137	NO. 2 ENGINE - REPLACE SPECIFIC IDENTIFIED MAIN TURBINE ENGINE FUEL PUMPS (FUEL PUMP), PART NUMBER 3060760-4, SERVICE BULLETIN					CATEGORY 2	Not Applicable - TO FUEL CONTROL BY PART NUMBER
Eff. Date: 15-MAR-2006		MOS HRS/MSC ENC	-	11-MAY-2016 7767.7 5968	-		
SB TFE731-73-5145	NO. 2 ENGINE - ENGINE FUEL AND CONTROLLING - DISTRIBUTION - REPLACEMENT OF FUEL FLOW METER TUBE ASSEMBLIES, PN 3061157-1 AND PN 3061148-1, WITH IMPROVED FUEL HOSE ASSEMBLY, PN 3061288-1, AND FUEL TUBE ASSEMBLY, PN 70060172-1, ON TFE731-20, -40 MODEL ENGINES., SERVICE BULLETIN					CATEGORY 1	Complied With
Eff. Date: 05-OCT-2016		MOS HRS/MSC ENC	-	08-FEB-2017 7846.9 6056	-		
SB TFE731-73-5145 PARA (E)(2)	NO. 2 ENGINE - FCU TO FLOW METER TUBE ASSEMBLY INSPECTION					CATEGORY 1	Complied With
Eff. Date: 05-OCT-2016		MOS HRS/MSC ENC	-	08-FEB-2017 7846.9 6056	-		
SB TFE731-73-5145 PARA (E)(3)	NO. 2 ENGINE - REPLACEMENT OF THE EXISTING FUEL FLOW METER TO FLOW DIVIDER TUBE ASSEMBLY, PN 3061148-1, AND FCU TO FLOW METER TUBE ASSEMBLY, PN 3061157-1					CATEGORY 1	Complied With
Eff. Date: 05-OCT-2016		MOS HRS/MSC ENC	-	08-FEB-2017 7846.9 6056	-		
SB TFE731-73-5146	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-28, -30, -37, -47, -69, AND -79, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	Deferred - TO BE C/W AT ENGINE MPI/CZI INSPECTIONS
Eff. Date: 04-MAY-2017		MOS HRS/MSC	-				

?-Insufficient Information +- Task exists in Inspection Manual (S)-Suppressed Requirement (Ex)-Excluded Tasks *-Estimated Due(New Requirement) (EFF)-Effective C/W (EBT)-Estimated Base Time

MASTER AD/SI REPORT

AIRCRAFT

All Bulletins With Compliance or Due

29-Jun-2026 11:49 AM

Model: LEARJET 45 Serial: 45-134 RegNo: N751JC HRS: 9832.1 AFL: 7527 As Of: 31-May-2026

TaskNbr	Task Description	Unit	Interval	C/W	NextDue	Disposition	MOC
SB TFE731-73-5146 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - CONTROLLING - INSTALL IMPROVED FUEL CONTROL ASSEMBLY (FCA), PN 3070800-28, -30, -37, -47, -69, AND -79, WITH IMPROVED SOLENOID ATTACHMENT SCREWS ON TFE731-20, -40, -50, AND -60 ENGINE MODELS, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 24-JAN-2018		MOS HRS/MSC	DUE	-	10653.4		
SB TFE731-73-SB13	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - MODEL CH-R1 FUEL CONTROL -CONVERT FUEL CONTROL ASSEMBLIES, PN 3070800-3X TO PN 3070800-4X, SERVICE BULLETIN						
Eff. Date: 14-MAR-2012		MOS HRS/MSC	-				
SB TFE731-79-5106 R07	NO. 2 ENGINE - INSTALL AN IMPROVED OIL DRAINBACK SYSTEM, SERVICE BULLETIN					CATEGORY 3	
Eff. Date: 06-FEB-2013		MOS HRS/MSC	-				
SB TFE731-79-5125	NO. 2 ENGINE - ENGINE - OIL DISTRIBUTION - INSTALL NEW FORWARD NO. 6 BEARING OIL SUPPLY TUBE ASSEMBLY, PN 3060900-2, AND MID NO. 6 BEARING OIL SUPPLY TUBE ASSEMBLY, PN 3060901-6, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 25-JUL-2013		MOS HRS/MSC	-				
SB TFE731-79-5127	NO. 2 ENGINE - OIL - DISTRIBUTION - INSTALL TWO-PIECE AIR-OIL COOLER SUPPLY TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 14-MAR-2014		MOS HRS/MSC	-	-	11031.7		
SB TFE731-79-5129	NO. 2 ENGINE - OIL - STORAGE - INSTALL IMPROVED OIL TANK INSTRUCTION PLATE TO PREVENT OIL TANK OVERSERVICING ON TFE731-20, -40, -60 MODEL ENGINES, SERVICE BULLETIN					CATEGORY 2	
Eff. Date: 09-MAY-2018		MOS HRS/MSC	DUE	-	10653.4		
ASB TFE731-A72-5185	NO. 2 ENGINE - ENGINE - TURBINE SECTION - INSPECT/REPLACE (IF REQUIRED) SPECIFIC IDENTIFIED HIGH PRESSURE (HP) TURBINE ROTOR DISCS, PART NO. 3060841-1, ALERT SERVICE BULLETIN					CATEGORY 1	Complied With
Eff. Date: 05-JUL-2006		MOS HRS/MSC ENC	-	17-APR-2007 5031.7 3810	-		
ASB TFE731-A73-5126 R01	NO. 2 ENGINE - ENGINE FUEL AND CONTROL - DISTRIBUTION - REPLACE FUEL PUMP TO MOTIVE FLOW PUMP TUBE ASSEMBLY, PART NO. 3061191-2 WITH PART NO. 3061314-2, ALERT SERVICE BULLETIN						
Eff. Date: 10-NOV-2005		MOS HRS/MSC ENC	-	01-JUL-2000 -	-		
ASB TFE731-A73-5133	NO. 2 ENGINE - REPLACE INLET FILTER SCREEN, PART NO. 765310, ON IDENTIFIED MOTIVE FLOW PUMPS, ALERT SERVICE BULLETIN						Complied With
Eff. Date: 16-AUG-2004		MOS HRS/MSC ENC	A/R	07-APR-2005 3269.3 2436	-		