



1

#### TURN ON

First of all charge your head torch. Then press the power button to turn on the COB LED Headlamp for 100% brightness function.

2

# TO LOWER THE LED BRIGTHNESS

Press the power button again to switch to 40% brightness function.

3

### TO TURN ON THE XPE LIGHT & TURN DOWN

Press the power button again to turn on the XPE side light 100% light function. Press the power button again to turn down XPE light to 40% brightness function.

4

## TO TURN OFF

Press the power button again to turn off the head torch.

5

## STROBE LIGHT

Press the power button and the induction button for 2 seconds at the same time to turn on the blinking function.

6

## **INDUCTION MODE:**

In this mode you can wave your hand to turn on or turn off the light. The sensor area is near the induction button.

www.gr8ful.co.uk

