SOUTH DAKOTA WATER W	ELL COMPLETION REPORT	07-92
Location SE 14 SW 14 Sec WII Twp SN Rg R4E	Well Owner: Mark Simpson	
County North	Business Name: Apple Creek Deve	elopment, LLC
Lawrence	Address: 1750 Fountain P	laza Dr.
Please mark well location with an "X"	Rapid City, SD	57702
w           E	WELL LOG:	DEPTH
"	FORMATION	FROM TO
	Spearfish	0 60
Well Completion Date	MinneKAHTA	60 104
Nov 11 05 1 Mile	OPEAKE	104 250
T Mile	MinnelusA	250 900
LOCATION: Distance from nearest potential pollution source (septic tank, abandoned well.	MAdison	900 1500
feed lot, etc.)? 500 ft. from Septic (identify source).	Englewood	1500 1505
PROPOSED USE: 4, H. D.		7555 (755)
□ Domestic/Stock □ Municipal □ Business □ Test Holes		
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well		
METHOD OF DRILLING:		
Air Rotary	STATIC WATER LEVEL 460	Fe
CASING DATA: Steel Plastic Other	If flowing: closed in pressure	P:
If other describe	GPM flowthrough	inch pip
PIPEWEIGHT DIAMETER FROM TO HOLE DIAMETER	Controlled by 🔲 Valve 🔲 Reducers 🔲 Other	
57.5 LB/FT 1338 IN O FT 63 FT 173 IN	Reduced Flowrate	
36 LB/FT 95/8 IN +2 FT 915 FT 1214 IN	Can well be completely shut in?	
23 LB/FT 7 IN 878 FT 1050 FT 8314 IN	WELL TEST DATA:	
GROUTING DATA	☐ Pumped Describe: AIR À	eveloped)
Grout Type No. of Sacks Grout Weight From To	Bailed	
	Other	•
Passing 0 14 lb/gal 878 h/050 h	Pumping Level Below Land Surface  840 ft. After 4 Hrs. pumped —	10000000000
Describe grouting procedure <u>Pressure grouted through</u>	ft After Hrs. pumped —	
<u> </u>	If pump installed, pump rate	
SCREEN:  Perforated pipe  Manufactured	REMARKS WATER PERMITT No.	
DiameterIN LengthFEET  Material	Note: See Attached N	1870 M
Slot Size Set From Feet to Feet	cementing Details	810 870
Other information	COMOSTING DETAILS	RECEIVED
one monaton	771	DEC - 1 1 3
WAS A PACKER OR SEAL USED?  YES  NO	This well was drilled under license #	
If so, what material?	And this report is true and accurate.  Drilling firm Taylor Drilling	WATER RIFE
Describe packer(s) and location?	Signature of License Representative:	
	KIK	RECEIVED
DISINFECTION: Was well disinfected upon completion?  YES, How:	Signature of Well Owner or Equitable Property Holder	DEC - 1 2005
Laboratory sent to for waterNO, Why Not? Solution	Organizate of Well Owner of Equitable Property Holder	
quality analysis		PROGRAM

Mark Simpson Apple Creek Development, LLC

9 5/8" Casing was pressure grouted with 200 sacks of Portland cement with no return of cement to surface. A cement bond log showed top of cement @ 590 ft. Casing was jet perforated with 4 shots @ 575 ft. Circulation through perforation was not good enough to pump cement grout. A 1" trimmy line was set along side 9 5/8" casing to 205 ft. 300 sacks of Portland cement was pumped to fill annular space to surface. 60 sacks of Portland cement was used to squeeze into the bond log perforations.

DEC - 1
WATER RICHARD
PROGE