

Company

Owner: Jet Linx Aviation, LLC
Operator: Jet Linx Aviation, LLC

Major Assemblies

Airframe	560 (Citation Ultra)	560-0279	02-Feb-2018	7,203.9 Hrs	7,240 Ldg	7,170.5 ACH	7,166.6 Hrs Meter
Eng 1	JT15D-5D	PCE-500046	07-Oct-2017	7,170.5 Hrs	7,207 Enc	Events	
Eng 2	JT15D-5D	PCE-500044	07-Oct-2017	7,170.5 Hrs	7,207 Enc	0 Events	

Additional Information

Cost: 12,806+
Man Hrs: 89.5+

Analyst: Jeff Dougherty jdougherty@traxxall.com

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
PN/SN	MOC Note or Component Condition								DUE	Remaining	
▼ 0 - --											
Annual Records Audit Non-Grounding Item							RE				
 0 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)						Mos	10-Nov-2017	12	+48	30-Nov-2018 9.8 Months (+1461 Days)	
						Hrs					
						Ldg					
Perform Preflight Inspection							RE				
 0 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)						Days	02-Feb-2018	10		12-Feb-2018 4 Days	
						Hrs	7,203.9				
						Ldg	7,240				
Verify Revision Status of AFM Non Grounding Item							RE				
 0 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)						Days	03-Jan-2018	30		28-Feb-2018 20 Days	
						Hrs	7,192.6				
						Ldg	7,223				
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS											
051201	Inspection Phase 1						RE			≈10-Sep-2018	
 5 A/F						Mos	21-Jul-2017	24	+2	31-Jul-2019 1.5 Years (+61 Days)	
						Hrs	7,122	300	+30	7,422 218.1 Hrs (+30)	
						Ldg	7,168				
051202	Inspection Phase 2						RE			≈10-Sep-2018	
 5 A/F						Mos	21-Jul-2017	24	+2	31-Jul-2019 1.5 Years (+61 Days)	
						Hrs	7,122	300	+30	7,422 218.1 Hrs (+30)	
						Ldg	7,168				
051203	Inspection Phase 3						RE			≈10-Sep-2018	
 5 A/F						Mos	21-Jul-2017	24	+2	31-Jul-2019 1.5 Years (+61 Days)	
						Hrs	7,122	300	+30	7,422 218.1 Hrs (+30)	
						Ldg	7,168				
051204	Inspection Phase 4						RE			≈10-Sep-2018	
 5 A/F						Mos	21-Jul-2017	24	+2	31-Jul-2019 1.5 Years (+61 Days)	
						Hrs	7,122	300	+30	7,422 218.1 Hrs (+30)	
						Ldg	7,168				
051205	Inspection Phase 5						RE				
 5 A/F						Mos	21-Oct-2016	36	+2	31-Oct-2019 1.7 Years (+61 Days)	
						Hrs	6,848.2	1,200	+100	8,048.2 844.3 Hrs (+100)	
						Ldg	6,940				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
051206	Inspection Phase 6						RE (N/A)		Continuous Inspection Program	
 5 A/F					Mos					
					Hrs					
					Ldg					
051207	Inspection Phase 7						RE (N/A)		Continuous Inspection Program	
 5 A/F					Mos					
					Hrs					
					Ldg					
051208	Inspection Phase 8						RE (N/A)		Continuous Inspection Program	
 5 A/F					Mos					
					Hrs					
					Ldg					
051211	Inspection Phase 11						RE			
 5 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0) (NOTE: Every 3 to 6 calendar months)					Mos	11-Oct-2017	6	+1	30-Apr-2018	81 Days (+30)
					Hrs	7,170.5				
					Ldg	7,207				
051213	Inspection Phase 13						RE		Continuous Inspection Program	≈12-May-2025
 5 A/F (ZONE: 810)					Mos	17-Sep-2007				
					Hrs	4,823.4	5,000	+10	9,823.4	2,619.5 Hrs (+10)
					Ldg	5,396				
051214	Inspection Phase 14						T		Continuous Inspection Program	≈29-May-2031
 5 A/F					Mos	15-Nov-1994				
					Hrs	0	12,000	+10	12,000	4,796.1 Hrs (+10)
					Ldg	0				
051215	Inspection Phase 15						RE		Continuous Inspection Program	≈29-Jul-2025
 5 A/F					Mos	17-Sep-2007				
					Hrs	4,823.4	4,000	+10	[9,900.4]	2,696.5 Hrs (+10)
					Ldg	5,396				
051216	Inspection Phase 16						RA		Continuous Inspection Program	≈09-Nov-2025
 5 A/F (NOTE: Initial inspection is due at 10,000 hrs total time, then at 15,000 hrs total time, then repeats every 3,000 hrs thereafter. Adjust the first two frequencies as required to come due at the proper times.)					Mos	17-Sep-2007				
					Hrs	4,823.4	5,000	+10	[10,000.4]	2,796.5 Hrs (+10)
					Ldg	5,396				
051217	Inspection Phase 17						RE		Continuous Inspection Program	≈08-Nov-2025
 5 A/F					Mos	15-Nov-1994				
					Hrs	0	10,000	+10	10,000	2,796.1 Hrs (+10)
					Ldg	0				
051218	Inspection Phase 18						RE			
 5 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)					Mos	11-Oct-2017	12	+1	31-Oct-2018	8.8 Months (+30 Days)
					Hrs	7,170.5				
					Ldg	7,207				
051220	Inspection Phase 20						RE			
 5 A/F (NOTE: As required by 14 CFR 91.411, 91.413 and RVSM certification)					Mos	06-Oct-2016	24	+1	31-Oct-2018	8.8 Months (+30 Days)
					Hrs	6,848.2				
					Ldg	6,940				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
051221 5 A/F	Inspection Phase 21								RE	
					Mos	20-Oct-2016	24	+1	31-Oct-2018	8.8 Months (+30 Days)
					Hrs	6,848.2				
					Ldg	6,940				
051228 5 A/F	Inspection Phase 28								RE (N/A)	Continuous Inspection Program
					Mos					
					Hrs					
					Ldg					
051230 5 A/F	Inspection Phase 30								RE	Continuous Inspection Program ≈10-Jul-2019
					Mos	21-Jul-2017				
					Hrs	7,122	600	+10	7,722	518.1 Hrs (+10)
					Ldg	7,168				
051232 5 A/F	Inspection Phase 32								T	Continuous Inspection Program ≈02-Jun-2050
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0	15,000		15,000	7,760 Ldg
051233 5 A/F	Inspection Phase 33								T	Continuous Inspection Program ≈02-Jun-2050
					Mos					
					Hrs					
					Ldg		15,000		15,000	7,760 Ldg
051234 5 A/F	Inspection Phase 34								RE	Continuous Inspection Program ≈04-Jun-2035
					Mos	27-Apr-2016				
					Hrs	6,720.9	6,725	+10	13,445.9	6,242 Hrs (+10)
					Ldg	6,832				
051235 5 A/F	Inspection Phase 35								RE (N/A)	Continuous Inspection Program
					Mos					
					Hrs					
					Ldg					
051248 5 A/F	Inspection Phase 48								RE	
					Mos	31-Oct-2015	72	+1	31-Oct-2021	3.7 Years (+30 Days)
					Hrs	6,646.3				
					Ldg	6,778				
051249 5 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)	Inspection Phase 49								RE	
					Mos	11-Oct-2017	36	+2	31-Oct-2020	2.7 Years (+61 Days)
					Hrs	7,170.5	1,200	+100	8,370.5	1,166.6 Hrs (+100)
					Ldg	7,207				
051253 5 A/F	Inspection Phase 53								RE (N/A)	Continuous Inspection Program
					Mos					
					Hrs					
					Ldg					
051255 5 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0) (Tol. Adjustment: -2d)	Inspection Phase 55								RE	Continuous Inspection Program
					Mos	15-Dec-2017	3	+1	31-Mar-2018	51 Days (+30)
					Hrs	7,170.7	200	+10	7,370.7	166.8 Hrs (+10)
					Ldg	7,208				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
051256	Inspection Phase 56								RE	
5 A/F (NOTE: As required by Title 14 of the Code of Federal Regulations 91.207. (This interval limitation CANNOT be exceeded.))					Mos	21-Jul-2017	12	+1	21-Jul-2018	5.4 Months (+31 Days)
					Hrs	7,122				
					Ldg	7,168				
051259	Inspection Phase 59								RE (A/R)	Continuous Inspection Program
5 A/F					Mos	06-Mar-2012				
					Hrs	5,666.4				
					Ldg	6,046				
051261	Inspection Phase 61								T	Continuous Inspection Program ≈28-Sep-2034
5 A/F					Mos	15-Nov-1994				
					Hrs	0	13,200	+10	13,200	5,996.1 Hrs (+10)
					Ldg	0				
051262	Inspection Phase 62								T	Continuous Inspection Program ≈29-May-2041
5 A/F					Mos	15-Nov-1994				
					Hrs	0	15,600	+10	15,600	8,396.1 Hrs (+10)
					Ldg	0				
051263	Inspection Phase 63								T	Continuous Inspection Program ≈29-May-2041
5 A/F					Mos	15-Nov-1994				
					Hrs	0	15,600	+10	15,600	8,396.1 Hrs (+10)
					Ldg	0				
051264	Inspection Phase 64								RE	
5 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0) (NOTE: For airplanes that operate in moderate, or severe corrosion environments. Refer to Chapter 51, Corrosion Severity Maps - Description and Operation)					Mos	11-Oct-2017	6	+1	11-Apr-2018	62 Days (+30)
					Hrs	7,170.5				
					Ldg	7,207				
051265	Inspection Phase 65								RE	Continuous Inspection Program ≈19-May-2019
5 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)					Mos	11-Oct-2017				
					Hrs	7,170.5	500		7,670.5	466.6 Hrs
					Ldg	7,207				
051266	Inspection Phase 66								RE	≈06-Oct-2033
5 A/F					Mos	21-Oct-2016				
					Hrs	6,848.2	6,000	+10	12,848.2	5,644.3 Hrs (+10)
					Ldg	6,940				
051267	Inspection Phase 67								T	Continuous Inspection Program ≈08-Nov-2025
5 A/F					Mos	15-Nov-1994				
					Hrs	0	10,000	+10	10,000	2,796.1 Hrs (+10)
					Ldg	0				
0512B	Inspection Phase B								RE	Continuous Inspection Program ≈10-Apr-2018
5 A/F					Mos	21-Jul-2017				
					Hrs	7,122	150	+30	7,272	68.1 Hrs (+30)
					Ldg	7,168				
0512MA	Inspection Phase MA								RE (N/A)	Continuous Inspection Program
5 A/F					Mos					
					Hrs					
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
0512MC	Inspection Phase MC								RE Continuous Inspection Program	≈15-Oct-2020
5 A/F	(NOTE: This inspection is a Chapter 4 requirement; therefore, the interval limitation CANNOT be exceeded)					Mos 27-Apr-2016				
						Hrs 6,720.9	1,456		8,176.9	973 Hrs
						Ldg 6,832				
0512MD	Inspection Phase MD								RE Continuous Inspection Program	≈30-Dec-2021
5 A/F	(NOTE: This inspection is a Chapter 4 requirement; therefore, the interval limitation CANNOT be exceeded)					Mos 21-Feb-2014				
						Hrs 6,087.7	2,523		8,610.7	1,406.8 Hrs
						Ldg 6,333				
0512ME	Inspection Phase ME								RE Continuous Inspection Program	≈06-May-2020
5 A/F	(NOTE: This inspection is a Chapter 4 requirement; therefore, the interval limitation CANNOT be exceeded)					Mos 27-Nov-2002				
						Hrs 3,568	4,450		8,018	814.1 Hrs
						Ldg				
0512MF	Inspection Phase MF								RE Continuous Inspection Program	≈16-Nov-2021
5 A/F	(NOTE: This inspection is a Chapter 4 requirement; therefore, the interval limitation CANNOT be exceeded)					Mos 27-Nov-2002				
						Hrs 3,568	5,000		8,568	1,364.1 Hrs
						Ldg				
0512MG	Inspection Phase MG								T Continuous Inspection Program	≈02-Aug-2029
5 A/F	(NOTE: This inspection is a Chapter 4 requirement; therefore, the interval limitation CANNOT be exceeded)					Mos 15-Nov-1994				
						Hrs 0				
						Ldg 0	10,000		10,000	2,760 Ldg
0512MI	Inspection Phase MI								RE Continuous Inspection Program	≈30-Jul-2026
5 A/F	(NOTE: This inspection is a Chapter 4 requirement; therefore, the interval limitation CANNOT be exceeded)					Mos 17-Feb-2009				
						Hrs 5,131.4	5,130		10,261.4	3,057.5 Hrs
						Ldg 5,645				
0512MJ	Inspection Phase MJ								RE Continuous Inspection Program	≈06-Nov-2030
5 A/F	(NOTE: This inspection is a Chapter 4 requirement; therefore, the interval limitation CANNOT be exceeded)					Mos 26-Feb-2013				
						Hrs 5,897.7	5,900		11,797.7	4,593.8 Hrs
						Ldg 6,189				
0512MK	Inspection Phase MK								RE Continuous Inspection Program	≈04-Jun-2035
5 A/F	(NOTE: This inspection is a Chapter 4 requirement; therefore, the interval limitation CANNOT be exceeded)					Mos 27-Apr-2016				
						Hrs 6,720.9	6,725		13,445.9	6,242 Hrs
						Ldg 6,832				
0512MM	Inspection Phase MM								RE (N/A) Continuous Inspection Program	
5 A/F						Mos				
						Hrs				
						Ldg				
5-50-00-01	Hard/Overweight landings								RE (A/R) Unscheduled Maintenance Check	
5 A/F						Mos 15-Nov-1994				
						Hrs 0				
						Ldg 0				
5-50-00-02	Overspeed - Exceeding placard speeds of flaps or landing gear, or exceeding airplane design speed								RE (A/R) Unscheduled Maintenance Check	
5 A/F						Mos 15-Nov-1994				
						Hrs 0				
						Ldg 0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
5-50-00-03  5 A/F	Severe air turbulence or severe maneuvers					Mos 15-Nov-1994 Hrs 0 Ldg 0	RE (A/R)		Unscheduled Maintenance Check	
5-50-00-04  5 A/F	Lightning strike					Mos 15-Nov-1994 Hrs 0 Ldg 0	RE (A/R)		Unscheduled Maintenance Check	
5-50-00-05  5 A/F	Foreign object damage					Mos 15-Nov-1994 Hrs 0 Ldg 0	RE (A/R)		Unscheduled Maintenance Check	
5-50-00-06  5 A/F	Towing with a Large Fuel Unbalance or High Drag/Side Loads due to Ground Handling					Mos 15-Nov-1994 Hrs 0 Ldg 0	RE (A/R)		Unscheduled Maintenance Check	
5-50-00-07  5 A/F	Jammed Nose Wheel					Mos 15-Nov-1994 Hrs 0 Ldg 0	RE (A/R)		Unscheduled Maintenance Check	
5-50-00-08  5 A/F (NOTE: NOTE: Airplanes having AL5112 power units installed in all locations, are not required to perform this inspection. Airplanes -0206 and On have AL5112 power units. This inspection must be performed within five flights or ten flight hours, whichever occurs first of the failure of any component of the cabin fluorescent lighting system. Refer to AD-95-22-01 and Aerospace Lighting Corporation Information Bulletin IB-96-001.)	Fluorescent Lighting Component Failure Inspection					Mos 15-Nov-1994 Hrs 0 Ldg 0	RE (A/R)		Unscheduled Maintenance Check	
5-50-00-09  5 A/F	Exposure to High Winds While the Aircraft is Parked Check					Mos Hrs Ldg	RE (A/R)		Unscheduled Maintenance Check	
A510002  5 A/F Ref.:51-10-00-210	Airplane Wash 051206					Mos Hrs Ldg	RE (A/R)		Continuous Inspection Program	
FAA 14 CFR Part 47  5 A/F Expiration Date 31-Mar-2021 (AVG MAN HRS: 0) (APX COST [USD]: 0)	FAA - Aircraft Registration (Renew)					Mos 26-Jan-2018 Hrs 7,203.3 Ldg 7,239	RE 36		FAA, FAA +6 31-Mar-2021	3.1 Years (+183 Days)
FAA RVSM  5 A/F	FAA - RVSM Height Monitoring					Mos 27-Oct-2016 Hrs 6,988.2 Ldg 7,052	RE 24		FAR91 31-Oct-2018	8.8 Months

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 8 - LEVELING AND WEIGHING.										
08-10-01-001	Aircraft Weighing and Balancing						RE		AMM	
 8 A/F Inspected Date 29-Dec-2015						Mos	29-Dec-2015	36	31-Dec-2018	10.9 Months
						Hrs	6,610.9			
						Ldg	6,759			
▼ 11 - PLACARDS AND MARKINGS										
560-11-08	Avionics J-Box and Left Logic Module Box Placard Installation						RE (-)		Mandatory	
 11 A/F Eff: 07-Nov-2003 Complied With						Mos	17-Feb-2004			
						Hrs	3,901			
						Ldg	4,565			
A113001	Interior Placards, Exterior Placards, Decals, Markings and Identification Plate - Inspect for security of installation and legibility - Examine						RE		Continuous Inspection Program	
 11 A/F 051205 Ref:11-00-00-210 (ZONE: 211, 231, 232, 233, 234, 237, 241, 242, 243, 244) (NOTE: More zone: 245, 246, 249, 251, 252, 261, 262, 271, 272, 311, 321, 531, 631,710, 720)						Mos	21-Oct-2016	36	+2 (31-Oct-2019)	1.7 Years (+61 Days)
						Hrs	6,848.2	1,200	+100 (8,048.2)	844.3 Hrs (+100)
						Ldg	6,940			
▼ 12 - SERVICING - ROUTINE MAINTENANCE										
C122100	Nose Gear Torque Links and Uplock Rollers - Lubrication						RE		Continuous Inspection Program	≈10-Sep-2018
 12 A/F 051202 Ref.:12-21-02-640 (ZONE: 710)						Mos		24	(31-Jul-2019)	1.5 Years (+61 Days)
						Hrs	300		(7,422)	218.1 Hrs (+30)
						Ldg				
C122101	Main Landing Gear - Lubrication						RE		Continuous Inspection Program	≈10-Sep-2018
 12 A/F 051202 Ref.:12-21-02-641 (ZONE: 720, 730)						Mos		24	+2 (31-Jul-2019)	1.5 Years (+61 Days)
						Hrs	300	+30 (7,422)	218.1 Hrs (+30)	
						Ldg				
▼ 21 - AIR CONDITIONING AND PRESSURIZATION										
	AC Compressor						RE (O/C)			
 21 A/F 1250160 2138						Mos	11-May-2012			
						Hrs	5,684.9			
						Ldg	6,055			
	AC Condenser						RE (O/C)			
 21 A/F 1250180-7 937						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
	AC Receiver Drier						RE (O/C)			
 21 A/F Unknown Unknown						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
	ACM Bypass Valve						RE (O/C)			
 21 A/F 754751-2 940613						Mos	28-Nov-2003			
						Hrs	3,873			
						Ldg	0			
	ACM Control Unit						RE (O/C)			
 21 A/F C35020A 1508						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
21 A/F 1173T0635 NSN	ACM Overheat Switch	0			Mos	18-May-1999			RE (O/C)	
		0			Hrs	2,217				
		0			Ldg	0				
21 A/F 782343-2 940811	ACM Refrigerator Package Assembly	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
21 A/F 738384-26 900534	Air Conditioning - Environment Control Unit (Hamilton Standard ACM)	0			Mos	28-Apr-2008			RE (O/C)	
		0			Hrs	4,930.1				
		0			Ldg	5,482				
21 A/F 1250151 411	Air Conditioning Compressor Motor	0			Mos	27-Nov-2002			RE (O/C)	
		0			Hrs	3,568				
		0			Ldg	0				
21 A/F Unknown Unknown	Air Conditioning Hour Meter (ACH)				Mos	15-Nov-1994			RE (O/C)	
					Hrs	0				
					Ldg	0				
21 A/F Unknown Unknown	Air Conditioning Motor Brushes				Mos	15-Nov-1994			RE (O/C)	
					Hrs	0				
					Ldg	0				
21 A/F 032105 NSN	Avionics Bay Cooling Box Fan	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
21 A/F 19A827 NSN	Avionics Bay Vane Axial Blower	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
21 A/F GBC300-82 Unknown	Barometric Switch	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
21 A/F 130620-2 12A0011	Cabin Altitude Controller	0			Mos	08-Jan-2003			RE (O/C)	
		0			Hrs	3,597				
		0			Ldg	0				
21 A/F GB300NA161 0705730	Cabin Altitude Pressure Switch	0			Mos	17-Sep-2007			RE (O/C)	
		0			Hrs	4,823				
		0			Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
21 A/F C668511-0103 19911	Cabin Pressure Indicator								RE (O/C)	
		0				Mos	15-Nov-1994			
		0				Hrs	0			
21 A/F 754661-5 91019057	Cabin Temperature Controller	0				Mos	10-Aug-1996			
		0				Hrs	866			
		0				Ldg	0			
21 A/F 1942T100-11 1459	Cabin Temperature Sensor	0				Mos	09-Dec-2014			
		0				Hrs	6,264			
		0				Ldg	6,478			
21 A/F 3A1003-10 NSN	Centrifugal Blower	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
21 A/F BC64A-2 Unknown	Cockpit Defog Fan Assembly	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
21 A/F 5703-4 1178	Cockpit Defogger Fan	0				Mos	29-Sep-2014			
		0				Hrs	6,214.5			
		0				Ldg	6,429			
21 A/F BYLB50907 653	Compression Actuator	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
21 A/F 5A3032 NSN	Door Actuator Motor Assembly	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
21 A/F 1173T42-1 2439	Duct Overheat Sensor	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
21 A/F 754691-1 NSN	Duct Temperature Sensor	0				Mos	01-Aug-2000			
		0				Hrs	2,780			
		0				Ldg	0			
21 A/F 27441482-06 12AH39	Emergency Pressure Valve	0				Mos	19-May-1999			
		0				Hrs	2,220			
		0				Ldg	0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
21 A/F Unknown Unknown	Emergency Pressurization Valve								RE (O/C)	
						Mos	15-Nov-1994			
						Hrs	0			
21 A/F 1250240-3 684	Evaporator Aft									
		0				Mos	15-Nov-1994			
		0				Hrs	0			
21 A/F 1250240-1 674	Evaporator Fwd									
		0				Mos	15-Nov-1994			
		0				Hrs	0			
21 A/F 1988-00-1 1951	Flow Control Pressure Regulator Valve No.1									
		0				Mos	09-Dec-2014			
		0				Hrs	6,264			
21 A/F 1988-00-1 0040	Flow Control Pressure Regulator Valve No.2									
		0				Mos	01-Mar-2002			
		0				Hrs	0			
21 A/F NYLC50466 1194	Flow Divider Cabin Underfloor Actuator									
		0				Mos	15-Nov-1994			
		0				Hrs	0			
21 A/F Unknown Unknown	Freon A/C-Hobbs Meter									
						Mos	15-Nov-1994			
						Hrs	0			
21 A/F 4124X NSN	Instrument Panel Fan									
		0				Mos	15-Nov-1994			
		0				Hrs	0			
21 A/F BC61A901-2 2649A	Overhead Cabin Fan									
		0				Mos	21-Jul-2017			
		0				Hrs	7,122			
21 A/F 130358-1 123209	Pneumatic Relay									
		0				Mos	15-Nov-1994			
		0				Hrs	0			
21 A/F 1250232-4 9570	Pressure Switch									
		0				Mos	11-May-2012			
		0				Hrs	5,684.9			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 21 A/F 103648-14 119-284	Primary Outflow Valve								RE (O/C)	
		0			Mos	28-Jan-2011				
		0			Hrs	5,658.7				
		0			Ldg	6,039				
 21 A/F C668513-0101 346388	Rate Of Change Indicator								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 21 A/F 1103P240-1 734	S243 Primary Pressure Switch								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 21 A/F 1103P240-2 729	S244 Secondary Pressure Switch								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 21 A/F 103648-14 63-L0015	Secondary Outflow Valve								RE (O/C)	
		0			Mos	12-Nov-2014				
		0			Hrs	6,246.6				
		0			Ldg	6,462				
 21 A/F 27221274 5AK77	Temp Duct Sensor								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 21 A/F Unknown Unknown	Thermal Actuator Assembly								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 21 A/F 738386-3 940710	Water Separator								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 21 A/F Eff: 05-Jul-2013 Not Applicable	2013-09-11 Par. (g),(h) Air Conditioning - Inspection for P/N, Compressor Hour Meter and Maintenance Records								RE (-)	Mandatory
					Days	06-Jun-2013				
		N/A BY P/N			Hrs	5,950				
					Ldg	6,226				
 21 A/F Eff: 29-Sep-2015 Not Applicable	2015-17-12 Para. (g) & (h) Air Conditioning Motor P/N and Hour Meter Review								RE (-)	Mandatory
					Days	09-Sep-2015				
		EQUIPMENT NOT INSTALLED			Hrs	6,579.2				
					Ldg	6,728				
 21 A/F Eff: 29-Sep-2015 Not Applicable	2015-17-12 Para. (i) Air Conditioning Motor Brushes Replacement								RE (-)	Mandatory
					Mos	09-Sep-2015				
		EQUIPMENT NOT INSTALLED			Hrs	6,579.2				
					Ldg	6,728				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
5-11-00(2)(A)(1)  21 A/F 738384-26 900534	Air Conditioning - Environment Control Unit (Hamilton Standard ACM) - Overhaul					Mos 28-Apr-2008 Hrs 4,930.1 Ldg 5,482	RE 5,000	AWL, Component Time Limits		≈29-Aug-2025 2,726.2 Hrs
5-11-00(2)(A)(2)  21 A/F BC61A901-2 2649A	Air Conditioning - Overhead Cabin Fan - Replace/Overhaul					Mos 21-Jul-2017 Hrs 7,122 Ldg 7,168	RE 1,200	Component Time Limits		≈10-Mar-2021 1,118.1 Hrs
5-11-00(2)(A)(3)  21 A/F 5703-4 1178	Air Conditioning - Defog Fan - Replace/Overhaul					Mos 29-Sep-2014 Hrs 6,214.5 Ldg 6,429	RE 3,500	Component Time Limits		≈23-Jan-2025 2,510.6 Hrs
5-11-00(2)(A)(4)  21 A/F 1250151 411	Air Conditioning - Compressor Drive Motor Brushes (Compressor Motors 1134104-1, -5 or FWA1134104-1, -5 only) - Replace					Mos Hrs Ldg	RE (N/A)	Component Time Limits		
560-21-10  21 A/F Eff: 17-Feb-1995 Complied With	Additional Outflow Valve Replacements					Mos 10-Dec-2001 Hrs 3,235 Ldg 0	RE (-)	Mandatory		
560-21-10 R01  21 A/F Eff: 24-May-1996 Complied With	Additional Outflow Valve Replacements					Mos 26-May-1995 Hrs 297.8 Ldg 425	RE (-)	Mandatory		
560-21-14  21 A/F Eff: 16-Mar-2000 Not Applicable	Air Conditioning - Flood Cooling Diode Repalcement EQUIPMENT NOT INSTALLED					Mos 27-Feb-2001 Hrs 30,314 Ldg 0	RE (-)	Recommended		
95-25-10  21 A/F Eff: 22-Jan-1996 Not Applicable	Outflow/Safety Valve N/A BY S/N					Mos 19-Jan-1996 Hrs 594.1 Ldg 387	RE (-)	Mandatory		
A215001  21 A/F 051202,... Ref.:21-51-00-610 (ZONE: 312)	Air Cycle Machine (Hamilton Standard) - Check oil level					Mos 21-Jul-2017 Hrs 7,122 Ldg 7,168	RE 24 300	Continuous Inspection Program +2 +30	≈10-Sep-2018 #21-Jul-2019 #7,422	
A215200  21 A/F Ref.:21-52-00-212 (ZONE: 311, 312)	Vapor Cycle Cooling System Hour Meter Check (Compressor Motors 1134104-1, -5 or FWA1134104-1, -5 only) - Perform (Chapter 4 Item)					Mos Hrs Ldg	RE (N/A)	Continuous Inspection Program		
A215201  21 A/F 1250160 2138 Ref.:21-52-00-213 (ZONE: 311, 312) (AVG MAN HRS: 0) (APX COST [USD]: 0)	Vapor Cycle Cooling System 500 Compressor Hour Maintenance 051265					Mos 11-Oct-2017 Hrs 7,170.5 Ldg 7,207 ACH 7,170.5	RE 500	Continuous Inspection Program +10	≈19-May-2019 (7,670.5)	466.6 Hrs

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A215202	Vapor Cycle Cooling System 12 Month Maintenance								RE Continuous Inspection Program	
 21 A/F	051218 Ref.:21-52-00-214 (ZONE: 311, 312) (AVG MAN HRS: 0) (APX COST [USD]: 0)				Mos	11-Oct-2017	12	+1 (31-Oct-2018)	8.8 Months (+30 Days)	
					Hrs	7,170.5				
					Ldg	7,207				
A217001	Humidity Regulator (Water Separator) - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 21 A/F	051202 Ref.:21-70-00-160 (ZONE: 312)				Mos		24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
					Hrs		300	+30 (7,422)	218.1 Hrs (+30)	
					Ldg					
B210000	Environmental System - Perform operational check								RE Continuous Inspection Program	
 21 A/F	051205 Ref.:21-00-00-710 (ZONE: ENG)				Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs	1,200		+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					
B211001	Emergency Pressurization Valve - Perform operational test								RE Continuous Inspection Program	≈10-Sep-2018
 21 A/F	051204 Ref.:21-11-00-710 (ZONE: ENG)				Mos		24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
					Hrs		300	+30 (7,422)	218.1 Hrs (+30)	
					Ldg					
B211002	Flow Control Shutoff and Check Valve (Dukes Valves and Parker Hannifin/Janitrol Check Valves that have a serial number suffix B or that have a serial number higher than 4AD39) - Perform operational test								RE Continuous Inspection Program	
 21 A/F	051205 Ref.:21-11-00-711 (ZONE: ENG)				Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs	1,200		+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					
B211003	Flow Control Shutoff and Check Valve (Parker Hannifin/ Janitrol Check Valves that have a serial number lower than 4AD39 and that do not have a serial number suffix B) - Perform operational test								RE (N/A) Continuous Inspection Program	
 21 A/F	Ref.:21-11-00-711 (ZONE: ENG)				Mos					
					Hrs					
					Ldg					
B211004	Emergency Pressurization Valve (Airplanes -0539 and On) - Perform operational test								RE Continuous Inspection Program	≈10-Sep-2018
 21 A/F	051204 Ref.:21-11-00-713 (ZONE: ENG)				Mos		24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
					Hrs		300	+30 (7,422)	218.1 Hrs (+30)	
					Ldg					
B212001	Tailcone Bleed Air Lines - Perform leak check								RE Continuous Inspection Program	
 21 A/F	051205 Ref.:36-11-00-210 (ZONE: 311, 312,ENG)				Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs	1,200		+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					
B212002	Vertical Scale Instrument Panel Cooling Fan - Perform operational check								RE Continuous Inspection Program	
 21 A/F	051205 Ref.:21-24-00-710 (ZONE: 231, 232,AUX)				Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs	1,200		+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					
B212003	Avionics Bay Cooling Fans - Perform operational check								RE Continuous Inspection Program	
 21 A/F	051205 Ref.:21-25-00-710 (ZONE: AUX)				Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs	1,200		+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					
B213000	Pressurization - Perform operational check								RE Continuous Inspection Program	
 21 A/F	051205 Ref.:21-31-00-710 (ZONE: ENG)				Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs	1,200		+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B213001	Barometric Cabin Altitude Pressure Switch - Perform functional test						RE		Continuous Inspection Program	
21 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:21-31-05-720 (ZONE: 245, LAB)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B213005	Pressurization System - Perform operational check						RE		Continuous Inspection Program	
21 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:21-32-00-710					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B213006	Primary Outflow Valve Cabin Altitude Limiter Valve - Perform functional test						RE		Continuous Inspection Program	
21 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:21-32-00-730 (ZONE: 171, 172)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B213006	Secondary Outflow Valve Cabin Altitude Limiter Valve - Perform functional test						RE		Continuous Inspection Program	
21 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:21-32-00-730 (ZONE: 171, 172)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
C215001	Air Cycle Machine (Hamilton Standard) - Change oil						RE		Continuous Inspection Program	≈10-Jul-2019
21 A/F	051230				Mos					
Ref.:21-51-00-680 (ZONE: 312)					Hrs		600	+10	(7,722)	518.1 Hrs (+10)
					Ldg					
D213001	Pressurization Controller - Clean or replace filter						RE		Continuous Inspection Program	
21 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:21-31-00-160 (ZONE: 244)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
D213003	Pneumatic Relay Cartridge Filter - Replace						RE		Continuous Inspection Program	
21 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:21-31-00-901 (ZONE: 171, 172)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
D213004	Disable Solenoid Valve Filter - Clean or replace						RE		Continuous Inspection Program	
21 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:21-31-00-161					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
SL560-21-09	Air Conditioning - Transmittal Of Fort Worth Airworks Service Bulletin 99-101						RE (-)		Recommended	
21 A/F					Mos	31-Oct-2005				
Eff: 03-Apr-2000 Complied With					Hrs	4,405				
					Ldg	0				
SL560-21-10	Air Conditioning - Outflow Valve Static Pressure Line Inspection Replacement						RE (-)		Recommended	
21 A/F					Mos	26-May-1995				
Eff: 12-Dec-2000 Complied With					Hrs	297.8				
					Ldg	425				
SL560-21-11 R01	Air Conditioning - Ram Air Inlet Drain Line Inspection						RE (-)		Recommended	
21 A/F					Mos	05-Sep-2002				
Eff: 01-Mar-2002 Complied With					Hrs	3,494				
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
PN/SN	MOC Note or Component Condition								DUE	Remaining	
▼ 22 - AUTOFLIGHT											
	Aileron Servo 22 A/F 4006719-906 94077221						RE (O/C)				
		0					Mos	15-Nov-1994			
		0					Hrs	0			
		0					Ldg	0			
	Autopilot Control 22 A/F 7003897-923 94090739						RE (O/C)				
		0					Mos	15-Nov-1994			
		0					Hrs	0			
		0					Ldg	0			
	Elevator Servo 22 A/F 4006719-904 95047652						RE (O/C)				
		0					Mos	14-Apr-2015			
		0					Hrs	6,416.2			
		0					Ldg	6,582			
	Rudder Servo 22 A/F 4006719-906 94057186						RE (O/C)				
		0					Mos	15-Nov-1994			
		0					Hrs	0			
		0					Ldg	0			
	2002-22-13 22 A/F Eff: 20-Dec-2002 Not Applicable	Rockwell Collins, Inc. - Flight management computers (FMC)					RE (-)		Mandatory (Appliance AD)		
		EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
							Hrs	6,186			
							Ldg	6,407			
	2008-02-06 22 A/F Eff: 26-Feb-2008 Not Applicable (AVG MAN HRS: 7)	Garmin International - GSM 85 Servo Gearbox Units					RE (-)		Mandatory (Appliance AD)		
		EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
							Hrs	6,186			
							Ldg	6,407			
	98-08-20 22 A/F Eff: 02-Jun-1998 Not Applicable Brand A:9990-1998-08-20	AlliedSignal Aerospace Bendix/King Model KSA 470 Autopilot Servo Actuators, part numbers 065-0076-10 through 065-0076-15.					RE (-)		Mandatory (Appliance AD)		
		EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
							Hrs	6,186			
							Ldg	6,407			
	99-01-14 22 A/F Eff: 12-Feb-1999 Not Applicable	To Prevent A "Random Reset" Condition Of The Electronic Flight Instrument System					RE (-)		Mandatory (Appliance AD)		
		EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
							Hrs	6,186			
							Ldg	6,407			
	A221001 22 A/F Ref.:22-11-01-210	Aileron Servo Actuator and Mount - Inspect					RE		Continuous Inspection Program		
		051205					Mos	36			
							Hrs	1,200			
							Ldg	+2			
	A222001 22 A/F Ref.:22-11-01-212	Rudder Servo Actuator and Mount - Inspect					RE		Continuous Inspection Program		
		051205					Mos	36			
							Hrs	1,200			
							Ldg	+2			
	A223001 22 A/F Ref.:22-11-01-211	Elevator Servo Actuator and Mount - Inspect					RE		Continuous Inspection Program		
		051205					Mos	36			
							Hrs	1,200			
							Ldg	+2			
					36			+2		(31-Oct-2019)	1.7 Years (+61 Days)
					1,200			+100		(8,048.2)	844.3 Hrs (+100)
					1,200			+100		(8,048.2)	844.3 Hrs (+100)
					1,200			+100		(8,048.2)	844.3 Hrs (+100)

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B221002	Autopilot Disengagement and Warning Test - Perform test						RE		Continuous Inspection Program	
22 A/F	051205					Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:22-11-03-710						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
						Ldg				
B221003	Autopilot Disengagement and Warning Test - Perform test						RE		Continuous Inspection Program	
22 A/F	051205					Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:22-11-03-711						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
						Ldg				
SL560-22-01 R01	Autopilot Disconnect Switch Splice Inspection/Replacement						RE (-)		Recommended	
22 A/F						Mos	11-Sep-1997			
Eff: 21-Feb-1997 Complied With						Hrs	1,483			
						Ldg	0			
▼ 23 - COMMUNICATIONS										
	AFIS Antenna						RE (O/C)			
23 A/F		0				Mos	17-Nov-1994			
VFS10-90-5		0				Hrs	9			
3220		0				Ldg	0			
	Allied Flitefone VI w/Voice Privacy Factory Option						RE (O/C)			
23 A/F						Mos	15-Nov-1994			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Audio Amplifier						RE (O/C)			
23 A/F	No.1	0				Mos	20-Jul-2016			
5636-1		0				Hrs	6,783.4			
1205		0				Ldg	6,881			
	Audio Amplifier						RE (O/C)			
23 A/F	No.2	0				Mos	27-Nov-2002			
5636-1		0				Hrs	3,568			
143		0				Ldg	0			
	Cabin Handset Phone						RE (O/C)			
23 A/F		0				Mos	07-Feb-2008			
400-0123-210		0				Hrs	4,872			
9466		0				Ldg	0			
	Cockpit Handset Phone						RE (O/C)			
23 A/F		0				Mos	24-Jan-2008			
400-0123-210		0				Hrs	4,866			
3036		0				Ldg	0			
	Cockpit Voice Recorder						RE (O/C)			
23 A/F						Mos	15-Nov-1994			
Unknown						Hrs	0			
Unknown						Ldg	0			
	Cockpit Voice Recorder Battery Pack (Sundstrand, Fairchild GA100 , Fairchild A200S, L-3FA2100)						RE		Component Time Limits	
23 A/F		0				Yrs	24-Sep-2012	6	[30-Nov-2018]	9.8 Months
GA100-0000		0				Hrs	5,794.9			
02247		0				Ldg	6,121			
Manufactured Date 24-Sep-2012										

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 23 A/F 7510784-835 Unknown	Comm Cluster Module						RE (O/C)			
	No.1	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 23 A/F 7510784-835 Unknown	Comm Cluster Module						RE (O/C)			
	No.2	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 23 A/F S251-1120-00 Unknown	CVR Controller						RE (O/C)			
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 23 A/F 93-A055-95 00597	CVR Microphone						RE (O/C)			
		0			Mos	20-Oct-2016				
		0			Hrs	6,848.2				
		0			Ldg	6,940				
 23 A/F DK100 SC55867	CVR Underwater Locator Beacon Replacement						RE (Due)		[28-Feb-2022]	4.1 Years
		0			Mos	20-Oct-2016				
		0			Hrs	6,848.2				
		0			Ldg	6,940				
 23 A/F Unknown Unknown	Flight Data Recorder Underwater Locator Beacon						RE (O/C)			
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 23 A/F Unknown Unknown	HF KHF-950 Factory Option						RE (O/C)			
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 23 A/F Unknown Unknown	High Frequency Antenna						RE (O/C)			
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 23 A/F 071-01268-0001 2532	KA594 High Frequency Adapter						RE (O/C)			
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 23 A/F 064-01017-0001 13004	KAC952 HF Power Amp Coupler						RE (O/C)			
	No.1	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 23 A/F 071-01274-0002 3151	KCU951/KFS594 High Frequency Controller						RE (O/C)			
	No.1	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
23 A/F Unknown Unknown	KCU951/KFS594 High Frequency Controller No.2					Mos	15-Nov-1994		RE (O/C)	
						Hrs	0			
						Ldg	0			
23 A/F 064-01015-0000 6680	KTR953 HF Receiver/Exciter	0				Mos	10-Dec-2001		RE (O/C)	
		0				Hrs	3,235			
		0				Ldg	0			
23 A/F 622-6520-005 3927	No. 1 Comm Control	0				Mos	03-Sep-2008		RE (O/C)	
		0				Hrs	5,004			
		0				Ldg	0			
23 A/F 622-6520-005 1916	No. 2 Comm Control	0				Mos	27-Nov-2002		RE (O/C)	
		0				Hrs	3,568			
		0				Ldg	0			
23 A/F 50-95-01 2726	Phone Antenna	0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			
23 A/F 400-0125-2000 4370	Transceiver Phone	0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			
23 A/F VFS10-90-7 107	VHF Comm Antenna No.1	0				Mos	19-Jan-1996		RE (O/C)	
		0				Hrs	594			
		0				Ldg	0			
23 A/F VF-10-108-2 1073	VHF Comm Antenna No.2	0				Mos	31-Oct-2005		RE (O/C)	
		0				Hrs	4,405			
		0				Ldg	0			
23 A/F 622-6152-011 33005 Brand C:232001	VHF Communication Transceiver No.1	0				Mos	20-Oct-2014		RE (O/C)	
		0				Hrs	6,236.8			
		0				Ldg	6,452			
23 A/F 622-6152-011 33058	VHF Communication Transceiver No.2	0				Mos	14-Jan-2004		RE (O/C)	
		0				Hrs	3,901			
		0				Ldg	0			
23 A/F 7510700-765 Unknown	VHF Integrated Control Unit No.1	0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
VHF Integrated Control Unit										
 23 A/F 7510700-765 Unknown	No.2	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
2006-19-04 Honeywell International, Inc - COM unit and Mode S transponder										
 23 A/F Eff: 17-Oct-2006 Not Applicable Brand A:9990-2006-19-04	EQUIPMENT NOT INSTALLED				Mos	07-Nov-2006			RE (-) Mandatory (Appliance AD)	
					Hrs	4,712				
					Ldg	0				
2006-19-04 Paragraph (h) Honeywell International, Inc - Replacement of certain Transponders										
 23 A/F Eff: 17-Oct-2006 Not Applicable	EQUIPMENT NOT INSTALLED				Mos	07-Nov-2006			RE (-) Mandatory (Appliance AD)	
					Hrs	4,712				
					Ldg	0				
2014-17-02 Communications - ELT (This AD replaces AD 2013-18-09)										
 23 A/F Eff: 09-Sep-2014 Not Applicable (AVG MAN HRS: 1)	EQUIPMENT NOT INSTALLED				Mos	09-Sep-2014			RE (-) Mandatory (Appliance AD)	
					Hrs	6,186				
					Ldg	6,407				
560-23-21 R01 AFIS Antenna Replacement										
 23 A/F Eff: 12-Apr-1996 Complied With					Mos	01-Jun-1996			RE (-) Recommended	
					Hrs	765				
					Ldg	0				
560-23-22 Avtech Audio Control Panel Modification										
 23 A/F Eff: 18-Oct-1996 Complied With					Mos	02-Apr-1997			RE (-) Mandatory	
					Hrs	1,224.6				
					Ldg	1,598				
560-23-32 RNZ-850 Navigation Radio Upgrade										
 23 A/F Complied With					Mos	04-Mar-2004			RE (-) Mandatory	
					Hrs	3,951				
					Ldg	4,626				
560-23-32 R01 RNZ-850 Navigation Radio Upgrade										
 23 A/F Eff: 11-Nov-2003 Complied With					Mos	04-Mar-2004			RE (-) Mandatory	
					Hrs	3,951				
					Ldg	4,626				
A231001 High Frequency Antenna and Tension Unit - Inspect										
 23 A/F 051205 Ref.:23-10-01-210 (ZONE: 312, 340)					Mos	21-Oct-2016	36	+2	RE Continuous Inspection Program (31-Oct-2019) 1.7 Years (+61 Days)	
					Hrs	6,848.2	1,200	+100	(8,048.2) 844.3 Hrs (+100)	
					Ldg	6,940				
A236002 Control Surface Bond Jumper - Inspect										
 23 A/F 051205 Ref.:20-21-02-280					Mos		36	+2	RE Continuous Inspection Program (31-Oct-2019) 1.7 Years (+61 Days)	
					Hrs		1,200	+100	(8,048.2) 844.3 Hrs (+100)	
					Ldg					
A237001 Cockpit Voice Recorder - Inspect										
 23 A/F 051205 Ref.:23-70-00-210					Mos		36	+2	RE Continuous Inspection Program (31-Oct-2019) 1.7 Years (+61 Days)	
					Hrs		1,200	+100	(8,048.2) 844.3 Hrs (+100)	
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
B231002	Honeywell Standby Control Head - Perform operational test						RE (N/A)		Continuous Inspection Program	
 23 A/F						Mos				
Ref.:23-13-00-710 (ZONE: AUX)						Hrs				
						Ldg				
B236001	Static Discharge Wick - Inspect						RE		Continuous Inspection Program	
 23 A/F						Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
051205						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
Ref.:23-61-00-760						Ldg				
B237002	Cockpit Voice Recorder - Perform operational check						RE		Continuous Inspection Program	≈10-Sep-2018
 23 A/F						Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
051201						Hrs	300	+30	(7,422)	218.1 Hrs (+30)
Unknown						Ldg				
Unknown										
Ref.:23-70-00-710 (ZONE: AUX)										
B237004	Underwater Locator Beacon - Perform operational test						RE		Continuous Inspection Program	
 23 A/F						Mos	20-Oct-2016	24	+1	31-Oct-2018
051221						Hrs	6,848.2			8.8 Months (+30 Days)
DK100						Ldg	6,940			
SC55867										
Ref.:23-70-00-711 (ZONE: 312)										
SL560-23-15	Communication -Transmittal Of Airshow Service Bulletin 920720-1 Airshow 400 Digital Interface Unit						RE (-)		Optional	
 23 A/F						Mos	29-Feb-2000			
Eff: 04-Nov-1999 Not	EQUIPMENT NOT INSTALLED					Hrs	2,578			
Applicable						Ldg	0			
SL560-23-16 R01	Communications - Airshow Reliability Improvements and Service Pack Software Upgrade						RE (-)		Recommended	
 23 A/F						Mos	24-Jan-2003			
Eff: 07-Nov-2002 Not	EQUIPMENT NOT INSTALLED					Hrs	3,610			
Applicable						Ldg	0			
▼ 24 - ELECTRICAL POWER										
	Ammeter						RE (O/C)			
 24 A/F	No.1					Mos	15-Nov-1994			
C662501-0104		0				Hrs	0			
127		0				Ldg	0			
	Ammeter						RE (O/C)			
 24 A/F	No.2					Mos	15-Nov-1994			
C662501-0104		0				Hrs	0			
125		0				Ldg	0			
	Battery Disconnect Relay						RE (O/C)			
 24 A/F						Mos	15-Nov-1994			
A876K		0				Hrs	0			
TA12642		0				Ldg	0			
	Battery Temp Gage						RE (O/C)			
 24 A/F						Mos	15-Nov-1994			
1229-1		0				Hrs	0			
1901		0				Ldg	0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
24 A/F 1529-1 Unknown	Battery Temp Monitor								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
24 A/F 1166-1 NSN	Battery Temp Sensor								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
24 A/F Unknown Unknown	Cabin Altitude Switch								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
24 A/F Unknown Unknown	Current/Voltage Sensor								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
24 A/F C662502-0101 1671	DC Voltmeter								RE (O/C)	
		0			Mos	06-Aug-2000				
		0			Hrs	2,787				
		0			Ldg	0				
24 A/F 51525-001F 94073	Generator Control Unit No.1								RE (O/C)	
		0			Mos	04-Sep-2013				
		0			Hrs	5,988.1				
		0			Ldg	6,250				
24 A/F 51525-001F P1729	Generator Control Unit No.2								RE (O/C)	
		0			Mos	18-Sep-2008				
		0			Hrs	5,012				
		0			Ldg	0				
24 A/F RG-380E/44 40625802	Main Battery Life Limit								RE (O/C)	
		0			Mos	13-Jan-2014				
		0			Hrs	6,057.9				
		0			Ldg	6,315				
24 A/F 1645-1 1029	Overvoltage Sensor								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
24 A/F 23085-004 2022	Starter/Generator Left								RE (O/C)	
		0			Mos	13-Jul-2016				
		0			Hrs	6,776.2				
		0			Ldg	6,875				
24 A/F 23085-004 92106	Starter/Generator Right								RE (O/C)	
		0			Mos	21-Jul-2017				
		0			Hrs	7,122				
		0			Ldg	7,168				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
Starter/Generator Brushes										
 24 A/F Unknown Unknown	Left					Mos	15-Nov-1994	RE (O/C)		
						Hrs	0			
						Ldg	0			
Starter/Generator Brushes										
 24 A/F Unknown Unknown	Right					Mos	15-Nov-1994	RE (O/C)		
						Hrs	0			
						Ldg	0			
Static Inverter										
 24 A/F SPC10J 271	No.1	0					Mos	23-Jan-1999	RE (O/C)	
		0					Hrs	2,093		
		0					Ldg	0		
Static Inverter										
 24 A/F SPC10J 314	No.2	0					Mos	23-Jan-1999	RE (O/C)	
		0					Hrs	2,093		
		0					Ldg	0		
5-11-00(2)(M)(1) Starter Generator - Overhaul										
 24 A/F 23085-004 2022	Left					Mos	13-Jul-2016	RE	Component Time Limits	≈04-Sep-2019
						Hrs	6,776.2	1,000	7,776.2	572.3 Hrs
						Ldg	6,875			
5-11-00(2)(M)(1) Starter Generator - Overhaul										
 24 A/F 23085-004 92106	Right					Mos	21-Jul-2017	RE	Component Time Limits	≈21-Aug-2020
						Hrs	7,122	1,000	8,122	918.1 Hrs
						Ldg	7,168			
5-11-00(2)(M)(2) Starter-Generator bearings (Starter-Generators prior to mod B not incorporating Lucas Aerospace Service Bulletin 23085-004-24-01) - Replace										
 24 A/F 23085-004 2022	Left					Mos	RE (N/A)		Component Time Limits	
						Hrs				
						Ldg				
5-11-00(2)(M)(2) Starter-Generator bearings (Starter-Generators prior to mod B not incorporating Lucas Aerospace Service Bulletin 23085-004-24-01) - Replace										
 24 A/F 23085-004 92106	Right					Mos	RE (N/A)		Component Time Limits	
						Hrs				
						Ldg				
560-24-16 Trim PC Board Modification and Elevator Electric Trim Motor Modification										
 24 A/F Complied With						Mos	21-Oct-1995	RE (-)	Recommended	
						Hrs	505			
						Ldg	0			
560-24-21 R01 GCU Start Modification										
 24 A/F Eff: 14-Nov-1997 Complied With						Mos	31-Jul-1999	RE (-)	Recommended	
						Hrs	2,326			
						Ldg	0			
560-24-22 Electrical Power - Circuit Breaker Terminal Screw Length Inspection/Replacement										
 24 A/F Eff: 20-Jul-2000 Complied With						Mos	29-Mar-2001	RE (-)	Recommended	
						Hrs	3,067			
						Ldg	0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-24-27 24 A/F Complied With	Electrical Power - Wing Wire Routing Improvement/Flap Hydraulic Line Inspection					Mos 10-Dec-2001 Hrs 3,235 Ldg 0	RE (-)		Recommended	
560-24-30 24 A/F Eff: 28-Sep-2000 Complied With	Electrical Power - Circuit Breaker Insulators Installation					Mos 08-Aug-2001 Hrs 3,199 Ldg 0	RE (-)		Recommended	
560-24-36 24 A/F Not Applicable	CXX Right Circuit Breaker Panel Modification N/A BY AIRCRAFT S/N EFFECTIVITY					Mos 01-Aug-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory	
560-24-36 R01 24 A/F Not Applicable	CXX Right Circuit Breaker Panel Modification N/A BY AIRCRAFT S/N EFFECTIVITY					Mos 01-Aug-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory	
560-24-36 R02 24 A/F Not Applicable	CXX Right Circuit Breaker Panel Modification N/A BY AIRCRAFT S/N EFFECTIVITY					Mos 01-Aug-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory	
560-24-36 R03 24 A/F Eff: 13-Feb-2004 Not Applicable	CXX Right Circuit Breaker Panel Modification N/A BY AIRCRAFT S/N EFFECTIVITY					Mos 01-Aug-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory	
560-24-37 24 A/F Complied With	Main Power Wire Anchor Improvement					Mos 27-Nov-2002 Hrs 3,568 Ldg 0	RE (-)		Recommended	
560-24-39 24 A/F Eff: 24-Jan-2002 Complied With	Electrical Power - Sealed Lead Acid Battery Installation					Mos 01-Apr-2002 Hrs 3,363 Ldg 0	RE (-)		Optional	
560-24-42 24 A/F Eff: 11-Nov-2003 Complied With	Relay Shield Installation					Mos 02-Mar-2004 Hrs 3,951 Ldg 4,626	RE (-)		Mandatory	
98-20-17 24 A/F EQUIPMENT NOT INSTALLED	To Prevent The Battery From Shorting Out Or Exploding					Mos 09-Sep-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory	
A242001 24 A/F Ref.:24-00-00-210	Nose Area Electrical Components - Inspect 051205					Mos Hrs Ldg	RE 36 1,200	Continuous Inspection Program +2 +100	(31-Oct-2019) (8,048.2)	1.7 Years (+61 Days) 844.3 Hrs (+100)

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A245001	Circuit Breaker Panels - Inspect						RE		Continuous Inspection Program	
24 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:24-45-00-212 (ZONE: 245, 246)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A245002	Cockpit Side Console - Inspect						RE		Continuous Inspection Program	
24 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:24-45-00-210 (ZONE: 245, 246)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A245003	Avionics Relay Junction Box - Inspect						RE (N/A)		Continuous Inspection Program	
24 A/F					Mos					
Ref.:24-00-00-211					Hrs					
					Ldg					
A245004	Aft Power Junction Box - Inspect						RE		Continuous Inspection Program	
24 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:24-45-00-211 (ZONE: 311, 312)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B243001	DC Generator System - Perform operational test						RE		Continuous Inspection Program	≈10-Sep-2018
24 A/F	051204				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:24-30-00-710 (ZONE: ENG)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
B244001	Overvoltage System - Perform functional test						RE		Continuous Inspection Program	≈10-Sep-2018
24 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:24-41-02-710 (ZONE: AUX)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
D243003	Lead Acid Battery - Inspect						RE		Continuous Inspection Program	
24 A/F	051255				Mos	15-Dec-2017	3	+1	(31-Mar-2018)	51 Days (+30)
Ref.:24-35-00-760 (ZONE: 311) (AVG MAN HRS: 0) (APX COST [USD]: 0) (Tol. Adjustment: -2d) (NOTE: NOTE: The inspection schedule may be adjusted after the useful battery life is established, based on operations)					Hrs	7,170.7	200	+10	(7,370.7)	166.8 Hrs (+10)
					Ldg	7,208				
▼ 25 - EQUIPMENT/FURNISHINGS										
	Co-Pilots Life Vest Recertify						RE			
25 A/F					Mos	06-Oct-2016	60		06-Oct-2021	3.7 Years
					Hrs	6,848.2				
					Ldg	6,940				
	Cabin Briefer Computer						RE (O/C)			
25 A/F Unknown Unknown					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
	Cabin Briefer Control						RE (O/C)			
25 A/F PBS400-2-G5 23		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
	Coffee Pot						RE (O/C)			
25 A/F Unknown Unknown					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 25 A/F P0723E105P 061873	Co-Pilots Life Vest						RE (O/C)			
		0			Mos	06-Oct-2016				
		0			Hrs	6,848.2				
		0			Ldg	6,940				
 25 A/F Unknown Unknown	Crew Seat						RE (O/C)			
	Copilot				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 25 A/F Unknown Unknown	Crew Seat						RE (O/C)			
	Pilot				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 25 A/F Expiration Date 30-Apr-2020	Defibrillator Battery Life Limit						RE (Due)			
					Mos	29-Sep-2014			30-Apr-2020	2.2 Years
					Hrs	6,214.5				
					Ldg	6,429				
 25 A/F 110-337 1062840	ELT Antenna						RE (O/C)			
	No.1	0			Mos	10-Dec-2001				
		0			Hrs	3,235				
		0			Ldg	0				
 25 A/F 453-6500 01192	ELT Interface						RE (O/C)			
		0			Mos	10-Dec-2001				
		0			Hrs	3,235				
		0			Ldg	0				
 25 A/F 453-5012-601 Unknown	Emergency Locator Transmitter						RE (O/C)			
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 25 A/F Unknown Unknown	Extended Baggage Tube Factory Option						RE (O/C)			
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 25 A/F PR-3025FAA Unknown	First Aid Kit						RE (O/C)			
		0			Mos	21-Oct-2016				
		0			Hrs	6,848.2				
		0			Ldg	6,940				
 25 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)	First Aid Kit Inspection						RE			
					Mos	31-Oct-2017	12		31-Oct-2018	8.8 Months
					Hrs	7,170.5				
					Ldg	7,207				
 25 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)	Flaregun Cartridges Life Limit						RE			
					Mos	15-Dec-2017	39		[31-Jan-2021]	3 Years
					Hrs	7,170.7				
					Ldg	7,208				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
Heartstart FRx Defibrillator										
 25 A/F 861304 B14H-04058							RE (O/C)			
		0				Mos	21-Jul-2017			
		0				Hrs	7,122			
				0	Ldg	7,168				
Heartstart FRx Defibrillator Battery Replacement										
 25 A/F M5070A Unknown Expiration Date 30-Sep-2018							RE (Due)			
		0				Mos	29-Sep-2014	30-Sep-2018	7.8 Months	
		0				Hrs	6,214.5			
				0	Ldg	6,429				
Heartstart FRx Defibrillator SMART Pads Replacement										
 25 A/F 98983139261 Unknown Expiration Date 28-Feb-2019							RE (Due)			
						Mos	12-Jan-2017	28-Feb-2019	1.1 Years	
						Hrs	6,953.6			
				Ldg	7,018					
Heartstart FRx Defibrillator SMART Pads Replacement										
 25 A/F 98983139261 Unknown Expiration Date 28-Feb-2019							RE (Due)			
						Mos	12-Jan-2017	28-Feb-2019	1.1 Years	
						Hrs	6,953.6			
				Ldg	7,018					
Heartstart FRx Defibrillator Visual Inspection										
 25 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)							RE			
						Mos	03-Jan-2018	6	03-Jul-2018	4.8 Months
						Hrs	7,192.6			
				Ldg	7,223					
Inspect Rosen Sun Visor System										
  25 A/F							RE			
						Mos	21-Jul-2017			
						Hrs	7,122	150	7,272	68.1 Hrs
				Ldg	7,168					
Life Vest										
 25 A/F P0723E105P 597710	No.1						RE (O/C)			
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
				0	Ldg	6,940				
Life Vest										
 25 A/F P0723E105P 597844	No.10						RE (O/C)			
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
				0	Ldg	6,940				
Life Vest										
 25 A/F P0723E105P 597752	No.2						RE (O/C)			
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
				0	Ldg	6,940				
Life Vest										
 25 A/F P0723E105P 597827	No.3						RE (O/C)			
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
				0	Ldg	6,940				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
Life Vest										
25 A/F P0723E105P 597839	No.4								RE (O/C)	
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
		0				Ldg	6,940			
Life Vest										
25 A/F P0723E105P 597826	No.5								RE (O/C)	
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
		0				Ldg	6,940			
Life Vest										
25 A/F P0723E105P 597709	No.6								RE (O/C)	
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
		0				Ldg	6,940			
Life Vest										
25 A/F P0723E105P 597780	No.7								RE (O/C)	
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
		0				Ldg	6,940			
Life Vest										
25 A/F P0723E105P 597804	No.8								RE (O/C)	
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
		0				Ldg	6,940			
Life Vest										
25 A/F P0723E105P 597748	No.9								RE (O/C)	
		0				Mos	06-Oct-2016			
		0				Hrs	6,848.2			
		0				Ldg	6,940			
Locator Beacon Battery Pack										
25 A/F 452-0133 370372-015 Expiration Date 31-Jul-2021									RE (Due)	
		0				Mos	18-Aug-2016		31-Jul-2021	3.5 Years
		0				Hrs	6,814.5			
		0				Ldg	6,914			
Locator Beacon Transmitter										
25 A/F 453-5000-999 170-00724									RE (O/C)	
		0				Mos	17-Sep-2007			
		0				Hrs	4,823			
		0				Ldg	0			
No. 2 ELT Antenna										
25 A/F ELT10-177-2 1142									RE (O/C)	
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
Passenger Seat										
25 A/F Unknown Unknown	No.1								RE (O/C)	
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time		
PN/SN	MOC Note or Component Condition								DUE	Remaining		
 25 A/F Unknown Unknown	Passenger Seat						RE (O/C)					
	No.2						Mos	15-Nov-1994				
							Hrs	0				
							Ldg	0				
 25 A/F Unknown Unknown	Passenger Seat						RE (O/C)					
	No.3						Mos	15-Nov-1994				
							Hrs	0				
							Ldg	0				
 25 A/F Unknown Unknown	Passenger Seat						RE (O/C)					
	No.4						Mos	15-Nov-1994				
							Hrs	0				
							Ldg	0				
 25 A/F Unknown Unknown	Passenger Seat						RE (O/C)					
	No.5						Mos	15-Nov-1994				
							Hrs	0				
							Ldg	0				
 25 A/F Unknown Unknown	Passenger Seat						RE (O/C)					
	No.6						Mos	15-Nov-1994				
							Hrs	0				
							Ldg	0				
 25 A/F Unknown Unknown	Passenger Seat						RE (O/C)					
	No.7						Mos	15-Nov-1994				
							Hrs	0				
							Ldg	0				
 25 A/F Unknown Unknown	Passenger Seat						RE (O/C)					
	No.8						Mos	15-Nov-1994				
							Hrs	0				
							Ldg	0				
 25 A/F Unknown Unknown	Passenger Seat						RE (O/C)					
	No.9						Mos	15-Nov-1994				
							Hrs	0				
							Ldg	0				
 25 A/F P0723E105P 597844	Pilots Life Vest						RE (O/C)					
		0						Mos	06-Oct-2016			
		0						Hrs	6,848.2			
		0						Ldg	6,940			
 25 A/F	Pilots Life Vest Recertify						RE					
							Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years	
							Hrs	6,848.2				
							Ldg	6,940				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
Pyrotechnic Signaling Device Inspection										
 25 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)						Mos	15-Dec-2017	12	31-Dec-2018	10.9 Months
						Hrs	7,170.7			
						Ldg	7,208			
Transducer										
 25 A/F 2504-900 1710						Mos	08-Dec-1997	RE (O/C)		
						Hrs	1,614			
						Ldg	0			
True Airspeed/Airtime Display										
 25 A/F Unknown Unknown						Mos	15-Nov-1994	RE (O/C)		
						Hrs	0			
						Ldg	0			
2002-21-01 BRITAX SELL GMBH-WATER BOILERS ,COFFEE & BEVERAGE MAKERS - Electrical terminal contact pins										
 25 A/F Eff: 27-Nov-2002 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014	RE (-)	Mandatory (Appliance AD)	
						Hrs	6,186			
						Ldg	6,407			
2003-26-06 Anjou - Safety Belts and Restraint Systems										
 25 A/F Eff: 17-Feb-2004 Not Applicable Brand A:9990-2003-26-06 (AVG MAN HRS: 1)	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014	RE (-)	Mandatory (Appliance AD)	
						Hrs	6,186			
						Ldg	6,407			
2007-04-15 Sicma Aero Seat - Installing new tab locks										
 25 A/F Eff: 23-Mar-2007 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014	RE (-)	Mandatory (Appliance AD)	
						Hrs	6,186			
						Ldg	6,407			
2010-02-06 Sicma Aero Seat 90xx and 92xx Series Passenger Seats										
 25 A/F Eff: 24-Feb-2010 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014	RE (-)	Mandatory (Appliance AD)	
						Hrs	6,186			
						Ldg	6,407			
2011-21-08 SICMA AERO SEAT - Equipment/Furnishings - Passenger Seat Assemblies										
 25 A/F Eff: 23-Nov-2011 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	30-Jan-2012	RE (-)	Mandatory (Appliance AD)	
						Hrs	5,663.6			
						Ldg	6,043			
2011-23-06 Equipment/Furnishing - To Detect Cracks in the Central and Lateral Spreaders on Passenger Seats. (SUPERSEDED BY FAA AD 2012-08-07)										
 25 A/F Eff: 21-Nov-2011 Not Applicable Brand A:9990-2011-23-06	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014	RE (-)	Mandatory (Appliance AD)	
						Hrs	6,186			
						Ldg	6,407			
2017-16-01 Emergency Locator Beacon (Ameri-King Corporation) - Inspect/ Replace										
 25 A/F Eff: 24-Oct-2017 (AVG MAN HRS: 6)						Mos		RE (-)	Mandatory	
						Hrs			[24-Oct-2018]	8.6 Months
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597710 Restored Date 06-Oct-2016	No.1					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597752 Restored Date 06-Oct-2016	No.2					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597827 Restored Date 06-Oct-2016	No.3					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597839 Restored Date 06-Oct-2016	No.4					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597826 Restored Date 06-Oct-2016	No.5					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597709 Restored Date 06-Oct-2016	No.6					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597780 Restored Date 06-Oct-2016	No.7					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597804 Restored Date 06-Oct-2016	No.8					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
256010	Life Vest - Recertification								RE	CMM
 25 A/F P0723E105P 597748 Restored Date 06-Oct-2016	No.9					Mos	06-Oct-2016	60	31-Oct-2021	3.7 Years
						Hrs	6,848.2			
						Ldg	6,940			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
25-NOAA  25 A/F	406 ELT Registration Renewal								RE Custom Task	
					Mos	21-Oct-2016	24		21-Oct-2018	8.5 Months
					Hrs	6,848.2				
					Ldg	6,940				
560-25-20 R01  25 A/F Eff: 19-Jul-1996 Not Applicable	Interior Cabinetry Replacement N/A BY AIRCRAFT S/N EFFECTIVITY								RE (-) Mandatory	
					Mos	01-Aug-2014				
					Hrs	6,186				
					Ldg	6,407				
560-25-21  25 A/F Eff: 06-Oct-1997 Complied With	Overhead Console Retainer Modification								RE (-) Recommended	
					Mos	27-Feb-1998				
					Hrs	1,705				
					Ldg	0				
560-25-25  25 A/F Eff: 29-Jan-1999 Complied With	Escape Hatch Sidewall Panel Installatin								RE (-) Recommended	
					Mos	16-Nov-1999				
					Hrs	2,436				
					Ldg	0				
74-08-09 R3  25 A/F Eff: 28-Mar-2012 Complied With (AVG MAN HRS: 3)	Equipment/furnishings - Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles								RE Mandatory	≈24-Apr-2019
					Mos	27-Jan-2016				
					Hrs	6,646.3	1,000		7,646.3	442.4 Hrs
					Ldg	6,778				
94-21-06  25 A/F Eff: 25-Nov-1994 Not Applicable	Lap Belt Assemblies and Restraint Systems EQUIPMENT NOT INSTALLED								RE (-) Mandatory (Appliance AD)	
					Mos	09-Sep-2014				
					Hrs	6,186				
					Ldg	6,407				
96-12-09  25 A/F Eff: 29-Jul-1996 Not Applicable (NOTE: PTC Seating Products Division, B/E Aerospace (PTC) Model 950 series passenger seat equipped with footrest assembly.)	Passengers Seat EQUIPMENT NOT INSTALLED								RE (-) Mandatory (Appliance AD)	
					Mos	09-Sep-2014				
					Hrs	6,186				
					Ldg	6,407				
98-25-10 R1  25 A/F Eff: 14-Jan-2000 Complied With Brand A:9990-1998-25-10 R1	Aircraft Belts, Inc - Seat Restraint Systems								RE (-) Mandatory (Appliance AD)	
					Mos	07-Apr-1999				
					Hrs	2,159.2				
					Ldg	2,670				
A251001  25 A/F 051205 Ref.:25-11-01-210 (ZONE: 241, 242)	Pilot and Copilot Crew Seat - Inspect								RE Continuous Inspection Program	
					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A251002  25 A/F 051205 Ref.:25-11-01-211	Pilot and Copilot Seat Track Stops - Inspect								RE Continuous Inspection Program	
					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A251004	Cockpit Instrument Panels and Components - Inspect								RE	Continuous Inspection Program
 25 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:25-10-00-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A252001	Passenger Seats - Inspect								RE	Continuous Inspection Program
 25 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:25-20-00-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A252002	Passenger Seat Track Stops - Inspect								RE	Continuous Inspection Program
 25 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:25-20-00-211					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A256001	Emergency Equipment - Inspect								RE	Continuous Inspection Program
 25 A/F	051218				Mos	11-Oct-2017	12	+1	(31-Oct-2018)	8.8 Months (+30 Days)
Ref.:25-60-00-210 (AVG MAN HRS: 0) (APX COST [USD]: 0)					Hrs	7,170.5				
					Ldg	7,207				
A256003	Life Preserver - Inspect								RE	Continuous Inspection Program
 25 A/F	051218				Mos	11-Oct-2017	12	+1	(31-Oct-2018)	8.8 Months (+30 Days)
Ref.:25-60-00-280 (AVG MAN HRS: 0) (APX COST [USD]: 0)					Hrs	7,170.5				
					Ldg	7,207				
A256004	Smoke Goggle Assembly Detailed Inspection								RE	Continuous Inspection Program
 25 A/F	051218				Mos	11-Oct-2017	12	+1	(31-Oct-2018)	8.8 Months (+30 Days)
Ref.:25-60-00-211 (ZONE: 241, 242) (AVG MAN HRS: 0) (APX COST [USD]: 0)					Hrs	7,170.5				
					Ldg	7,207				
A256101	Artex C406-N Emergency Locator Beacon System - Visually inspect								RE (N/A)	Continuous Inspection Program
 25 A/F					Mos					
Ref.:25-61-05-210 (ZONE: 340)					Hrs					
					Ldg					
A256107	C406-2 Emergency Locator Transmitter (ELT) Detailed Inspection								RE (N/A)	Continuous Inspection Program
 25 A/F					Mos					
Ref.:25-61-07-220 (ZONE: 340)					Hrs					
					Ldg					
B256001	Emergency Locator Beacon System - Visually inspect and perform operational check								RE	Continuous Inspection Program
 25 A/F	051256				Mos		12	+1	(21-Jul-2018)	5.4 Months (+31 Days)
Ref.:25-60-00-710 (ZONE: 340) (NOTE: Note: Required by Title 14 of the Code of Federal Regulations 91.207)					Hrs					
					Ldg					
B256101	Artex C406-N Emergency Locator Beacon System - Perform functional check								RE (N/A)	Continuous Inspection Program
 25 A/F					Mos					
Ref.:25-61-05-720 (ZONE: 340)					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
B256107	C406-2 Emergency Locator Transmitter (ELT) Functional Test						RE	Continuous Inspection Program		
 25 A/F	051256				Mos		12	+1	(21-Jul-2018)	5.4 Months (+31 Days)
	Ref.:25-61-07-720 (ZONE: 340) (NOTE: Note: Required by Title 14 of the Code of Federal Regulations 91.207)				Hrs					
					Ldg					
SL560-25-03	Transmittal of Eastern Aero Marine Service Bulletin SBV-25-2, Equipment/Furnishings - Life Preservers and Individual Flotation Devices Replacement of CO2 Inflator - Mandatory						RE (-)		Mandatory	
 25 A/F					Mos	02-Apr-1997				
	Eff: 15-Nov-1996 Complied With				Hrs	1,224				
					Ldg	1,598				
SL560-25-09	Transmittal of Pacific Scientific Aerospace Service Bulletin SB 25-1111432, Information Regarding the Potential Failure of the Guarded Rotary Buckle Plastic Handle						RE (-)		Mandatory	
 25 A/F					Mos	11-Jul-2008				
	Eff: 10-Dec-2007 Complied With				Hrs	4,966				
					Ldg	0				
▼ 26 - FIRE PROTECTION										
	Engine Fire Bottle						RE (O/C)		Component Time Limits	
 26 A/F	Aft	0			Mos	21-Sep-2012				
	32700015	0			Hrs	0				
	12294C1	0			Ldg	0				
	Engine Fire Bottle						RE (O/C)		Component Time Limits	
 26 A/F	Fwd	0			Mos	21-Sep-2012				
	32700015	0			Hrs	0				
	12289C1				Ldg	0				
	Engine Fire Detector Sensor						RE (O/C)			
 26 A/F	No.1	0			Mos	15-Nov-1994				
	244-18882	0			Hrs	0				
	NSN	0			Ldg	0				
	Engine Fire Detector Sensor						RE (O/C)			
 26 A/F	No.2	0			Mos	25-Jun-2014				
	244-18882	0			Hrs	6,169.6				
	130802	0			Ldg	6,393				
	Engine fire extinguisher cartridge						RE		Component Time Limits	
 26 A/F	Aft - No.1	0			Yrs	29-Sep-2014	10		[30-Jun-2024]	6.4 Years
	AE13083-5	0			Hrs	6,214.5				
	AEN1-177	0			Ldg	6,429				
	Manufactured Date 29-Sep-2014									
	Engine fire extinguisher cartridge						RE		Component Time Limits	
 26 A/F	Aft - No.2	0			Yrs	29-Sep-2014	10		[30-Jun-2024]	6.4 Years
	AE13083-5	0			Hrs	6,214.5				
	AEN1-177	0			Ldg	6,429				
	Manufactured Date 29-Sep-2014									

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
PN/SN	MOC Note or Component Condition								DUE	
Engine fire extinguisher cartridge										
	26 A/F AE13083-5 AEN1-177 Manufactured Date 29-Sep-2014	Fwd - No.1							RE	Component Time Limits
		0				Yrs	29-Sep-2014	10	[30-Jun-2024]	6.4 Years
		0				Hrs	6,214.5			
		0				Ldg	6,429			
Engine fire extinguisher cartridge										
	26 A/F AE13083-5 AEN1-177 Manufactured Date 29-Sep-2014	Fwd - No.2							RE	Component Time Limits
		0				Yrs	29-Sep-2014	10	[30-Jun-2024]	6.4 Years
		0				Hrs	6,214.5			
		0				Ldg	6,429			
Fire Detector Control										
	26 A/F 377-02830 9418007	No.1							RE (O/C)	
		0				Mos	06-Sep-2017			
		0				Hrs	7,157.6			
		0				Ldg	7,200			
Fire Detector Control										
	26 A/F 377-02830 9409006	No.2							RE (O/C)	
		0				Mos	06-Sep-2017			
		0				Hrs	7,157.6			
		0				Ldg	7,200			
Heat Exchange Precooler										
	26 A/F Unknown Unknown	Left							RE (O/C)	Component Time Limits
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
Heat Exchange Precooler										
	26 A/F Unknown Unknown	Right							RE (O/C)	Component Time Limits
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
Monthly Portable Fire Extinguisher Inspection										
	26 A/F Brand C:262007 (AVG MAN HRS: 0) (APX COST [USD]: 0)								RE	Custom Task
						Mos	03-Jan-2018	1	28-Feb-2018	20 Days
						Hrs	7,192.6			
						Ldg	7,223			
Portable Halon Fire Extinguisher										
	26 A/F C352 Y-94487	Cabin							RE (O/C)	
		0				Mos	30-Nov-2012			
		0				Hrs	5,844.9			
		0				Ldg	6,153			
Portable Halon Fire Extinguisher										
	26 A/F C352 B-02761848	Cockpit							RE (O/C)	
		0				Mos	27-Jan-2016			
		0				Hrs	6,646.3			
		0				Ldg	6,778			
2001-22-14 Overland Aviation Services - Fire Extinguishing System Bottle Cartridges										
	26 A/F Eff: 10-Dec-2001 Not Applicable (AVG MAN HRS: 8)	EQUIPMENT NOT INSTALLED							RE (-)	Mandatory (Appliance AD)
						Days	09-Sep-2014			
						Hrs	6,186			
						Ldg	6,407			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2003-26-14	Kidde Aerospace - Hand-Held Halon Fire Extinguishers Removal								RE (-)	Mandatory (Appliance AD)
26 A/F Eff: 20-Feb-2004 Not Applicable Brand A:9990-2003-26-14 (AVG MAN HRS: 1) (APX COST [USD]: 60)	EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014 Hrs 6,186 Ldg 6,407				
2006-04-04	Meggitt - Smoke detectors								RE (-)	Mandatory (Appliance AD)
26 A/F Eff: 24-Mar-2006 Not Applicable	EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014 Hrs 6,186 Ldg 6,407				
2006-04-10	This AD Requires Installing Identification Sleeves On The Wires For The Positive And Negative Studs Of The Engine And/ Or (APU) Fire Extinguishing Bottles, As Applicable, And Reconnecting The Wires To The Correct Terminal Studs. (Superseded by AD 2007-11-17)								RE (-)	Mandatory
26 A/F Eff: 24-Mar-2006 Complied With						Mos 17-Apr-2006 Hrs 4,570 Ldg 0				
2007-11-17	Wires for the positive and negative terminal studs of the engine and/or auxiliary power unit (APU) fire extinguishing bottles.								RE (-)	Mandatory
26 A/F Eff: 06-Jul-2007 Complied With (AVG MAN HRS: 4)						Days 17-Sep-2007 Hrs 4,823.4 Ldg 5,396				
2010-01-03	Fire Fighting Enterprises Limited - Fire Protection								RE (-)	Mandatory (Appliance AD)
26 A/F Eff: 20-Jan-2010 Not Applicable Brand A:9990-2010-01-03	EQUIPMENT NOT INSTALLED					Mos 26-Jan-2010 Hrs 5,273 Ldg 0				
2010-04-16	SICLI - Identification & Removal of Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers								RE (-)	Mandatory (Appliance AD)
26 A/F Eff: 08-Mar-2010 Not Applicable Brand A:9990-2010-04-16 (NOTE: Within 90 days after the effective date of this AD, replace all Type H1-10 AIR Halon 1211 (BCF) portable fire extinguishers manufactured by SICLI, having P/N 1708337B4 and having any serial number listed in Table 1 of this AD, with serviceable fire extinguishers)	EQUIPMENT NOT INSTALLED					Mos 26-Jun-2010 Hrs 5,452.6 Ldg 5,880				
2017-19-05	Smoke Detection - Inspection / Replacement								RE (-)	Mandatory
26 A/F Eff: 31-Oct-2017 Not Applicable (AVG MAN HRS: 0) (APX COST [USD]: 0)						Mos 04-Oct-2017 Hrs Ldg				
2017-19-05 Par. 2(f)(1)	Smoke Detection - Inspection								RE (-)	Mandatory
26 A/F Eff: 31-Oct-2017 Not Applicable (AVG MAN HRS: 0) (APX COST [USD]: 0) (NOTE: APPLICABILITY: This AD also applies to those smoke detectors with P/Ns and S/Ns listed in Figure 1 to paragraph (c) of this AD; installed on, but not limited to, any airplane, certificated in any category, listed in paragraphs (c)(2)(i) or (ii) of this AD.NOTE: Refer to Siemens Service Information Letter (SIL) No. PMC-26-002, Revision No. 1, dated January 2016; or Siemens SIL No. PMC-26-003, Revision No. 2, dated February 2016.)						Days 04-Oct-2017 Hrs Ldg				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2017-19-05 Par. 2(f)(2)	Smoke Detection - Replacement						RE (-)		Mandatory	
 26 A/F Eff: 31-Oct-2017 Not Applicable (AVG MAN HRS: 0) (APX COST [USD]: 0) (NOTE: APPLICABILITY: P/N PMC1102-02 [Cargo compartments] with Manufacturing date (month/year) - 122010 to 112011 inclusive; and P/N PMC3100-00 Detectors [Cargo compartments] with Manufacturing date (month/year) - 032011 to 012012 inclusive.NOTE: Refer to Siemens Service Information Letter (SIL) No. PMC-26-002, Revision No. 1, dated January 2016; or Siemens SIL No. PMC-26-003, Revision No. 2, dated February 2016.)						Mos Hrs Ldg	04-Oct-2017			
5-11-00(2)(D)(1)	Fire Protection - Engine fire extinguisher cartridges - Replace (In Service Limitation)						RE (N/A)		Component Time Limits	
 26 A/F AE13083-5 AEN1-177	Aft - No.1					Mos Hrs Ldg				
5-11-00(2)(D)(1)	Fire Protection - Engine fire extinguisher cartridges - Replace (In Service Limitation)						RE (N/A)		Component Time Limits	
 26 A/F AE13083-5 AEN1-177	Aft - No.2					Mos Hrs Ldg				
5-11-00(2)(D)(1)	Fire Protection - Engine fire extinguisher cartridges - Replace (In Service Limitation)						RE (N/A)		Component Time Limits	
 26 A/F AE13083-5 AEN1-177	Fwd - No.1					Mos Hrs Ldg				
5-11-00(2)(D)(1)	Fire Protection - Engine fire extinguisher cartridges - Replace (In Service Limitation)						RE (N/A)		Component Time Limits	
 26 A/F AE13083-5 AEN1-177	Fwd - No.2					Mos Hrs Ldg				
5-11-00(2)(D)(2)	Fire Protection - Engine Fire Extinguisher Container - Hydrostatic Test						RE		Component Time Limits	
 26 A/F 32700015 12294C1 Hydrostatic Tested Date 26-Sep-2017 Ref.:26-22-00-783 (AVG MAN HRS: 0) (APX COST [USD]: 0) (Tol. Adjustment: -6d)	Aft					Mos Hrs Ldg	27-Sep-2017 7,165.5 7,205	60	30-Sep-2022	4.6 Years
5-11-00(2)(D)(2)	Fire Protection - Engine Fire Extinguisher Container - Hydrostatic Test						RE		Component Time Limits	
 26 A/F 32700015 12289C1 Hydrostatic Tested Date 26-Sep-2017 Ref.:26-22-00-783 (AVG MAN HRS: 0) (APX COST [USD]: 0) (Tol. Adjustment: -6d)	Fwd					Mos Hrs Ldg	27-Sep-2017 7,165.5 7,205	60	30-Sep-2022	4.6 Years
5-11-00(2)(D)(3)	Fire Protection - Halon-type Fire Extinguisher - Hydrostatic Test						RE		Component Time Limits	
 26 A/F C352 Y-94487 Hydrostatic Tested Date 01-Aug-2014 Ref.:26-22-00-782	Cabin					Mos Hrs Ldg	01-Aug-2014 6,186 6,407	144	[31-Jan-2023]	5 Years
5-11-00(2)(D)(3)	Fire Protection - Halon-type Fire Extinguisher - Hydrostatic Test						RE		Component Time Limits	
 26 A/F C352 B-02761848 Hydrostatic Tested Date 27-Jan-2016 Ref.:26-22-00-782	Cockpit					Mos Hrs Ldg	27-Jan-2016 6,646.3 6,778	144	[31-Oct-2027]	9.7 Years

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-26-01	Fire Bottle Wire Identification Sleeve Installation						RE (-)		Mandatory	
 26 A/F Eff: 01-Apr-2005 Complied With						Mos 28-Apr-2005				
						Hrs 4,221				
						Ldg 4,915				
97-04-15	Pacific Scientific Company, HTL/Kin-Tech Division, Fire Extinguisher Bottle Cartridges						RE (-)		Mandatory (Appliance AD)	
 26 A/F Eff: 07-Mar-1997 Not Applicable	EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014				
						Hrs 6,186				
						Ldg 6,407				
98-24-27	First Technology Fire and Safety Ltd. Toilet Compartment Fire Extinguisher						RE (-)		Mandatory (Appliance AD)	
 26 A/F Eff: 29-Jan-1999 Not Applicable	EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014				
						Hrs 6,186				
						Ldg 6,407				
99-04-10	Prevent Fire in the Passenger Compartment Resulting from Failure of the Fluorescent Light Ballast of the Cabin Sidewall						RE (-)		Mandatory (Appliance AD)	
 26 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014				
						Hrs 6,186				
						Ldg 6,407				
A262003	Portable Hand Fire Extinguisher - Inspect						RE			
 26 A/F Cabin 051218 C352 Y-94487 Ref.:26-22-00-780 (ZONE: 242, 272) (AVG MAN HRS: 0) (APX COST [USD]: 0)						Mos 11-Oct-2017	12	+1 (31-Oct-2018)	8.8 Months (+30 Days)	
						Hrs 7,170.5				
						Ldg 7,207				
A262003	Portable Hand Fire Extinguisher - Inspect						RE			
 26 A/F Cockpit 051218 C352 B-02761848 Ref.:26-22-00-780 (ZONE: 242, 272) (AVG MAN HRS: 0) (APX COST [USD]: 0)						Mos 11-Oct-2017	12	+1 (31-Oct-2018)	8.8 Months (+30 Days)	
						Hrs 7,170.5				
						Ldg 7,207				
B262004	Cabin Mounted Halon-type Fire Extinguishers - Empty, inspect for damage and recharge						RE	Continuous Inspection Program		
 26 A/F Cabin 051248 C352 Y-94487 Ref.:26-22-00-781 (ZONE: LAB)						Mos 31-Oct-2015	72	+1 (31-Oct-2021)	3.7 Years (+30 Days)	
						Hrs 6,646.3				
						Ldg 6,778				
B262004	Cockpit Mounted Halon-type Fire Extinguishers - Empty, inspect for damage and recharge						RE	Continuous Inspection Program		
 26 A/F Cockpit 051248 C352 B-02761848 Ref.:26-22-00-781 (ZONE: LAB)						Mos 31-Oct-2015	72	+1 (31-Oct-2021)	3.7 Years (+30 Days)	
						Hrs 6,646.3				
						Ldg 6,778				
B262005	Engine Fire Extinguisher System - Perform functional test						RE	Continuous Inspection Program		
 26 A/F 051205 Ref.:26-21-00-720						Mos	36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
						Hrs	1,200	+100 (8,048.2)	844.3 Hrs (+100)	
						Ldg				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
CIL-26-01	Fire Protection - Fire Extinguisher Bottle Cartridge Ground Stud Torquing						RE (-)		Mandatory	
26 A/F Eff: 10-May-2016 (AVG MAN HRS: 0.5)						Mos			[10-May-2019]	1.2 Years
						Hrs			[7,929.3]	725.4 Hrs
						Ldg				
CIL-26-01 R1	Fire Protection - Fire Extinguisher Bottle Cartridge Ground Stud Torquing						T		Mandatory	
26 A/F Eff: 16-Jun-2016 (AVG MAN HRS: 0.5) (NOTE: NOTE: This Service Letter applies to airplanes listed in the EFFECTIVITY section that have had the firebottle squibs replaced or manufactured between April 2013 and July 2014.)						Mos	36		[16-Jun-2019]	1.4 Years
						Hrs	1,200		[7,956.5]	752.6 Hrs
						Ldg				
SL560-26-01A	Transmittal of Meggitt Safety Systems Service Bulletin 26-36 - Thermistors Detectors						RE (-)		Mandatory	
26 A/F Eff: 18-Jun-2007 Complied With						Mos	11-Jul-2008			
						Hrs	4,966			
						Ldg	0			
▼ 27 - FLIGHT CONTROLS										
	Aileron Assembly						RE (O/C)			
27 A/F Unknown Unknown	Left					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
	Aileron Assembly						RE (O/C)			
27 A/F Unknown Unknown	Right					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
	Aileron Trim Actuator						RE (O/C)			
27 A/F 5565450-90 2688-90		0				Mos	12-Nov-2010			
		0				Hrs	5,567.5			
		0				Ldg	5,970			
	Electrical Trim Mixer Actuator						RE (O/C)			
27 A/F 44430-3657 T569		0				Mos	11-Sep-1997			
		0				Hrs	1,483			
		0				Ldg	0			
	Elevator Trim Actuator						RE (O/C)			
27 A/F 5565450-81 NSN	Left	0				Mos	09-Nov-1997			
		0				Hrs	1,564			
		0				Ldg	0			
	Elevator Trim Actuator						RE (O/C)			
27 A/F 5565450-82 NSN	Right	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Flap Actuator						RE (O/C)			
27 A/F 1535000 333	No.1	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
PN/SN	MOC Note or Component Condition								DUE	Remaining	
 27 A/F 1535000 327	Flap Actuator	RE (O/C)									
	No.2	0			Mos	15-Nov-1994					
		0			Hrs	0					
		0			Ldg	0					
 27 A/F 66720 1107	Flap Control Valve	RE (O/C)									
		0			Mos	15-Nov-1994					
		0			Hrs	0					
		0			Ldg	0					
 27 A/F CC50380 NSN	Left Wing - Flap Aft Roller								RE	AWL, Component Time Limits	≈28-May-2029
	Left Inboard	0			Mos	03-Jun-2005					
		0			Hrs	4,272					
		0			Ldg	4,957	5,000		9,957	2,717 Ldg	
 27 A/F CC50380 NSN	Left Wing - Flap Aft Roller								RE	AWL, Component Time Limits	≈28-May-2029
	Left Outboard	0			Mos	03-Jun-2005					
		0			Hrs	4,272					
		0			Ldg	4,957	5,000		9,957	2,717 Ldg	
 27 A/F CC50380 NSN	Left Wing - Flap Aft Roller								RE	AWL, Component Time Limits	≈28-May-2029
	Right Inboard	0			Mos	03-Jun-2005					
		0			Hrs	4,272					
		0			Ldg	4,957	5,000		9,957	2,717 Ldg	
 27 A/F CC50380 NSN	Left Wing - Flap Aft Roller								RE	AWL, Component Time Limits	≈28-May-2029
	Right Outboard	0			Mos	03-Jun-2005					
		0			Hrs	4,272					
		0			Ldg	4,957	5,000		9,957	2,717 Ldg	
 27 A/F CC50380 NSN	Right Wing - Flap Aft Roller								RE	AWL, Component Time Limits	≈28-May-2029
	Left Inboard	0			Mos	03-Jun-2005					
		0			Hrs	4,272					
		0			Ldg	4,957	5,000		9,957	2,717 Ldg	
 27 A/F CC50380 NSN	Right Wing - Flap Aft Roller								RE	AWL, Component Time Limits	≈28-May-2029
	Left Outboard	0			Mos	03-Jun-2005					
		0			Hrs	4,272					
		0			Ldg	4,957	5,000		9,957	2,717 Ldg	
 27 A/F CC50380 NSN	Right Wing - Flap Aft Roller								RE	AWL, Component Time Limits	≈28-May-2029
	Right Inboard	0			Mos	03-Jun-2005					
		0			Hrs	4,272					
		0			Ldg	4,957	5,000		9,957	2,717 Ldg	
 27 A/F CC50380 NSN	Right Wing - Flap Aft Roller								RE	AWL, Component Time Limits	≈28-May-2029
	Right Outboard	0			Mos	03-Jun-2005					
		0			Hrs	4,272					
		0			Ldg	4,957	5,000		9,957	2,717 Ldg	

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
 27 A/F 5565450-71 NSN	Rudder Trim Actuator								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 27 A/F 68930 418	Safety Speed Brake Valve								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 27 A/F 1535500-1 272	Speed Brake Actuator No.1								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 27 A/F 1535500-1 283	Speed Brake Actuator No.2								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 27 A/F 66720 1116	Speed Brake Flap Control Valve								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 2003-23-02 27 A/F Eff: 28-Nov-2003 Not Applicable	Pitch Trim and Autopilot Servo CW SB 560-34-93								RE (-)	Mandatory
					Mos	08-Jan-2004				
					Hrs	3,901				
					Ldg	0				
 2008-19-01 27 A/F Eff: 29-Sep-2008 Not Applicable	Harco Labs - AOA Probes EQUIPMENT NOT INSTALLED								RE (-)	Mandatory (Appliance AD)
					Mos	09-Sep-2014				
					Hrs	6,186				
					Ldg	6,407				
 560-27-08 27 A/F Eff: 23-Jun-1995 Complied With	Rudder Trim Tab Actuator Guard Fastener Replacement								RE (-)	Recommended
					Mos	17-Feb-2004				
					Hrs	3,901				
					Ldg	0				
 560-27-09 27 A/F Complied With	Improved Elevator Trim Sector Installation								RE (-)	Mandatory
					Mos	14-Jan-1996				
					Hrs	594.1				
					Ldg	387				
 560-27-10 27 A/F Eff: 22-Aug-1997 Complied With	Elevator Trim Sector Adjustable Friction Block Installation								RE (-)	Recommended
					Mos	27-Feb-1998				
					Hrs	1,705				
					Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-27-11	Aileron/Rudder Interconnect Clamp Replacement						RE (-)		Recommended	
 27 A/F Eff: 23-Jan-1998 Complied With					Mos	16-Nov-1999				
					Hrs	2,436				
					Ldg	0				
560-27-13	Flight Controls - Trim Tab Actuator Grease Fitting Installation						RE (-)		Optional	
 27 A/F Eff: 09-Feb-2001 Complied With					Mos	27-Nov-2002				
					Hrs	3,568				
					Ldg	0				
560-27-17	Pitch Trim Printed Circuit Board (PCB) Improvement						RE (-)		Mandatory	
 27 A/F Eff: 11-Jan-2005 Complied With					Mos	31-Oct-2005				
					Hrs	4,405				
					Ldg	5,073				
A271003	Aileron and Aileron Trim Tab - Inspect						RE	Continuous Inspection Program	≈10-Sep-2018	
 27 A/F 051202 Ref.:27-11-00-210 (ZONE: 532, 632)					Mos		24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
					Hrs		300	+30 (7,422)	218.1 Hrs (+30)	
					Ldg					
A271004	Control Wheel - Inspect						RE	Continuous Inspection Program	≈10-Sep-2018	
 27 A/F 051201 Ref.:27-11-00-211 (ZONE: 247, 248)					Mos		24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
					Hrs		300	+30 (7,422)	218.1 Hrs (+30)	
					Ldg					
A271005	Aileron, Rudder, and Elevator Trim Tab Control and Indicator - Inspect						RE	Continuous Inspection Program	≈10-Sep-2018	
 27 A/F 051201 Ref.:27-11-00-212 (ZONE: 243)					Mos		24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
					Hrs		300	+30 (7,422)	218.1 Hrs (+30)	
					Ldg					
A271006	Aileron Control Cable - Inspect						RE	Continuous Inspection Program		
 27 A/F 051205 Ref.:27-11-00-222					Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs		1,200	+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					
A271007	Aileron Trim Cable - Inspect						RE	Continuous Inspection Program		
 27 A/F 051205 Ref.:27-11-00-223					Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs		1,200	+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					
A271008	Aileron Trim Tab Actuator Disassembly (with grease fittings) - Inspect						RE	Continuous Inspection Program		
 27 A/F 051205 Ref.:27-11-00-643					Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs		1,200	+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					
A271014	Aileron Drive Bracket - Inspect						T	Continuous Inspection Program	≈02-Jun-2050	
 27 A/F 051232 Ref.:27-11-00-213 (ZONE: 532, 632)					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0	15,000	(15,000)	7,760 Ldg	

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A271015	Aileron Yoke - Inspect								T Continuous Inspection Program	≈02-Jun-2050
 27 A/F	051233				Mos	15-Nov-1994				
Ref.:27-11-00-214 (ZONE: 532, 632)					Hrs	0				
					Ldg	0	15,000		(15,000)	7,760 Ldg
A272002	Rudder and Rudder Trim Tab - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 27 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:27-21-00-210 (ZONE: 321, 340)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A272003	Rudder Pedals - Inspect								RE Continuous Inspection Program	
 27 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:27-21-03-212 (ZONE: 241, 242)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A272005	Rudder Cable - Inspect								RE Continuous Inspection Program	
 27 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:27-21-06-222					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A272006	Rudder Trim Cable - Inspect								RE Continuous Inspection Program	
 27 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:27-21-06-223					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A272007	Rudder Trim Tab Actuator Disassembly (with grease fittings) - Inspect								RE Continuous Inspection Program	
 27 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:27-21-00-643					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A273002	Elevator - Externally inspect								RE Continuous Inspection Program	≈10-Sep-2018
 27 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:27-31-00-210 (ZONE: 331, 332)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A273005	Control Columns - Inspect								RE Continuous Inspection Program	
 27 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:27-31-02-212					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A273006	Elevator Linkage - Inspect								RE Continuous Inspection Program	
 27 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:27-31-00-211 (ZONE: 321, 340)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A273007	Flap/Elevator Electric Trim Mixer Assembly - Inspect								RE Continuous Inspection Program	
 27 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:27-51-00-213					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A273008  27 A/F Ref.:27-31-00-222	Elevator Cable - Inspect 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
A273009  27 A/F Ref.:27-31-00-223	Elevator Trim Cable - Inspect 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
A273010  27 A/F Ref.:27-31-00-643 (ZONE: 331, 332)	Elevator Trim Tab Actuator Disassembly (with grease fittings) - Inspect 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
A275003  27 A/F Ref.:27-51-00-220	Flap Preselect Cable - Inspect 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
A275004  27 A/F Ref.:27-51-00-210 (ZONE: 512, 522,612, 622)	Flap - Inspect 051202						RE 24	Continuous Inspection Program +2 (31-Jul-2019)	1.5 Years (+61 Days)	218.1 Hrs (+30)
					Mos					
					Hrs		300	+30 (7,422)		
					Ldg					
A275007  27 A/F Ref.:27-51-00-211	Flap Bell Cranks - Inspect 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
A275021  27 A/F Ref.:27-51-00-212	Flap Crosstie System - Inspect 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
A275022  27 A/F Ref.:27-31-07-210	Flap/Elevator Trim Mixer Interconnect Cable System - Inspect 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
A276001  27 A/F Ref.:27-61-00-210 (ZONE: 522, 622)	Speed Brake System - Inspect 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B271001  27 A/F Ref.:27-11-00-220	Aileron Trim Tab - Check free play 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B271002  27 A/F Ref.:27-11-00-221	Aileron and Aileron Trim Tab - Check travel 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B272001  27 A/F Ref.:27-21-00-220	Rudder Trim Tab - Check free play 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B272004  27 A/F Ref.:27-21-00-221	Rudder and Rudder Trim Tab - Check travel 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B273003  27 A/F Ref.:27-31-00-221 (ZONE: 331, 332)	Elevator and Elevator Trim Tab - Check travel 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B273004  27 A/F Ref.:27-31-00-220 (ZONE: 331, 332)	Elevator Trim Tab - Check free play 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B273015  27 A/F Ref.:27-31-07-710 (ZONE: AUX)	Elevator Electrical Trim Mixer System - Perform operational check 051201						RE 24	Continuous Inspection Program +2 (31-Jul-2019)	≈10-Sep-2018 1.5 Years (+61 Days)	218.1 Hrs (+30)
					Mos					
					Hrs		300	+30 (7,422)		
					Ldg					
B275004  27 A/F Ref.:27-51-00-712	Flap Approach Warning Switch - Perform operational check 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B275006  27 A/F Ref.:27-51-00-714	Flap - Check travel 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B275009  27 A/F Ref.:27-51-04-790 (ZONE: 512, 612)	Flap Hydraulic Actuator - Perform leak check 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					
B277001  27 A/F Ref.:27-71-00-210	Control Lock System - Inspect and perform operational check 051205						RE 36	Continuous Inspection Program +2 (31-Oct-2019)	1.7 Years (+61 Days)	844.3 Hrs (+100)
					Mos					
					Hrs		1,200	+100 (8,048.2)		
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
C271001	Aileron Trim Tab Actuator - Lubricate, perform operational check and check travel						RE		Continuous Inspection Program	≈10-Sep-2018
27 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:27-11-00-640 (ZONE: 532)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
C272001	Rudder Trim Tab Actuator - Lubricate, perform operational check and travel check						RE		Continuous Inspection Program	≈10-Sep-2018
27 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:27-21-00-640 (ZONE: 241, 340,342)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
C273001	Elevator Trim Tab Actuator - Lubricate, perform operational check and travel check						RE		Continuous Inspection Program	≈10-Sep-2018
27 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:27-31-00-640 (ZONE: AUX, 331, 332)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
SL560-27-05	Aileron/Rudder Interconnect Rigging Inspection						RE (-)		Recommended	
27 A/F					Mos	11-Sep-1997				
Eff: 24-Jan-1997 Complied With					Hrs	1,483				
					Ldg	0				
SL560-27-06	Rudder/Aileron Interconnect Bolt Inspection						RE (-)		Mandatory	
27 A/F					Mos	14-Nov-1997				
Complied With					Hrs	1,582.4				
					Ldg	2,009				
SL560-27-10A	Flight Controls - Electric Elevator Trim Runaway Procedure						RE (-)		Mandatory	
27 A/F					Mos	13-Oct-2003				
Eff: 10-Oct-2003 Complied With					Hrs	3,819.7				
					Ldg	4,469				
SL560-27-13	Rudder Pedal Support Inspection						RE (-)		Recommended	
27 A/F					Mos	12-Nov-2010				
Eff: 13-Feb-2006 Complied With					Hrs	5,567.5				
					Ldg	5,970				
▼ 28 - FUEL										
	Defuel Single Pt Valve						RE (O/C)			
28 A/F	Left				Mos	15-Nov-1994				
61084-2					Hrs	0				
Unknown					Ldg	0				
	Defuel Single Pt Valve						RE (O/C)			
28 A/F	Right				Mos	15-Nov-1994				
61084-2					Hrs	0				
Unknown					Ldg	0				
	Electric Fuel Boost Pump						RE (O/C)			
28 A/F	No.1				Mos	15-Nov-1994				
1C7-12					Hrs	0				
6AK83					Ldg	0				

Task No	Description	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN										DUE	Remaining
 28 A/F 1C7-12 6AK84	Electric Fuel Boost Pump						RE (O/C)				
	No.2		0				Mos	15-Nov-1994			
			0				Hrs	0			
			0				Ldg	0			
 28 A/F 60221-4 Unknown	Fuel Float Valve						RE (O/C)				
	Left		0				Mos	15-Nov-1994			
			0				Hrs	0			
			0				Ldg	0			
 28 A/F 60221-4 Unknown	Fuel Float Valve						RE (O/C)				
	Right		0				Mos	15-Nov-1994			
			0				Hrs	0			
			0				Ldg	0			
 28 A/F L15H-3 6875	Fuel Low Level Switch						RE (O/C)				
	No.1		0				Mos	22-Nov-2005			
			0				Hrs	4,435			
			0				Ldg	0			
 28 A/F L15H-3 NSN	Fuel Low Level Switch						RE (O/C)				
	No.2		0				Mos	15-Nov-1994			
			0				Hrs	0			
			0				Ldg	0			
 28 A/F 300047-13001 16869	Fuel Qty Compensator						RE (O/C)				
	Left		0				Mos	15-Nov-1994			
			0				Hrs	0			
			0				Ldg	0			
 28 A/F 300047-13001 16863	Fuel Qty Compensator						RE (O/C)				
	Right		0				Mos	15-Nov-1994			
			0				Hrs	0			
			0				Ldg	0			
 28 A/F Unknown Unknown	Fuel Vent Float Valve						RE (O/C)				
	Left						Mos	15-Nov-1994			
							Hrs	0			
							Ldg	0			
 28 A/F Unknown Unknown	Fuel Vent Float Valve						RE (O/C)				
	Right						Mos	15-Nov-1994			
							Hrs	0			
							Ldg	0			
 28 A/F 61086 Unknown	Manual Fuel Shutoff Valve						RE (O/C)				
	Left		0				Mos	15-Nov-1994			
			0				Hrs	0			
			0				Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 28 A/F 61086 Unknown	Manual Fuel Shutoff Valve								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 28 A/F 3244850 C29042	Motive Fuel Valve								RE (O/C)	
	Left	0			Mos	10-Dec-2001				
		0			Hrs	3,235				
		0			Ldg	0				
 28 A/F 3244850 C29039	Motive Fuel Valve								RE (O/C)	
	Right	0			Mos	10-Dec-2001				
		0			Hrs	3,235				
		0			Ldg	0				
 28 A/F 61087 Unknown	Pilot High Level Valve								RE (O/C)	
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 28 A/F 61087 Unknown	Pilot High Level Valve								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 28 A/F 840203-103 Unknown	Pressure Relief Valve								RE (O/C)	
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 28 A/F 840203-103 Unknown	Pressure Relief Valve								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 28 A/F 80002-101 Unknown	Single Point Refuel Valve								RE (O/C)	
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 28 A/F 80002-101 Unknown	Single Point Refuel Valve								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
2006-06-03	Airplane Flight Manual (AFM)								RE (-)	Mandatory
 28 A/F Eff: 20-Apr-2006 Complied With					Mos	01-Jun-2006				
					Hrs	4,611				
					Ldg	5,224				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2006-06-03 Paragraph (i)	Airplane Flight Manual (AFM) - Inspection and Modification						RE (-)		Mandatory	
 28 A/F Eff: 20-Apr-2006 Complied With					Mos	01-Jun-2006				
					Hrs	4,611				
					Ldg	5,224				
560-28-05	Improved Fuel Crossfeed Select Knob Availability						RE (-)		Optional	
 28 A/F Eff: 18-Aug-1995 Complied With					Mos	24-Aug-2011				
					Hrs	5,663.6				
					Ldg	6,043				
560-28-06	Left Engine Motive Flow Line Replacement and Clamp Installation						RE (-)		Recommended	
 28 A/F Eff: 24-Jan-1997 Complied With					Mos	11-Sep-1997				
					Hrs	1,483				
					Ldg	0				
560-28-07	Fuel Line Support Installation						RE (-)		Recommended	
 28 A/F Eff: 05-May-1999 Complied With					Mos	10-Dec-2001				
					Hrs	3,235				
					Ldg	0				
560-28-10	Wing Fuel Boost Pump Wire Routing Improvement						RE (-)		Mandatory	
 28 A/F Eff: 23-Apr-2004 Complied With					Mos	10-Jun-2004				
					Hrs	4,040.5				
					Ldg	4,718				
560-28-14	Fuel Check Valve Modification						RE (-)		Recommended	
 28 A/F Complied With					Mos	12-Nov-2010				
					Hrs	5,567.5				
					Ldg	5,970				
A281001	Wing Fuel Storage Area - Inspect						RE	Continuous Inspection Program		
 28 A/F					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:28-10-00-210	051205				Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A282002	Wing Fuel System Component (Inboard of wing root) - Inspect.						RE	Continuous Inspection Program		
 28 A/F					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:28-20-00-211	051205				Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B282003	Fuel System - Perform operational check						RE	Continuous Inspection Program		
 28 A/F					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:28-20-00-710	051205				Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B282004	Fuel System - Perform operational check						RE	Continuous Inspection Program		
 28 A/F					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:28-20-00-711	051205				Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B284001	Low Fuel Warning System - Perform operational check									
 28 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:28-42-00-710					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
D282002	Fuel Filter Element - Change									
 28 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:28-21-05-900 (ZONE: 512, 612)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
SIL No. GEN-108 R2	Jet Fuel Containing Fatty Acid Methyl Esters (FAME)									
 28 ENG1					Mos				T (A/R)	Service Information Letter
Eff: 01-Nov-2017					Hrs					
					Enc					
SL560-28-03A	Transmittal of Parker Hannifin Corporation - Airborne Air & Fuel Products Service Letter No. 41, RAPCO Fleet Support Inc. Overhaul of Airborne Fuel Pumps									
 28 A/F					Mos	03-Jul-1996			RE (-)	Mandatory
Complied With					Hrs	822				
					Ldg	0				
SL560-28-03A R01	Transmittal of Parker Hannifin Corporation - Airborne Air & Fuel Products Service Letter No. 41, RAPCO Fleet Support Inc. Overhaul of Airborne Fuel Pumps									
 28 A/F					Mos	03-Jul-1996			RE (-)	Mandatory
Eff: 19-Jul-1996 Complied With					Hrs	822				
					Ldg	0				
▼ 29 - HYDRAULIC POWER										
	Check Valve Hydraulic Flow Switch									
 29 A/F	No.1				Mos	15-Nov-1994			RE (O/C)	
3520020100-4		0			Hrs	0				
3493		0			Ldg	0				
	Check Valve Hydraulic Flow Switch									
 29 A/F	No.2				Mos	15-Nov-1994			RE (O/C)	
3520020100-4		0			Hrs	0				
3495		0			Ldg	0				
	Hydraulic Pressure Switch									
 29 A/F					Mos	15-Nov-1994			RE (O/C)	
1106P59		0			Hrs	0				
Unknown		0			Ldg	0				
	Hydraulic Pump									
 29 A/F	Left				Mos	11-Jan-2002			RE (O/C)	
24195-LAA		0			Hrs	3,250				
3544		0			Ldg	0				
	Hydraulic Pump									
 29 A/F	Right				Mos	15-Nov-1994			RE (O/C)	
24195-LAA		0			Hrs	0				
5268		0			Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 29 A/F 40500-7 532	Main Hyd Reservoir	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
 29 A/F AV24B1325C5 P50543	Motor Actuator Valve	0			Mos	15-Nov-1994			RE (O/C)	
	No.1	0			Hrs	0				
		0			Ldg	0				
 29 A/F AV24B1325C5 P27533	Motor Actuator Valve	0			Mos	15-Nov-1994			RE (O/C)	
	No.2	0			Hrs	0				
		0			Ldg	0				
 29 A/F 4614 162A	Pressure Relief Valve	0			Mos	13-Jan-2014			RE (O/C)	
		0			Hrs	6,057.9				
		0			Ldg	6,315				
 29 A/F 61510-1 1107A	Solenoid Bypass Valve	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
 29 A/F OAS5322-3-1700 328	Thermal Relief Valve	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
560-29-02	Improved Hydraulic Pump Pressure Hose Installation								RE (-)	Recommended
 29 A/F Eff: 12-Apr-1996 Complied With					Mos	10-Aug-1996				
					Hrs	866				
					Ldg	0				
560-29-04	Hydraulic Tube Replacement (Supplemental Data Revision)								RE (-)	Mandatory
 29 A/F Eff: 30-Jan-2004 Complied With					Mos	30-Jul-2003				
					Hrs	3,783.1				
					Ldg	4,322				
560-29-05 R01	Hydraulic Power - Landing Gear Return Line Check Valve Replacement								RE (-)	Mandatory
 29 A/F Eff: 23-Aug-2001 Complied With					Mos	27-Nov-2002				
					Hrs	3,568.3				
					Ldg	4,192				
560-29-08	Hydraulic Pressure Line Routing Improvement								RE (-)	Recommended
 29 A/F Complied With					Mos	12-Dec-2012				
					Hrs	5,567.5				
					Ldg	5,970				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-29-08 R01	Hydraulic Pressure Line Routing Improvement								RE (-)	Recommended
 29 A/F Eff: 10-Feb-2011 Complied With						Mos	12-Dec-2012			
						Hrs	5,567.5			
						Ldg	5,970			
A291002	Hydraulic Sub-Panel - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 29 A/F						Mos	21-Jul-2017	24	+2	≈21-Jul-2019
	051201,...					Hrs	7,122	300	+30	≈7,422
	Ref.:29-11-06-210 (ZONE: 311)					Ldg	7,168			
D291001	Hydraulic Filters and Filter Element - Inspect and replace filter element								RE Continuous Inspection Program	
 29 A/F						Mos		36	+2	(31-Oct-2019) 1.7 Years (+61 Days)
	051205					Hrs		1,200	+100	(8,048.2) 844.3 Hrs (+100)
	Ref.:29-11-04-901 (ZONE: 311, 312)					Ldg				
SL560-29-04	Hydraulic Line Installation Inspection (SUPERSEDED)								RE (-)	Service Letter
 29 A/F Eff: 18-Aug-1999 Complied With						Mos	16-Nov-1999			
						Hrs	2,436			
						Ldg	0			
▼ 30 - ICE AND RAIN PROTECTION										
	Alcohol Windshield Anti-Ice Pump								RE (O/C)	
 30 A/F 476411 NSN		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Anti Icing Valve								RE (O/C)	
 30 A/F 540-0406-4 2562	Left	0				Mos	14-Dec-2015			
		0				Hrs	6,610.9			
		0				Ldg	6,759			
	Anti Icing Valve								RE (O/C)	
 30 A/F 540-0406-4 2718	Right	0				Mos	15-Dec-2015			
		0				Hrs	6,610.9			
		0				Ldg	6,759			
	Anti-Ice Bleed Air Wndshld Heat Exchanger								RE (O/C)	
 30 A/F 10663A 187		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Anti-Ice Bleed Air Wndshld Heat Exchanger Press S130 Switch								RE (O/C)	
 30 A/F 1115P25 2262A		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Anti-Ice Bleed Air Wndshld Temp XMTR26 Sensor								RE (O/C)	
 30 A/F 27231272-20A 8AK18		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 30 A/F 1169-1 2146	Bleed Air Monitor								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F 800888-1 F30960	Bleed Valve Actuator								RE (O/C)	
	Left	0			Mos	10-Dec-2001				
		0			Hrs	3,235				
		0			Ldg	0				
 30 A/F 800888-1 F22028	Bleed Valve Actuator								RE (O/C)	
	Right	0			Mos	15-Dec-2015				
		0			Hrs	6,610.9				
		0			Ldg	6,759				
 30 A/F 3D2353-06 N12722	Deice Control Slv18 Valve								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F 3D2353-06 N4589	Deice Control Slv19 Valve								RE (O/C)	
	Left	0			Mos	12-Nov-2010				
		0			Hrs	5,567.5				
		0			Ldg	5,970				
 30 A/F 1106P55-1 Unknown	Deice Pressure ST003 Switch								RE (O/C)	
	No.1	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F 1106P55-1 Unknown	Deice Pressure ST004 Switch								RE (O/C)	
	No.2	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F 67410-1 201ABCDEG	Engine Anti-Ice Solenoid Valve								RE (O/C)	
	Left	0			Mos	11-Sep-1997				
		0			Hrs	1,483				
		0			Ldg	0				
 30 A/F 67410-1 538	Engine Anti-Ice Solenoid Valve								RE (O/C)	
	Right	0			Mos	06-Jan-1997				
		0			Hrs	1,125				
		0			Ldg	0				
 30 A/F P29S-5D5225-05 MCJK810	Horizontal Stabilizer Deice Boot								RE (O/C)	
	No.1	0			Mos	12-Nov-2010				
		0			Hrs	5,567.5				
		0			Ldg	5,970				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 30 A/F 29S-5D5225-06 MCFD410	Horizontal Stabilizer Deice Boot								RE (O/C)	
	No.2	0			Mos	12-Nov-2010				
		0			Hrs	5,567.5				
		0			Ldg	5,970				
 30 A/F P35-5D5230-01 MANQ000	Outbrd Wing Deice Boot								RE (O/C)	
	No.1	0			Mos	12-Nov-2010				
		0			Hrs	5,567.5				
		0			Ldg	5,970				
 30 A/F P35-5D5230-02 MAZF400	Outbrd Wing Deice Boot								RE (O/C)	
	No.2	0			Mos	12-Nov-2010				
		0			Hrs	5,567.5				
		0			Ldg	5,970				
 30 A/F PH502 NSN	Pitot Tube								RE (O/C)	
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F PH502 NSN	Pitot Tube								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F Unknown Unknown	Pitot Tube								RE (O/C)	
	StandBy				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 30 A/F 27441500-01 4AK21	Ram Air Modulating Temp Control Valve								RE (O/C)	
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F 27441500-01 4AK22	Ram Air Modulating Temp Control Valve								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F 27431501-04 7AK28	Temp Control S94 Sensor								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 30 A/F 27431501-04 7AK29	Temp Control S95 Sensor								RE (O/C)	
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
 30 A/F 1173T42-3 1511	Temp Control SI002 Switch Left						RE (O/C)			
		0				Mos	15-Nov-1994			
		0				Hrs	0			
 30 A/F 1173T42-3 1505	Temp Control SR002 Switch Right						RE (O/C)			
		0				Mos	15-Nov-1994			
		0				Hrs	0			
 30 A/F 27241287 10A1129	Temp Control Valve						RE (O/C)			
		0				Mos	09-Nov-2000			
		0				Hrs	2,891			
 30 A/F 67410-2 2639ABCE	Windshield Anti-Ice Bleed Air Control Valve						RE (O/C)			
		0				Mos	15-Nov-1994			
		0				Hrs	0			
 30 A/F 1H123-1 8AK37	Wing Anti-Ice Bleed Air Crossflow Isolation Valve						RE (O/C)			
		0				Mos	15-Nov-1994			
		0				Hrs	0			
 30 A/F 67410-2 2659ABCE	Wing Anti-Ice Bleed Air Pressure Reg Shutoff Vt001 Valve Left						RE (O/C)			
		0				Mos	15-Nov-1994			
		0				Hrs	0			
 30 A/F 67410-2 2648ABCE	Wing Anti-Ice Bleed Air Pressure Reg Shutoff Vt002 Valve Right						RE (O/C)			
		0				Mos	15-Nov-1994			
		0				Hrs	0			
 30 A/F Ref.:30-14-00-710	Ice and Rain Protection - Wing Anti-Ice Crossfeed Valve - Operational Check						RE (N/A)			
						Mos	Inspection Time Limits			
						Hrs				
 30 A/F Eff: 10-Dec-2001 Complied With	Ice and Rain Protection - Windshield Anti-Ice Bleed Air Switch Inspection/Replacement						T (A/R)			
						Mos	03-Jun-2002			
						Hrs	3,438.6			
 30 A/F Eff: 27-Mar-2008 Complied With	Engine Inlet Anti-Ice Valve Support Bracket Installation						RE (-)			
						Mos	12-Nov-2010			
						Hrs	5,567.5			
						Ldg	5,970			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
98-04-38	AFM - Limitations Section - Icing						RE (-)		Mandatory	
 30 A/F						Mos	05-May-1998			
	Eff: 25-Mar-1998 Complied With					Hrs	1,782.3			
						Ldg	2,262			
A301001	Left Wing Heated Leading Edge Bleed Air Outlet Holes - Inspect						RE (N/A)		Continuous Inspection Program	
 30 A/F						Mos				
	Ref.:30-11-00-213 (ZONE: 511, 611)					Hrs				
						Ldg				
A301002	Wing Heated Leading Edge and Plumbing - Inspect						RE (N/A)		Continuous Inspection Program	
 30 A/F						Mos				
	Ref.:30-11-00-210					Hrs				
						Ldg				
A301003	Wing Heated Leading Edge Bleed Air Components - Inspect						RE (N/A)		Continuous Inspection Program	
 30 A/F						Mos				
	Ref.:30-11-00-212 (ZONE: 511, 512,611, 612)					Hrs				
						Ldg				
A301004	Wing Heated Leading Edge Anti-Ice Tailcone Components - Inspect						RE (N/A)		Continuous Inspection Program	
 30 A/F						Mos				
	Ref.:30-11-00-211 (ZONE: 311, 312)					Hrs				
						Ldg				
A301005	Right Wing Heated Leading Edge Bleed Air Outlet Holes - Inspect						RE (N/A)		Continuous Inspection Program	
 30 A/F						Mos				
	Ref.:30-14-00-213 (ZONE: 511, 611)					Hrs				
						Ldg				
A301006	Wing Heated Leading Edge and Plumbing - Inspect						RE (N/A)		Continuous Inspection Program	
 30 A/F						Mos				
	Ref.:30-14-00-210					Hrs				
						Ldg				
A301008	Wing Heated Leading Edge Anti-Ice Tailcone Components - Inspect						RE (N/A)		Continuous Inspection Program	
 30 A/F						Mos				
	Ref.:30-14-00-211 (ZONE: 311, 312)					Hrs				
						Ldg				
A301009	Inboard Wing Deice Boot - Inspect						RE (N/A)		Continuous Inspection Program	
 30 A/F						Mos				
	Ref.:30-12-00-280 (ZONE: 521, 621)					Hrs				
						Ldg				
A304001	Windshield Bleed Air Augmenter Door and Shroud - Inspect						RE		Continuous Inspection Program	
 30 A/F						Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
	051205					Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
	Ref.:30-41-00-210 (ZONE: 221, 222)					Ldg				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A304003	Windshield Bleed Air Controls - Inspect						RE		Continuous Inspection Program	
 30 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:30-41-04-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A304004	Windshield Alcohol Reservoir - Inspect						RE		Continuous Inspection Program	
 30 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:30-42-00-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B301001	Wing Bleed Air Anti-Ice System - Perform operational test						RE		Continuous Inspection Program	
 30 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:30-11-00-710					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B301002	Wing Anti-Ice Crossflow Valve Operational Check - Perform (Chapter 4 Item)						RE (N/A)		Continuous Inspection Program	
 30 A/F					Mos					
1H123-1					Hrs					
8AK37					Ldg					
Ref.:30-14-00-710 (ZONE: ENG)										
B301003	Pneumatic Deice System - Perform operational check						RE		Continuous Inspection Program	≈10-Sep-2018
 30 A/F	051204				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:30-12-00-710 (ZONE: ENG)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
B301005	Wing Bleed Air Anti-Ice Systems - Perform operational test						RE		Continuous Inspection Program	
 30 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:30-14-00-712					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B301006	Pneumatic Deice System - Perform operational check						RE		Continuous Inspection Program	≈10-Sep-2018
 30 A/F	051204				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:30-12-00-711 (ZONE: ENG)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
B304001	Windshield Anti-Ice - Perform operational check						RE		Continuous Inspection Program	
 30 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:30-41-00-710					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B304004	Windshield Alcohol Pump - Perform operational test						RE		Continuous Inspection Program	≈10-Sep-2018
 30 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:30-42-00-710 (ZONE: AUX)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
D304004	Windshield Alcohol Reservoir Filter - Inspect and clean						RE		Continuous Inspection Program	
 30 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:30-42-00-130					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560-30-07A	Ice And Rain Protection - Approach And Landing In Icing Conditions Addition To Flight Manual								RE (-)	Mandatory
 30 A/F Complied With						Mos	06-Jan-1997			
						Hrs	1,125			
						Ldg	0			
▼ 31 - INDICATING / RECORDING SYSTEM										
	Accelerometer								RE (O/C)	
 31 A/F 7000992 6862	No.1	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Accelerometer								RE (O/C)	
 31 A/F 7000992 6863	No.2	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Digital Clock								RE (O/C)	
 31 A/F M877A5V 5834	Copilot	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Digital Clock								RE (O/C)	
 31 A/F M877A5V 5828	Pilot	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	EGPWS Accelerometer								RE (O/C)	
 31 A/F 979-0223-001 1191		0				Mos	02-Apr-1997			
		0				Hrs	1,224			
		0				Ldg	0			
	Fairchild F1000 Underwater Locator Beacon								RE (O/C)	Component Time Limits
 31 A/F Unknown Unknown						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
	FDR Impact Switch								RE (O/C)	
 31 A/F 6895-D-2-X-5-5 Unknown		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Flight Data Recorder								RE (O/C)	
 31 A/F C664503-0104 NSN		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	Master Warning Annunciator								RE (O/C)	
 31 A/F 465-1-17 582		0				Mos	12-Nov-2010			
		0				Hrs	5,567.5			
		0				Ldg	5,970			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
2002-20-09	Rockwell Collins - Adaptive flight display units									
31 A/F Eff: 12-Nov-2002 Not Applicable Brand A:9990-2002-20-09	EQUIPMENT NOT INSTALLED				Mos	09-Sep-2014		RE (-)	Mandatory (Appliance AD)	
					Hrs	6,186				
					Ldg	6,407				
5-11-00(2)(F)(1)	Indicating/Recording - Sundstrand Flight Data Recorder - Perform maintenance per schedule published in SundstrandService Information Letter							RE (N/A)	Component Time Limits	
31 A/F C664503-0104 NSN					Mos					
					Hrs					
					Ldg					
560-31-09	Indicating/ Recording Systems - Inadvertent Power Brake Low Pressure Annunciation							RE (-)	Recommended	
31 A/F Eff: 31-Jan-2001 Complied With					Mos	27-Nov-2002				
					Hrs	3,568				
					Ldg	0				
A313001	Flight Data Recorder - Inspect							RE	Continuous Inspection Program	
31 A/F Ref.:31-30-00-210	051205				Mos			36	+2 (31-Oct-2019)	1.7 Years (+61 Days)
					Hrs			1,200	+100 (8,048.2)	844.3 Hrs (+100)
					Ldg					
A313002	Underwater Locator Beacon Installed on Flight Data Recorder - Inspect							RE (N/A)	Continuous Inspection Program	
31 A/F Unknown Unknown Ref.:31-30-00-211 (ZONE: 312)	051221				Mos					
					Hrs					
					Ldg					
B313002	Underwater Locator Beacon Installed on Flight Data Recorder - Perform operational test							RE (N/A)	Continuous Inspection Program	
31 A/F Unknown Unknown Ref.:31-30-00-280 (ZONE: 312)	051221				Mos					
					Hrs					
					Ldg					
CIL-31-01	Indicating/Recording Systems - CVR, FDR, and CVDR 90-Day Battery Underwater Locator Beacon (ULB) Installation							T (A/R)	Service Letter, Informational	
31 A/F Eff: 02-Feb-2018 (NOTE: EFFECTIVITY: All Citation airplanes that are equipped with a Textron Aviation engineered CVR, FDR, or CVDR installation.)					Mos					
					Hrs					
					Ldg					
▼ 32 - LANDING GEAR										
	Anti-skid Accumulator							RE (O/C)		
32 A/F 57C57652 RH0765		0			Mos	15-Nov-1994				
		0			Hrs		0			
		0			Ldg		0			
	Brake Control Box							RE (O/C)		
32 A/F 42-927-1 178		0			Mos	10-Aug-1996				
		0			Hrs		866			
		0			Ldg		0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
32 A/F 634343 NSN	Brake Press Pump Assembly	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
32 A/F OAS5319-1 376	Dump Valve	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
32 A/F 2341128 30718D	Emergency Air Bottle Gauge	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
32 A/F 895232-0875 397	Emergency Air Brake Valve	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
32 A/F 42-92750 151A	Fault Display Unit	0			Mos	21-Oct-1995			RE (O/C)	
		0			Hrs	505				
		0			Ldg	0				
32 A/F 66710 200	Landing Gear Control Valve	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
32 A/F 1EN118-6 Unknown	Main Gear Down & Lock Switch Left	0			Mos	08-Nov-1997			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
32 A/F 1EN118-6 NSN	Main Gear Down & Lock Switch Right	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
32 A/F 65-430087 NSN	Main Gear Up & Locked Switch Left	0			Mos	17-Sep-2007			RE (O/C)	
		0			Hrs	5,396				
		0			Ldg	0				
32 A/F 65-430087 NSN	Main Gear Up & Locked Switch Right	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
32 A/F 1523100-7 389 (NOTE: Note: Teijin Seiki)	Main Landing Gear Actuator Assembly						RE	AWL, Component Time Limits		≈02-Jun-2050
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	15,000		15,000	7,760 Ldg
32 A/F 1523100-8 379 (NOTE: Note: Teijin Seiki)	Main Landing Gear Actuator Assembly						RE	AWL, Component Time Limits		≈02-Jun-2050
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	15,000		15,000	7,760 Ldg
32 A/F 6641000-35 108	Main Landing Gear Assembly and Attaching Hardware						RE	AWL, Component Time Limits		≈10-Jul-2035
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	11,425		11,425	4,185 Ldg
32 A/F 6641000-36 112	Main Landing Gear Assembly and Attaching Hardware						RE	AWL, Component Time Limits		≈10-Jul-2035
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	11,425		11,425	4,185 Ldg
32 A/F 9912569-3 Unknown	Main Landing Gear Brace Actuator						RE	AWL, Component Time Limits		≈02-Oct-2184
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	50,100		50,100	42,860 Ldg
32 A/F 9912569-2 Unknown	Main Landing Gear Brace Actuator						RE	AWL, Component Time Limits		≈02-Oct-2184
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	50,100		50,100	42,860 Ldg
32 A/F 2-1529-7 2633	Main Landing Gear Brake Assembly						RE (O/C)			
	Left	0			Mos	21-Oct-2016				
		0			Hrs	6,848.2				
		0			Ldg	6,940				
32 A/F Unknown Unknown	Main Landing Gear Brake Assembly						RE (O/C)			
	Right	0			Mos	21-Oct-2016				
		0			Hrs	6,848.2				
		0			Ldg	6,940				
32 A/F Unknown Unknown	Main Landing Gear Oleo Assembly Except Outer Bearing Assembly						RE (O/C)	AWL, Component Time Limits		
	Left				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
32 A/F Unknown Unknown	Main Landing Gear Oleo Assembly Except Outer Bearing Assembly						RE (O/C)	AWL, Component Time Limits		
	Right				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				

Task No	Description								Categories	Time
PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
 32 A/F Unknown Unknown	Main Landing Gear Oleo Assembly Outer Bearing Assembly Left						RE (O/C)	AWL, Component Time Limits		
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 32 A/F Unknown Unknown	Main Landing Gear Oleo Assembly Outer Bearing Assembly Right						RE (O/C)	AWL, Component Time Limits		
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 32 A/F 195-183 2507	Main Landing Gear Shuttle Valve Left						RE (O/C)			
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
 32 A/F 195-183 2931	Main Landing Gear Shuttle Valve Right						RE (O/C)			
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
 32 A/F 220K28-1 63412620	Main Landing Gear Tire Left New						RE (O/C)			
						Mos	02-Feb-2018			
		0				Hrs	7,203.9			
		0				Ldg	7,240			
 32 A/F 220K28-1 63542624	Main Landing Gear Tire Right New						RE (O/C)			
						Mos	02-Feb-2018			
		0				Hrs	7,203.9			
		0				Ldg	7,240			
 32 A/F 5541220-2 NSN	Main Landing Gear Torque Link Bolt Left						RE	AWL, Component Time Limits	≈18-Jul-2027	
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0	9,510	9,510	2,270 Ldg
 32 A/F 5541220-2 NSN	Main Landing Gear Torque Link Bolt Right						RE	AWL, Component Time Limits	≈18-Jul-2027	
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0	9,510	9,510	2,270 Ldg
 32 A/F Unknown Unknown	Main Landing Gear Trailing Link Assembly Left						RE (O/C)	AWL, Component Time Limits		
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 32 A/F Unknown Unknown	Main Landing Gear Trailing Link Assembly Right						RE (O/C)	AWL, Component Time Limits		
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			

Task No	Description								Categories	Time
PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
 32 A/F 5522710-15 NSN	Main Landing Gear Trunnion Fitting						RE		AWL, Component Time Limits	≈02-May-2083
	Aft - Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	22,900		22,900	15,660 Ldg
 32 A/F 5522710-15 NSN	Main Landing Gear Trunnion Fitting						RE		AWL, Component Time Limits	≈02-May-2083
	Aft - Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	22,900		22,900	15,660 Ldg
 32 A/F 6522057-5 NSN	Main Landing Gear Trunnion Fitting						RE		AWL, Component Time Limits	≈02-May-2083
	Fwd - Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	22,900		22,900	15,660 Ldg
 32 A/F 6522057-6 NSN	Main Landing Gear Trunnion Fitting						RE		AWL, Component Time Limits	≈02-May-2083
	Fwd - Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	22,900		22,900	15,660 Ldg
 32 A/F Unknown Unknown	Main Landing Gear Trunnion Machining						RE (O/C)		AWL, Component Time Limits	
	Left				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 32 A/F Unknown Unknown	Main Landing Gear Trunnion Machining						RE (O/C)		AWL, Component Time Limits	
	Right				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 32 A/F 5527504-2 WMP1508	Main Landing Gear Uplock Actuator						RE (O/C)			
	Left	0			Mos	06-Mar-2012				
		0			Hrs	5,666.4				
		0			Ldg	6,046				
 32 A/F 5527504-2 3477	Main Landing Gear Uplock Actuator						RE (O/C)			
	Right	0			Mos	06-Mar-2012				
		0			Hrs	5,666.4				
		0			Ldg	6,046				
 32 A/F 3-1490-1 28001315	Main Landing Gear Wheel Assembly						RE (O/C)			
	Left	0			Mos	25-Sep-2012				
		0			Hrs	5,794.9				
		0			Ldg	6,121				
 32 A/F 3-1490-1 2355	Main Landing Gear Wheel Assembly						RE (O/C)			
	Right	0			Mos	13-Jan-2014				
		0			Hrs	6,057.9				
		0			Ldg	6,315				

Task No	Description	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
	PN/SN									DUE	Remaining
	32 A/F 40-955 3136	Main Landing Gear Wheel Transducer						RE (O/C)			
		Left	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	32 A/F 40-955 3099	Main Landing Gear Wheel Transducer						RE (O/C)			
		Right	0			Mos	16-May-1995				
			0			Hrs	290				
			0			Ldg	0				
	32 A/F Unknown Unknown	Metering Valve						RE (O/C)			
						Mos	15-Nov-1994				
						Hrs	0				
						Ldg	0				
	32 A/F 95367-9 849	MLG Master Brake Cylinder						RE (O/C)			
		Copilot - Left	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	32 A/F 95367-10 1320	MLG Master Brake Cylinder						RE (O/C)			
		Copilot - Right	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	32 A/F 95367-10 1289	MLG Master Brake Cylinder						RE (O/C)			
		Pilot - Left	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	32 A/F 95367-9 848	MLG Master Brake Cylinder						RE (O/C)			
		Pilot - Right	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	32 A/F 1EN118-6 Unknown	Nose Gear Down & Lock Switch						RE (O/C)			
			0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	32 A/F 65-430087 NSN	Nose Gear Up & Locked Switch						RE (O/C)			
			0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	32 A/F 1523200-9 1522B (NOTE: Note: Teijin Seiki)	Nose Landing Gear Actuator Assembly						RE	AWL, Component Time Limits	≈19-Jul-2056	
			0			Mos	21-Nov-2013				
			0			Hrs	6,025.6				
			4,817			Ldg	6,288	15,000		16,471	9,231 Ldg

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
 32 A/F 6642000-34 4 (NOTE: except Fork and Piston Assembly (Part Number 6642000-3, -209))	Nose Landing Gear Assembly and Attaching Hardware						RE	AWL, Component Time Limits	≈02-Mar-2084	
		0 Mos 15-Nov-1994								
		0 Hrs 0								
		0 Ldg 0 23,100						23,100	23,100	15,860 Ldg
 32 A/F 6642000-3 NSN	Nose Landing Gear Fork and Piston Assembly						RE	AWL, Component Time Limits	≈02-Sep-2043	
		0 Mos 15-Nov-1994								
		0 Hrs 0								
		0 Ldg 0 13,380						13,380	13,380	6,140 Ldg
 32 A/F 6613056-3 NSN	Nose Landing Gear Trunnion Support Left						RE	AWL, Component Time Limits	≈02-Mar-2037	
		0 Mos 15-Nov-1994								
		0 Hrs 0								
		0 Ldg 0 11,820						11,820	11,820	4,580 Ldg
 32 A/F 6613056-4 NSN	Nose Landing Gear Trunnion Support Right						RE	AWL, Component Time Limits	≈02-Mar-2037	
		0 Mos 15-Nov-1994								
		0 Hrs 0								
		0 Ldg 0 11,820						11,820	11,820	4,580 Ldg
 32 A/F 5543001-11 680A	Nose Shimmy Damper						RE (O/C)			
		0 Mos 02-Mar-2016								
		0 Hrs 6,670.9								
		0 Ldg 6,799								
 32 A/F 5565624-19 NSN	Nose Steering Bungee Assembly						RE (O/C)			
		0 Mos 15-Nov-1994								
		0 Hrs 0								
		0 Ldg 0								
 32 A/F 184F13-5 62332772	Nose Tire						RE (O/C)			
		0 Mos 16-Nov-2016								
		0 Hrs 6,890.6								
		0 Ldg 6,974								
 32 A/F 5527504-2 1389	Nose Uplock Actuator						RE (O/C)			
		0 Mos 15-Nov-1994								
		0 Hrs 0								
		0 Ldg 0								
 32 A/F 3-1418 3945	Nose Wheel Assembly						RE (O/C)			
		0 Mos 02-Jan-2004								
		0 Hrs 3,894								
		0 Ldg 4,553								
 32 A/F 95905 215A	Parking Brake Valve						RE (O/C)			
		0 Mos 15-Nov-1994								
		0 Hrs 0								
		0 Ldg 0								

Task No	Description					TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition												DUE	Remaining
	Pneumatic Blowdown/Emergency Brake Bottle										RE		Component Time Limits	
	32 A/F 212940-2 1046 Manufactured Date 15-Nov-1994 (NOTE: NOTE: Manufactured by HTL Advanced Technology/Pacific Scientific)		0			Yrs	15-Nov-1994	24		[31-May-2018]	3.7 Months			
			0			Hrs	0							
			0			Ldg	0							
	Power Brake Antiskid Valve										RE (O/C)			
	32 A/F 38-707-2 805		0			Mos	21-Oct-1995							
			0			Hrs	505							
			0			Ldg	0							
	Power Brake Assembly Motor										RE (O/C)			
	32 A/F MP50B1 723		0			Mos	03-Feb-1999							
			0			Hrs	2,105							
			0			Ldg	0							
	Pressure Switch										RE (O/C)			
	32 A/F 1206P27 3238		0			Mos	10-Jan-2003							
			0			Hrs	3,599							
			0			Ldg	4,230							
	Right Main Landing Gear Oleo Upper Cap Life Limit										RE		≈02-Jun-2160	
	32 A/F 6541521-2, 3 Unknown		0			Mos	15-Nov-1994							
			0			Hrs	0							
			0			Ldg	0	41,400		41,400	34,160 Ldg			
2006-18-08	Goodyear Aviation - Nosewheel tires	 32 A/F Eff: 11-Oct-2006 Not Applicable Brand A:9990-2006-18-08	EQUIPMENT NOT INSTALLED							RE (-)		Mandatory (Appliance AD)		
						Mos	09-Sep-2014							
						Hrs	6,186							
						Ldg	6,407							
2012-17-01	Goodyear - Landing gear	 32 A/F Eff: 13-Sep-2012 Not Applicable Brand A:9990-2012-17-01	P/N NOT INSTALLED							RE (-)		Mandatory (Appliance AD)		
						Mos	28-Aug-2014							
						Hrs	6,186							
						Ldg	6,407							
5-11-00(2)(G)(11)	Pneumatic Blowdown/Emergency Brake Bottle - Recertification	 32 A/F 212940-2 1046 Hydrostatic Tested Date 03-Oct-2017 (AVG MAN HRS: 0) (APX COST [USD]: 0)								RE (A/R)		Component Time Limits		
						Yrs	11-Oct-2017							
						Hrs	7,170.5							
						Ldg	7,207							
5-11-00(2)(G)(12)	Pneumatic (Nitrogen) Storage Bottle - Hydrostatic Test	 32 A/F 212940-2 1046 Hydrostatic Tested Date 03-Oct-2017 Ref.:32-31-09-280 (AVG MAN HRS: 0) (APX COST [USD]: 0)								RE		Component Time Limits		
						Mos	11-Oct-2017	36		31-Oct-2020	2.7 Years			
						Hrs	7,170.5							
						Ldg	7,207							

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-32-12	9912305-09 Anti-Skid Fault Detector Inspection/Replacement  32 A/F Eff: 18-Aug-1995 Complied With					Mos 21-Oct-1995 Hrs 505 Ldg 0	RE (-)		Recommended	
560-32-13	Gear Warning Horn Filter Capacitor Installation  32 A/F Eff: 10-Nov-1995 Complied With					Mos 14-Aug-1996 Hrs 866 Ldg 0	RE (-)		Recommended	
560-32-14	Antiskid Control Unit Replacement  32 A/F Eff: 24-May-1996 Complied With					Mos 10-Aug-1996 Hrs 866 Ldg 0	RE (-)		Recommended	
560-32-15	Antiskid Drive Clip Replacement  32 A/F Eff: 24-May-1996 Complied With					Mos 10-Aug-1996 Hrs 866 Ldg 0	RE (-)		Recommended	
560-32-16	Transmittal of BFGoodrich Service Bulletin 195-183-32-1, Landing Gear - Main Brake Shuttle Valve Improvements  32 A/F Eff: 19-Jul-1996 Complied With					Mos 02-Apr-1997 Hrs 1,224 Ldg 0	RE (-)		Recommended	
560-32-17	Power Brake Hydraulic Pump Screw Replacement  32 A/F Complied With					Mos 11-Sep-1997 Hrs 1,483 Ldg 0	RE (-)		Recommended	
560-32-18	Antiskid System Diode Removal  32 A/F Eff: 20-Feb-1998 Complied With					Mos 03-Feb-1999 Hrs 2,105 Ldg 0	RE (-)		Recommended	
560-32-19	Brake Motor Coupling Replacement  32 A/F Eff: 10-Apr-1998 Complied With					Mos 03-Feb-1999 Hrs 2,105 Ldg 0	RE (-)		Recommended	
560-32-20 R01	Brake Line Replacement  32 A/F Eff: 05-Apr-1999 Complied With					Mos 27-Nov-2002 Hrs 2,568 Ldg 0	RE (-)		Recommended	
560-32-22 R03	Landing Gear On Ground Operation Modification  32 A/F Eff: 12-Mar-1999 Complied With					Mos 10-Dec-2001 Hrs 3,235 Ldg 0	RE (-)		Recommended	

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-32-27  32 A/F Complied With	NLG Actuator Replacement					Mos 17-Nov-2004 Hrs 4,120 Ldg 0	RE (-)		Mandatory	
560-32-27 R01  32 A/F Complied With	NLG Actuator Replacement					Mos 17-Nov-2004 Hrs 4,120 Ldg 0	RE (-)		Mandatory	
560-32-27 R02  32 A/F Eff: 08-Oct-2004 Complied With	NLG Actuator Replacement					Mos 17-Nov-2004 Hrs 4,120 Ldg 0	RE (-)		Mandatory	
560-32-33  32 A/F Eff: 09-Mar-2006 Complied With	Brake Hydraulic Pack Filter Bowl Replacement					Mos 12-Nov-2010 Hrs 5,567.5 Ldg 5,970	RE (-)		Recommended	
95-24-10  32 A/F Eff: 21-Feb-1996 Not Applicable	Michelin 22 x 5.75 12/10PR Tires EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory (Appliance AD)	
A320001  32 A/F Ref.:32-00-00-210 (ZONE: 710, 720,730)	Landing Gear General Visual Inspection (Corrosion Inspection)					Mos Hrs Ldg	RE (N/A)		Continuous Inspection Program	
A320002  32 A/F 051218 Ref.:32-00-00-210 (AVG MAN HRS: 0) (APX COST [USD]: 0)	Landing Gear General Visual Inspection (Corrosion Inspection)					Mos 11-Oct-2017 Hrs 7,170.5 Ldg 7,207	RE 12		Continuous Inspection Program +1 (31-Oct-2018)	8.8 Months (+30 Days)
A321001  32 A/F 051202 Ref.:32-11-01-210 (ZONE: 720, 730)	Main Landing Gear - Inspect					Mos Hrs Ldg	RE 24 300		Continuous Inspection Program +2 (31-Jul-2019) (7,422)	≈10-Sep-2018 1.5 Years (+61 Days) 218.1 Hrs (+30)
A321002  32 A/F 051202 Ref.:32-11-01-220 (ZONE: 720, 730)	Main Gear Strut - Check extension					Mos Hrs Ldg	RE 24 300		Continuous Inspection Program +2 (31-Jul-2019) (7,422)	≈10-Sep-2018 1.5 Years (+61 Days) 218.1 Hrs (+30)
A321003  32 A/F 051202 Ref.:32-11-02-210 (ZONE: 720, 730)	Main Landing Gear - Inspect					Mos Hrs Ldg	RE 24 300		Continuous Inspection Program +2 (31-Jul-2019) (7,422)	≈10-Sep-2018 1.5 Years (+61 Days) 218.1 Hrs (+30)

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
A322001	Shimmy Damper - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202,...				Mos	21-Jul-2017	24	+2	≈21-Jul-2019	
Ref.:32-21-02-610 (ZONE: 710)					Hrs	7,122	300	+30	≈7,422	
					Ldg	7,168				
A322002	Nose Gear Assembly - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-21-01-210 (ZONE: 710)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A323002	Nose Gear Uplock - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-31-05-211 (ZONE: 710)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A323003	Emergency Gear Extension System - Inspect cable								RE Continuous Inspection Program	
 32 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:32-31-08-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A323004	Main Gear Uplock - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-31-05-210 (ZONE: 720, 730)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A323005	Main Gear Uplock - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-31-05-212 (ZONE: 720, 730)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A323006	Main Landing Gear Trailing Link Internal Bore - Inspect								RE Continuous Inspection Program	
 32 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:32-30-00-210 (ZONE: 720, 730)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A324001	Main Gear Wheel, Tire and Bearing - Inspect and service								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-41-01-210 (ZONE: 720, 730)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A324002	Nose Wheel, Tire and Bearing (Without Gravel Runway Option) - Inspect and service								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-41-02-210 (ZONE: 710)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A324003	Nose Wheel, Tire and Bearing (With Gravel Runway Option) - Inspect and service								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-41-02-211 (ZONE: 710)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
A324004	Brake Master Cylinder (Airplanes) - Inspect						RE	Continuous Inspection Program		≈10-Sep-2018
 32 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-42-02-210 (ZONE: 231, 232)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A324005	Emergency Brake Control Valve - Inspect						RE	Continuous Inspection Program		
 32 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:32-42-09-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A324007	Brake Reservoir and Antiskid System Components - Inspect						RE	Continuous Inspection Program		
 32 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:32-42-00-210 (ZONE: 131, 222)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A324012	Main Landing Gear Wheel Brake - Inspect						RE	Continuous Inspection Program		≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-42-01-210 (ZONE: 720, 730)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A324013	Brake Metering Valve - Inspect						RE	Continuous Inspection Program		≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-42-10-710 (ZONE: 222)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A324014	Main Gear Wheel, Tire and Bearing - Inspect and service						RE	Continuous Inspection Program		≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-41-01-211 (ZONE: 720, 730)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A325001	Nose Steering Arm Support Bracket, Bungee and Bell- crank - Inspect						RE	Continuous Inspection Program		
 32 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:32-51-00-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A325002	Nose Steering System Cable - Inspect						RE	Continuous Inspection Program		
 32 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:32-51-00-211					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A325003	Gravel Runway/Nose Wheel Spin-Up Components - Inspect						RE (N/A)	Continuous Inspection Program		
 32 A/F					Mos					
Ref.:32-43-00-211 (ZONE: 131, 231, 710)					Hrs					
					Ldg					
A325004	Nose Wheel Spin-Up Control - Inspect						RE	Continuous Inspection Program		≈10-Sep-2018
 32 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:32-43-00-210 (ZONE: 212)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A325009	Nose Landing Gear Fork - Inspect (Chapter 4 Item)								T Continuous Inspection Program	≈02-Aug-2019
 32 A/F	0512MG					Mos				
	Ref.:32-21-01-250 (ZONE: 710)					Hrs				
						Ldg	10,000	(10,000)		2,760 Ldg
B324006	Main Gear Wheel Brakes - Check wear								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202,...					Mos	21-Jul-2017	24	+2	≈21-Jul-2019
	Ref.:32-42-01-211 (ZONE: 720, 730)					Hrs	7,122	300	+30	≈7,422
						Ldg	7,168			
B324008	Antiskid Brake System - Perform operational check								RE Continuous Inspection Program	
 32 A/F	051205					Mos		36	+2	(31-Oct-2019) 1.7 Years (+61 Days)
	Ref.:32-42-00-710					Hrs		1,200	+100	(8,048.2) 844.3 Hrs (+100)
						Ldg				
B324009	Emergency Brake System - Perform operational test								RE Continuous Inspection Program	
 32 A/F	051205					Mos		36	+2	(31-Oct-2019) 1.7 Years (+61 Days)
	Ref.:32-42-09-710					Hrs		1,200	+100	(8,048.2) 844.3 Hrs (+100)
						Ldg				
B325001	Nose Wheel Spin-Up System - Perform functional test								RE Continuous Inspection Program	
 32 A/F	051205					Mos		36	+2	(31-Oct-2019) 1.7 Years (+61 Days)
	Ref.:32-43-00-710					Hrs		1,200	+100	(8,048.2) 844.3 Hrs (+100)
						Ldg				
B326001	Landing Gear Hydraulic Systems (Airplanes -0001 thru -0538) - Perform adjustment/test								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202					Mos		24	+2	(31-Jul-2019) 1.5 Years (+61 Days)
	Ref.:32-01-00-710 (ZONE: AUX, 210, 221, 222, 235, 710, 720, 730)					Hrs		300	+30	(7,422) 218.1 Hrs (+30)
						Ldg				
B326002	Landing Gear - Perform timed cycle test								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202					Mos		24	+2	(31-Jul-2019) 1.5 Years (+61 Days)
	Ref.:32-01-00-711 (ZONE: AUX, 710, 720, 730)					Hrs		300	+30	(7,422) 218.1 Hrs (+30)
						Ldg				
B326004	Landing Gear Hydraulic Systems - Perform test								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202					Mos		24	+2	(31-Jul-2019) 1.5 Years (+61 Days)
	Ref.:32-01-00-712 (ZONE: AUX, 210, 221, 222, 235, 710, 720, 730)					Hrs		300	+30	(7,422) 218.1 Hrs (+30)
						Ldg				
C325013	Nose Wheel Inner Axle - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 32 A/F	051202					Mos		24	+2	(31-Jul-2019) 1.5 Years (+61 Days)
	Ref.:32-41-02-212 (ZONE: 710)					Hrs		300	+30	(7,422) 218.1 Hrs (+30)
						Ldg				
D324007	Antiskid System Motor/Pump Filter - Replace filter element								RE Continuous Inspection Program	
 32 A/F	051205					Mos		36	+2	(31-Oct-2019) 1.7 Years (+61 Days)
	Ref.:32-42-00-901 (ZONE: 131, 222)					Hrs		1,200	+100	(8,048.2) 844.3 Hrs (+100)
						Ldg				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
D324010  32 A/F Ref.:32-42-00-902	Brake Reservoir Air Filter - Replace filter element 051205								RE Continuous Inspection Program (31-Oct-2019)	1.7 Years (+61 Days)
					Mos		36	+2		
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
D324011  32 A/F Ref.:32-42-00-160	Brake Reservoir Supply Line Filter - Clean 051205								RE Continuous Inspection Program (31-Oct-2019)	1.7 Years (+61 Days)
					Mos		36	+2		
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
D324012  32 A/F Ref.:32-42-02-160 (ZONE: 231, 232)	Master Cylinder In-Line Filter - Clean 051205								RE Continuous Inspection Program (31-Oct-2019)	1.7 Years (+61 Days)
					Mos		36	+2		
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
SL560-32-31  32 A/F Complied With	Main Landing Gear Extend Pneumatic Line Clearance Inspection								RE (-) Recommended	
					Mos	26-May-1995				
					Hrs	297				
					Ldg	0				
SL560-32-33  32 A/F Eff: 18-Oct-1996 Complied With	Transmittal of BFGoodrich Service Letter SL1728 Landing Gear - Nose Wheel								RE (-) Informational	
					Mos	02-Apr-1997				
					Hrs	1,224				
					Ldg	0				
SL560-32-34  32 A/F Eff: 30-Oct-1998 Complied With	Nose Gear Steering Bungee Inspection								RE (-) Recommended	
					Mos	31-Jul-1999				
					Hrs	2,326				
					Ldg	0				
SL560-32-37  32 A/F	This Service Letter has been CANCELLED								RE (-)	
					Mos	03-Oct-2003				
					Hrs	3,819				
					Ldg	0				
SL560-32-40  32 A/F Complied With	Nose Landing Gear Ice Protection Boot Installation								RE (-) Optional	
					Mos	19-May-2008				
					Hrs	4,937				
					Ldg	0				
SL560-32-41  32 A/F Eff: 14-Nov-2005 Complied With	Goodrich Nose Wheel Inspection/Replacement								RE (-) Mandatory	
					Mos	17-Apr-2006				
					Hrs	4,570				
					Ldg	5,193				
SL560-32-50  32 A/F Eff: 15-May-2009 Complied With	Emergency Gear Release Inspection								RE (-) Mandatory	
					Mos	12-Nov-2010				
					Hrs	5,567.5				
					Ldg	5,970				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
▼ 33 - LIGHTS										
 33 A/F Unknown Unknown	Anti Collision Light Assy Left							RE (O/C)		
						Mos	15-Nov-1994			
						Hrs	0			
 33 A/F Unknown Unknown	Anti Collision Light Assy Right					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 33 A/F Unknown Unknown	CF001 Indirect Light Power Unit No.10					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 33 A/F Unknown Unknown	CF002 Indirect Light Power Unit No.9					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 33 A/F Unknown Unknown	CU24 Indirect Light Power Unit No.8					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 33 A/F Unknown Unknown	CU25 Indirect Light Power Unit No.7					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 33 A/F Unknown Unknown	CU26 Indirect Light Power Unit No.6					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 33 A/F Unknown Unknown	CU27 Indirect Light Power Unit No.5					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 33 A/F Unknown Unknown	CU28 Indirect Light Power Unit No.4					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 33 A/F Unknown Unknown	CU29 Indirect Light Power Unit No.3					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			

Task No	Description					CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI				DUE	Remaining
 33 A/F Unknown Unknown	CU30 Indirect Light Power Unit									
	No.2					Mos	15-Nov-1994		RE (O/C)	
						Hrs	0			
						Ldg	0			
 33 A/F AL-5112 44266	CU31 Indirect Light Power Unit									
	No.1	0				Mos	12-Nov-2010		RE (O/C)	
		0				Hrs	5,567.5			
		0				Ldg	5,970			
 33 A/F 24621-3 NSN	Emergency Battery Pack									
		0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			
 33 A/F AL0581 8446	Indirect Lighting Inverter									
	Aft	0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			
 33 A/F AL5114 4993	Indirect Lighting Inverter									
	Fwd	0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			
 33 A/F EM2044-1 265A	INVT-115V EL Panel									
		0				Mos	29-Nov-2008		RE (O/C)	
		0				Hrs	5,049			
		0				Ldg	0			
 33 A/F 273-1 3078	Light Panel Dimmer									
	No.1	0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			
 33 A/F 273-1 3080	Light Panel Dimmer									
	No.2	0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			
 33 A/F 273-1 3109	Light Panel Dimmer									
	No.3	0				Mos	15-Nov-1994		RE (O/C)	
		0				Hrs	0			
		0				Ldg	0			
 33 A/F 30-2140-5 748	Rotating/Flashing Beacon									
		0				Mos	30-Jun-1998		RE (O/C)	
		0				Hrs	1,837			
		0				Ldg	0			

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition									DUE	Remaining
 33 A/F 60-2799-1 16240	Strobe Power Supply							RE (O/C)			
	No.1		0			Mos	21-Oct-2016				
			0			Hrs	6,848.2				
			0			Ldg	6,940				
 33 A/F 60-2799-1 5367	Strobe Power Supply							RE (O/C)			
	No.2		0			Mos	18-Jun-2015				
			0			Hrs	6,484.2				
			0			Ldg	6,652				
 33 A/F Unknown Unknown	Tail Light Assembly							RE (O/C)			
						Mos	15-Nov-1994				
						Hrs	0				
					Ldg	0					
560-33-12	Main Landing Gear Taxi Light Installation							RE (-)		Recommended	
 33 A/F Eff: 01-Aug-1995 Complied With						Mos	21-Oct-1995				
						Hrs	505				
						Ldg	0				
560-33-14	Tail Navigation Light Socket Inspection/Modification							RE (-)		Recommended	
 33 A/F Complied With						Mos	21-Oct-1995				
						Hrs	505				
						Ldg	0				
560-33-17 R01	Main Landing Gear Light Assembly Modification							RE (-)		Recommended	
 33 A/F Eff: 24-Jan-1997 Complied With						Mos	27-Feb-1998				
						Hrs	1,705				
						Ldg	0				
95-22-01	Aerospace Lighting Corporation Power Units and Power Supplies - Fluorescent Lighting System							RE (-)		Mandatory (Appliance AD)	
 33 A/F Eff: 04-Dec-1995 Complied With	INSTALLED NEW POWER SUPPLY					Mos	03-Jan-1996				
						Hrs	579.3				
						Ldg	824				
A332001	Indirect Cabin Fluorescent Lighting - Inspect							RE	Continuous Inspection Program		
 33 A/F Ref.:33-21-01-210	051205					Mos	36		+2	(31-Oct-2019)	1.7 Years (+61 Days)
						Hrs	1,200		+100	(8,048.2)	844.3 Hrs (+100)
						Ldg					
A335001	Emergency Lights, Battery Box and Batteries - Inspect							RE	Continuous Inspection Program		
 33 A/F Ref.:33-51-01-210	051205					Mos	36		+2	(31-Oct-2019)	1.7 Years (+61 Days)
						Hrs	1,200		+100	(8,048.2)	844.3 Hrs (+100)
						Ldg					
A335002	Emergency Exit Lights - Inspect							RE	Continuous Inspection Program ≈10-Sep-2018		
 33 A/F Ref.:33-51-01-211 (ZONE: 251, 252)	051201					Mos	24		+2	(31-Jul-2019)	1.5 Years (+61 Days)
						Hrs	300		+30	(7,422)	218.1 Hrs (+30)
						Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A335003	Emergency Lights, Battery Box and Batteries - Inspect								RE Continuous Inspection Program	
33 A/F	051205					Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:33-51-01-212						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
						Ldg				
B335001	Emergency Lights Operational Check - Perform								RE Continuous Inspection Program	≈10-Sep-2018
33 A/F	051201					Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:33-51-01-710 (ZONE: BAT)						Hrs	300	+30	(7,422)	218.1 Hrs (+30)
						Ldg				
▼ 34 - NAVIGATION										
	No.1 VHF Nav Controller								RE (O/C)	
34 A/F 622-6521-013 15181						Mos	09-Mar-2001			
						Hrs	3,040			
						Ldg	0			
	No.1 VHF Nav Reciever								RE (O/C)	
34 A/F 622-7194-101 1819						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
	No.2 VHF Nav Controller								RE (O/C)	
34 A/F 622-6521-013 15059						Mos	27-Nov-2002			
						Hrs	3,568			
						Ldg	0			
	No.2 VHF Nav Reciever								RE (O/C)	
34 A/F 622-7194-101 1822						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
	ADF Antenna								RE (O/C)	
34 A/F 622-7383-001 21LBH	No.1	0				Mos	31-Oct-2005			
		0				Hrs	4,405			
		0				Ldg	0			
	ADF Antenna								RE (O/C)	
34 A/F 622-7383-001 1514	No.2	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	ADF Module								RE (O/C)	
34 A/F 7510114-901 Unknown	No.1	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
	ADF Module								RE (O/C)	
34 A/F Unknown Unknown	No.2					Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			

Task No	Description								Categories	Time
PN/SN	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	DUE	Remaining
 34 A/F Unknown Unknown	ADF-2 Only W/Honeywell Primus II Factory Option					RE (O/C)				
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 34 A/F 400-045500-0003 589	AFIS Data Management Unit					RE (O/C)				
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
 34 A/F 7014700-601 94030235	Air Data Computer No.1					RE (O/C)				
		0				Mos	10-Dec-2001			
		0				Hrs	3,235			
		0				Ldg	0			
 34 A/F 7014700-601 94060294	Air Data Computer No.2					RE (O/C)				
		0				Mos	10-Dec-2001			
		0				Hrs	3,235			
		0				Ldg	0			
 34 A/F Unknown Unknown	Airborn Flt Info Sys (Global AFIS) Factory Option					RE (O/C)				
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 34 A/F Unknown Unknown	Airborn Flt Info Sys (Glogal AFIS) Factory Option					RE (O/C)				
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
 34 A/F 1703-147-2 419	Angle Of Attack Heat Monitor					RE (O/C)				
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
 34 A/F 965-0113-008 1227	Angle Of Attack Indexer					RE (O/C)				
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
 34 A/F C11605-1 428	Angle Of Attack Indicator					RE (O/C)				
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
 34 A/F C11606-9 566	Angle Of Attack Stall Warning Computer					RE (O/C)				
		0				Mos	03-Feb-1999			
		0				Hrs	0			
		0				Ldg	0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
 34 A/F 1703-15 446	Angle Of Attack Transmitter								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 066-01143-0601 2445	ATC Transponder No.1								RE (O/C)	
		0			Mos	27-Nov-2002				
		0			Hrs	3,568				
		0			Ldg	0				
 34 A/F 066-01143-0601 2446	ATC Transponder No.2								RE (O/C)	
		0			Mos	27-Nov-2002				
		0			Hrs	3,568				
		0			Ldg	0				
 34 A/F 7014331-921 94050234	Bezel Display Unit No.1								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7014331-921 94050237	Bezel Display Unit No.2								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7513000-835 Unknown	Clearance Delivery Control								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7012977-753 Unknown	Cntr EFIS Display								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 31990-1 4120	Configuration Module No.1								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F Unknown Unknown	Configuration Module No.2								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 34 A/F 7016986-707 94060301	Copilot Primary Flight Display Controller								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
34 A/F Unknown Unknown	Data Transfer Unit	RE (O/C)								
						Mos	15-Nov-1994			
						Hrs	0			
						Ldg	0			
34 A/F 400-015655-0101 386	Data Transfer Unit	RE (O/C)								
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
34 A/F 4020577-3 96065986	Directional Gyro No.1	RE (O/C)								
		0				Mos	31-Oct-2005			
		0				Hrs	4,405			
		0				Ldg	0			
34 A/F 4020577-3 86073800	Directional Gyro No.2	RE (O/C)								
		0				Mos	03-Mar-2006			
		0				Hrs	4,519			
		0				Ldg	0			
34 A/F 7017000-80162 990221977	Display Guidance Computer No.1	RE (O/C)								
		0				Mos	09-Apr-2015			
		0				Hrs	6,414.1			
		0				Ldg	6,579			
34 A/F 7017000-81162 94110376	Display Guidance Computer No.2	RE (O/C)								
		0				Mos	06-May-2002			
		0				Hrs	3,407			
		0				Ldg	0			
34 A/F DMNI50-2-2 58219	DME Antenna Aft	RE (O/C)								
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
34 A/F DMNI50-2-2 57658	DME Antenna Fwd	RE (O/C)								
		0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			
34 A/F 622-7318-001 2354	DME Indicator No.1	RE (O/C)								
		0				Mos	23-Dec-2007			
		0				Hrs	4,841			
		0				Ldg	0			
34 A/F 622-7318-001 3368	DME Indicator No.2	RE (O/C)								
		0				Mos	27-Nov-2002			
		0				Hrs	3,568			
		0				Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 34 A/F 622-7309-101 1615	DME Receiver Transmitter								RE (O/C)	
	No.1	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 622-7309-101 1620	DME Receiver Transmitter								RE (O/C)	
	No.2	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7014300-901 94100585	EFIS Display								RE (O/C)	
	No.1	0			Mos	13-Jul-1998				
		0			Hrs	1,845				
		0			Ldg	0				
 34 A/F 7014300-901 0410E036	EFIS Display								RE (O/C)	
	No.2	0			Mos	09-Feb-2016				
		0			Hrs	6,654				
		0			Ldg	6,786				
 34 A/F 2594484 782070056	Flux Detector								RE (O/C)	
	No.1	0			Mos	12-Nov-2010				
		0			Hrs	5,567.5				
		0			Ldg	5,970				
 34 A/F 2594484 94060928	Flux Detector								RE (O/C)	
	No.2	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F Unknown Unknown	FMS-Configuration Module								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 34 A/F RGS10-48 316	Glideslope Antenna								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 17960-0102-001 X2277	GNS/FMS Display								RE (O/C)	
	No.1	0			Mos	17-Feb-2017				
		0			Hrs	6,979.4				
		0			Ldg	7,046				
 34 A/F S67-1575-39 8571	GPS Antenna								RE (O/C)	
		0			Mos	02-Apr-1997				
		0			Hrs	1,224				
		0			Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
34 A/F 965-1076-040-212-212 2638	Ground Proximity Warning Sys Computer								RE (O/C)	
		0			Mos	10-Dec-2001				
		0			Hrs	3,235				
		0			Ldg	0				
34 A/F 7510100-731 Unknown	Intergrated NAV Unit No.1								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
34 A/F 7510100-733 Unknown	Intergrated NAV Unit No.2								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
34 A/F 30490-1 Unknown	Loop VLF Coupler Left								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
34 A/F C660501-0301 NSN	Magnetic Compass								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
34 A/F 31-10-01 2780	Marker Beacon Antenna								RE (O/C)	
		0			Mos	27-Feb-1998				
		0			Hrs	1,705				
		0			Ldg	0				
34 A/F 7014332-841 98031764	MFD Bezel Display Unit								RE (O/C)	
		0			Mos	04-Nov-2002				
		0			Hrs	3,558				
		0			Ldg	0				
34 A/F 7018341-909 93120227	Mode Flight Director Selector No.1								RE (O/C)	
		0			Mos	10-Dec-2001				
		0			Hrs	3,235				
		0			Ldg	0				
34 A/F 7018341-909 95080497	Mode Flight Director Selector No.2								RE (O/C)	
		0			Mos	07-Oct-2010				
		0			Hrs	5,566.3				
		0			Ldg	5,966				
34 A/F 7007062-941 94061382	Multifunction Display Controller								RE (O/C)	
		0			Mos	02-Apr-1997				
		0			Hrs	1,224				
		0			Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 34 A/F 7510164-921 Unknown	NAV Cluster Module								RE (O/C)	
	No.1	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7510164-921 Unknown	NAV Cluster Module								RE (O/C)	
	No.2	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7510134-731 Unknown	NAV Module								RE (O/C)	
	No.1	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7510134-731 Unknown	NAV Module								RE (O/C)	
	No.2	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F DMN4-17-1B 5540	Navigation Antenna								RE (O/C)	
	No.1	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F Unknown Unknown	Navigation Antenna								RE (O/C)	
	No.2				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 34 A/F 622-6522-005 9752	No.1 ADF Control								RE (O/C)	
		0			Mos	16-Dec-2002				
		0			Hrs	3,589				
		0			Ldg	0				
 34 A/F 622-7382-101 2490	No.1 ADF Receiver								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 622-6522-005 9756	No.2 ADF Control								RE (O/C)	
		0			Mos	11-Dec-2002				
		0			Hrs	3,581				
		0			Ldg	0				
 34 A/F 622-7382-101 2739	No.2 ADF Receiver								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
 34 A/F C307FCL A1803	Oat Indicator	RE (O/C)								
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7016986-707 94060294	Pilot Primary Flight Display Controller	RE (O/C)								
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F D37C15 Unknown	Pitot Pressure Switch	RE (O/C)								
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7021450-921 95081395	Primus 650 Radar Receiver/Transmitter	RE (O/C)								
		0			Mos	07-Feb-2006				
		0			Hrs	4,500				
		0			Ldg	0				
 34 A/F	Primus 650 Radar Receiver/Transmitter Inspection	RE								≈02-Oct-2021
					Mos	07-Feb-2006				
				476	Hrs	4,500	4,500		8,524	1,320.1 Hrs
					Ldg	5,146				
 34 A/F 501-1228-03 1126	PS-835 Emergency Power Supply	RE (O/C)								
		0			Mos	25-Apr-2017				
		0			Hrs	7,041.7				
		0			Ldg	7,086				
 34 A/F 7008471-803 92091642	Radar Controller	RE (O/C)								
		0			Mos	28-Sep-2004				
		0			Hrs	4,097				
		0			Ldg	0				
 34 A/F 622-2855-011 9432	Radio Alt Transceiver	RE (O/C)								
		0			Mos	02-Apr-1997				
		0			Hrs	1,224				
		0			Ldg	0				
 34 A/F 7012100-825 Unknown	Radio Management Unit No.1	RE (O/C)								
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7012100-825 Unknown	Radio Management Unit No.2	RE (O/C)								
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
34 A/F 7007453-903 98014575	Rate Of Turn Gyro No.1	RE (O/C)								
		0			Mos	04-Feb-1999				
		0			Hrs	2,105				
		0			Ldg	0				
34 A/F 622-0954-001 5872	Receiver Radio Alt Antenna Aft	RE (O/C)								
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
34 A/F 2593379-1 94051299	Remote Compensator	RE (O/C)								
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
34 A/F 7016954-903 94010198	Remote Course Control No.1	RE (O/C)								
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
34 A/F Unknown Unknown	Secondary Flight Adu	RE (O/C)								
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
34 A/F Unknown Unknown	Secondary Flight Display	RE (O/C)								
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
34 A/F Unknown Unknown Ref.:34-21-17-960	Securaplane Standby Battery	RE (O/C) Component Time Limits								
					Mos					
					Hrs					
					Ldg					
34 A/F WL102AMS6 AP538	Standby Altimeter	RE (O/C)								
		0			Mos	08-Oct-2008				
		0			Hrs	5,034				
		0			Ldg	0				
34 A/F 501-1228-03 1126	Standby Flight Display Battery	RE (O/C)								
		0			Mos	25-Apr-2017				
		0			Hrs	7,041.7				
		0			Ldg	7,086				
34 A/F 501-1197-05 1856	Standby Gyro	RE (O/C)								
		0			Mos	15-Nov-2016				
		0			Hrs	6,890.4				
		0			Ldg	6,973				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 34 A/F Unknown Unknown	Standby Gyro Power Supply						RE (O/C)			
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 34 A/F 520-3150-002 2105A	Standby Hsi Indicator	0			Mos	20-Jan-2006				
		0			Hrs	4,466				
		0			Ldg	0				
 34 A/F 501-1318-01 4174	Static Converter	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 78-8051-9200-8 JSA09802422	Stormscope Antenna	0			Mos	18-Jun-1999				
		0			Hrs	2,257				
		0			Ldg	0				
 34 A/F 78-8060-5900-9 JSD01105383	Stormscope Display	0			Mos	05-Apr-2004				
		0			Hrs	3,992				
		0			Ldg	0				
 34 A/F 78-8051-9160-4 JXP08803849	Stormscope Processor	0			Mos	05-Apr-2004				
		0			Hrs	3,992				
		0			Ldg	0				
 34 A/F S72-1735-3 9633	TCAS Antenna Bottom	0			Mos	31-Oct-2005				
		0			Hrs	4,405				
		0			Ldg	0				
 34 A/F 071-01548-0200 6537	TCAS Antenna Top	0			Mos	02-Apr-1997				
		0			Hrs	1,224				
		0			Ldg	0				
 34 A/F 071-00097-1000 3201	TCAS Configuration Module	0			Mos	02-Apr-1997				
		0			Hrs	1,224				
		0			Ldg	0				
 34 A/F 071-01507-4404 3353	TCAS Control	0			Mos	21-Jul-2017				
		0			Hrs	7,122				
		0			Ldg	7,168				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
 34 A/F 066-01146-1211 M11306	TCAS Processor								RE (O/C)	
		0			Mos	03-May-2017				
		0			Hrs	7,051.5				
		0			Ldg	7,094				
 34 A/F 102DB1AG A2732	Temperature Probe								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F Unknown Unknown	Top Aft Div Transponder Antenna								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 34 A/F Unknown Unknown	Top Forward Div Transponder Antenna								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 34 A/F 622-0954-001 5871	Transmitter Radio Alt Antenna Fwd								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F DMNI50-2-2 62871	Transponder Antenna Aft								RE (O/C)	
		0			Mos	02-Apr-1997				
		0			Hrs	1,224				
		0			Ldg	0				
 34 A/F DMNI50-2-2 63368	Transponder Antenna Fwd								RE (O/C)	
		0			Mos	02-Apr-1997				
		0			Hrs	1,224				
		0			Ldg	0				
 34 A/F 7000622-901 94077517	Vertical Flight Director Gyro No.1								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 7000622-901 94077516	Vertical Flight Director Gyro No.2								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F 11455-2 Unknown	VLF Antenna								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
 34 A/F 30050-0909-1121 Unknown	VLF Sensor								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 34 A/F Unknown Unknown	VLF/Omega Global GNS-X Factory Option								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
2000-03-09	Residual Ice								RE (-)	Mandatory
 34 A/F Eff: 03-Apr-2000 Complied With					Mos	07-Apr-2000				
					Hrs	2,644				
					Ldg	3,171				
2000-03-09 Paragraph (a)	Residual Ice - Airplane Flight Manual (AFM) Revisions								RE (-)	Mandatory
 34 A/F Eff: 03-Apr-2000 Complied With					Mos	07-Apr-2000				
					Hrs	2,644				
					Ldg	3,171				
2000-03-09 Paragraph (b)	Residual Ice - Modification								RE (-)	Mandatory
 34 A/F Eff: 03-Apr-2000 Complied With					Mos	07-Apr-2000				
					Hrs	2,644				
					Ldg	3,171				
2001-15-17	Rockwell Collins. CTL-92 - Transponder Control Panels								RE (-)	Mandatory (Appliance AD)
 34 A/F Eff: 20-Aug-2001 Not Applicable Brand A:9990-2001-15-17	EQUIPMENT NOT INSTALLED				Mos	09-Sep-2014				
					Hrs	6,186				
					Ldg	6,407				
2001-23-17	Garmin GNS 430 units								RE (-)	Mandatory (Appliance AD)
 34 A/F Eff: 28-Dec-2001 Not Applicable Brand A:9990-2001-23-17	EQUIPMENT NOT INSTALLED				Mos	01-Apr-2002				
					Hrs	3,361				
					Ldg	0				
2002-06-05	Mode C 621A-3 Air Traffic Control (ATC) Transponders								RE (-)	Mandatory (Appliance AD)
 34 A/F Eff: 26-Apr-2002 Not Applicable	EQUIPMENT NOT INSTALLED				Mos	09-Sep-2014				
					Hrs	6,186				
					Ldg	6,407				
2002-06-06 Para. (d)(1)	Determine Whether The Altitude Information From Any Tdr-94 Mode S Transponder (Cpn 622-9352-004) Or Tdr-94D Mode S Transponder (Cpn 622-9120-004) Is Derived From A Digital Air Data Source Or A Gillham (Gray Code) Encoded Source								RE (-)	Mandatory (Appliance AD)
 34 A/F Eff: 03-May-2002 Not Applicable	EQUIPMENT NOT INSTALLED				Mos	09-Sep-2014				
					Hrs	6,186				
					Ldg	6,407				
2002-13-07 Para. (d)(1)	Inspect Any Affected Iru For Proper Function								RE (-)	Mandatory (Appliance AD)
 34 A/F Eff: 09-Aug-2002 Not Applicable	EQUIPMENT NOT INSTALLED				Mos	09-Sep-2014				
					Hrs	6,186				
					Ldg	6,407				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2002-14-19	Rockwell Collins, Inc. ADC-85, ADC-85A, ADC-850D, and ADC-850F Air Data Computers								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 23-Aug-2002 Not Applicable Brand A:9990-2002-14-19 (AVG MAN HRS: 6) (APX COST [USD]: 1,040)	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	09-Sep-2014 6,186 6,407			
2003-04-06	Inspect Primus Integrated Nav Unit/Revise AFM (SUPERSEDED BY AD 2006- 22-05)								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 11-Mar-2003 Not Applicable Brand A:9990-2003-04-06	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	06-Mar-2003 3,659 0			
2004-08-15	Goodrich Avionics Systems, Inc - TAWS8000 terrain awareness warning systems (TAWS)								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 07-Jun-2004 Not Applicable Brand A:9990-2004-08-15 (AVG MAN HRS: 3) (APX COST [USD]: 195)	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	09-Sep-2014 6,186 6,407			
2004-08-16	Narco - AT150 Transponder Modification								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 01-Jun-2004 Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	09-Sep-2014 6,186 6,407			
2004-13-20	GPS navigation units								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 03-Aug-2004 Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	09-Sep-2014 6,186 6,407			
2004-16-14	Thales Avionics TA/RA VSI-TCAS Indicators								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 13-Sep-2004 Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	09-Sep-2014 6,186 6,407			
2004-21-04	Becker Flugfunkwerk AR-4201 Very High Frequency (VHF) AM Transceiver - Aircraft flight manual (AFM)								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 11-Dec-2001 Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	09-Sep-2014 6,186 6,407			
2005-01-19	GARMIN International Inc. - Mode S transponders								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 23-Feb-2005 Not Applicable Brand A:9990-2005-01-19	EQUIPMENT NOT INSTALLED					Days Hrs Ldg	09-Sep-2014 6,186 6,407			
2006-16-18	Sandel Avionics Incorporated - Installing a warning placard on the TAWS/RMI								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 25-Sep-2006 Not Applicable Brand A:9990-2006-16-18	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	07-Nov-2006 4,712 0			
2006-16-18 R1	Sandel Avionics Incorporated - Installing a warning placard on the TAWS/RMI								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 18-Jul-2008 Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	07-Nov-2006 4,712 0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2006-16-18 R1 Paragraph (f) (g)	Sandel Avionics Incorporated - Installing Placard and Revising Airplane Flight Manual (AFM)								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 26-Sep-2006 Not Applicable	EQUIPMENT NOT INSTALLED					Days 07-Nov-2006				
						Hrs 4,712				
						Ldg 0				
2006-16-18 R1 Paragraph (h)	Sandel Avionics Incorporated - Updating Software								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 31-Aug-2006 Not Applicable	EQUIPMENT NOT INSTALLED					Days 07-Nov-2006				
						Hrs 4,712				
						Ldg 0				
2006-22-05	Honeywell Primus II RNZ-850/-851 Integrated Navigation Unit (INU) - CANCELLED(SUPERCEDED BY AD 2010-07-02)								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 01-Dec-2006 Not Applicable	P/N NOT INSTALLED					Mos 18-Jan-2007				
						Hrs 4,774				
						Ldg 0				
2007-07-12	Honeywell NZ-2000, IC-800, or IC-800E Navigation Computers								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 02-May-2007 Not Applicable	EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014				
						Hrs 6,186				
						Ldg 6,407				
2007-23-13	Inspect - Adjustment Of Stall Warning System (Superseded by AD2008-26-04)								RE (-)	Mandatory
34 A/F Eff: 30-Nov-2007 Superseded						Mos 06-Dec-2007				
						Hrs 4,831				
						Ldg 0				
2008-26-04	Airspeed placards								RE (-)	Mandatory
34 A/F Eff: 28-Jan-2009 Complied With						Mos 17-Feb-2009				
						Hrs 5,131				
						Ldg 0				
2008-26-04 Paragraph (f)	Airspeed Placards - Airplane Flight Manual (AFM) Revision								RE (-)	Mandatory
34 A/F Eff: 30-Nov-2007 Complied With						Days 17-Feb-2009				
						Hrs 5,131				
						Ldg 0				
2008-26-04 Paragraph (g)	Airspeed Placards - Placard Installation								RE (-)	Mandatory
34 A/F Eff: 30-Nov-2007 Complied With						Days 17-Feb-2009				
						Hrs 5,131				
						Ldg 0				
2008-26-04 Paragraph (i)	Airspeed Placards - Terminating Action								RE (-)	Mandatory
34 A/F Eff: 28-Jan-2009 Complied With						Mos 17-Feb-2009				
						Hrs 5,131				
						Ldg 0				
2009-05-05	Avidyne Corporation (Avidyne) - Primary Flight Displays								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 03-Apr-2009 Not Applicable	EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014				
						Hrs 6,186				
						Ldg 6,407				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2009-05-08	Trimble or FreeFlight Systems 2101 I/O Approach Plus global positioning system (GPS)								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 20-Apr-2009 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
						Hrs	6,186			
						Ldg	6,407			
2009-08-01	Honeywell, Inc - FMSs								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 14-May-2009 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
						Hrs	6,186			
						Ldg	6,407			
2010-07-02	Honeywell, Inc - Integrated navigation units (INUs)								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 03-May-2010 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	30-Jan-2012			
						Hrs	5,663.6			
						Ldg	6,043			
2012-02-08	Aviation Communication & Surveillance Systems (ACSS) Traffic Alert and Collision Avoidance System (TCAS) Units - Navigation								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 13-Mar-2012 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
						Hrs	6,186			
						Ldg	6,407			
2012-26-15	Honeywell International Inc. - Air Data Pressure Transducers								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 24-Jan-2013 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	28-Aug-2014			
						Hrs	6,186			
						Ldg	6,407			
2012-26-15 R1	Honeywell International Inc. - Air Data Pressure Transducers (This action rescinds AD 2012-26-15, Amendment 39-17310 (78 FR 1735, January 9, 2013).)								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 03-Dec-2014 Complied With						Mos	19-Nov-2014			
						Hrs	6,252.9			
						Ldg	6,467			
2014-05-27	Rockwell Collins, Inc - Navigation - TPR-720 and TPR-900 Mode S transponders test and calibration								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 02-May-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	28-Aug-2014			
						Hrs	6,186			
						Ldg	6,407			
2014-18-01	Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02.								RE (-)	Mandatory (Appliance AD)
34 A/F Eff: 14-Oct-2014 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	21-Oct-2016			
						Hrs	6,848.2			
						Ldg	6,940			
2015-10-51	Avidyne Integrated Flight Display (IFD) - Navigation - Incorporate Operational Limitations into Airplane Flight Manual (AFM) or Airplane Flight Manual Supplement (AFMS) Limitation.								RE (-)	Mandatory (Appliance AD)
34 A/F Not Applicable	EQUIPMENT NOT INSTALLED					Mos	07-Jul-2015			
						Hrs	6,495.3			
						Ldg	6,663			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2017-04-06	Altimeter - United Instruments Model 5934 Series - Slow Diaphragm Leak									
34 A/F Eff: 07-Apr-2017	(AVG MAN HRS: 1) (NOTE: APPLICABILITY: This AD applies to United Instruments, Inc. 5934 series altimeters that were manufactured between January 2015 and February 2016 and installed in airplanes and helicopters. NOTE: Refer to United Instruments, Inc. Service Bulletin No. 13, dated March 25, 2016.)									
						Mos	12		Mandatory (Appliance AD)	58 Days
						Hrs				
						Ldg				
2017-11-11	ATC Transponder System - Automatic Dependent Surveillance Broadcast (ADS-B) Universal Access Transceiver Units									
34 A/F Eff: 11-Jul-2017 Not Applicable	(AVG MAN HRS: 0) (APX COST [USD]: 0) (UPDATE NOTE: Equipment not installed) (NOTE: APPLICABILITY: This AD applies to the following NavWorx, Inc., Automatic Dependent Surveillance-Broadcast (ADS-B) Universal Access Transceiver units (unit) installed on aircraft certificated in any category, including experimental: (1) Model ADS600-B part number (P/N) 200-0012; (2) Model ADS600-B P/N 200-0013; and (3) Model ADS600-EXP P/N 200-8013.)									
						Mos	15-Dec-2017		RE (-)	Mandatory
						Hrs	7,170.7			
						Ldg	7,208			
349000	JLAC Avionics Inspection #1									
34 A/F						Mos	09-Aug-2017		RE	Custom Task
						Hrs	7,145		12	31-Aug-2018 6.8 Months
						Ldg	7,187			
349001	JLAC Avionics Inspection #2									
34 A/F						Mos	20-Oct-2016		RE	Custom Task
						Hrs	6,848.2		24	31-Oct-2018 8.8 Months
						Ldg	6,940			
349002	JLAC Avionics Inspection #3									
34 A/F						Mos	20-Oct-2016		RE	Custom Task
						Hrs	6,848.2		24	31-Oct-2018 8.8 Months
						Ldg	6,940			
349004	Radio Station License Replace									
34 A/F						Mos	29-May-2009		RE	Custom Task
						Hrs	0		120	29-May-2019 1.3 Years
						Ldg	0			
349999.1	EGPWS Database Update									
34 A/F						Mos	09-Aug-2017		RE	Custom Task
						Hrs	7,145		12	09-Aug-2018 6.1 Months
						Ldg	7,187			
34NAVDB	Flight Management System (FMS) Navigation Database Update									
34 A/F Expiration Date 01-Mar-2018 (AVG MAN HRS: 0) (APX COST [USD]: 0)						Mos	02-Feb-2018		RE (Due)	01-Mar-2018 21 Days
						Hrs	7,203.9			
						Ldg	7,240			
560-34-143	Speed Limitation Placard Installation									
34 A/F Complied With						Mos	30-Sep-2014		RE (-)	Mandatory
						Hrs	6,215.8			
						Ldg	6,430			
560-34-143 R01	Speed Limitation Placard Installation									
34 A/F Eff: 21-Nov-2007 Complied With						Days	11-Jul-2008		RE (-)	Mandatory
						Hrs	4,966			
						Ldg	5,520			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-34-57 R01  34 A/F Eff: 15-Nov-1996 Complied With	MS-560 Mode Selector Lighting Improvement					Mos Hrs Ldg	10-Dec-2001 3,235 0		RE (-) Optional	
560-34-61  34 A/F Eff: 11-Mar-1997 Complied With	P-1000 Phase III Avionics System Software Improvement					Mos Hrs Ldg	10-Dec-2001 3,235 0		RE (-) Optional	
560-34-66  34 A/F Eff: 21-Mar-1997 Complied With	Number 2 Flight Guidance Computer Wire Bundle Identification Tag Inspection/Replacement					Mos Hrs Ldg	11-Sep-1997 1,483 0		RE (-) Recommended	
560-34-68  34 A/F Eff: 12-Dec-1997 Complied With	Compass Wiring Modification					Mos Hrs Ldg	27-Feb-1998 1,705 0		RE (-) Optional	
560-34-69  34 A/F Complied With	Safe Flight Angle of Attack Computer Modification					Mos Hrs Ldg	04-Feb-1999 2,105 2,605		RE (-) Mandatory	
560-34-69 R01  34 A/F Complied With	Safe Flight Angle of Attack Computer Modification					Mos Hrs Ldg	04-Feb-1999 2,105 2,605		RE (-) Mandatory	
560-34-69 R02  34 A/F Eff: 19-Sep-1997 Complied With	Safe Flight Angle of Attack Computer Modification					Mos Hrs Ldg	04-Feb-1999 2,105 2,605		RE (-) Mandatory	
560-34-76  34 A/F Eff: 13-May-1998 Complied With	Navigation - UNS1-1CSP 603.4 Software Upgrade					Mos Hrs Ldg	10-Dec-2001 3,235 0		RE (-) Optional	
560-34-79 R01  34 A/F Complied With	Reduced Vertical Separation Minimum (RVSM) Operation Modification					Mos Hrs Ldg	10-Dec-2001 3,235 0		RE (-) Optional	
560-34-79 R02  34 A/F Eff: 20-Dec-2005	Reduced Vertical Separation Minimum (RVSM) Operation Modification					Mos Hrs Ldg		T (A/R)	Optional	

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-34-82	GNS-XLS Software Mod 4 Upgrade								RE (-)	Recommended
 34 A/F Eff: 15-Apr-1999 Complied With						Mos	07-Jul-1999			
						Hrs	2,283			
						Ldg	0			
560-34-86	GNS-XL Software Mod 4 Upgrade								RE (-)	Recommended
 34 A/F Eff: 24-May-1999 Complied With						Mos	27-Sep-1999			
						Hrs	2,392			
						Ldg	0			
560-34-89	Navigation - UNS-1K 603.4 Software Upgrade								RE (-)	Recommended
 34 A/F Eff: 12-Aug-2002 Complied With						Mos	08-Oct-2002			
						Hrs	3,517			
						Ldg	0			
560-34-90 R01	GNS-XL/XLS FMS Mod 6 Software Upgrade								RE (-)	Recommended
 34 A/F Eff: 05-Dec-2003 Complied With						Mos	10-Dec-2001			
						Hrs	3,235			
						Ldg	0			
560-34-93	Honeywell P-1000 Phase 5 Software and Autopilot Pitch Trim Installation								RE (-)	Mandatory
 34 A/F Complied With						Mos	10-Dec-2001			
						Hrs	3,235.7			
						Ldg	3,804			
560-34-93 R01	Honeywell P-1000 Phase 5 Software and Autopilot Pitch Trim Installation								RE (-)	Mandatory
 34 A/F Complied With						Mos	10-Dec-2001			
						Hrs	3,235.7			
						Ldg	3,804			
560-34-93 R02	Honeywell P-1000 Phase 5 Software and Autopilot Pitch Trim Installation								RE (-)	Mandatory
 34 A/F Eff: 13-Aug-2004 Complied With						Mos	10-Dec-2001			
						Hrs	3,235.7			
						Ldg	3,804			
560-34-94	Navigation - UNS-1Csp 603.4 Software Upgrade								RE (-)	Recommended
 34 A/F Eff: 01-Jun-2001 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	01-Apr-2002			
						Hrs	3,361			
						Ldg	0			
95-01-01	Transponders - Check/Mod TRT 250 Transpnders								RE (-)	Mandatory (Appliance AD)
 34 A/F Eff: 06-Feb-1995 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
						Hrs	6,186			
						Ldg	6,407			
95-26-15 R1	Allied Signal - Traffic Alert and Collision Avoidance Systems								RE (-)	Mandatory (Appliance AD)
 34 A/F Eff: 26-Dec-1996 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
						Hrs	6,186			
	(AVG MAN HRS: 1) (NOTE: NOTE: Refer to Allied signal SB TPA-81A-34-82 or SB TPA-81A-34-84.)					Ldg	6,407			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
96-24-06  34 A/F Eff: 05-Dec-1996 Complied With	Icing Condition or Ice on the Wing Addition to AFM (Superseded by AD 2000-03-09)					Mos 06-Jan-1997 Hrs 1,125 Ldg 0	RE (-)		Mandatory	
97-01-12  34 A/F Eff: 25-Feb-1997 Not Applicable	Airtell International, Inc., - Centaurus Model C3-100 Ground Proximity Warning System EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory (Appliance AD)	
97-05-03 R1  34 A/F Eff: 20-Apr-1999 Complied With	AlliedSignal Avionics, Inc. Models GNS-XLS and GNS-XL Flight Management Systems					Mos 02-Apr-1997 Hrs 1,224 Ldg 0	RE (-)		Mandatory (Appliance AD)	
98-14-03  34 A/F Eff: 16-Aug-1998 Not Applicable	ALLIEDSIGNAL, INC. - KT 76A Transponders EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory (Appliance AD)	
98-25-02  34 A/F Eff: 22-Dec-1998 Complied With	BF Goodrich Avionics Systems, Inc. SKYWATCH SKY497 Installations with a Top-Mounted Antenna					Mos 07-Apr-1999 Hrs 2,159.2 Ldg 2,670	RE (-)		Mandatory (Appliance AD)	
99-23-22  34 A/F Not Applicable Brand A:9990-1999-23-22	Mode C Transponder EQUIPMENT NOT INSTALLED					Mos 09-Sep-2014 Hrs 6,186 Ldg 6,407	RE (-)		Mandatory (Appliance AD)	
A341008  34 A/F 051220 Ref.:34-11-10-220 (ZONE: 141, 142)	Static Port Height and Slope Check (Airplanes certified for RVSM) - Perform					Mos 06-Oct-2016 Hrs 6,848.2 Ldg 6,940	RE	Continuous Inspection Program		24 +1 31-Oct-2018 8.8 Months (+30 Days)
A341009  34 A/F 051205 Ref.:34-13-06-730	Safe Flight Angle-Of-Attack System - Perform check					Mos 36 Hrs 1,200 Ldg	RE	Continuous Inspection Program		+2 (31-Oct-2019) 1.7 Years (+61 Days) +100 (8,048.2) 844.3 Hrs (+100)
A341012  34 A/F 051220 Ref.:34-11-07-220 (ZONE: 141, 142)	Static Port Height and Slope Check (AirplanesCertified for RVSM Operation) - Perform check					Mos 24 Hrs Ldg	RE	Continuous Inspection Program		+1 (31-Oct-2018) 8.8 Months (+30 Days)
A342001  34 A/F 051205 Ref.:34-21-01-210	Magnetic Compass and Compass Card - Inspect					Mos 36 Hrs 1,200 Ldg	RE	Continuous Inspection Program		+2 (31-Oct-2019) 1.7 Years (+61 Days) +100 (8,048.2) 844.3 Hrs (+100)

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B341001	Airspeed Indicators, Overspeed Warning Switch, and Landing Gear Warning Switch Including Installed Altimeters Maximum Difference Allowable Check (A/C Not Certified For RVSM) - Perform calibration test						RE (N/A)		Continuous Inspection Program	
 34 A/F Ref.:34-11-00-280 (ZONE: AUX)					Mos					
					Hrs					
					Ldg					
B341002	Teledyne Angle-of-Attack System - Perform operational test						RE		Continuous Inspection Program	
 34 A/F Ref.:34-13-00-710	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B341003	Automatic Pressure Altitude Reporting System, Air Data Computer, and Altimeter (Airplanes Not Certified for RVSM) - Perform calibration test required by 14 CFR 91.411						RE (N/A)		Continuous Inspection Program	
 34 A/F Ref.:34-14-00-730 (ZONE: LAB)					Mos					
					Hrs					
					Ldg					
B341004	Barometric Altimeter (Airplanes Not Certified for RVSM) - Perform calibration required by 14 CFR 91.411						RE (N/A)		Continuous Inspection Program	
 34 A/F Ref.:34-14-00-731 (ZONE: AUX)					Mos					
					Hrs					
					Ldg					
B341005	Pitot and Static System (Airplanes Not Certified for RVSM) - Perform leak test required by 14 CFR 91.411						RE (N/A)		Continuous Inspection Program	
 34 A/F Ref.:34-11-00-780 (ZONE: AUX)					Mos					
					Hrs					
					Ldg					
B341010	Air Data Systems - Perform check						RE		Continuous Inspection Program	
 34 A/F 7014700-601 94030235 Ref.:34-11-25-720 (ZONE: AUX)	No.1 051220				Mos	06-Oct-2016	24	+1	31-Oct-2018	8.8 Months (+30 Days)
					Hrs	6,848.2				
					Ldg	6,940				
B341010	Air Data Systems - Perform check						RE		Continuous Inspection Program	
 34 A/F 7014700-601 94060294 Ref.:34-11-25-720 (ZONE: AUX)	No.2 051220				Mos	06-Oct-2016	24	+1	31-Oct-2018	8.8 Months (+30 Days)
					Hrs	6,848.2				
					Ldg	6,940				
B341011	Air Data Systems Check (AirplanesCertified for RVSM Certification) - Perform check						RE		Continuous Inspection Program	
 34 A/F Ref.:34-11-07-720 (ZONE: AUX)	051220				Mos		24	+1	(31-Oct-2018)	8.8 Months (+30 Days)
					Hrs					
					Ldg					
B341013	Air Data Systems - Perform check						RE		Continuous Inspection Program	
 34 A/F Ref.:34-11-26-720 (ZONE: AUX)	051220				Mos		24	+1	(31-Oct-2018)	8.8 Months (+30 Days)
					Hrs					
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B341014	Air Data Systems - Perform check						RE	Continuous Inspection Program		
 34 A/F	051220				Mos		24	+1	(31-Oct-2018)	8.8 Months (+30 Days)
Ref.:34-11-30-720 (ZONE: AUX)					Hrs					
					Ldg					
B341301	Teledyne Primary Angle-of-Attack Flap-Position Potentiometer Adjustment - Perform operational check						RE	Continuous Inspection Program		
 34 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:34-13-00-711					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B341302	Teledyne Secondary Angle-of-Attack Flap-Position Potentiometer Adjustment. Perform operational check						RE	Continuous Inspection Program		
 34 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:34-13-00-713					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B341303	Teledyne Angle-of-Attack System. Perform Flight Calibration						RE	Continuous Inspection Program		
 34 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:34-13-00-715					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B341304	Safe Flight Angle-of-Attack System Check (Airplanes - Perform operational check						RE	Continuous Inspection Program		
 34 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:34-13-02-710					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B341305	Safe Flight Secondary Angle-of-Attack System Check (if installed) - Perform operational check						RE	Continuous Inspection Program		
 34 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:34-13-05-710					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B341306	Teledyne Primary Angle-of-Attack System Anti-Ice Mode Test - Perform operational check						RE (N/A)	Continuous Inspection Program		
 34 A/F					Mos					
Ref.:34-13-00-712 (ZONE: AUX)					Hrs					
					Ldg					
B341307	Teledyne Secondary Angle-of-Attack System Anti-Ice Mode Test - Perform operational check						RE (N/A)	Continuous Inspection Program		
 34 A/F					Mos					
Ref.:34-13-00-714 (ZONE: AUX)					Hrs					
					Ldg					
B341308	Safe Flight Angle-of-Attack System Ice Mode Check - Perform Operational Check						RE (N/A)	Continuous Inspection Program		
 34 A/F					Mos					
Ref.:34-13-02-711 (ZONE: AUX)					Hrs					
					Ldg					
B341309	Safe Flight Secondary Angle-of-Attack System Ice Mode Check (Airplanes -0400 thru -0538, if installed). Perform Operational Check						RE (N/A)	Continuous Inspection Program		
 34 A/F					Mos					
Ref.:34-13-05-711 (ZONE: AUX)					Hrs					
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B341310 34 A/F Ref.:34-13-02-720	Safe Flight Angle-of-Attack System - Perform Flight Calibration 051205						RE	Continuous Inspection Program		
					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B341311 34 A/F Ref.:34-13-05-720	Safe Flight Secondary Angle-of-Attack System (if installed) - Perform Flight Calibration 051205						RE	Continuous Inspection Program		
					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B342001 34 A/F Ref.:34-21-05-710	Compass Systems and ADF Bearing - Perform operational test 051205						RE	Continuous Inspection Program		
					Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
B342003 34 A/F Unknown Unknown Ref.:34-21-12-760 (AVG MAN HRS: 0) (APX COST [USD]: 0)	PS-835 Emergency Power Supply - Perform capacity test 051218						RE	Continuous Inspection Program		
					Mos	11-Oct-2017	12	+1	(31-Oct-2018)	8.8 Months (+30 Days)
					Hrs	7,170.5				
					Ldg	7,207				
B342004 34 A/F Unknown Unknown Ref.:34-21-12-761 (ZONE: AUX, 110, 211) (AVG MAN HRS: 0) (APX COST [USD]: 0)	PS-835 Emergency Power Supply - Perform periodic check 051211						RE	Continuous Inspection Program		
					Mos	11-Oct-2017	3		(30-Apr-2018)	81 Days (+30)
					Hrs	7,170.5				
					Ldg	7,207				
B342005 34 A/F 501-1228-03 1126 Ref.:34-21-12-763	PS-850 and PS-855 Emergency Power Supply - Perform capacity test						RE (N/A)	Continuous Inspection Program		
					Mos					
					Hrs					
					Ldg					
B342006 34 A/F 501-1228-03 1126 Ref.:34-21-12-710 (ZONE: BAT)	PS-850 and PS-855 Emergency Power Supply - Perform periodic check						RE (N/A)	Continuous Inspection Program		
					Mos					
					Hrs					
					Ldg					
B342008 34 A/F 501-1228-03 1126 Ref.:34-21-12-712 (ZONE: BAT)	Standby Flight Display Battery Pack - Perform functional check						RE (N/A)	Continuous Inspection Program		
					Mos					
					Hrs					
					Ldg					
B342010 34 A/F 501-1228-03 1126 Ref.:34-21-17-760 (ZONE: BAT)	Securaplane Standby Battery Operational Check - Perform Energy Level Check						RE (N/A)	Continuous Inspection Program		
					Mos					
					Hrs					
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B342011  34 A/F Ref.:34-21-16-720	Collins Pro-Line 21 AHRS Compass Accuracy Check						RE (N/A)	Continuous Inspection Program		
						Mos				
						Hrs				
						Ldg				
B345001  34 A/F 066-01143-0601 2445 Ref.:34-54-00-730 (ZONE: LAB)	Transponder System - Perform calibration test required by 14 CFR 91.413 No.1 051220					Mos	06-Oct-2016	24	+1	31-Oct-2018 8.8 Months (+30 Days)
						Hrs	6,848.2			
						Ldg	6,940			
B345001  34 A/F 066-01143-0601 2446 Ref.:34-54-00-730 (ZONE: LAB)	Transponder System - Perform calibration test required by 14 CFR 91.413 No.2 051220					Mos	06-Oct-2016	24	+1	31-Oct-2018 8.8 Months (+30 Days)
						Hrs	6,848.2			
						Ldg	6,940			
CIL-34-02  34 A/F Eff: 18-Mar-2013 Not Applicable	Transmittal of Honeywell SILD201301000032, Primus II Integrated Radio System EQUIPMENT NOT INSTALLED					Mos	30-Apr-2013			
						Hrs	5,934.3			
						Ldg	6,216			
FAR 91.411  34 A/F Inspected Date 06-Oct-2016	Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43					Mos	06-Oct-2016	24		FAR91, FAR 91 31-Oct-2018 8.8 Months
						Hrs	6,848.2			
						Ldg	6,940			
FAR 91.411  34 A/F Inspected Date 06-Oct-2016	Air Data Computer tests and inspections per FAR 91.411 Appendix E of Part 43					Mos	06-Oct-2016	24		FAR91, FAR 91 31-Oct-2018 8.8 Months
						Hrs	6,848.2			
						Ldg	6,940			
FAR 91.411  34 A/F (AVG MAN HRS: 0) (APX COST [USD]: 0)	Altimeter Standby Indicator tests and inspections per FAR 91.411					Mos	06-Oct-2016	24		FAR91, FAR 91 31-Oct-2018 8.8 Months
						Hrs	7,165.5			
						Ldg	7,205			
FAR 91.411  34 A/F Certified Date 06-Oct-2016	Pitot/ Static Systems Leak check per FAR 91.411 Appendix E of Part 43					Mos	06-Oct-2016	24		FAR91, FAR 91 31-Oct-2018 8.8 Months
						Hrs	6,848.2			
						Ldg	6,940			
SL560-34-11A  34 A/F Eff: 23-Jun-1997 Complied With	Navigation - KLN 89B, KLN 90B and KLN 900 GPS Instrument Landing System Approach Restrictions					Mos	11-Nov-1997			
						Hrs	1,483			
						Ldg	0			
SL560-34-18  34 A/F Eff: 12-Sep-2002	Navigation - TCAS Compatability with RVSM Operations					Mos		T (A/R)		Informational
						Hrs				
						Ldg				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
SL560-34-21A  34 A/F Eff: 17-Feb-2003 Not Applicable	Navigation - Transmittal of Honeywell Technical Newsletter A23-3850-001 EQUIPMENT NOT INSTALLED					Mos 06-Mar-2003 Hrs 3,659.1 Ldg 4,290	RE (-)		Mandatory	
SL560-34-23  34 A/F Not Applicable	GNS-XL Flight Management System (FMS) Mod 4 Upgrade EQUIPMENT NOT INSTALLED					Mos 30-Dec-2004 Hrs 4,143 Ldg 0	RE (-)		Recommended	
SL560-34-29  34 A/F Eff: 17-Mar-2006 Complied With	Elementary Surveillance Transponder Product Improvement					Mos 30-Jun-2007 Hrs 4,813 Ldg 5,385	RE (-)		Mandatory	
SL560-34-34A  34 A/F Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures					Mos 17-Feb-2009 Hrs 5,132.4 Ldg 5,646	RE (-)		Mandatory	
SL560-34-34A R01  34 A/F Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures					Mos 17-Feb-2009 Hrs 5,131 Ldg 0	RE (-)		Mandatory	
SL560-34-34A R02  34 A/F Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures					Mos 17-Feb-2009 Hrs 5,131 Ldg 0	RE (-)		Mandatory	
SL560-34-34A R03  34 A/F Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures					Mos 17-Feb-2009 Hrs 5,131 Ldg 0	RE (-)		Mandatory	
SL560-34-34A R04  34 A/F Eff: 17-Nov-2008 Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures					Yrs 17-Feb-2009 Hrs 5,131 Ldg 0	RE (-)		Mandatory	
SL560-34-35A  34 A/F Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures					Mos 23-Feb-2009 Hrs 5,141 Ldg 5,650	RE (-)		Mandatory	
SL560-34-35A R01  34 A/F Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures					Mos 23-Feb-2009 Hrs 5,141 Ldg 0	RE (-)		Mandatory	

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 SL560-34-35A R02 34 A/F Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures								RE (-)	Mandatory
					Mos	23-Feb-2009				
					Hrs	5,141				
					Ldg	0				
 SL560-34-35A R03 34 A/F Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures								RE (-)	Mandatory
					Mos	23-Feb-2009				
					Hrs	5,141				
					Ldg	0				
 SL560-34-35A R04 34 A/F Eff: 17-Nov-2008 Complied With	Stall Warning System Calibration, Adjustment, and In-Flight Test Procedures								RE (-)	Mandatory
					Yrs	23-Feb-2009				
					Hrs	5,141				
					Ldg	0				
 SL560-34-36 34 A/F Eff: 16-Feb-2009 Not Applicable	Transmittal of Honeywell SWB MST 67A-SW5								RE (-)	Recommended
	EQUIPMENT NOT INSTALLED					Mos	12-Nov-2010			
					Hrs	5,567.5				
					Ldg	5,970				
▼ 35 - OXYGEN										
 35 A/F	Co-Pilots Oxygen Mask Overhaul								RE	
					Mos	12-Nov-2014	144		30-Nov-2026	8.8 Years
					Hrs	6,246.6				
					Ldg	6,462				
 35 A/F Unknown Unknown	Goggles Installation Factory Option								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 35 A/F 176176-64 N320701/0515 Manufactured Date 01-Apr-2016 (NOTE: Note: with DOT Rating of DOT3HT1850)	Oxygen Cylinder	0			Yrs	06-Oct-2016	24		Component Time Limits	22.2 Years
		0			Hrs	6,848.2				
		0			Ldg	6,940				
 35 A/F 174252-17 02158	Oxygen Mask								RE (O/C)	
	Copilot	0			Mos	27-Feb-2003				
		0			Hrs	3,655				
		0			Ldg	0				
 35 A/F 174252-17 01379	Oxygen Mask								RE (O/C)	
	Pilot	0			Mos	27-Feb-2003				
		0			Hrs	3,655				
		0			Ldg	0				
 35 A/F C668512-0101 726	Oxygen Pressure Gauge								RE (O/C)	
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 35 A/F P24031 2844	Oxygen Pressure Switch								RE (O/C)	
		0			Mos	31-Oct-2005				
		0			Hrs	4,405				
		0			Ldg	0				
 35 A/F 172170-01 1043	Oxygen Supply Regulator								RE (O/C)	
		0			Mos	30-Jan-2012				
		0			Hrs	5,663.6				
		0			Ldg	6,043				
 35 A/F Unknown Unknown	Passenger Oxygen Mask No.1								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 35 A/F Unknown Unknown	Passenger Oxygen Mask No.10								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 35 A/F Unknown Unknown	Passenger Oxygen Mask No.2								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 35 A/F Unknown Unknown	Passenger Oxygen Mask No.3								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 35 A/F Unknown Unknown	Passenger Oxygen Mask No.4								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 35 A/F Unknown Unknown	Passenger Oxygen Mask No.5								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 35 A/F Unknown Unknown	Passenger Oxygen Mask No.6								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 35 A/F Unknown Unknown	Passenger Oxygen Mask No.7								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				

Task No	Description		TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition									DUE	Remaining
 35 A/F Unknown Unknown	Passenger Oxygen Mask							RE (O/C)			
	No.8						Mos	15-Nov-1994			
							Hrs	0			
							Ldg	0			
 35 A/F Unknown Unknown	Passenger Oxygen Mask							RE (O/C)			
	No.9						Mos	15-Nov-1994			
							Hrs	0			
							Ldg	0			
 35 A/F	Pilots Oxygen Mask Overhaul							RE			
							Mos	12-Nov-2014	144	30-Nov-2026	8.8 Years
							Hrs	6,246.6			
							Ldg	6,462			
2007-26-11		Intertechnique Zodiac Aircraft Systems - F5341 High-pressure oxygen cylinder						RE (-)		Mandatory (Appliance AD)	
 35 A/F Eff: 28-Jan-2008 Not Applicable Brand A:9990-2007-26-11	EQUIPMENT NOT INSTALLED						Mos	09-Sep-2014			
							Hrs	6,186			
							Ldg	6,407			
2009-21-10		AVOX Systems and B/E Aerospace Oxygen Cylinder Assemblies						RE (-)		Mandatory (Appliance AD)	
 35 A/F Not Applicable	EQUIPMENT NOT INSTALLED						Mos	09-Sep-2014			
							Hrs	6,186			
							Ldg	6,407			
2009-21-10 R1		AVOX Systems and B/E Aerospace Oxygen Cylinder Assemblies						RE (-)		Mandatory (Appliance AD)	
 35 A/F Eff: 04-Feb-2010 Not Applicable Brand A:9990-2009-21-10R1	EQUIPMENT NOT INSTALLED						Mos	09-Sep-2014			
							Hrs	6,186			
							Ldg	6,407			
2010-11-05		AVOX Systems and B/E Aerospace - Type 2HT Oxygen Cylinders						RE (-)		Mandatory (Appliance AD)	
 35 A/F Eff: 06-Jul-2010 Not Applicable Brand A:9990-2010-11-05 (AVG MAN HRS: 0.5) (APX COST [USD]: 42.5) (NOTE: Within 60 days after the effective date of this AD, inspect the oxygen cylinder installed in the airplane to determine the serial number and replace if needed)	EQUIPMENT NOT INSTALLED						Mos	09-Sep-2014			
							Hrs	6,186			
							Ldg	6,407			
2011-01-09		B/E Aerospace - Oxygen - PBE units having PN 119003-11						RE (-)		Mandatory (Appliance AD)	
 35 A/F Eff: 09-Feb-2011 Not Applicable Brand A:9990-2011-01-09 (AVG MAN HRS: 1) (APX COST [USD]: 85)	EQUIPMENT NOT INSTALLED						Mos	30-Jan-2012			
							Hrs	5,663.6			
							Ldg	6,043			
2011-14-08		B/E Aerospace, Continuous Flow Passenger Oxygen Mask Assembly						RE (-)		Mandatory (Appliance AD)	
 35 A/F Eff: 19-Aug-2011 Not Applicable Brand A:9990-2011-14-08 (AVG MAN HRS: 0.5) (APX COST [USD]: 48.5)	EQUIPMENT NOT INSTALLED						Mos	30-Jan-2012			
							Hrs	5,663.6			
							Ldg	6,043			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
2012-11-09	Chemical oxygen generator installation								RE (-)	Mandatory (Appliance AD)
35 A/F Eff: 10-Aug-2012 Not Applicable Brand A:9990-2012-11-09 (AVG MAN HRS: 26) (APX COST [USD]: 8,210)	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	30-Jan-2012 5,663.6 6,043			
2012-11-09 R1	Chemical Oxygen Generator Installation								RE (-)	Mandatory (Appliance AD)
35 A/F Eff: 27-Jul-2015 Not Applicable Brand A:9990-2012-11-09R1	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	10-Sep-2015 6,579.2 6,728			
2015-08-07 Paragraph (g)	Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators - Inspection								RE (-)	Mandatory (Appliance AD)
35 A/F Not Applicable	P/N NOT INSTALLED					Mos Hrs Ldg	19-May-2017 7,068.3 7,114			
2015-08-07 Paragraph (h)	Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators - Replacement								RE (-)	Mandatory (Appliance AD)
35 A/F Not Applicable	P/N NOT INSTALLED					Mos Hrs Ldg	19-May-2017 7,068.3 7,114			
2015-23-09 Para (g)	Oxygen - Inspect Each Flightcrew Oxygen Mask Regulator To Identify The Part Number And Serial Number								RE (-)	Mandatory (Appliance AD)
35 A/F Eff: 28-Dec-2015 Not Applicable	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	20-Jan-2016 6,642.3 6,776			
2016-11-20 Paragraph (g)	Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11 - Inspection								RE (-)	Mandatory (Appliance AD)
35 A/F Eff: 15-Jul-2016 Not Applicable Brand A:9990-2016-11-20(g)	EQUIPMENT NOT INSTALLED					Mos Hrs Ldg	21-Oct-2016 6,848.2 6,940			
2016-11-20 Paragraph (h)	Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11 - Replacement								RE (-)	Mandatory (Appliance AD)
35 A/F Eff: 15-Jul-2016 Not Applicable Brand A:9990-2016-11-20(h)						Mos Hrs Ldg	04-Oct-2017 7,165.5 7,205			
2017-18-12 Par. 2(i)	Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - New Inspection for Airplanes With PBE, P/N 119003-21, Installed								T	Mandatory (Appliance AD)
35 A/F Eff: 16-Oct-2017 (AVG MAN HRS: 0.5) (NOTE: NOTE: Réfer to B/E Aerospace SB No. 119003-35-013, Rev. 002, dated July 19,2017.)						Mos Hrs Ldg	6 16-Apr-2018			67 Days
2017-18-12 Par. 2(j)	Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units - New Replacement for Airplanes With PBE, P/N 119003-21, Installed								T (Before Next Flight)	Mandatory (Appliance AD)
35 A/F Eff: 16-Oct-2017 (AVG MAN HRS: 0.5) (NOTE: NOTE: Refer to B/E Aerospace SB No. 119003-35-013, Rev. 002, dated July 19, 2017.)						Mos Hrs Ldg	[16-Apr-2018]			67 Days

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
5-11-00(2)(I)(1)(2)(3)	Oxygen Cylinder - Hydrostatic Test								RE	Component Time Limits
 35 A/F 176176-64 N320701/0515 Hydrostatic Tested Date 06-Oct-2016 Ref.:35-10-00-780 (NOTE: Note: DOT Cylinder Marking 3HT 1850)						Yrs	06-Oct-2016	3	31-Oct-2019	1.7 Years
						Hrs	6,848.2			
						Ldg	6,940			
5-11-00(2)(I)(4)	Oxygen mask, Scott EROS - Overhaul								RE (N/A)	
 35 A/F 174252-17 02158 (NOTE: NOTE: Under normal environmental conditions and use, the masks must be overhauled every six years. If masks are exposed to environments that accelerate aging of elastomer components, periodic inspection may warrant shorter intervals between overhaul periods. Refer to Scott/EROS MA/MC Series Quick-Donning Mask-Regulator Assembly Operating Instruction booklet, part number 89201-01 for overhaul.)	Copilot					Mos				
						Hrs				
						Ldg				
5-11-00(2)(I)(4)	Oxygen mask, Scott EROS - Overhaul								RE (N/A)	
 35 A/F 174252-17 01379 (NOTE: NOTE: Under normal environmental conditions and use, the masks must be overhauled every six years. If masks are exposed to environments that accelerate aging of elastomer components, periodic inspection may warrant shorter intervals between overhaul periods. Refer to Scott/EROS MA/MC Series Quick-Donning Mask-Regulator Assembly Operating Instruction booklet, part number 89201-01 for overhaul.)	Pilot					Mos				
						Hrs				
						Ldg				
560-35-06A	174252-06 Oxygen Mask Switch Modification								RE (-)	Mandatory
 35 A/F Eff: 23-Dec-1994 Complied With						Mos	03-Jan-1995			
						Hrs	81.2			
						Ldg	114			
560-35-07	Crew Oxygen Mask Installation With Improved Microphone								RE (-)	Recommended
 35 A/F Eff: 23-Aug-1996 Complied With						Mos	02-Apr-1997			
						Hrs	1,224			
						Ldg	0			
97-18-03	Puritan-Bennett Aero Systems Co. - Cone and Seal Assemblies								RE (-)	Mandatory (Appliance AD)
 35 A/F Eff: 22-Sep-1997 Not Applicable	EQUIPMENT NOT INSTALLED					Mos	09-Sep-2014			
						Hrs	6,186			
						Ldg	6,407			
99-08-21	Puritan-Bennett Aero Systems Company C351-2000 Series Passenger Oxygen Masks and Portable Oxygen Masks - Passenger Oxygen Masks								RE (-)	Mandatory (Appliance AD)
 35 A/F Eff: 02-Jun-1999 Not Applicable Brand A:9990-1999-08-21	N/A BY MANUFACTURE					Mos	06-Oct-1999			
						Hrs	2,411			
						Ldg	0			
A351001	Oxygen System - Inspect								RE	Continuous Inspection Program
 35 A/F 051205 Ref.:35-00-05-210						Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
						Ldg				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A351007	Passenger Oxygen Masks- Inspect								RE Continuous Inspection Program	
 35 A/F	051218					Mos	11-Oct-2017	12	+1 (31-Oct-2018)	8.8 Months (+30 Days)
Ref.:35-20-00-210 (AVG MAN HRS: 0) (APX COST [USD]: 0)						Hrs	7,170.5			
						Ldg	7,207			
B350006	Oxygen System, Flow Fuses and Shuttle Valves - Perform functional test								RE Continuous Inspection Program	
 35 A/F	051205					Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)
Ref.:35-10-00-721						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
						Ldg				
B351002	Oxygen System - Perform functional test								RE Continuous Inspection Program	
 35 A/F	051205					Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)
Ref.:35-10-00-720						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
						Ldg				
B351003	Oxygen Mask Inspection, Flow Check and Micro- phone Operational Check - Perform								RE Continuous Inspection Program	
 35 A/F	051205					Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)
Ref.:35-10-01-710 (ZONE: 241, 242)						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)
						Ldg				
SL560-35-03	Oxygen Capillary Line Support Inspection								RE (-) Recommended	
 35 A/F						Mos	02-Apr-1997			
Eff: 15-Nov-1996 Complied With						Hrs	1,224			
						Ldg	0			
SL560-35-04	Oxygen - Portable Oxygen Cylinder Mask Inspection/Replacement								RE (-) Recommended	
 35 A/F						Mos	01-Apr-2002			
Eff: 10-Mar-2001 Not Applicable	EQUIPMENT NOT INSTALLED					Hrs	3,361			
						Ldg	0			
SL560-35-07	Transmittal Of Inter technique Service Bulletin MXH-35-240 Revision 2								RE (-) Mandatory	
 35 A/F						Mos	31-May-2013			
Not Applicable	N/A BY P/N AND S/N INSTALLED					Hrs	5,950.9			
						Ldg	6,226			
SL560-35-07 R01	Transmittal Of Inter technique Service Bulletin MXH-35-240 Revision 2								RE (-) Mandatory	
 35 A/F						Mos	31-May-2013			
Not Applicable	N/A BY P/N AND S/N INSTALLED					Hrs	5,950.9			
						Ldg	6,226			
▼ 36 - PNEUMATIC										
 36 A/F	Bleed Air Check Valve								RE (O/C)	
1553-00-18	No.1					Mos	15-Nov-1994			
786		0				Hrs	0			
		0				Ldg	0			
 36 A/F	Bleed Air Check Valve								RE (O/C)	
1553-00-18	No.2					Mos	15-Nov-1994			
770		0				Hrs	0			
		0				Ldg	0			

Task No	Description						TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition													DUE	Remaining
 36 A/F 38E85-5C B2496	Pneumatic Regulator													RE (O/C)	
							0			Mos	03-Feb-1999				
							0			Hrs	2,105				
							0			Ldg	0				
A361004	Bleed Air Check Valve - Inspect											RE	Continuous Inspection Program	≈10-Sep-2018	
 36 A/F 1553-00-18 786 Ref.:36-11-00-211 (ZONE: 311, 312)	No.1 051203									Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
										Hrs		300	+30	(7,422)	218.1 Hrs (+30)
										Ldg					
A361004	Bleed Air Check Valve - Inspect											RE	Continuous Inspection Program	≈10-Sep-2018	
 36 A/F 1553-00-18 770 Ref.:36-11-00-211 (ZONE: 311, 312)	No.2 051203									Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
										Hrs		300	+30	(7,422)	218.1 Hrs (+30)
										Ldg					
A361005	Engine Bleed Air Bellows Leak Check											RE	Continuous Inspection Program	≈10-Sep-2018	
 36 A/F 051204 Ref.:36-10-00-210 (ZONE: 410, 420)										Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
										Hrs		300	+30	(7,422)	218.1 Hrs (+30)
										Ldg					
A361101	Tailcone Bleed Air Lines Leak Check											RE	Continuous Inspection Program	≈10-Sep-2018	
 36 A/F 051204 Ref.:36-11-00-210 (ZONE: 410, 411, 412, 420, ENG)										Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
										Hrs		300	+30	(7,422)	218.1 Hrs (+30)
										Ldg					
A361102	Tailcone Bleed Air Line Peri-Seals Detailed Inspection. Inspect											RE	Continuous Inspection Program	≈10-Sep-2018	
 36 A/F 051204 Ref.:36-11-01-220 (ZONE: 410, 420)										Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
										Hrs		300	+30	(7,422)	218.1 Hrs (+30)
										Ldg					
D361100	Service Air System Peri-Seal Replacement											RE	Continuous Inspection Program		
 36 A/F 051205 Ref.:36-11-01-960 (ZONE: 311, 312)										Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
										Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
										Ldg					
SL560-36-01A	Inspection/Replacement Of Periseal											RE (-)		Mandatory	
 36 A/F Eff: 04-Aug-1997 Complied With										Mos	07-Aug-1997				
										Hrs	1,453				
										Ldg	0				
▼ 37 - VACUUM															
D371001	Vacuum Regulator (Pressure Line) - Clean or replace in- line filter screen											RE	Continuous Inspection Program		
 37 A/F 051205 Ref.:37-11-00-901										Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
										Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
										Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
▼ 38 - WATER/WASTE										
Motor And Pump Toilet										
 38 A/F 17200-382 NSN		0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
B383001 Refreshment Center Drains - Perform operational check										
 38 A/F Ref.:38-30-00-710	051205				Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)	
					Ldg					
▼ 51 - STANDARD PRACTICES AND STRUCTURES - GENERAL										
A510001 Exterior Moisture Drain Holes - Inspect										
 51 A/F Ref.:51-10-00-160 (ZONE: 131, 132, 141, 151, 161, 171, 172,) (NOTE: More zone: 411, 412, 511, 512, 611, 612)	051201				Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)	
					Hrs	300	+30	(7,422)	218.1 Hrs (+30)	
					Ldg					
▼ 52 - DOORS										
Cabin Door Seal										
 52 A/F S15501-1 NSN		0			Mos	02-Apr-1997			RE (O/C)	
		0			Hrs	1,224				
		0			Ldg	0				
Emergency Exit Door										
 52 A/F Unknown Unknown					Mos	15-Nov-1994			RE (O/C)	
					Hrs	0				
					Ldg	0				
Emergency Exit Seal										
 52 A/F R881204 Unknown		0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Ldg	0				
Nose Baggage Door										
 52 A/F Unknown Unknown	Left				Mos	15-Nov-1994			RE (O/C)	
					Hrs	0				
					Ldg	0				
Nose Baggage Door										
 52 A/F Unknown Unknown	Right				Mos	15-Nov-1994			RE (O/C)	
					Hrs	0				
					Ldg	0				
560-52-12 R02 Doors - Rain Gutter Fastener Inspection/Replacement										
 52 A/F Eff: 20-Mar-2000 Complied With					Mos	10-Dec-2001			RE (-) Recommended	
					Hrs	3,235				
					Ldg	0				
A521001 Standard Cabin Door Inflatable Seal - Perform visual inspection										
 52 A/F Ref.:52-10-01-210	051205				Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)	
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A521003	Standard Cabin Door - Inspect						RE		Continuous Inspection Program	
 52 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:52-10-01-211					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A521004	Standard Cabin Door Locking Pins - Inspect						RE		Continuous Inspection Program	≈12-May-2025
 52 A/F	051213				Mos					
Ref.:52-10-02-210					Hrs		5,000	+10	(9,823.4)	2,619.5 Hrs (+10)
					Ldg					
A521005	Standard Cabin Door Locking Components Bearing Plates - Inspect						T		Continuous Inspection Program	≈09-Nov-2025
 52 A/F	051216				Mos					
Ref.:52-10-02-211 (ZONE: 810)					Hrs		10,000	+10	(10,000.4)	2,796.5 Hrs (+10)
					Ldg					
A521006	Optional Rotary Latching Cargo Cabin Door - Inspect seal, handle, extend/retract system, upper and lower lock mechanism and perform force test						RE (N/A)		Continuous Inspection Program	≈10-Sep-2018
 52 A/F	051201				Mos				(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:52-10-04-710 (ZONE: 810)					Hrs				(7,422)	218.1 Hrs (+30)
					Ldg					
A521007	Optional Pin Latching Cargo Cabin Door Visual Inspection - Perform						RE		Continuous Inspection Program	
 52 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:52-10-05-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A521008	Entrance Door Secondary Seal - Inspect						RE		Continuous Inspection Program	≈10-Sep-2018
 52 A/F	051201,...				Mos	21-Jul-2017	24	+2	≈21-Jul-2019	
Ref.:52-10-01-212 (ZONE: 810)					Hrs	7,122	300	+30	≈7,422	
					Ldg	7,168				
A522002	Emergency Exit Door Inspection - Inspect						RE		Continuous Inspection Program	
 52 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:52-20-01-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A523001	Nose Baggage Door and Latches - Inspect						RE		Continuous Inspection Program	
 52 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:52-30-01-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A523002	Tailcone Door - Inspect						RE		Continuous Inspection Program	
 52 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:52-30-01-211 (ZONE: 311, 312)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A526001	Standard Cabin Door Step (If Installed) - Inspect						RE		Continuous Inspection Program	≈10-Sep-2018
 52 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:52-60-01-210 (ZONE: 810)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A526002	Standard Cabin Door Composite Step (If Installed)) - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 52 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:52-60-01-211 (ZONE: 810)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
B521008	Cabin Entrance Door Secondary Seal - Do an operational test								RE Continuous Inspection Program	
 52 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:21-30-00-711					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
C521002	Cabin Door Hinge - Lubricate								RE Continuous Inspection Program	
 52 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:52-10-01-640					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
SL560-52-05A	Emergency Exit Inspection								RE (-) Mandatory	
 52 A/F					Days	11-May-2012				
Eff: 12-Jan-2011 Complied With					Hrs	5,684.9				
					Ldg	6,055				
▼ 53 - FUSELAGE										
	Nose Landing Gear Actuator Fitting								RE AWL, Component Time Limits	≈02-Mar-2084
 53 A/F		0			Mos	15-Nov-1994				
6511105-1		0			Hrs	0				
NSN		0			Ldg	0	23,100		23,100	15,860 Ldg
	Radome								RE (O/C)	
 53 A/F					Mos	15-Nov-1994				
Unknown					Hrs	0				
Unknown					Ldg	0				
560-53-19	Cockpit Floorboard Installation Inspection/Repair								RE (-) Mandatory	
 53 A/F					Mos	01-Jun-1996				
Eff: 22-Mar-1996 Complied With					Hrs	765.3				
					Ldg	1,047				
560-53-20	AN3-5A Bolt Inspection/Replacement								RE (-) Recommended	
 53 A/F					Mos	02-Apr-1997				
Eff: 12-Apr-1996 Complied With					Hrs	1,224				
					Ldg	0				
560-53-22	Radome Diverter Strip Electrical Resistance Inspection								RE (-) Mandatory	
 53 A/F					Mos	02-Apr-1997				
Eff: 24-Jan-1997 Complied With					Hrs	1,224.6				
					Ldg	1,598				
560-53-23 R01	Main Carry Thru Lug Inspection/Repair								RE (-) Recommended	
 53 A/F					Mos	03-Feb-1999				
Eff: 12-Sep-1997 Complied With					Hrs	2,105				
					Ldg	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-53-25	Tailcone Baggage Compartment Support Improvement									
 53 A/F Complied With						Mos	27-Feb-1998		RE (-)	Recommended
						Hrs	1,705			
						Ldg	0			
560-53-26 R02	Lower Stub Wing Fairing Inspection/Repair									
 53 A/F Eff: 16-Dec-1998 Complied With						Mos	26-Apr-2002		RE (-)	Recommended
						Hrs	3,402			
						Ldg	0			
560-53-27	Cabin Entrance Aft Doorpost Inspection/Repair									
 53 A/F Eff: 10-Feb-1999 Complied With						Mos	16-Nov-1999		RE (-)	Recommended
						Hrs	2,436			
						Ldg	0			
560-53-29	Fuselage - Nose Wheel Steering Bracket Replacement									
 53 A/F Complied With						Mos	15-Feb-2000		RE (-)	Mandatory
						Hrs	2,549			
						Ldg	3,083			
560-53-29 R01	Fuselage - Nose Wheel Steering Bracket Replacement									
 53 A/F Complied With						Mos	01-Mar-2001		RE (-)	Mandatory
						Hrs	3,035			
						Ldg	3,614			
560-53-29 R02	Fuselage - Nose Wheel Steering Bracket Replacement									
 53 A/F Eff: 14-Oct-1999 Complied With						Mos	01-Mar-2001		RE (-)	Mandatory
						Hrs	3,035			
						Ldg	3,614			
A530001	Nose Landing Gear Wheel Well General Visual Inspection (Corrosion Inspection)									
 53 A/F	051218					Mos	11-Oct-2017	12	RE	Continuous Inspection Program
Ref.:53-00-00-210 (ZONE: 131, 132) (AVG MAN HRS: 0) (APX COST [USD]: 0)						Hrs	7,170.5	+1	(31-Oct-2018)	8.8 Months (+30 Days)
						Ldg	7,207			
A530002	Nose Landing Gear Wheel Well General Visual Inspection (Corrosion Inspection)									
 53 A/F	051264					Mos	11-Oct-2017	6	RE	Continuous Inspection Program
Ref:53-00-00-210 (ZONE: 131, 132) (AVG MAN HRS: 0) (APX COST [USD]: 0) (NOTE: For airplanes that operate in moderate, or severe corrosion environments. Refer to Chapter 51, Corrosion Severity Maps - Description and Operation)						Hrs	7,170.5	+1	(11-Apr-2018)	62 Days (+30)
						Ldg	7,207			
A531001	Forward Side of Pressure Bulkhead, Stringers and Bulk- heads - Inspect									
 53 A/F	051205					Mos		36	RE	Continuous Inspection Program
Ref.:53-10-00-210						Hrs	1,200	+2	(31-Oct-2019)	1.7 Years (+61 Days)
						Ldg		+100	(8,048.2)	844.3 Hrs (+100)
A531002	Underfloor - Inspect									
 53 A/F	051205					Mos		36	RE	Continuous Inspection Program
Ref:53-20-08-210						Hrs	1,200	+2	(31-Oct-2019)	1.7 Years (+61 Days)
						Ldg		+100	(8,048.2)	844.3 Hrs (+100)

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A531003	Aft Pressure Bulkhead Tailcone General Inspection - Inspect						RE		Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-20-04-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A531004	Front and Rear Spar Carry-Thru - Inspect						RE		Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-10-09-210 (ZONE: 171, 172)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A531005	Cabin Door Frame - Inspect (Chapter 4 Item)						RE (N/A)		Continuous Inspection Program	
 53 A/F					Mos					
Ref.:53-10-09-290 (ZONE: 151, 161, 251, 252)					Hrs					
					Ldg					
A531006	Emergency Exit Door Frame - Inspect (Chapter 4 Item)						RE		Continuous Inspection Program	≈15-Oct-2020
 53 A/F	0512MC				Mos					
Ref.:53-10-09-212 (ZONE: 252)					Hrs		1,456		(8,176.9)	973 Hrs
					Ldg					
A531007	Windshield, Cockpit Side Window and Cabin Window Frames - Inspect (Chapter 4 Item)						RE		Continuous Inspection Program	≈30-Jul-2026
 53 A/F	0512MI				Mos					
Ref.:53-30-00-211					Hrs		5,130		(10,261.4)	3,057.5 Hrs
					Ldg					
A531008	Fuselage Interior Cabin Structure - Inspect						RE		Continuous Inspection Program	≈10-Sep-2018
 53 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:53-10-09-216 (ZONE: 241, 242, 251, 252, 261, 262, 271, 272)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A531009	Cockpit and Cabin Structure - Inspect						RE		Continuous Inspection Program	≈08-Nov-2025
 53 A/F	051217				Mos					
Ref.:53-10-00-211 (ZONE: All CabinZones)					Hrs		10,000	+10	(10,000)	2,796.1 Hrs (+10)
					Ldg					
A531010	Optional Pin-Latch Cargo-Door and Door Frame - Inspect						RE		Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-10-09-215					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A531011	Main Carry-Thru to Wing Spar Lugs - Inspect						T		Continuous Inspection Program	≈08-Nov-2025
 53 A/F	051267				Mos					
Ref.:53-10-00-270 (ZONE: 511, 611)					Hrs		10,000	+10	(10,000)	2,796.1 Hrs (+10)
					Ldg					
A531012	Cabin Door Threshold - Inspect						RE		Continuous Inspection Program	≈10-Sep-2018
 53 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:53-10-09-213 (ZONE: 151)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A531013	Forward Pressure Bulkhead Attach Angles - Inspect (Chapter 4 Item)						RE	Continuous Inspection Program		≈04-Jun-2035
 53 A/F	0512MK				Mos					
Ref.:53-10-00-251 (ZONE: 141, 142,231, 232)					Hrs		6,725		(13,445.9)	6,242 Hrs
					Ldg					
A531014	Aft Pressure Bulkhead Attach Angles - Inspect (Chapter 4 Item)						RE	Continuous Inspection Program		≈04-Jun-2035
 53 A/F	0512MK				Mos					
Ref.:53-10-00-252 (ZONE: 171, 172,271, 272)					Hrs		6,725		(13,445.9)	6,242 Hrs
					Ldg					
A531015	Aft Pressure Bulkhead Web - Inspect						RE	Continuous Inspection Program		≈04-Jun-2035
 53 A/F	051234				Mos					
Ref.:53-10-04-210 (ZONE: 271, 272)					Hrs		6,725	+10	(13,445.9)	6,242 Hrs (+10)
					Ldg					
A531016	Cabin Doorframe (Pin Latching Optional Cargo Door) - Inspect						RE	Continuous Inspection Program		
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-10-00-212					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A531017	Main Spar Carry-Thru Assembly - Inspect						T	Continuous Inspection Program		≈29-May-2031
 53 A/F	051214				Mos					
Ref.:53-10-09-251 (ZONE: 161, 162, 171, 172)					Hrs		12,000	+10	(12,000)	4,796.1 Hrs (+10)
					Ldg					
A531019	Wing Attach Bolt and Lug - Inspect						RE	Continuous Inspection Program		
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-10-09-219					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A531020	Forward Side of Forward Pressure Bulkhead Web - Inspect (Chapter 4 Item)						RE	Continuous Inspection Program		≈06-May-2020
 53 A/F	0512ME				Mos					
Ref.:53-10-00-213 (ZONE: 131, 132, 221, 222)					Hrs		4,450		(8,018)	814.1 Hrs
					Ldg					
A531021	Aft Side of Aft Pressure Bulkhead Web - Inspect (Chapter 4 Item)						RE	Continuous Inspection Program		≈06-May-2020
 53 A/F	0512ME				Mos					
Ref.:53-10-04-211 (ZONE: 311, 312)					Hrs		4,450		(8,018)	814.1 Hrs
					Ldg					
A531023	Cabin Door Frame - Inspect (Chapter 4 Item)						RE (N/A)	Continuous Inspection Program		
 53 A/F					Mos					
Ref.:53-10-10-210 (ZONE: 151, 161, 251, 252)					Hrs					
					Ldg					
A531024	Optional Rotary Latch Cargo Door and Door Frame - Inspect						RE (N/A)	Continuous Inspection Program		
 53 A/F					Mos					
Ref.:53-10-09-215 (ZONE: 151, 161,251, 261)					Hrs					
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A531037	Stub Wing Shear Attach Fitting Bolt - Inspect								RE Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-10-02-210 (ZONE: 511, 611)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A532001	Control Pedestal Area - Inspect								RE Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-20-02-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A532002	Nose Gear Wheel Well - Inspect								RE Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-10-09-218					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A532003	Aft Cabin Underfloor - Inspect for corrosion								RE Continuous Inspection Program	
 53 A/F	051218				Mos	11-Oct-2017	12	+1	(31-Oct-2018)	8.8 Months (+30 Days)
Ref.:53-10-09-217 (ZONE: 171, 172) (AVG MAN HRS: 0) (APX COST [USD]: 0)					Hrs	7,170.5				
					Ldg	7,207				
A533001	Fuselage Exterior Skin - Inspect (Chapter 4 Item)								RE Continuous Inspection Program	≈30-Dec-2021
 53 A/F	0512MD				Mos					
Ref.:53-30-00-210 (ZONE: 141, 142, 151, 152, 161, 162, 171, 172, 261, 262)					Hrs		2,523		(8,610.7)	1,406.8 Hrs
					Ldg					
A533003	Cabin Lower Skin Longitudinal Splice - Inspect (Chapter 4 Item)								RE Continuous Inspection Program	≈06-Nov-2030
 53 A/F	0512MJ				Mos					
Ref.:53-30-00-251 (ZONE: 141, 142, 151, 152, 161, 162, 171, 172)					Hrs		5,900		(11,797.7)	4,593.8 Hrs
					Ldg					
A533006	Fuselage Exterior Skin Corrosion Inspection - Inspect								RE Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-30-00-214					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A533010	Perform Fuselage Skin Joint Eddy Current Inspection								RE Continuous Inspection Program	
 53 A/F	051249				Mos	11-Oct-2017	36	+2	(31-Oct-2020)	2.7 Years (+61 Days)
Ref.:53-30-00-250 (ZONE: 241, 242,251, 252,261, 262,271, 272) (AVG MAN HRS: 0) (APX COST [USD]: 0) (NOTE: Note: As described in Model 500 Series Nondestructive Testing Manual Part 6)					Hrs	7,170.5	1,200	+100	(8,370.5)	1,166.6 Hrs (+100)
					Ldg	7,207				
A535001	Nose Cap (Radome) - Inspect								RE Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-50-00-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A535002	Stinger Assembly - Inspect								RE Continuous Inspection Program	
 53 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:53-50-10-210 (ZONE: 321, 322)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
B527001	Door Warning System - Inspect and perform operational check						RE		Continuous Inspection Program	≈10-Sep-2018
 53 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:52-70-01-710 (ZONE: AUX)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
B535001	Radome - Check electrical bonding						RE		Continuous Inspection Program	≈10-Sep-2018
 53 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:53-50-00-750 (ZONE: 110)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
SL560-53-05	Dorsal Fin Vane Inspection						RE (-)		Recommended	
 53 A/F					Mos	31-Oct-2005				
Eff: 17-Nov-2004 Complied With					Hrs	4,405				
					Ldg	0				
SL560-53-06	Intercostal Drainage Path Inspection						RE (-)		Recommended	
 53 A/F					Mos	31-Oct-2005				
Complied With					Hrs	4,405				
					Ldg	0				
▼ 54 - NACELLES/PYLONS										
	Inlet Assembly						RE (O/C)			
 54 A/F	Left	0			Mos	15-Nov-1994				
6552500-1		0			Hrs	0				
NSN		0			Ldg	0				
	Inlet Assembly						RE (O/C)			
 54 A/F	Right	0			Mos	15-Nov-1994				
6552500-2		0			Hrs	0				
NSN		0			Ldg	0				
560-54-03 R02	Nacelles/Pylons - Engine Inlet Vapor Barrier Installation						RE (-)		Recommended	
 54 A/F					Mos	16-Nov-1999				
Eff: 17-Sep-1998 Complied With					Hrs	2,436				
					Ldg	0				
560-54-04 R01	Nacelles/Pylons - Engine Inlet Vapor Barrier Installation						RE (-)		Recommended	
 54 A/F					Mos	10-Dec-2001				
Eff: 16-Mar-2000 Complied With					Hrs	3,235				
					Ldg	0				
A541001	Engine Nacelle, Pylon and Firewall - Inspect						RE		Continuous Inspection Program	
 54 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:54-50-01-210					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					
A541002	Engine Support Structures - Inspect						T		Continuous Inspection Program	≈09-Nov-2025
 54 A/F	051216				Mos					
Ref.:54-50-01-211 (ZONE: 410, 420)					Hrs		10,000	+10	(10,000.4)	2,796.5 Hrs (+10)
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
▼ 55 - STABILIZERS										
A551001	Horizontal Stabilizer - Externally inspect						RE	Continuous Inspection Program		≈10-Sep-2018
 55 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:55-10-01-210 (ZONE: 331, 332)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A551002	Vertical Stabilizer Aft Edge - Inspect						RE	Continuous Inspection Program		≈10-Sep-2018
 55 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:55-30-01-270 (ZONE: 340)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A551003	Horizontal Stabilizer Aft Spar Area General Visual Inspection (Corrosion Inspection)						RE (N/A)	Continuous Inspection Program		
 55 A/F					Mos					
Ref.:55-10-01-212 (ZONE: 340)					Hrs					
					Ldg					
A551004	Vertical Stabilizer Aft Spar Assembly General Visual Inspection (Corrosion Inspection)						RE (N/A)	Continuous Inspection Program		
 55 A/F					Mos					
Ref.:55-30-01-212 (ZONE: 331, 332)					Hrs					
					Ldg					
A551005	Horizontal Stabilizer Aft Spar Area General Visual Inspection (Corrosion Inspection)						RE	Continuous Inspection Program		
 55 A/F	051218				Mos	11-Oct-2017	12	+1	(31-Oct-2018)	8.8 Months (+30 Days)
Ref.:55-10-01-212 (AVG MAN HRS: 0) (APX COST [USD]: 0)					Hrs	7,170.5				
					Ldg	7,207				
A551006	Horizontal Stabilizer Rib Location Borescope Inspection						RE	Continuous Inspection Program		≈06-Oct-2033
 55 A/F	051266				Mos					
Ref.:55-10-01-290 (ZONE: 331, 332)					Hrs		6,000	+10	(12,848.2)	5,644.3 Hrs (+10)
					Ldg					
A553001	Vertical Stabilizer - Externally inspect						RE	Continuous Inspection Program		≈10-Sep-2018
 55 A/F	051202				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:55-30-01-210 (ZONE: 340)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A553003	Vertical Stabilizer Forward Spar Cap Strap - Inspect						T	Continuous Inspection Program		≈29-Jul-2025
 55 A/F	051215				Mos					
Ref.:55-30-01-250 (ZONE: 340)					Hrs		10,000	+10	(9,900.4)	2,696.5 Hrs (+10)
					Ldg					
A553005	Vertical Stabilizer Aft Spar Flange - Inspect						T	Continuous Inspection Program		≈29-Jul-2025
 55 A/F	051215				Mos					
Ref.:55-30-01-251 (ZONE: 340)					Hrs		10,000	+10	(9,900.4)	2,696.5 Hrs (+10)
					Ldg					
A553006	Vertical Stabilizer - Internally inspect						RE	Continuous Inspection Program		
 55 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:55-30-01-211					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
A553007	Vertical Stabilizer Aft Spar Inspection								T Continuous Inspection Program	≈29-Jul-2025
 55 A/F	051215					Mos				
Ref.:55-30-01-252 (ZONE: 340)						Hrs	10,000	+10	(9,900.4)	2,696.5 Hrs (+10)
						Ldg				
A553008	Vertical Stabilizer Aft Spar Assembly General Visual Inspection (Corrosion Inspection)								RE Continuous Inspection Program	
 55 A/F	051218					Mos	11-Oct-2017	12	+1 (31-Oct-2018)	8.8 Months (+30 Days)
Ref.:55-30-01-212 (ZONE: 331, 332) (AVG MAN HRS: 0) (APX COST [USD]: 0)						Hrs	7,170.5			
						Ldg	7,207			
A555001	Horizontal Stabilizer - Internally inspect								RE Continuous Inspection Program	
 55 A/F	051205					Mos	21-Oct-2016	36	+2 (31-Oct-2019)	1.7 Years (+61 Days)
Ref.:55-10-01-211						Hrs	6,848.2	1,200	+100 (8,048.2)	844.3 Hrs (+100)
						Ldg	6,940			
SL560-55-02	Horizontal Stabilizer Attach Bolt/Nut Torque Verification								RE (-) Recommended	
 55 A/F						Mos	11-Sep-1997			
Eff: 21-Mar-1997 Complied With						Hrs	1,483			
						Ldg	0			
SL560-55-03 R2	Stabilizers - Horizontal Stabilizer Rib Borescope Inspection								RE (-) Mandatory	
 55 A/F						Mos	21-Oct-2016			
Eff: 09-Jul-2015 Complied With						Hrs	6,848.2			
(NOTE: This service letter is only applicable to airplanes that have accumulated 6,000 hours at the time of release of the original issue. This service letter must be accomplished at the next Phase 5 Inspection after reaching 6,000 hours.)						Ldg	6,940			
▼ 56 - WINDOWS										
	Cabin Door Window								RE (O/C)	
 56 A/F	Left No.1					Mos	15-Nov-1994			
5512207-1		0				Hrs	0			
NSN		0				Ldg	0			
	Cabin Window								RE (O/C)	
 56 A/F	Left No.2					Mos	15-Nov-1994			
5511260-8		0				Hrs	0			
NSN		0				Ldg	0			
	Cabin Window								RE (O/C)	
 56 A/F	Left No.3					Mos	15-Nov-1994			
5511260-8		0				Hrs	0			
NSN		0				Ldg	0			
	Cabin Window								RE (O/C)	
 56 A/F	Left No.4					Mos	15-Nov-1994			
5511260-8		0				Hrs	0			
NSN		0				Ldg	0			
	Cabin Window								RE (O/C)	
 56 A/F	Left No.5					Mos	15-Nov-1994			
5511260-8		0				Hrs	0			
NSN		0				Ldg	0			

Task No	PN/SN	Description	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
											DUE	Remaining
	56 A/F 5511260-8 NSN	Cabin Window	Left No.6								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511260-8 NSN	Cabin Window	Left No.7								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511260-8 NSN	Cabin Window	Right No.2								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511260-8 NSN	Cabin Window	Right No.3								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511260-8 NSN	Cabin Window	Right No.4								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511260-8 NSN	Cabin Window	Right No.5								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511260-8 NSN	Cabin Window	Right No.6								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511260-8 NSN	Cabin Window	Right No.7								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511260-8 NSN	Emergency Door Window	Right No.1								RE (O/C)	
				0			Mos	15-Nov-1994				
				0			Hrs	0				
				0			Ldg	0				
	56 A/F 5511275-717 2145	Foul Weather Window									RE (O/C)	
				0			Mos	31-Oct-2005				
				0			Hrs	4,405				
				0			Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 56 A/F 5511285-6 11-19-04	Inner Side Window								RE (O/C)	
	Copilot	0			Mos	31-Oct-2005				
		0			Hrs	4,405				
		0			Ldg	0				
 56 A/F 5511285-5 9-14-05	Inner Side Window								RE (O/C)	
	Pilot	0			Mos	31-Oct-2005				
		0			Hrs	4,405				
		0			Ldg	0				
 56 A/F PAS9912064-15 13273	Main Windshield								RE (O/C)	
	Left	0			Mos	28-Jan-2011				
		0			Hrs	5,658.7				
		0			Ldg	6,039				
 56 A/F E149000-10 2918	Main Windshield								RE (O/C)	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 56 A/F 5511285-48 NSN	Outer Side Window								RE (O/C)	
	Copilot	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 56 A/F 5511285-3 NSN	Outer Side Window								RE (O/C)	
	Pilot	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
56-10-00(3)(A)	Copilot's Side Window Cracks/Pits/Chips/Gouges Inspection								RE (A/R)	Discretionary
 56 A/F (SOURCE: MM 56-10-00 Tables 802, 803)					Mos					
					Hrs					
					Ldg					
56-10-00(3)(A)	Copilot's Windshield Cracks/Pits/Chips/Gouges Inspection								RE (A/R)	Discretionary
 56 A/F (SOURCE: MM 56-10-00 Tables 802, 803)					Mos					
					Hrs					
					Ldg					
56-10-00(3)(A)	Pilot's Side Window Cracks/Pits/Chips/Gouges Inspection								RE (A/R)	Discretionary
 56 A/F (SOURCE: MM 56-10-00 Tables 802, 803)					Mos					
					Hrs					
					Ldg					
56-10-00(3)(A)	Pilot's Windshield Cracks/Pits/Chips/Gouges Inspection								RE (A/R)	Discretionary
 56 A/F (SOURCE: MM 56-10-00 Tables 802, 803)					Mos					
					Hrs					
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
A561001	Airplane Windows - Inspect						RE		Continuous Inspection Program	≈10-Sep-2018
56 A/F	051201				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:56-10-00-210 (ZONE: 241, 242,251, 252,261, 262,271, 272)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
A561002	Windshield and Flight Compartment Side Windows - Prism inspection						RE		Continuous Inspection Program	
56 A/F	051249				Mos	11-Oct-2017	36	+2	(31-Oct-2020)	2.7 Years (+61 Days)
Ref.:56-10-00-280 (ZONE: 241, 242) (AVG MAN HRS: 0) (APX COST [USD]: 0)					Hrs	7,170.5	1,200	+100	(8,370.5)	1,166.6 Hrs (+100)
					Ldg	7,207				
A561003	Inner Side Window Inspection						RE (N/A)		Continuous Inspection Program	
56 A/F	Copilot				Mos					
5511285-6					Hrs					
11-19-04					Ldg					
Ref.:56-10-00-281 (ZONE: 242)										
A561003	OuterSide Window Inspection						RE (N/A)		Continuous Inspection Program	
56 A/F	Copilot				Mos					
5511285-48					Hrs					
NSN					Ldg					
Ref.:56-10-00-281 (ZONE: 242)										
A561004	Inner Side Window Inspection						T		Continuous Inspection Program	
56 A/F	Copilot				Mos					
051259					Hrs		150	+10		
5511285-6					Ldg					
11-19-04										
Ref.:56-10-00-281 (ZONE: 242)										
A561004	Outer Side Window Inspection						T		Continuous Inspection Program	
56 A/F	Copilot				Mos					
051259					Hrs		150	+10		
5511285-48					Ldg					
NSN										
Ref.:56-10-00-281 (ZONE: 242)										
▼ 57 - WINGS										
	Flap Assy						RE (O/C)			
57 A/F	Left Inboard	0			Mos	15-Nov-1994				
Unknown		0			Hrs	0				
Unknown		0			Ldg	0				
	Flap Assy						RE (O/C)			
57 A/F	Left Outboard				Mos	15-Nov-1994				
Unknown					Hrs	0				
Unknown					Ldg	0				
	Flap Assy						RE (O/C)			
57 A/F	Right Inboard				Mos	15-Nov-1994				
Unknown					Hrs	0				
Unknown					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 57 A/F Unknown Unknown	Flap Assy						RE (O/C)			
	Right Outboard				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 57 A/F Unknown Unknown	Fuel Caps/Locking Factory Option						RE (O/C)			
					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 57 A/F 6522047-1 NSN	Main Landing Gear Side Brace Support Fitting						RE	AWL, Component Time Limits	≈02-Nov-2090	
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	24,700	24,700	17,460 Ldg	
 57 A/F 6522047-2 NSN	Main Landing Gear Side Brace Support Fitting						RE	AWL, Component Time Limits	≈02-Nov-2090	
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0	24,700	24,700	17,460 Ldg	
560-57-07	Flap Vent Holes Installation						T (A/R)		Recommended	
 57 A/F Eff: 16-Feb-1996 Complied With					Mos	10-Aug-1996				
					Hrs	866				
					Ldg	0				
A570001	Main Landing Gear Wheel Well General Visual Inspection (Corrosion Inspection)						RE (N/A)		Continuous Inspection Program	
 57 A/F Ref.:57-00-00-212 (ZONE: 171, 172)					Mos					
					Hrs					
					Ldg					
A570002	Main Landing Gear Wheel Well General Visual Inspection (Corrosion Inspection)						RE		Continuous Inspection Program	
 57 A/F 051218 Ref.:57-00-00-212 (ZONE: 171, 172) (AVG MAN HRS: 0) (APX COST [USD]: 0)					Mos	11-Oct-2017	12	+1 (31-Oct-2018)	8.8 Months (+30 Days)	
					Hrs	7,170.5				
					Ldg	7,207				
A570003	Aft Wing Spar Area General Visual Inspection (Corrosion Inspection)						RE (N/A)		Continuous Inspection Program	
 57 A/F Ref.:57-00-00-213 (ZONE: 171, 172)					Mos					
					Hrs					
					Ldg					
A570004	Aft Wing Spar Area General Visual Inspection (Corrosion Inspection)						RE		Continuous Inspection Program	
 57 A/F 051218 Ref.:57-00-00-213 (ZONE: 171, 172) (AVG MAN HRS: 0) (APX COST [USD]: 0)					Mos	11-Oct-2017	12	+1 (31-Oct-2018)	8.8 Months (+30 Days)	
					Hrs	7,170.5				
					Ldg	7,207				
A571004	Wing Lower Leading Edge Outboard of WS 91.073. - Inspect						RE		Continuous Inspection Program	
 57 A/F 051205 Ref.:57-00-00-251 (ZONE: 521, 621)					Mos		36	+2 (31-Oct-2019)	1.7 Years (+61 Days)	
					Hrs		1,200	+100 (8,048.2)	844.3 Hrs (+100)	
					Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
A571005	Inboard Lower Main Wing Spar Cap and Strap Inspection								T	Continuous Inspection Program
 57 A/F	051261									≈28-Sep-2034
Ref.:57-00-00-252 (ZONE: 171, 172)										
A571006	Inboard Lower Main Wing Spar Cap and Spar Strap Inspection								T	Continuous Inspection Program
 57 A/F	051261									≈28-Sep-2034
Ref.:57-00-00-253 (ZONE: 171, 172)										
A571007	Outboard Lower Main Wing Spar Cap and Strap Inspection								T	Continuous Inspection Program
 57 A/F	051262									≈29-May-2041
Ref.:57-00-00-254 (ZONE: 511, 512, 521, 522, 531, 532, 611,) (NOTE: More zone: 612, 621, 622, 631, 632)										
A571008	Inboard Lower Rear Wing Spar Cap Inspection								T	Continuous Inspection Program
 57 A/F	051263									≈29-May-2041
Ref.:57-00-00-255 (ZONE: 171, 172)										
A571009	Outboard Lower Rear Wing Spar Cap Inspection								T	Continuous Inspection Program
 57 A/F	051263									≈29-May-2041
Ref.:57-00-00-256 (ZONE: 512, 522,532, 612,622, 632)										
A573001	Wings - Inspect								RE	Continuous Inspection Program
 57 A/F	051205									
Ref.:57-00-00-210										
A573003	Wing Jack Pad - Inspect								T	Continuous Inspection Program
 57 A/F	051214									≈29-May-2031
Ref.:57-00-00-250 (ZONE: 512, 612)										
A574005	Flap Bell Crank Attach Points - Inspect								RE	Continuous Inspection Program
 57 A/F	051202									≈10-Sep-2018
Ref.:57-20-01-210 (ZONE: 512, 522,612, 622)										
A575001	Flap - Inspect								RE	Continuous Inspection Program
 57 A/F	051205									
Ref.:57-00-00-211										
SL560-57-01 R01	Wings - Notification Of Leading Edge Skin Rework Requirement When A Deice Boot Is Removed								RE (-)	Mandatory
 57 A/F										
Eff: 15-Feb-2001 Complied With										

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
▼ 71 - POWER PLANT										
71 A/F 9912455-2 1779	Engine Aft Mount	RE (O/C)								
	Left	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9				
71 A/F 9912455-2 1778	Engine Aft Mount	RE (O/C)								
	Right	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9				
71 A/F 9912455-2 1779	Engine Aft Mount Isolator	RE Component Time Limits ≈27-Feb-2026								
	Left	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
71 A/F 9912455-2 1778	Engine Aft Mount Isolator	RE Component Time Limits ≈27-Feb-2026								
	Right	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
71 A/F 9912455-1 4082	Engine Fwd Lower Mount	RE (O/C)								
	Left	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9				
71 A/F 9912455-1 4075	Engine Fwd Lower Mount	RE (O/C)								
	Right	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9				
71 A/F 9912455-1 4082	Engine Fwd Lower Mount Isolator	RE Component Time Limits ≈27-Feb-2026								
	Left	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
71 A/F 9912455-1 4075	Engine Fwd Lower Mount Isolator	RE Component Time Limits ≈27-Feb-2026								
	Right	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
71 A/F 9912455-1 4091	Engine Fwd Upper Mount	RE (O/C)								
	Left	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9				
71 A/F 9912455-1 4072	Engine Fwd Upper Mount	RE (O/C)								
	Right	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
 71 A/F 9912455-1 4091	Engine Fwd Upper Mount Isolator								RE	Component Time Limits ≈27-Feb-2026
	Left	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
		0			Ldg	6,759				
 71 A/F 9912455-1 4072	Engine Fwd Upper Mount Isolator								RE	Component Time Limits ≈27-Feb-2026
	Right	0			Mos	21-Dec-2015				
		0			Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
		0			Ldg	6,759				
5-11-00(2)(L)(1)  71 A/F 9912455-2 1779	Engine Aft Mount - Overhaul or Replace								RE	Component Time Limits ≈27-Feb-2026
	Left				Mos	21-Dec-2015				
					Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
					Ldg	6,759				
5-11-00(2)(L)(1)  71 A/F 9912455-2 1778	Engine Aft Mount - Overhaul or Replace								RE	Component Time Limits ≈27-Feb-2026
	Right				Mos	21-Dec-2015				
					Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
					Ldg	6,759				
5-11-00(2)(L)(1)  71 A/F 9912455-1 4091	Engine Fwd Mount - Overhaul or Replace								RE	Component Time Limits ≈27-Feb-2026
	Left				Mos	21-Dec-2015				
					Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
					Ldg	6,759				
5-11-00(2)(L)(1)  71 A/F 9912455-1 4082	Engine Fwd Mount - Overhaul or Replace								RE	Component Time Limits ≈27-Feb-2026
	Left				Mos	21-Dec-2015				
					Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
					Ldg	6,759				
5-11-00(2)(L)(1)  71 A/F 9912455-1 4075	Engine Fwd Mount - Overhaul or Replace								RE	Component Time Limits ≈27-Feb-2026
	Right				Mos	21-Dec-2015				
					Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
					Ldg	6,759				
5-11-00(2)(L)(1)  71 A/F 9912455-1 4072	Engine Fwd Mount - Overhaul or Replace								RE	Component Time Limits ≈27-Feb-2026
	Right				Mos	21-Dec-2015				
					Hrs	6,610.9	3,500		10,110.9	2,907 Hrs
					Ldg	6,759				
5-11-00(2)(L)(3)  71 A/F	Left Engine Bolts (NAS464P8-67) and Nuts (AN320-8) used to install engine (through engine mount isolators) - Replace								RE (N/A)	Component Time Limits
					Mos					
					Hrs					
					Ldg					
5-11-00(2)(L)(3)  71 A/F	Right Engine Bolts (NAS464P8-67) and Nuts (AN320-8) used to install engine (through engine mount isolators) - Replace								RE (N/A)	Component Time Limits
					Mos					
					Hrs					
					Ldg					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-71-02	Bleed Air Line Clamp Replacement								RE (-)	Recommended
 71 A/F Eff: 19-Jan-1996 Complied With						Mos 01-May-1996				
						Hrs 722				
						Ldg 0				
560-71-03 R02	Lower Cowl Door Fireseal Installation								RE (-)	Recommended
 71 A/F Eff: 19-Jul-1996 Complied With						Mos 02-Apr-1997				
						Hrs 1,224				
						Ldg 0				
A711000	Engine - Complete a general inspection								RE Continuous Inspection Program	≈10-Sep-2018
 71 A/F 051204 Ref.:71-01-04-210 (ZONE: 410, 411,412, 420,512, 612) (NOTE: NOTE: This inspection is applicable to JT15D-5A and JT15D-5D engines)						Mos	24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs 300	+30 (7,422)			218.1 Hrs (+30)
						Ldg				
A711001	Engine - Complete a general inspection								RE Continuous Inspection Program	≈10-Sep-2018
 71 A/F 051204 Ref.:71-01-05-210 (ZONE: 410, 411,420, 512,612) (NOTE: NOTE: This inspection is applicable to PW535A engines)						Mos	24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs 300	+30 (7,422)			218.1 Hrs (+30)
						Ldg				
A711002	Engine - Complete a general inspection								RE Continuous Inspection Program	≈10-Sep-2018
 71 A/F 051204 Ref.:71-02-00-210 (ZONE: 410, 411,420, 512,612) (NOTE: NOTE: This inspection is applicable to PW535B engines)						Mos	24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs 300	+30 (7,422)			218.1 Hrs (+30)
						Ldg				
A711006	Engine Inlet Inner and Outer Duct - Inspect								RE Continuous Inspection Program	≈10-Sep-2018
 71 A/F 051204 Ref.:71-11-00-210 (ZONE: 410, 420)						Mos	24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs 300	+30 (7,422)			218.1 Hrs (+30)
						Ldg				
A711007	Engine Inlet Inner Duct and Nose-Cap - Complete the inspection								RE Continuous Inspection Program	≈10-Sep-2018
 71 A/F 051204 Ref.:71-11-00-211 (ZONE: 410, 420)						Mos	24	+2 (31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs 300	+30 (7,422)			218.1 Hrs (+30)
						Ldg				
A713001	Engine Oil Chip Detector (if installed) - Inspect								RE (N/A) Continuous Inspection Program	
 71 A/F Ref.:71-30-01-760 (ZONE: 410, 420)						Mos				
						Hrs				
						Ldg				
▼ 72 - ENGINE										
	Accessory Drive Gearbox								RE (O/C)	
 72 ENG1 3031170 NSN		0				Mos 10-Dec-2001				
		0				Hrs 3,235				
		0				Enc 0				
	Accessory Drive Gearbox								RE (O/C)	
 72 ENG2 3031170 NSN		0				Mos 10-Dec-2001				
		0				Hrs 3,235				
		0				Enc 0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time	
PN/SN	MOC Note or Component Condition								DUE	Remaining	
 72 ENG1 Unknown Unknown	Anti-Icing Valve								RE (O/C)		
					Mos	15-Nov-1994					
					Hrs	0					
					Enc	0					
 72 ENG2 Unknown Unknown	Anti-Icing Valve								RE (O/C)		
					Mos	15-Nov-1994					
					Hrs	0					
					Enc	0					
 72 ENG1 3117501-01 NSN	High Turbine Blades								RE (O/C)		
		0			Mos	10-Dec-2001					
		0			Hrs	3,235					
		0			Enc	0					
 72 ENG2 3117501-01 NSN	High Turbine Blades								RE (O/C)		
		0			Mos	10-Dec-2001					
		0			Hrs	3,235					
		0			Enc	0					
 72 ENG1 3118976-01 Unknown	LC Rotor Fan Balancing Assembly								RE (O/C)		
		0			Mos	10-Dec-2001					
		0			Hrs	3,235					
		0			Enc	0					
 72 ENG2 3118976-01 Unknown	LC Rotor Fan Balancing Assembly								RE (O/C)		
		0			Mos	10-Dec-2001					
		0			Hrs	3,235					
		0			Enc	0					
560-72-01 R01	Engine Cowling Modification to Accommodate Pratt & Whitney Canada Engine Fuel Accumulator Installation								RE (-)	Recommended	
 72 A/F Complied With					Mos	11-Sep-1997					
					Hrs	1,483					
					Ldg	0					
720000-0401	High Turbine Rotor Disk								RE	EMM - Life Limit ≈26-Mar-2074	
 72 ENG1 3036411 A003BA3D (NOTE: NOTE: 7. When installed in Czech CAA application, a Flight Count Factor of 1.1 mustbe applied for JT15D-5 engines built to B.S. 713 and JT15D-5R engines (Ref.Table 3).)		0			Mos	14-Dec-2015					
		0			Hrs	6,610.9					
		0			Enc	6,759	14,000		20,759	13,552	Enc
720000-0401	High Turbine Rotor Disk								RE	EMM - Life Limit ≈26-Mar-2074	
 72 ENG2 3036411 A003AAKW (NOTE: NOTE: 7. When installed in Czech CAA application, a Flight Count Factor of 1.1 mustbe applied for JT15D-5 engines built to B.S. 713 and JT15D-5R engines (Ref.Table 3).)		0			Mos	14-Dec-2015					
		0			Hrs	6,610.9					
		0			Enc	6,759	14,000		20,759	13,552	Enc
720100	Engine Minor Periodic Inspection								RE	EMM - Requirement ≈18-Jun-2018	
 72 ENG1					Mos	21-Jul-2017	24	+2	31-Jul-2019	1.5 Years (+61 Days)	
					Hrs	7,122	300	+30	7,422	251.5 Hrs (+30)	
					Enc	7,168					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
720100 72 ENG2	Engine Minor Periodic Inspection								RE EMM - Requirement	≈18-Jun-2018
					Mos	21-Jul-2017	24	+2	31-Jul-2019	1.5 Years (+61 Days)
					Hrs	7,122	300	+30	7,422	251.5 Hrs (+30)
					Enc	7,168				
723000-0101 72 ENG1 Unknown Unknown	LP Compressor Rotor Balance Assembly								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
723000-0101 72 ENG2 Unknown Unknown	LP Compressor Rotor Balance Assembly								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
723200-0101 72 ENG1 3041512 A0001A0C	Low Boost Compressor Hub								RE EMM - Life Limit	≈30-Apr-2130
		0			Mos	14-Dec-2014				
		3,617.7			Hrs	6,610.9				
		2,537			Enc	6,759	30,000		34,222	27,015 Enc
723200-0101 72 ENG2 3041512 A0001P1K	Low Boost Compressor Hub								RE EMM - Life Limit	≈29-Mar-2127
		0			Mos	15-Nov-1994				
		3,439.9			Hrs	6,610.9				
		3,278			Enc	6,759	30,000		33,481	26,274 Enc
723200-0201 72 ENG1 3041231 82A448	Rotor, Fan Low Compressor								RE EMM - Life Limit	≈27-Sep-2112
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0	30,000		30,000	22,793 Enc
723200-0201 72 ENG2 3041231 82A449	Rotor, Fan Low Compressor								RE EMM - Life Limit	≈27-Sep-2112
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0	30,000		30,000	22,793 Enc
723400-0101 72 ENG1 3040939 9E160 (NOTE: NOTE: 6. When installed in Czech CAA application, a Flight Count Factor of 1.5 mustbe applied for JT15D-5 engines built to B.S. 713 and JT15D-5R engines (Ref.Table 3).)	Centrifugal Impeller								RE EMM - Life Limit	≈27-Sep-2037
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0	12,000		12,000	4,793 Enc
723400-0101 72 ENG2 3040939 9E161 (NOTE: NOTE: 6. When installed in Czech CAA application, a Flight Count Factor of 1.5 mustbe applied for JT15D-5 engines built to B.S. 713 and JT15D-5R engines (Ref.Table 3).)	Centrifugal Impeller								RE EMM - Life Limit	≈27-Sep-2037
		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0	12,000		12,000	4,793 Enc
725071-0101 72 ENG1 3119770-01 6K721	Combustion Liner								RE (O/C)	
		0			Mos	28-Sep-2004				
		0			Hrs	4,097				
		0			Enc	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
725071-0101	Combustion Liner								RE (O/C)	
 72 ENG2 3119770-01 8K009		0			Mos	17-Sep-2007				
		0			Hrs	4,823				
		0			Enc	0				
725200-0101	Low Turbine Rotor 2nd Stage Disk								RE	EMM - Life Limit ≈27-Jan-2046
 72 ENG1 3022212 84A300		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0	14,000		14,000	6,793 Enc
725200-0101	Low Turbine Rotor 2nd Stage Disk								RE	EMM - Life Limit ≈27-Jan-2046
 72 ENG2 3022212 84A310		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0	14,000		14,000	6,793 Enc
725300-0101	Low Turbine Rotor 3rd Stage Disk								RE	EMM - Life Limit ≈27-Jan-2046
 72 ENG1 3036113 84A297		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0	14,000		14,000	6,793 Enc
725300-0101	Low Turbine Rotor 3rd Stage Disk								RE	EMM - Life Limit ≈27-Jan-2046
 72 ENG2 3036113 82A296		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0	14,000		14,000	6,793 Enc
72-JT15D-015	Engine Hot Section Inspection								RE	EMM - Requirement ≈28-Jan-2021
 72 ENG1					Mos	14-Dec-2015				
					Hrs	6,610.9	1,750	-/+50	8,360.9	1,190.4 Hrs (+50)
					Enc	6,759				
72-JT15D-015	Engine Hot Section Inspection								RE	EMM - Requirement ≈28-Jan-2021
 72 ENG2					Mos	14-Dec-2015				
					Hrs	6,610.9	1,750	-/+50	8,360.9	1,190.4 Hrs (+50)
					Enc	6,759				
72-JT15D-016	Engine Overhaul								RE	EMM - Requirement ≈07-Dec-2025
 72 ENG1 (NOTE: Note: For JT15D-4 Post SB 7115, For JT15D-4D Post SB7189, For JT15D-4B Post SB 7189 and/or 7275)					Mos	14-Dec-2015				
					Hrs	6,610.9	3,500		10,110.9	2,940.4 Hrs
					Enc	6,759				
72-JT15D-016	Engine Overhaul								RE	EMM - Requirement ≈07-Dec-2025
 72 ENG2 (NOTE: Note: For JT15D-4 Post SB 7115, For JT15D-4D Post SB7189, For JT15D-4B Post SB 7189 and/or 7275)					Mos	15-Dec-2015				
					Hrs	6,610.9	3,500		10,110.9	2,940.4 Hrs
					Enc	6,759				
72-JT15D-019	Electronic Bleed Valve Control / Electronic Engine Control (D5 Series and the 4C) - Inspection (at Engine Overhaul)								RE	≈18-May-2020
 72 ENG1 800831-1-001 C93111802 Ref:SB JT15D-72-7003					Mos	14-Dec-2015				
					Hrs	6,610.9	1,500	-/+50	8,110.9	940.4 Hrs (+50)
					Enc	6,759				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
72-JT15D-019	Electronic Bleed Valve Control / Electronic Engine Control (D5 Series and the 4C) - Inspection (at Engine Overhaul)								RE	≈18-May-2020
 72 ENG2 800831-1-001 C94071216 Ref:SB JT15D-72-7003					Mos	15-Dec-2015				
					Hrs	6,610.9	1,500	-/+50	8,110.9	940.4 Hrs (+50)
					Enc	6,759				
7642 R1	Transfer of Manufacturing Rights for Various Parts							T (A/R)	Category 10	
 72 ENG1 Eff: 10-Jan-2018 (AVG MAN HRS: 1.5)					Mos					
					Hrs					
					Enc					
7642 R1	Transfer of Manufacturing Rights for Various Parts							T (A/R)	Category 10	
 72 ENG2 Eff: 10-Jan-2018 (AVG MAN HRS: 1.5)					Mos					
					Hrs					
					Enc					
7643	Replacement of Shipping Container							T (A/R)	Category 7	
 72 ENG1 Eff: 23-Oct-2017 (AVG MAN HRS: 1.5)					Mos					
					Hrs					
					Enc					
Engine 1	Pratt & Whitney of Canada - JT15D-5D							RE (-)		
 72 A/F JT15D-5D PCE-500046	Time at install:				Mos					
					Hrs					
					Ldg					
Engine 2	Pratt & Whitney of Canada - JT15D-5D							RE (-)		
 72 A/F JT15D-5D PCE-500044	Time at install:				Mos					
					Hrs					
					Ldg					
SIL No. GEN-044	Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation							RE (-)	Service Information Letter	
 72 ENG1 Eff: 03-Jun-1998					Mos					
					Hrs					
					Enc					
SIL No. GEN-044	Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation							RE (-)	Service Information Letter	
 72 ENG2 Eff: 03-Jun-1998					Mos					
					Hrs					
					Enc					
SIL No. GEN-044 R1	Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation							T (A/R)	Service Information Letter	
 72 ENG1 Eff: 16-Oct-2017					Mos					
					Hrs					
					Enc					
SIL No. GEN-044 R1	Return of Engine Parts to Pratt & Whitney Canada Inc. (P&WC) for Investigation - Evaluation							T (A/R)	Service Information Letter	
 72 ENG2 Eff: 16-Oct-2017					Mos					
					Hrs					
					Enc					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
SL560-72-06	Transmittal of P&WC SB JT15D-72-7463 Turbofan Engine Oil Pressure And Compressor Air Pressure Tubes - Replacement Of								RE (-)	Recommended
 72 A/F Eff: 21-Jul-1995 Complied With						Mos	10-Aug-1996			
						Hrs	866			
						Ldg	0			
SL560-72-07	Transmittal of P&WC SB JT15D-72-7477 Fuel Pressure to Cooler Tube Support Strut - Introduction of								RE (-)	Recommended
 72 A/F Eff: 22-Mar-1996 Complied With						Mos	01-May-1996			
						Hrs	722			
						Ldg	0			
SL560-72-14	Transmittal of P&WC SB JT15D-72-7527 Turbofan Engine - Field Inspection/Replacement of Rear Inner Compressor Stator								RE (-)	Informational
 72 A/F Eff: 24-Jan-1997 Complied With	COMPLIED WITH BY ALTERNATE METHOD OF COMPLIANCE					Mos	28-Jul-2000			
						Hrs	2,750			
						Ldg	0			
SL560-72-16	Transmittal of P&WC Service Letter JT15D-023								RE (-)	Informational
 72 A/F Eff: 16-Apr-1999 Complied With						Mos	07-Jul-1999			
						Hrs	2,283			
						Ldg	0			
▼ 73 - ENGINE - FUEL AND CONTROL										
	Chip Detector								RE (O/C)	
 73 ENG1 Unknown Unknown						Mos	15-Nov-1994			
						Hrs	0			
						Enc	0			
	Chip Detector								RE (O/C)	
 73 ENG2 Unknown Unknown						Mos	15-Nov-1994			
						Hrs	0			
						Enc	0			
	EFCU Wiring Harness								RE (O/C)	
 73 ENG1 3119566-01 AA2880		0				Mos	10-Dec-2001			
		0				Hrs	3,235			
		0				Enc	0			
	EFCU Wiring Harness								RE (O/C)	
 73 ENG2 3119566-01 AA3614		0				Mos	10-Dec-2001			
		0				Hrs	3,235			
		0				Enc	0			
	Fuel Flow Indicator								RE (O/C)	
 73 A/F 9912430-3 155		0				Mos	07-Jan-2016			
		0				Hrs	6,620.5			
		0				Ldg	6,764			
	Fuel Surge Accumulator								RE (O/C)	
 73 ENG1 Unknown Unknown						Mos	15-Nov-1994			
						Hrs	0			
						Enc	0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
73 ENG2 Unknown Unknown	Fuel Surge Accumulator								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
73 ENG1 1103P0448 4067	Low Fuel Pressure Switch								RE (O/C)	
		0			Mos	27-Oct-1999				
		0			Hrs	2,430				
73 ENG2 1103P0448 6549	Low Fuel Pressure Switch								RE (O/C)	
		0			Mos	28-Sep-2004				
		0			Hrs	4,097				
73 ENG1 Unknown Unknown	Oil By-Pass Indicator								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
73 ENG2 Unknown Unknown	Oil By-Pass Indicator								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
73 ENG1 Unknown Unknown	Valve Chip Collector								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
73 ENG2 Unknown Unknown	Valve Chip Collector								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
731000-0101 Unknown Unknown	Engine Bleed Valve Actuator								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
731000-0101 Unknown Unknown	Engine Bleed Valve Actuator								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
731000-0201 Unknown Unknown	Schedule Modulator								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
731000-0201	Schedule Modulator									
73 ENG2 Unknown Unknown						Mos	15-Nov-1994		RE (O/C)	
						Hrs	0			
						Enc	0			
731005-0101	Nozzle Assy Fuel									
73 ENG1 Unknown Unknown						Mos	15-Nov-1994		RE (O/C)	
						Hrs	0			
						Enc	0			
731005-0101	Nozzle Assy Fuel									
73 ENG2 Unknown Unknown						Mos	15-Nov-1994		RE (O/C)	
						Hrs	0			
						Enc	0			
731010-0101	Fuel Pump									
73 ENG1 717100 607 Brand A:731001		0				Mos	10-Dec-2001		RE (O/C)	
		0				Hrs	3,235			
		0				Enc	0			
731010-0101	Fuel Pump									
73 ENG2 717101-1 375 Brand A:731001		0				Mos	10-Dec-2001		RE (O/C)	
		0				Hrs	3,235			
		0				Enc	0			
731030-0101	Motive Flow Valve									
73 ENG1 3244850-1 C29042 (NOTE: Inspect and recertify as per latest published CMM)		0				Mos	14-Dec-2015		RE (O/C)	
		0				Hrs	6,610.9			
		0				Enc	6,759			
731030-0101	Motive Flow Valve									
73 ENG2 3244850-1 C29039 (NOTE: Inspect and recertify as per latest published CMM)		0				Mos	15-Dec-2015		RE (O/C)	
		0				Hrs	6,610.9			
		0				Enc	6,759			
731040-0101	Flow Divider Valve									
73 ENG1 26395-2 1058 (NOTE: Inspect and recertify as per latest published CMM)		0				Mos	14-Dec-2015		RE (O/C)	
		0				Hrs	6,610.9			
		0				Enc	6,759			
731040-0101	Flow Divider Valve									
73 ENG2 26395-2 367 (NOTE: Inspect and recertify as per latest published CMM)		0				Mos	10-Dec-2001		RE (O/C)	
		0				Hrs	3,235			
		0				Enc				
732000-0101	(HMU) Hydromechanical Unit									
73 ENG1 Unknown Unknown						Mos	15-Nov-1994		RE (O/C)	
						Hrs	0			
						Enc	0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
732000-0101 ⚙️ 73 ENG2 Unknown Unknown	(HMU) Hydromechanical Unit								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
732000-0201 ⚙️ 73 ENG1 800831-1-001 C93111802	Electronic Bleed Valve Control								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
732000-0201 ⚙️ 73 ENG2 800831-1-001 C94071216	Electronic Bleed Valve Control								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
732000-0401 ⚙️ 73 ENG1 Unknown Unknown	Main Wiring Harness								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
732000-0401 ⚙️ 73 ENG2 Unknown Unknown	Main Wiring Harness								RE (O/C)	
					Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
732010-0101 ⚙️ 73 ENG1 3244880-9 C4542	Fuel Control								RE (O/C)	
		0			Mos	14-Dec-2014				
		0			Hrs	6,610.9				
		0			Enc	6,759				
732010-0101 ⚙️ 73 ENG2 3244880-9 C4309	Fuel Control								RE (O/C)	
		0			Mos	15-Dec-2015				
		0			Hrs	6,610.9				
		0			Enc	6,759				
73-JT15D-008 📷 73 ENG1 26395-2 1058 Ref:SB JT15D-72-7003	Fuel Flow Divider Valve - Inspection and Re-certification (at Engine Overhaul)								RE	≈07-Dec-2025
					Mos	14-Dec-2015				
					Hrs	6,610.9	3,500	-/+50	10,110.9	2,940.4 Hrs (+50)
					Enc	6,759				
73-JT15D-008 📷 73 ENG2 26395-2 367 Ref:SB JT15D-72-7003	Fuel Flow Divider Valve - Inspection and Re-certification (at Engine Overhaul)								RE	≈07-Dec-2025
					Mos	15-Dec-2015				
					Hrs	6,610.9	3,500	-/+50	10,110.9	2,940.4 Hrs (+50)
					Enc	6,759				
73-JT15D-009 📷 73 ENG1 3244850-1 C29042 Ref:SB JT15D-72-7003	Motive Flow Valve - Inspection and Re-certification (at Engine Overhaul)								RE	≈07-Dec-2025
					Mos	14-Dec-2015				
					Hrs	6,610.9	3,500	-/+50	10,110.9	2,940.4 Hrs (+50)
					Enc	6,759				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
73-JT15D-009	Motive Flow Valve - Inspection and Re-certification (at Engine Overhaul)								RE	≈07-Dec-2025
73 ENG2 3244850-1 C29039 Ref:SB JT15D-72-7003						Mos	15-Dec-2015			
						Hrs	6,610.9	3,500	-/+50	10,110.9 2,940.4 Hrs (+50)
						Enc	6,759			
73-JT15D-012	Fuel System - Fuel Pump Outlet Filter (10 Micron), Check for Foreign Matter and/or Distortion and Replace								T	EMM - Requirement
73 ENG1 Ref:73-10-02						Mos		24	-/+30d	≈15-Nov-1996
						Hrs		300	-/+10%	≈300
						Enc				
73-JT15D-012	Fuel System - Fuel Pump Outlet Filter (10 Micron), Check for Foreign Matter and/or Distortion and Replace								T	EMM - Requirement
73 ENG2 Ref:73-10-02						Mos		24	-/+30d	≈15-Nov-1996
						Hrs		300	-/+10%	≈300
						Enc				
7630	Fuel Cooled Oil Cooler - Inspection/Replacement of								RE (-)	Category 3
73 ENG1 Eff: 11-Jun-2012 Complied With (AVG MAN HRS: 2)						Mos	30-Sep-2014			
						Hrs	6,214.5			
						Enc	6,429			
7630	Fuel Cooled Oil Cooler - Inspection/Replacement of								RE (-)	Category 3
73 ENG2 Eff: 11-Jun-2012 Complied With (AVG MAN HRS: 2)						Mos	30-Sep-2014			
						Hrs	6,214.5			
						Enc	6,429			
SL560-73-04	Transmittal of Pratt & Whitney Canada Service Information Letter SIL 7067 Flow Divider Valve								RE (-)	Recommended
73 A/F Eff: 07-Oct-1994 Complied With						Mos	15-Nov-1994			
						Hrs	8			
						Ldg	0			
SL560-73-05	Transmittal of Pratt & Whitney Canada Service Bulletin JT15D-72-7467 Flow Divider Valve - Replacement/Modification Of								RE (-)	Recommended
73 A/F Eff: 21-Aug-1995 Complied With						Mos	10-Aug-1996			
						Hrs	866			
						Ldg	0			
SL560-73-06	Transmittal of Pratt & Whitney Canada Service Letter JT15D-021 No Response To Power Lever Movement								RE (-)	Informational
73 A/F Eff: 19-Mar-1999 Complied With						Mos	16-Nov-1999			
						Hrs	2,436			
						Ldg	0			
▼ 74 - IGNITION										
	Igniter Plug Cable								RE (O/C)	
74 ENG1 Unknown Unknown	Inboard					Mos	15-Nov-1994			
						Hrs	0			
						Enc	0			
	Igniter Plug Cable								RE (O/C)	
74 ENG2 Unknown Unknown	Inboard					Mos	15-Nov-1994			
						Hrs	0			
						Enc	0			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
74 ENG1 Unknown Unknown	Igniter Plug Cable Outboard								RE (O/C)	
						Mos	15-Nov-1994			
						Hrs	0			
74 ENG2 Unknown Unknown	Igniter Plug Cable Outboard								RE (O/C)	
						Mos	15-Nov-1994			
						Hrs	0			
74 ENG1 53300-2 NSN	Ignitor Lead								RE (O/C)	
		0				Mos	10-Dec-2001			
		0				Hrs	3,235			
74 ENG2 53300-2 NSN	Ignitor Lead								RE (O/C)	
		0				Mos	07-Sep-2016			
		0				Hrs	6,835.1			
74 ENG1 CH34659-3 234792001002	Outboard Engine Ignitor								RE (O/C)	
		0				Mos	14-Dec-2015			
		0				Hrs	6,610.9			
74 ENG2 CH34659-3 NSN	Outboard Engine Ignitor								RE (O/C)	
		0				Mos	31-Oct-2005			
		0				Hrs	4,405			
74 ENG1 9049770-3 NN98359408	Outboard Ignition Exciter								RE (O/C)	
		0				Mos	14-Dec-2015			
		0				Hrs	6,610.9			
74 ENG2 9049770-3 97483893	Outboard Ignition Exciter								RE (-)	
		0				Mos	07-Sep-2016			
		0				Hrs	6,610.9			
74 ENG1 53300-1 NSN	Short Ignitor Lead								RE (O/C)	
		0				Mos	10-Dec-2001			
		0				Hrs	3,235			
74 ENG2 53300-1 NSN	Short Ignitor Lead								RE (O/C)	
		0				Mos	16-Feb-2017			
		0				Hrs	6,979.4			
74 ENG2 53300-1 NSN	Short Ignitor Lead								RE (O/C)	
		0				Mos	16-Feb-2017			
		0				Hrs	6,979.4			

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
741010-0101	Ignition Exciter								RE (O/C)	
 74 ENG1 9049770-3 NN98216467	No.1	0			Mos	14-Dec-2015				
		0			Hrs	6,610.9				
		0			Enc	6,759				
741010-0101	Ignition Exciter								RE (O/C)	
 74 ENG2 9049770-3 99164899	No.1	0			Mos	16-Feb-2017				
		0			Hrs	6,979.4				
		0			Enc	7,046				
741010-0102	Ignition Exciter								RE (O/C)	
 74 ENG1 CH34659-3 234312003002	No.2	0			Mos	14-Dec-2015				
		0			Hrs	6,610.9				
		0			Enc	6,759				
741010-0102	Ignition Exciter								RE (O/C)	
 74 ENG2 CH34659-3 Unknown	No.2	0			Mos	07-Oct-2010				
		0			Hrs	5,565.8				
		0			Enc	5,965				
742010-0101	Igniter Plug								RE (O/C)	
 74 ENG1 Unknown Unknown	Inboard				Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
742010-0101	Igniter Plug								RE (O/C)	
 74 ENG2 Unknown Unknown	Inboard				Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
742010-0102	Igniter Plug								RE (O/C)	
 74 ENG1 Unknown Unknown Ref:74-20-02	Outboard				Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
742010-0102	Igniter Plug								RE (O/C)	
 74 ENG2 Unknown Unknown Ref:74-20-02	Outboard				Mos	15-Nov-1994				
					Hrs	0				
					Enc	0				
74-JT15D-006	Main Wiring Harness - Inspection and Functional Check (at Engine Overhaul)								RE	≈18-Mar-2026
 74 ENG1 Ref:SB JT15D-72-7003					Mos	14-Dec-2015				
					Hrs	6,610.9	3,600	-/+50	10,210.9	3,040.4 Hrs (+50)
					Enc	6,759				
74-JT15D-006	Main Wiring Harness - Inspection and Functional Check (at Engine Overhaul)								RE	≈18-Mar-2026
 74 ENG2 Ref:SB JT15D-72-7003					Mos	14-Dec-2015				
					Hrs	6,610.9	3,600	-/+50	10,210.9	3,040.4 Hrs (+50)
					Enc	6,759				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
B742001	Engine Igniters - Perform operational check						RE (N/A)	Continuous Inspection Program		
 74 A/F						Mos				
Ref.:74-31-00-210 (ZONE: AUX, 410, 420)						Hrs				
						Ldg				
B742002	Engine Igniters - Perform operational check						RE (N/A)	Continuous Inspection Program		
 74 A/F						Mos				
Ref.:74-31-00-211 (ZONE: AUX, 410, 420)						Hrs				
						Ldg				
B742003	Engine Igniters - Perform operational check						RE (N/A)	Continuous Inspection Program		
 74 A/F						Mos				
Ref.:74-31-00-710 (ZONE: AUX, 410, 420)						Hrs				
						Ldg				
SL560-74-01	Transmittal of Pratt and Whitney, Canada Service Bulletin 7537, Turbofan - Replacement of Igniter Plugs						RE (-)		Informational	
 74 A/F						Mos	11-Sep-1997			
Eff: 20-Jun-1997 Complied With						Hrs	1,483			
						Ldg	0			
SL560-74-02	Ignition - Transmittal Of Pratt & Whitney Canada Service Bulletin 7567R1 Turbofan Engine Igniter Box Grounding Strap - Introduction Of						RE (-)		Recommended	
 74 A/F						Mos	14-Mar-2001			
Eff: 28-Sep-2000 Complied With						Hrs	3,046			
						Ldg	0			
▼ 75 - BLEED AIR										
	Bleed Control Valve						RE (O/C)			
 75 ENG1		0				Mos	10-Dec-2001			
Unknown		0				Hrs	3,235			
Unknown		0				Enc	0			
	Bleed Control Valve						RE (O/C)			
 75 ENG2		0				Mos	10-Dec-2001			
Unknown		0				Hrs	3,235			
Unknown		0				Enc	0			
▼ 76 - ENGINE CONTROLS										
	Engine Sync Actuator						RE (O/C)			
 76 A/F		0				Mos	15-Nov-1994			
5485-066		0				Hrs	0			
2341003J		0				Ldg	0			
	Synchronizer Control Box						RE (O/C)			
 76 A/F		0				Mos	03-Feb-1999			
213693		0				Hrs	2,105			
2491711D		0				Ldg	0			
04-11-00(E)(1)	Engine Controls - Complete a Time Limited Dispatch (TLD) Operational Check						RE (N/A)	Inspection Time Limits		
 76 A/F						Mos				
Ref.:76-14-00-710						Hrs				
						Ldg				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
560-76-01 R02	Engine Synchronizer Controller Replacement						RE (-)		Recommended	
 76 A/F Eff: 11-Aug-1999 Complied With					Mos	03-Feb-1999				
					Hrs	2,105				
					Ldg	0				
A761400	Time Limited Dispatch (TLD) Maintenance Check - Perform (Chapter 4 Item)						RE (N/A)		Continuous Inspection Program	
 76 A/F Ref.:76-14-00-710 (ZONE: 233, 234, 235, 243)					Mos					
					Hrs					
					Ldg					
B761500	Throttle Switch - Perform operational check						RE		Continuous Inspection Program	≈10-Sep-2018
 76 A/F 051202 Ref.:76-15-00-710 (ZONE: ENG)					Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)	
					Hrs	300	+30	(7,422)	218.1 Hrs (+30)	
					Ldg					
▼ 77 - ENGINE INDICATING										
	Engine Oil Pressure Transmitter						RE (O/C)			
 77 A/F 9912164-1 581968	Left New				Mos	02-Feb-2018				
		0			Hrs	7,203.9				
		0			Ldg	7,240				
	Engine Oil Pressure Transmitter						RE (O/C)			
 77 A/F 123479 48380	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
	Engine Oil Temperature Transmitter						RE (O/C)			
 77 A/F 102-00083 1499	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
	Engine Oil Temperature Transmitter						RE (O/C)			
 77 A/F 102-00083 1547	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
	Fuel Flow Transmitter						RE (O/C)			
 77 ENG1 9-231-28 4954		0			Mos	07-Jul-1995				
		0			Hrs	360				
		0			Enc	0				
	Fuel Flow Transmitter						RE (O/C)			
 77 ENG2 9-231-28 5267		0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Enc	0				
	Fuel Flow/Quantity Indicator						RE (O/C)			
 77 A/F Unknown Unknown					Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 77 A/F 10535N01M00 185	N1 Fan Tachometer Indicator	0			Mos	12-Nov-2010			RE (O/C)	
		0			Hrs	5,567.5				
		0			Ldg	5,970				
 77 ENG1 3118403-01 NSN	N1 Speed Sensor	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Enc	0				
 77 ENG2 3118403-01 NSN	N1 Speed Sensor	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Enc	0				
 77 ENG1 3032997 NSN	N2 Speed Sensor - Bottom	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Enc	0				
 77 ENG2 3032997 NSN	N2 Speed Sensor - Bottom	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Enc	0				
 77 ENG1 3032997 NSN	N2 Speed Sensor - Top	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Enc	0				
 77 ENG2 3032997 NSN	N2 Speed Sensor - Top	0			Mos	15-Nov-1994			RE (O/C)	
		0			Hrs	0				
		0			Enc	0				
 77 A/F 9912430-2 B258	N2 Turbine Tachometer Indicator				Mos	02-Feb-2018			RE (O/C)	
	Repaired			0	Hrs	7,203.9				
			0	Ldg	7,240					
7644	Replacement of T1 Thermocouple Harness						T (A/R)		Category 7	
 77 ENG1 Eff: 19-Dec-2017 (AVG MAN HRS: 1.5)					Mos					
					Hrs					
					Enc					
7644	Replacement of T1 Thermocouple Harness						T (A/R)		Category 7	
 77 ENG2 Eff: 19-Dec-2017 (AVG MAN HRS: 1.5)					Mos					
					Hrs					
					Enc					

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
▼ 78 - EXHAUST										
 78 A/F 9912377-13V7 Unknown	Engine Exhaust Nozzle								RE (O/C)	
	Left	0				Mos	15-Nov-1994			
		0				Hrs	0			
 78 A/F 9912377-13V7 Unknown	Engine Exhaust Nozzle								RE (O/C)	
	Right	0				Mos	15-Nov-1994			
		0				Hrs	0			
 78 A/F 262-0001-501 3068	Engine Thrust Reverser Assembly								RE (O/C)	
	Left	0				Mos	15-Nov-1994			
		0				Hrs	0			
 78 A/F 262-0001-503 3069	Engine Thrust Reverser Assembly								RE (O/C)	
	Right	0				Mos	17-Sep-2007			
		0				Hrs	0			
 78 A/F 65680 1994	Engine Thrust Reverser Control Valve								RE (O/C)	
	Left	0				Mos	15-Nov-1994			
		0				Hrs	0			
 78 A/F 65680 2001	Engine Thrust Reverser Control Valve								RE (O/C)	
	Right	0				Mos	15-Nov-1994			
		0				Hrs	0			
 78 A/F 13027-4 2746	Engine Thrust Reverser Isolation Valve								RE (O/C)	
	Left	0				Mos	15-Nov-1994			
		0				Hrs	0			
 78 A/F 13027-4 2753	Engine Thrust Reverser Isolation Valve								RE (O/C)	
	Right	0				Mos	15-Nov-1994			
		0				Hrs	0			
 78 A/F 62270 3901	Inboard Thrust Reverser Actuator								RE (O/C)	
	Left	0				Mos	15-Nov-1994			
		0				Hrs	0			
 78 A/F 62270 3903	Inboard Thrust Reverser Actuator								RE (O/C)	
	Right	0				Mos	15-Nov-1994			
		0				Hrs	0			
		0				Ldg	0			

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
 78 A/F 62270 3902	Outboard Thrust Reverser Actuator						RE (O/C)			
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 78 A/F 62270 3909	Outboard Thrust Reverser Actuator						RE (O/C)			
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 78 A/F Unknown Unknown	Stow Limit Switch						RE (O/C)			
	Left				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 78 A/F Unknown Unknown	Stow Limit Switch						RE (O/C)			
	Right				Mos	15-Nov-1994				
					Hrs	0				
					Ldg	0				
 78 A/F 225-0014-507 3068	Thrust Reverser Fan Duct						RE (O/C)			
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 78 A/F 225-0014-508 3069	Thrust Reverser Fan Duct						RE (O/C)			
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 78 A/F 202-0002-505 3068	Thrust Reverser Lower Door Assembly						RE (O/C)			
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 78 A/F 202-0002-506 3069	Thrust Reverser Lower Door Assembly						RE (O/C)			
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 78 A/F 225-0007-515 3068	Thrust Reverser Lower Mechanism						RE (O/C)			
	Left	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				
 78 A/F 225-0007-515 3069	Thrust Reverser Lower Mechanism						RE (O/C)			
	Right	0			Mos	15-Nov-1994				
		0			Hrs	0				
		0			Ldg	0				

Task No	Description	MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time Remaining
	PN/SN									DUE	
	78 A/F 202-0001-503 3068	Thrust Reverser Upper Door Assembly						RE (O/C)			
		Left	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	78 A/F 202-0001-504 3069	Thrust Reverser Upper Door Assembly						RE (O/C)			
		Right	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	78 A/F 225-0007-513 3068	Thrust Reverser Upper Mechanism						RE (O/C)			
		Left	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
	78 A/F 225-0007-513 3069	Thrust Reverser Upper Mechanism						RE (O/C)			
		Right	0			Mos	15-Nov-1994				
			0			Hrs	0				
			0			Ldg	0				
A783002		Thrust Reverser - Inspect						RE	Continuous Inspection Program	≈10-Sep-2018	
	78 A/F Ref.:78-31-00-210 (ZONE: 410, 420)					Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs	300	+30	(7,422)	218.1 Hrs (+30)	
						Ldg					
A783003		Thrust Reverser Electrical Junction Box - Inspect						RE	Continuous Inspection Program		
	78 A/F Ref.:78-31-02-210					Mos	36	+2	(31-Oct-2019)	1.7 Years (+61 Days)	
						Hrs	1,200	+100	(8,048.2)	844.3 Hrs (+100)	
						Ldg					
B783002		Thrust Reverser - Perform operational check						RE	Continuous Inspection Program	≈10-Sep-2018	
	78 A/F Ref.:78-31-00-710 (ZONE: AUX, 311, 312)					Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs	300	+30	(7,422)	218.1 Hrs (+30)	
						Ldg					
B783003		Thrust Reversers - Perform operational check						RE	Continuous Inspection Program	≈10-Sep-2018	
	78 A/F Ref:78-31-00-711 (ZONE: AUX, 311, 312)					Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs	300	+30	(7,422)	218.1 Hrs (+30)	
						Ldg					
B783101		Thrust Reverser Stow Limit Switch - Perform functional test						RE	Continuous Inspection Program	≈10-Sep-2018	
	78 A/F Ref.:78-31-00-720 (ZONE: 410, 420)					Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs	300	+30	(7,422)	218.1 Hrs (+30)	
						Ldg					
B783102		Thrust Reverser Stow Limit Switch - Perform functional test						RE	Continuous Inspection Program	≈10-Sep-2018	
	78 A/F Ref.:78-31-00-721 (ZONE: 410, 420)					Mos	24	+2	(31-Jul-2019)	1.5 Years (+61 Days)	
						Hrs	300	+30	(7,422)	218.1 Hrs (+30)	
						Ldg					

Task No	Description	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories	Time
PN/SN	MOC Note or Component Condition								DUE	Remaining
C783002	Thrust Reverser Actuating Mechanism - Lubricate, using the WC-393 lubrication method for the pivot bolt								RE Continuous Inspection Program	≈10-Sep-2018
78 A/F	051202,...				Mos	21-Jul-2017	24	+2	≈21-Jul-2019	
Ref.:78-31-00-640 (ZONE: AUX)					Hrs	7,122	300	+30	≈7,422	
					Ldg	7,168				
C783003	Thrust Reverser Actuating Mechanism - Lubricate, using the D-5100NS lubrication method for the slider								RE Continuous Inspection Program	≈10-Sep-2018
78 A/F	051202,...				Mos	21-Jul-2017	24	+2	≈21-Jul-2019	
Ref.:78-31-00-641 (ZONE: AUX)					Hrs	7,122	300	+30	≈7,422	
					Ldg	7,168				
C783004	Thrust Reverser Actuating Mechanism - Lubricate. Using the CSA lubrication method for the pivot bolt								RE Continuous Inspection Program	≈10-Jul-2019
78 A/F	051230				Mos	21-Jul-2017				
Ref.:78-31-00-642 (ZONE: AUX)					Hrs	7,122	600	+10	(7,722)	518.1 Hrs (+10)
					Ldg	7,168				
SL560-78-06	Transmittal of Nordam Service Bulletin CITV 78-2, Exhaust - Thrust Reverser - Replacement of Thrust Reverser Stang Fairing Support Former								RE (-) Recommended	
78 A/F					Mos	10-Aug-1996				
					Hrs	866				
					Ldg	0				
▼ 79 - OIL										
	Drain & Refill Oil System								RE (A/R)	
79 ENG1					Mos	14-Dec-2015				
					Hrs	6,610.9				
					Enc	6,759				
	Drain & Refill Oil System								RE (A/R)	
79 ENG2					Mos	12-Nov-2010				
					Hrs	5,567.5				
					Enc	5,970				
	Oil Pressure Switch								RE (O/C)	
79 ENG1		0			Mos	15-Nov-1996				
1103P89-2		0			Hrs	1,050				
Unknown		0			Enc	0				
	Oil Pressure Switch								RE (O/C)	
79 ENG2		0			Mos	22-Jan-1998				
1103P89-2		0			Hrs	1,657				
Unknown		0			Enc	0				
560-79-02	Oil Pressure Transmitter Installation Improvement								RE (-) Recommended	
79 A/F					Mos	02-Apr-1997				
Eff: 23-Aug-1996 Complied With					Hrs	1,224				
					Ldg	0				
722001-0101	Oil Pump								RE (O/C)	
79 ENG1		0			Mos	10-Dec-2001				
3104289-01		0			Hrs	3,235				
18A757		0			Enc	0				

Task No PN/SN	Description MOC Note or Component Condition	TSNI	TSOI	TSRI	TSI	CW	REQ	TOL	Categories DUE	Time Remaining
722001-0101	Oil Pump									
 79 ENG2 3104289-01 18A758		0			Mos	10-Dec-2001			RE (O/C)	
		0			Hrs	3,235				
		0			Enc	0				
79-JT15D-004	Oil Cooler - Inspection and Re-certification (at Engine Overhaul)									≈07-Dec-2025
 79 ENG1 Ref:SB JT15D-72-7003					Mos	14-Dec-2015			RE	
					Hrs	6,610.9	3,500	-/+50	10,110.9	2,940.4 Hrs (+50)
					Enc	6,759				
79-JT15D-004	Oil Cooler - Inspection and Re-certification (at Engine Overhaul)									≈07-Dec-2025
 79 ENG2 Ref:SB JT15D-72-7003					Mos	15-Dec-2015			T	
					Hrs	6,610.9	3,500	-/+50	10,110.9	2,940.4 Hrs (+50)
					Enc	6,759				
79-JT15D-007	Systems - Oil System - Oil Filter Element (non-cleanable) - Remove the Oil Filter Element and Inspect for Foreign Matter								RE (N/A)	EMM - Requirement
 79 ENG1 Brand C:792015					Mos					
					Hrs					
					Enc					
79-JT15D-007	Systems - Oil System - Oil Filter Element (non-cleanable) - Remove the Oil Filter Element and Inspect for Foreign Matter								RE (N/A)	EMM - Requirement
 79 ENG2 Brand C:792015					Mos					
					Hrs					
					Enc					
A793001	Engine Oil Filter - Inspect								RE (N/A)	Continuous Inspection Program
 79 A/F Ref.:79-31-00-610 (ZONE: 410, 420)					Mos					
					Hrs					
					Ldg					
▼ 80 - STARTING										
560-80-03 R02	Starting - Aircraft Parts Corporation (APC) Part Number 9912125-2 Starter Generator Inspection/Replacement								RE (-)	Recommended
 80 A/F Eff: 14-Apr-1998 Not Applicable	N/A BY P/N				Mos	05-Nov-1998				
					Hrs	2,010				
					Ldg	0				
A801001	Generator Brushes Lucas Aerospace Starter - Inspect								RE	Continuous Inspection Program ≈10-Sep-2018
 80 A/F	051204				Mos		24	+2	(31-Jul-2019)	1.5 Years (+61 Days)
Ref.:80-11-01-210 (ZONE: 410, 420) (NOTE: Airplanes 560-0001 and On Utilizing Lucas Starter Generators, Part Number 9912125-1 Only)					Hrs		300	+30	(7,422)	218.1 Hrs (+30)
					Ldg					
B801002	Starter Disengage System - Perform operational check								RE	Continuous Inspection Program
 80 A/F	051205				Mos		36	+2	(31-Oct-2019)	1.7 Years (+61 Days)
Ref.:80-11-01-710 (ZONE: 410, 411)					Hrs		1,200	+100	(8,048.2)	844.3 Hrs (+100)
					Ldg					