

NOTES

- o THESE PLANS ARE DESIGNED TO MEET THE REQUIREMENTS OF THE FLORIDA BUILDING CODE 6th EDITION (2017)
- o CONTRACTOR TO TAKE ALL MEASURES TO BLEED ALL AIR FROM THE THE BEAM CAVITY AND COMPLETELY FILL THE INTENDED SPACE.
- o CONTRACTOR SHALL REPAIR BLEED HOLES AND THE ROOF MEMBRANE AS REQUIRED.

REPAIRED BEAM TOP SECTION



REPAIRED BEAM SIDE SECTION



Д-Д

Cert of Auth #31375 CollinsEngineering@marcopros.net

COLLINS ENGINEERING LLC 761 Nautilus Ct., Marco Island, FL 34145

DWG# **CS-01**

1083