

09/15/21

Update






# What this update includes:

- A Project Overview
- B Highlight: Scour Prevention

Project Update: Status and Next steps


## Project Overview

- Maintenance on Groin 1, 2 &4
- Refacing of rock armor
  - Remove existing rock
  - Reestablish 3H:1V riverside slope
  - Place rock that is appropriately sized
- Scour Mitigation
  - Construct toe for the groins
  - Severe scour and rock loss seen at tips of Groin 1 and Groin 2
    - Scour apron and 'round head' tip designed using USACE design standards





Project Site Aerial



**Typical Section** 

#### Scour Hole

• Example: Tip of Groin 2

• Dimensions of scour hole:

• Depth: 8+ feet

• Width: 40 feet


• Length: 93 feet









### Tip of Groin #1





### Tip of Groin #1





#### Groin #1





# Project Update

- Project Bid Awarded
  - Won by Harris Sand & Gravel
- Rock Production Underway
  - DOWL verified the rock production efforts on 08/09/2021
- Permits in Hand
  - ADF&G: In-water work can start after 10/31/2021
  - USACE: Maintenance work covered by Nationwide Permit
  - DNR: Groins are within Erosion Control Easement. Notified of work.
  - CoV: Floodplain Development Permit Granted
- Next Steps:
  - Pre-construction meeting
  - Notify public of work: Work sites are dangerous and are closed to the public
  - Mobilization