

Customer

Substation – Drone Inspection Executive Brief

Inspection Date: September 12, 2025



Key Findings

- Site access and layout generally good.
- Vegetation encroachment along some boundaries.
- Equipment and structures appear in stable condition.
- Drainage and surface grading to be monitored.
- No critical defects identified during aerial inspection.

Recommended Next Steps

1. Trim vegetation and maintain clear perimeter zones.
2. Inspect drainage near access roads.
3. Protect stored components from exposure.
4. Schedule follow-up drone or thermal survey in 12 months.

Prepared by SkyQuest LLC | SkyQuestPA.com