## RIO GRANDE DIVERSION INFRASTRUCTURE INVENTORY

Structure Nan	ne: KANE CALLAN	N D		
Reported By:	Daniel Boyes			
Date: April 9, 2	2019			
Headgate Location:	<b>Latitude</b> 37.68561667	<b>Longitude</b> -106.3278		
Headgate Typ	e: Manually opera	ated 3' wide steel	slide gates (2)	
Condition: [	Diversion C C C C C C C C C C C C C C C C C C C	n and A □ ndition: B ⊠ C □ D □ F □	River Miles from North Channel Rio Grande Terminus (Point of Diversion): 5.61 mi	Structure Yes □ Submerged: No ⊠
Repair(s) or Ir structure instal		ompleted Since	2006: New headwall, hea	dgate, and return flow
structure. A she boulder diversi	ort feeder channel on across the river e is controlled by a	, located on the r r directs water int		
	nstallation of a slui		: The SMP Technical Advi e debris or, alternatively, o	
Comments: T	his ditch includes p	oriorities 36, 81, 9	97, 195, 290, and 1934-9.	
Notes:				

**Estimated Range of Cost:** Low





Diversion dam looking upstream



Diversion dam looking downstream



Headgate and feeder ditch



Flume looking upstream




RIO GRANDE DIVERSION INFRASTRUCTURE INVENTORY

KANE CALLAN DITCH

PHOTO LOG

Rio Grande Stream Management Plan



Headgate with channel margins from 1975 and 2015 overlaid.