SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

DIVERSION INFRASTRUCTURE INVENTORY				
Structure Name: BIG MEADOW D				
Reported By: Daniel Boyes				
Date: April 11	, 2019			
Headgate Location:	Latitude 38.102882	Longitude -106.206535		
Headgate Type: Manually operated 2.5' wide screw gate				
Headgate Condition:	A □ Diversion B ⋈ Other Cor C □ D □ F □	, , L	Stream Miles from Saguache Creek Terminus (Point of Diversion): 34.88 mi	Structure Yes □ Submerged: No ⊠
Structure Description: This structure is located on the outside of a meander. The diversion dam is a combination of boulders, sheet metal, fencing, and concrete. The diversion constricts the stream channel and appears to be causing downstream erosion. The diversion can form a barrier to fish passage, depending on flow and configuration. Debris accumulation is a minor issue on the diversion and at the headgate, which is tilted.				
recommends closer to the c allow for fish p	replacing the divers diversion. A new div	sion, repairing or re version would lower improvements wou	maintenance, reduce do	d relocating the headgate
Comments: This ditch is a priority 5.				
Notes:				

Estimated Range of Cost: Medium



Headgate outlet

Headgate and diversion dam



Diversion dam looking downstream



Diversion dam looking upstream



Flume looking downstream



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

BIG MEADOW DITCH

PHOTO LOG

Saguache Creek Stream Management Plan