

SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

Structure Name: SEITZ MCCLURE ASHLEY D

Reported By: Daniel Boyes

Date: April 3, 2019

Location:	Latitude	Longitude
	38.0646	-106.06071

Headgate Type: Manually operated 1.5' wide screw gate

Headgate Condition:	A <input type="checkbox"/>	Diversion and Other Condition:	A <input type="checkbox"/>	Stream Miles from Saguache Creek Terminus (Point of Diversion):	Structure Submerged: Yes <input type="checkbox"/>
	B <input type="checkbox"/>		B <input checked="" type="checkbox"/>	22.6 mi	No <input checked="" type="checkbox"/>
	C <input checked="" type="checkbox"/>		C <input type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input type="checkbox"/>		

Structure Description: This structure is located at the apex of a meander. The diversion dam is a welded steel check board structure which also services the Taylor A Ashley Ditch. A catwalk was installed on the diversion to improve access for maintenance.

Repair(s) or Improvement(s) Currently Needed: Sediment accumulation is an issue for this structure. The SMP Technical Advisory Team (TAT) recommends installing a sluice gate on the stream's north bank. A sluice gate would improve the sediment transport and reduce ditch maintenance at this location.

Comments: This ditch is a priority 35.

Notes:

Estimated Range of Cost: Low

Headgate looking downstream



Headgate outlet



Headgate and diversion dam



Diversion dam



Headgate next to Taylor A Ashley Ditch



Flume looking upstream



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

SEITZ MCCLURE ASHLEY DITCH

PHOTO LOG

Saguache Creek Stream Management Plan