

SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

Structure Name: HOUGLAND CREEK D

Reported By: Daniel Boyes

Date: April 11, 2019

Headgate	Latitude	Longitude
Location:	38.136972	-106.341169

Headgate Type: No headgate exists for this structure.

Headgate Condition:	A <input type="checkbox"/>	Diversion and Other Condition:	A <input type="checkbox"/>	Stream Miles from Saguache Creek Terminus (Point of Diversion):	Structure Submerged: Yes <input type="checkbox"/>
	B <input type="checkbox"/>		B <input type="checkbox"/>	54.61 mi	No <input checked="" type="checkbox"/>
	C <input type="checkbox"/>		C <input type="checkbox"/>		
	D <input type="checkbox"/>		D <input type="checkbox"/>		
	F <input type="checkbox"/>		F <input type="checkbox"/>		
	N/A <input checked="" type="checkbox"/>		N/A <input checked="" type="checkbox"/>		

Repair(s) or Improvement(s) Currently Needed: Installing a flume for this structure would improve the administration of Saguache Creek.

Structure Description: This ditch is on Mill Creek but affects the flows and administration of Saguache Creek. There is no diversion dam or headgate for this structure. It is simply a ditch running under County Road CC 36 and irrigating land adjacent to Saguache Creek.

Comments: This ditch is a priority 28.

Notes:

Estimated Range of Cost: Low

Ditch entrance looking downstream



Ditch culvert outlet



Channel looking upstream of ditch



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

HOUGLAND CREEK DITCH

PHOTO LOG

Saguache Creek Stream
Management Plan