

Issue Report

Hotel Contruction Mapping



Report created on August 25, 2020

Captured: August 23, 2020

Type	Count
Broken Part	2
Debris	1
Plan Deviation	2

No.	Summary	Type	Created	Status
5	Metal Recycle	Plan Deviation	Aug 25, 2020 at 6:40pm	Open
4	Curb installation	Plan Deviation	Aug 25, 2020 at 6:38pm	Open
3	Flashing Repair	Broken Part	Aug 25, 2020 at 6:37pm	Open
2		Debris	Aug 25, 2020 at 6:36pm	Open
1		Broken Part	Aug 25, 2020 at 6:35pm	Open

Broken Part



No.	Summary	Created	Status
3	Flashing Repair	Aug 25, 2020 at 6:37 PM	Open
1		Aug 25, 2020 at 6:35 PM	Open

No. 1 OPEN

Captured: Aug 23, 2020 at 7:05am



Type

Broken Part

Summary

N/A

Lat/Long

43.42295, -88.17842

Created

Aug 25, 2020 at 6:35pm by Sean Hanrahan

No. 3 OPEN***Captured:*** Aug 23, 2020 at 7:05am**Type**

Broken Part

Lat/Long

43.42267, -88.17893


Summary

Flashing Repair

Created

Aug 25, 2020 at 6:37pm by Sean Hanrahan


Debris



No.	Summary	Created	Status
2		Aug 25, 2020 at 6:36 PM	Open

No. 2 OPEN

Captured: Aug 23, 2020 at 7:05am



Type
Debris

Summary
N/A

Lat/Long
43.42267, -88.17893

Created
Aug 25, 2020 at 6:36pm by Sean Hanrahan

Plan Deviation



No.	Summary	Created	Status
5	Metal Recycle	Aug 25, 2020 at 6:40 PM	Open
4	Curb installation	Aug 25, 2020 at 6:38 PM	Open

No. 4 OPEN

Captured: Aug 23, 2020 at 7:05am



Type

Plan Deviation

Lat/Long

43.42308, -88.17918

Summary

Curb installation

Created

Aug 25, 2020 at 6:38pm by Sean Hanrahan

No. 5 OPEN***Captured:*** Aug 23, 2020 at 7:05am**Type**

Plan Deviation

Lat/Long

43.42218, -88.17868

Summary

Metal Recycle

Created

Aug 25, 2020 at 6:40pm by Sean Hanrahan