



Ph. 734 718 4287 Fax 586 336 3656

[www.michiganinfrared.com](http://www.michiganinfrared.com)


**MICHIGAN  
INFRARED  
CONSULTING LLC**

**Serving Metro Detroit**



Customer	John Q Customer
Address	16144 Forder Hwy
City State Zip	Detroit Michigan 48146
Date	2/28/11
Time of Day	6:30 am
Weather	Sunny 37 degrees Winds light and varible House faces West
Inspector	Certified Thermographer






Location	Main Electrical Service Panel
Date/Time	2/28/11 7:00am
Issue	Faulty Breaker
Recommendation	See Notes below



Location	Rear Bedroom Wall facing West
Date/Time	2/28/11 8:00am
Issue	Insulation Void
Recommendation	See Notes below



Location	Attic Main Heating/Cooling Trunk line
Date/Time	2/28/11 4:00pm
Issue	Gaps
Recommendation	See Notes below



Location	Living Room South Wall Adj to Master Bedroom South
Date/Time	2/28/11 9:00am
Issue	Insulation Void
Recommendation	See Notes below

## NOTES

**Air infiltration** around windows should be evaluated by a window specialist. Correction may include the installation of new weather striping and caulking. Correction of areas that appear to have **inadequate insulation or no insulation** are not easily remedied. Walls and floor areas that may need serviced may require the removal of drywall or other wall coverings and would require them to be re-installed, finished and painted. You will need to consult with an installation specialist regarding this condition. **Moisture** intrusion should always be confirmed with a moisture meter. **Electrical faults** should be evaluated by a licensed Electrician.

**This report is the exclusive property of the Inspection Company and the client whose name appears herewith, and its use by any unauthorized persons is prohibited.**