



Your Home Inspection Report



4433 75th St. SW, Mukilteo, WA 98275

3/28/2023 2:00pm – 4:00pm

Client Present: No

Broker Present: No

Summary reviewed with client: Yes

Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

Z-Home Inspections

Residential Home Inspection

This report contains confidential information and is supplied solely for use by the client(s) of:

Z-Home Inspections

Milton WA 98354

Client Information

Client: Dave Valdez

Phone: Email: davade4433@icloud.com

Agent: Adam Braddock

Phone: Email adambraddock@johnlscott.com

Inspection Company

Z-Home Inspections Lic.#2387

Phone 253-677-7731 email z.homeinspections@gmail.com

Conditions

Property— Not Occupied

Estimated Age 39 years

Inspection Date 3/28/2023

Time of inspection 2:00pm — 4:00pm

Electric On—Yes

Gas On— Yes

Water On—Yes

Temperature 45 degrees

Weather— Partly Cloudy

Soil Conditions—Dry

Space Below: — concrete slab - foundation

Building Type—Residential

Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

Z-Home Inspection

Inspection Report

This page is a Summary Report. There are no pictures, rather a brief description of an issue. Following summary will be an explanation in greater detail, usually accompanied by photos. Items in red typically require repair or replacement.

1. A small number of the electrical outlets tested as being not wired properly.
2. Recommend all detectors are supplied with fresh batteries and tested for proper operation.

Z-Home Inspections

Inspection Report

LIMITATIONS: Unless specifically included in the inspection, the following items and any related equipment, controls, electric systems and/or plumbing systems are excluded from this inspection: detached buildings or structures; fences and gates; retaining walls; underground drainage systems, catch basins or concealed sump pumps; swimming pools and related safety equipment, spas, hot tubs or saunas; whether deck, balcony and/or stair membranes are watertight; trees, landscaping, properties of soil, soil stability, erosion and erosion control; ponds, water features, irrigation or yard sprinkler systems; sport courts, playground, recreation or leisure equipment; areas below the exterior structures with less than 3 feet of vertical clearance; invisible fencing; sea walls, docks and boathouses; retractable awnings. Any comments made regarding these items are as a courtesy only.

- 1. Site**— The yard, hot tub/outdoor entertainment area, wood/composite deck, and carport were in good condition and appeared they should for a home 39 year old. The suspended wood deck appeared to be properly attached to home.



Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

2. Siding and Trim

The exterior siding is a natural wood clap type siding and on all sides of the home. The siding on the home appeared to be in good condition on all sides of the home.

The paint to the exterior of the home appeared to be in good condition on all sides of the home.

The exterior trim is a natural wood, most likely cedar or fir and in good condition on all sides of the home.

The eaves and fascia boards in good condition on most sides of the home.



Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

3. Windows

The home appears to have all updated double pane vinyl framed windows. All windows tested did operate as they should.

No jamming or loose window panels were detected at the time of the inspection.

There were no signs of failed window seals or broken glazing or glass.

All operable windows tested did lock properly at the time of the inspection.

Most screens appeared to be in place and in good condition.

Note: There are some double hung type windows in the home. It is important to know that both window panels need to be fully seated for the window to latch/lock proper.



4. Roof

The following items or areas are not included in this inspection: areas that could not be traversed or viewed clearly due to lack of access; solar roofing components. Any comments made regarding these items are made as a courtesy only. Note that the inspector does not provide an estimate of remaining life on the roof surface material, nor guarantee that leaks have not occurred in the roof surface, skylights or roof penetrations in the past. Regarding roof leaks, only active leaks, visible evidence of possible sources of leaks, and evidence of past leaks observed during the inspection are reported on as part of this inspection. The inspector does not guarantee or warrant that leaks will not occur in the future. Complete access to all roof and attic spaces during all seasons and during prolonged periods of all types of weather conditions (e.g. high wind and rain, melting snow) would be needed to do so. Occupants should monitor the condition of roofing materials in the future. For older roofs, recommend that a professional inspect the roof surface, flashings, appurtenances, etc. annually and maintain/repair as might be required. If needed, the roofer should enter attic space(s). Regarding the roof drainage system, unless the inspection was conducted during and after prolonged periods of heavy rain, the inspector was unable to determine if gutters, downspouts and extensions perform adequately or are leak-free.

There was the updated architectural composite asphalt type roofing material.

All materials looked to be intact and in good condition during the time of the inspection.

This roof covering should protect the home for at least 10+ more years under normal weather conditions and regular maintenance.

Note: As the home owner, take the time to take occasional ground surveys of the roof for moss build-up and/or trees limbs getting too close to the roofline (no closer than ten feet is recommended).



5. Gutters and Downspouts

The gutters and downspouts are of aluminum material.

The gutters appear to be in good condition and well attached to the home.

The gutters appear to have an adequate number of downspouts to help keep rainwater flowing away from the home on all sides.

Note: **Recommend establishing a regular maintenance schedule for having the gutter system cleaned and maintained to ensure the gutters are effectively protecting the home.**



6. Electrical

The following items are not included in this inspection: generator systems, transfer switches, surge suppressors, inaccessible or concealed wiring; underground utilities and systems; low-voltage lighting or lighting on timers or sensors. Any comments made regarding these items are as a courtesy only. Note that the inspector does not determine the adequacy of grounding or bonding, if this system has an adequate capacity for the client's specific or anticipated needs, or if this system has any reserve capacity for additions or expansion. The inspector does not operate circuit breakers as part of the inspection, and does not install or change light bulbs. The inspector does not evaluate every wall switch or receptacle, but instead 4433 75th St. SW, Mukilteo, WA 98275s a representative number of them per various standards of practice. When furnishings, stored items or child-protective caps are present some receptacles are usually inaccessible and are not 4433 75th St. SW, Mukilteo, WA 98275ed; these are excluded from this inspection. Receptacles that are not of standard 110 volt configuration, including 240-volt dryer receptacles, are not 4433 75th St. SW, Mukilteo, WA 98275ed and are excluded. The functionality of, power source for and placement of smoke and carbon monoxide alarms is not determined as part of this inspection. Upon taking occupancy, proper operating and placement of smoke and carbon monoxide alarms should be verified and batteries should be changed. These devices have a limited lifespan and should be replaced every 10 years. The inspector at 4433 75th St. SW, Mukilteo, WA 98275ts to locate and evaluate all main and sub-panels. However, panels are often concealed. If panels are found after the inspection, a qualified electrician should evaluate and repair if necessary. The inspector at 4433 75th St. SW, Mukilteo, WA 98275ts to determine the overall electrical service size, but such estimates are not guaranteed because the overall capacity may be diminished by lesser-rated components in the system. Any repairs recommended should be made by a licensed electrician.

The home's electrical service panel is located in the basement of the home.

The panel appeared to be the original panel and in good condition.

There was no sign of thermal activity or faulty breakers at the time of the inspection.

The breaker legend appeared to be well marked.

A small amount of the electrical outlets tested as being not properly wired (no ground/reversed wired).

Recommend a licensed electrician evaluate and remedy as needed.



Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

7. Plumbing

The following items are not included in this inspection: private/shared wells and related equipment; private sewage disposal systems; hot tubs or spas; main, side and lateral sewer lines; gray water systems; pressure boosting systems; trap primers; incinerating or composting toilets; fire suppression systems; water softeners, conditioners or filtering systems; plumbing components concealed within the foundation or building structure, or in inaccessible areas such as below tubs; underground utilities and systems; overflow drains for tubs and sinks; backflow prevention devices. Any comments made regarding these items are as a courtesy only. Note that the inspector does not operate water supply or shut-off valves due to the possibility of valves leaking or breaking when operated. The inspector does not 4433 75th St. SW, Mukilteo, WA 98275 for lead in the water supply, the water pipes or solder, does not determine if plumbing and fuel lines are adequately sized, and does not determine the existence or condition of underground or above-ground fuel tanks.

This home is served by a public water source and sewer systems.

The gas Rheem hot water heater appeared to be installed and manufactured in 2009 and nearing the end of it's life expectancy.

There were no apparent live leaks in the plumbing supply and/or waste systems.

The water pressure to the home tested to be at 90 psi. Recommended psi range is 40-80.

The water shut-off valve can be found at the water meter near the street.



Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

8. Heating

The following items are not included in this inspection: humidifiers, dehumidifiers, electronic air filters; solar, coal or wood-fired heat systems; thermostat or 4433 75th St. SW, Mukilteo, WA 98275 erature control accuracy and timed functions; heating components concealed within the building structure or in inaccessible areas; underground utilities and systems; safety devices and controls (due to automatic operation). Any comments made regarding these items are as a courtesy only. Note that the inspector does not provide an estimate of remaining life on heating or cooling system components, does not determine if heating or cooling systems are appropriately sized, does not 4433 75th St. SW, Mukilteo, WA 98275 coolant pressure, or perform any evaluations that require a pilot light to be lit, a shut-off valve to be operated, a circuit breaker to be turned "on" or a serviceman's or oil emergency switch to be operated. It is beyond the scope of this inspection to determine if furnace heat exchangers are intact and free of leaks. Condensation pans and drain lines may clog or leak at any time and should be monitored while in operation in the future. Where buildings contain furnishings or stored items, the inspector may not be able to verify that a heat source is present in all "liveable" rooms (e.g. bedrooms, kitchens and living/dining rooms).

The main heat source to the home is derived from a gas forced air unit located in the basement of the home.

The programmable thermostat did activate the gas furnace during the time of the inspection.

Due to the fact that the furnace is a gas furnace, it is recommended to have the gas unit be serviced by a licensed HVAC contractor on an annual basis.



9. Kitchen

The following items are not included in this inspection: household appliances such as stoves, ovens, cook tops, ranges, warming ovens, griddles, broilers, dishwashers, trash compactors, refrigerators, freezers, ice makers, hot water dispensers and water filters; appliance timers, clocks, cook functions, self and/or continuous cleaning operations, thermostat or 4433 75th St. SW, Mukilteo, WA 98275erature control accuracy, and lights. Any comments made regarding these items are as a courtesy only. Note that the inspector does not provide an estimate of the remaining life of appliances, and does not determine the adequacy of operation of appliances. The inspector does not note appliance manufacturers, models or serial numbers and does not determine if appliances are subject to recalls. Areas and components behind and obscured by appliances are inaccessible and excluded from this inspection.

The oven, stove top, garbage disposal, exhaust fan and dishwasher were operational during the time of the inspection.

All kitchen built-in cabinets doors and drawers were tested and operated as designed.




10. Bathroom

The following items are not included in this inspection: overflow drains for tubs and sinks; heated towel racks, saunas, steam generators, clothes washers, clothes dryers. Any comments made regarding these items are as a courtesy only. Note that the inspector does not determine the adequacy of washing machine drain lines, washing machine catch pan drain lines, or clothes dryer exhaust ducts. The inspector does not operate water supply or shut-off valves for sinks, toilets, bidets, clothes washers, etc. due to the possibility of valves leaking or breaking when operated. The inspector does not determine if shower pans or tub and shower enclosures are water tight, or determine the completeness or operability of any gas piping to laundry appliances.

All faucets, toilets, showers and exhaust fans were tested and operated as they should.

All bathroom built-in cabinets doors and drawers were tested and operated as designed.



Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

11. Entrance, Doors, and Interior

The following items are not included in this inspection: security, intercom and sound systems; communications wiring; central vacuum systems; elevators and stair lifts; cosmetic deficiencies such as nail-pops, scuff marks, dents, dings, blemishes or issues due to normal wear and tear in wall, floor and ceiling surfaces and coverings, or in equipment; deficiencies relating to interior decorating; low voltage and gas lighting systems. Any comments made regarding these items are as a courtesy only. Note that the inspector does not evaluate any areas or items which require moving stored items, furnishings, debris, equipment, floor coverings, insulation or similar materials. The inspector does not evaluate 4433 75th St. SW, Mukilteo, WA 98275 for asbestos, lead, radon, mold, hazardous waste, urea formaldehyde urethane, or any other toxic substance. Some items such as window, drawer, cabinet door or closet door operability are evaluated on a sampled basis. The client should be aware that paint may obscure wall and ceiling defects, floor coverings may obscure floor defects, and furnishings may obscure wall, floor and floor covering defects. If furnishings were present during the inspection, recommend a full evaluation of walls, floors and ceilings that were previously obscured when possible. Carpeting and flooring, when installed over concrete slabs, may conceal moisture. If dampness wicks through a slab and is hidden by floor coverings that moisture can result in unhygienic conditions, odors or problems that will only be discovered when/if the flooring is removed. or source of odors is not within the scope of this inspection.


All the various flooring coverings are in good condition.

All light fixtures, exhaust fans, ceiling fans, doors, door locks and handrails were tested and operated as designed.

The home has all the required smoke and carbon monoxide detectors in the home.

Recommend all detectors are supplied with fresh batteries and tested for proper operation.

Recommend a licensed contractor remedy these issues.



Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

12. Attic

The ceiling is well insulated with blown in type insulation.

All rafter/ roof trusses, sheathing, other materials appeared to be in good condition, properly constructed

All materials showed no signs of any water intrusion/ damage during the time of the inspection.

The attic space did appear to have the appropriate amount of ventilation.



Z-Home Inspections

Rodney Zimmerschied Licensed Home Inspector Lic.#2387

253-677-7731

Milton, WA 98354

z.homeinspections@gmail.com

13. Foundation— Concrete Slab

Structural components such as joists and beams, and other components such as piping, wiring and/or ducting that are obscured by under-floor insulation are also excluded from this inspection. Note that the inspector does not determine if support posts, columns, beams, joists, studs, trusses, etc. are of adequate size, spanning or spacing.
 The inspector does not guarantee or warrant that water will not accumulate in the basement in the future. Access to the basement during all seasons and during prolonged periods of all types of weather conditions (e.g. heavy rain, melting snow) would be needed to do so. The inspector does not determine the adequacy of basement floor or stairwell drains, or determine if such drains are clear or clogged.
 Note that all basement areas should be checked periodically for water intrusion, plumbing leaks and pest activity.

The home’s concrete slab foundation appeared to be in good condition.

There were no signs of excessive movement in the foundation as there were no major cracks observed during the time of the inspection.

As most of the foundation to a slab type foundation is not readily visible with most of it being covered, there are other ways to determine major movement in a foundation. These determinations can be deduced from major cracks in the walls and ceilings, jamming problems with both windows and doors.

There were no major cracks in the ceilings and walls of the home during the time of the inspection.

There were no problems with windows and doors jamming when tested during the time of the inspection.

