.....

CLIENT'S INFORMATION
CONTACT:
COMPANY:
E-MAR. ADDRESS:
PHONE NUMBER:

PROJECT ID:FAÇADE RESTORATION 415 BLEECKER ST, NEW YORK, NY 10014

				·										
											Friday	, October 31, 2025		
ITEM#	DWG.#	DETAIL #	CSI #	DESCRIPTION	QTY.	WASTE	QTY. W/ WASTE	UNIT	UNIT COST (MATERIAL)	UNIT COST (LAB. + EQUIP.)	TOTAL COST (MATERIAL)	TOTAL COST (LAB. + EQUIP.)	ITEM COST	TRADE
			10000	DIVISION 01 - GENERAL REQUIRMENTS										
1				Permits	1	0%	1	LS	\$ -	\$ -	\$ -	\$ -	\$ -	
2				Drawing Submission	1	0%	1	LS	\$ -	\$ -	\$ -	\$ -	\$ -	T
3				Supervision And Coordination	1	0%	1	LS	\$ -	\$ -	\$ -	\$ -	\$ -	
4				Final Cleanup	1	0%	1	LS	\$ -	\$ -	\$ -	\$ -	\$ -	
5				Mobilization Cost	1	0%	1	LS	\$ 3,500.0	\$ -	\$ 3,500.0	\$ -	\$ 3,500	
6				Temporary Control And Facilities	1	0%	1	LS	\$ -	\$ -	\$ -	\$ -	\$ -	

Column C					Subtotal (General Requirements)												\$:
				90000	DIVISION 09 - FINISHES												
Cable A 200 Cable Cabl	Ξ				EVERYWHERE EXTERIOR FINISH				E						E		E
Auto	7	A-100	A-100		Install New N Type Mortar In 1/4" Lifts. Wash Down All Masonry To Remove Any Mortar Splatter. Color Of Mortar To Match Original Mortar Color Per Mortar Testing. Analysis	863	10%	949	SF	s	0.31	\$ 3.2	\$ 294.3	\$ 3,075.7	s	3,370	
2	8	<u>A-100</u>	A-100		Code-B: Fire Escape Scrape And Remove Existing Paint And Rust. Prime And Coat Existing Fire Scrape With Rust Inhibitive Coating With A Minimum Cf 10 Year Warranty. Remediate All Damage Floor Slats, Stringers, Steps. Provide Additional Reinforcement At Wall Bracket And Reinforcement Channels If Necessary	3	0%	3	BASKET	s	320.00	\$ 490.5	\$ 960.0	\$ 1,471.5	s	2,432	
10	9	A-100	A-100		Scrape And Remove Existing Peeling Paint And Rust. Prime And Coat With Rust Inhibitive Coating With A Minimum Of 10 Year Warranty. Eor To Inspect 100% Of Window Guard For Structural Stability. Secure With Mechanical Anchors All Loose	20	10%	22	FT	s	2.65	\$ 6.4	\$ 58.3	S 140.4	ş	199	
12	10	A-100	A-100		Clean Metal Flashing From Stains, Scrape And Remove Existing Peeling Paint And Rust: Prime And Coat With Rust Inhibitive Coating With A Minimum Of 10 Year Warranty, Inspect Metal Flashing For Structural Stability. Secure With All Loose Metal	45	10%	50	rt	s	8.20	\$ 17.2	\$ 405.9	\$ 849.9	s	1,256	
12	11	A-100	A-100		Clean Cast Stone Lintel From Stains, Organic Growth, Repair All Cracks. Repoint All Joints. Patch And Remediate Spalled Stone	55	10%	61	FT	s	3.44	\$ 7.4	\$ 208.1	\$ 445.3	s	653	
13	12	A-100	A-100		Existing Wood Windows Are To Remain in Priscs. Insignet All Windows Wood Compress For Pedic Designers For Pedic Designers For Reside (1994). Destroyment in Infectation, Carefully, Bernous Loose, Flaking, O' Destroyment Long Hose Describers Melhoride, Audio Carefully Aller Long Hose Destroyment Anderson Carefully Angel Foreign Consolidation To Strongerish Destroyment Angel Pedic Ped	9	0%	9	EA	s	150.00	\$ 613.1	\$ 1,350.0	\$ 5,518.2	s	6,868	
14	13	A-100	A-100		Clean 100% Of The Existing Exterior Wall With Low Pressure Power Washing Andover Restoration Cleaning Solutions Listed In Contract Specifications Prior. At Completion Of Repairs At Front Elevation (West) Only, Contractor To Recoat The Entire	1130	10%	1243	si	s	0.61	\$ 4.4	\$ 758.2	\$ 5,494.1	s	6,252	
13	14	A-100	A-100		Remove And Replace Damage Window Precast Concrete Sill At Opening. Provide Self Adhering Waterproofing Membrane With End Dams Prior To Window Sill Installation. Include 25%	35	10%	39	FT	s	20.17	\$ 27.0	\$ 776.4	\$ 1,038.7	s	1,815	
10	15	A-100	A-100		Restore And Remediate Cracked, Chip Cast Stone Window Sills. Repoint 100% Of Remediate Procast All Stone Joints. Resurface 100% Of Stone Sill Surface With A Polymer Modified Repair Compound To Match Existing. Recoat 100% Of Stone Surface	35	10%	39	п	s	12.60	\$ 19.6	\$ 485.2	\$ 755.4	s	1,241	
12	16	A-100	A-100		Repoint 100% Of All Stone Joints. Patch And Remediate Spalled/ Crack Stone With Approved Repair Compound By Edison Coating Or Equal. Recoat 100% Of Stone Surface With	60	10%	66	FT	s	30.25	\$ 34.3	\$ 1,996.4	\$ 2,266.4	s	4,263	
Name on A Polipiac Loss, Cack And Company Brick, Match Color, Install Tisk Energy Color Center Vertically Mark Service 18	17	A-100	A-100		Inspect Existing Comice For Damage, Including Rot. Cracks, Warping Or Missing Sections. Inform Engineer of Record To Review Backspot Synctural Element And Confirm Structural Stability. Sand And Prime 100 % Of Wood Surfaces With High Quality, Oil Based Or Lates Primer. Provide Exercise Paint To Match existing Foliant To Match existing Plucis Sand All Quisits To	26	10%	29	FT	s	35.00	\$ 54.0	\$ 1,001.0	\$ 1,543.3	s	2,544	
19 A-100 Extra 100 A-100 To March Technique Are Experience Are Exp	18	A-100	A-100		Remove And Replace Loose, Crack And Damagad Brick, Match Color: Install Ties Every 15f 'On Center Vertically And Hotionitally, All New Face Brick Ties it To Be Carefully Toothed In So Brick Replacement That Size. Color, Rasage, Testure As Well As Hoaders, Coursing, Pointing and Alignment Match in Kand To Agiscent Surfaces. Include Additional 10th Allowance For Brick Replacement.	56	10%	62	SI	s	18.50	\$ 44.2	\$ 1,139.6	\$ 2,719.6	s	3,859	
Subtreal (Frishber) 5 3	19	A-100	A-100		Install New Backer Rod And Sealant At Expansion Joint. Sealant To Match Existing For Compatibility Purposes. Provide Closed	10	10%	11	FT	5	2.71	\$ 15.1	\$ 29.8	\$ 166.2	\$	196	
			l	l	Subtotal (Finishes)		L		1				1	1	<u> </u>		\$ 34
·																	
				_		_	_			_		_				_	_

SUR TOTAL

OVERMENDA MAN PROFIT

TOTAL BAKE BOD

Seemend Motes. The prices used while propering the extinuit or prices (as it is priced to provide the proper in the prices, So, it is printend to provide the price. So, it is printend to provide the price.