



813.822.5959

DucatiTampaBay.com

7202 E. Adamo Drive Tampa FL 33619

Repair Order

Due: \$0.00

Doc Number: 407143

Service Writer: Eric Lucas

Date Printed: 01/30/2026

Date Promised: 09/16/2025

[Redacted Customer Information]

Customer Information

Home Phone: [Redacted]

Cell Phone: [Redacted]

Email: [Redacted]

Fold Here

Summary

Approve	Decline	Unit	Job	Job Total
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	RENEW HARDWARE	\$429.34
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	REMOVE / PAINT / REINSTALL MIRRORS / REPLACE STICKERS ON MIRRORS	\$161.84
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	RENEW TANK LID	\$415.17
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	EXTRACT / RENEW SIDE STAND BOLT	\$127.64
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	POLISH/ RESTORE EXHAUST TIPS	\$77.50
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	DEFOG HEADLIGHTS	\$310.00
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	CLEAN WHEELS	\$155.00
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	REFURBISH SURFACE (NON BRAKING PORTION) OF ROTORS	\$310.00
<input checked="" type="checkbox"/>	<input type="checkbox"/>	2004 Ducati 998 MTX	REMOVE / REINSTALL TANK (FOR PAINT)	\$1,337.71
			Job Subtotal:	\$3,324.20
			Misc:	\$10.00
			Job Parts Subtotal:	\$857.71
			Job Labor Subtotal:	\$1,519.00
			Job Sublet Subtotal:	\$947.49
			Tax:	\$216.74
			Total:	\$3,550.94
			Less Deposits:	(\$3,550.94)
			Total Due:	\$0.00

PLEASE READ CAREFULLY, CHECK ONE OF THE STATEMENTS BELOW AND SIGN:

Please be advised, if paying by credit card, there will be a 3% surcharge fee applied to charges \$500 or more.

____ I DO NOT REQUEST A WRITTEN ESTIMATE AS LONG AS THE REPAIR COSTS DO NOT EXCEED \$ ____ THE SHOP MAY NOT EXCEED THIS AMOUNT WITHOUT MY WRITTEN OR ORAL APPROVAL.

____ I DO NOT REQUEST A WRITTEN ESTIMATE.

SIGNED _____ DATE _____

____ IT IS NECESSARY TO SAVE THE OLD PARTS

INTENDED PAYMENT METHOD: ____ CASH ____ CHECK ____ VISA ____ MC ____ AMEX

I hereby authorize the repair work to be done along with the necessary material, and hereby grant you and your employees permission to operate the vehicle herein described on public roads for testing and or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Dealer is not responsible for parts availability or delays beyond Dealer control. Customer acknowledges receipt of a copy hereof:

Note: You will be notified upon completion of any diagnostic work necessary to estimate the cost of repair or if the actual charges will exceed

Job Subtotal **\$161.84**

Approve: Decline:

RENEW TANK LID

Description:Customer requests renew tank lid and swap lock cylinders.

Resolution: * Disassembled and swapped lock barrels so same key can be used
- installed new tank cap per Ducati service manual

Parts

Part #	Qty	Description	Price	Discount	Total
89540012A	1.00	CAP SET, FUEL TANK	\$291.17	\$0.00	\$291.17
Parts Subtotal					\$291.17

Labor

Description	Technician	Hours	Total
RENEW TANK LID /SWAP LOCK CYLINDERS	Jarad Sanchez	0.8	\$124.00
Labor Subtotal			\$124.00

Job Subtotal **\$415.17**

Approve: Decline:

EXTRACT / RENEW SIDE STAND BOLT

Description:Customer requests evaluation to determine whether renewing side stand is necessary. Customer states lean angle on side stand seems excessive.

Resolution:Tech confirmed customer complaint and found one of the side stand bolts had sheared. Extracted sheared bolt and replaced with OEM bolt.

* Extracted and replaced side stand bolt per Ducati service manual
- confirmed SS switch is functioning normally

Parts

Part #	Qty	Description	Price	Discount	Total
82111032A	1.00	AXLE, SIDE STAND	\$50.14	\$0.00	\$50.14
Parts Subtotal					\$50.14

Labor

Description	Technician	Hours	Total
EXTRACT / RENEW SIDE STAND BOLT	Jarad Sanchez	0.5	\$77.50
Labor Subtotal			\$77.50

Job Subtotal **\$127.64**

Approve: Decline:

POLISH/ RESTORE EXHAUST TIPS

Description:Customer requests polish exhaust tips to remove surface corrosion / discoloration.

Resolution:Polished and restored exhaust tips per customer request.

Labor

Description	Technician	Hours	Total
POLISH/ RESTORE EXHAUST TIPS	Georges Nasr	0.5	\$77.50
Labor Subtotal			\$77.50

Job Subtotal **\$77.50**

Approve: Decline:

DEFOG HEADLIGHTS

Description:Customer requests to defog / light (wet) sand headlights to restore clarity

Resolution:Defogged and polished headlight glass and lens.

Labor

Description	Technician	Hours	Total
DEFOG HEADLIGHTS	Georges Nasr	2	\$310.00
Labor Subtotal			\$310.00

Job Subtotal **\$310.00**

Approve: Decline:

CLEAN WHEELS

Description:Customer requests restoration of wheels, preferably by cleaning.

Resolution:Cleaned wheels

Labor

Description	Technician	Hours	Total
CLEAN WHEELS	Georges Nasr	1	\$155.00
Labor Subtotal			\$155.00
Job Subtotal			\$155.00
Approve: <input checked="" type="checkbox"/>			Decline: <input type="checkbox"/>

REFURBISH SURFACE (NON BRAKING PORTION) OF ROTORS

Description:Customer states rotors have minor corrosion / discoloration. Customer requests to refinish the aesthetic surfaces.

Resolution:Refurbished rotors and all accessible / exposed bolts to remove as much corrosion as practicable without causing damage to components and preserving OEM character.
- Performed by GN

Parts

Part #	Qty	Description	Price	Discount	Total
49240381A	0.00	FRONT BRAKE DISC	\$542.44	\$0.00	\$0.00
49240111B	0.00	REAR BRAKE DISC	\$217.57	\$0.00	\$0.00
77152662B	0.00	SCREW M8X14	\$3.42	\$0.00	\$0.00
77110212A	0.00	SCREW	\$3.42	\$0.00	\$0.00
Parts Subtotal					\$0.00

Labor

Description	Technician	Hours	Total
REFURBISH SURFACE (NON BRAKING PORTION) OF ROTORS	Georges Nasr	2	\$310.00
Labor Subtotal			\$310.00
Job Subtotal			\$310.00
Approve: <input checked="" type="checkbox"/>			Decline: <input type="checkbox"/>

REMOVE / REINSTALL TANK (FOR PAINT)

Description:Customer requests remove / reinstall tank so it may be sent off to paint to fix a chip.

Resolution:While removing fuel tank, tech noted fuel delivery hoses had dry rot and were falling apart. New hoses ordered to replace and prevent future fuel leaks.

- * Picked up line on tank reassembly 01/01/26JS
- Replaced internal vent lines
- Replaced Flange Oring
- Reinstalled pump and flange

Parts

Part #	Qty	Description	Price	Discount	Total
88650011A	1.00	O-RING	\$17.64	\$0.00	\$17.64
59010571A	2.00	HOSE	\$63.91	\$0.00	\$127.82
43311641A	1.00	LABEL WARNING FUEL TANK	\$12.26	\$0.00	\$12.26
Parts Subtotal					\$157.72

Labor

Description	Technician	Hours	Total
REMOVE / REINSTALL TANK	Jarad Sanchez	1.5	\$232.50
Labor Subtotal			\$232.50

Sublet

Description	Total
PAINT TANK AND MIRRORS	\$947.49
Sublet Subtotal	\$947.49
Job Subtotal	\$1,337.71
Approve: <input checked="" type="checkbox"/>	Decline: <input type="checkbox"/>

All Jobs Subtotal:	<u>\$3,324.20</u>
Shop Supplies:	\$10.00
Tax:	\$216.74
Total:	<u>\$3,550.94</u>
Less Deposits:	(\$3,550.94)
Total Due:	<u><u>\$0.00</u></u>