

Elevation 1+ Fast Menu Item



23/09/2010

Navigating the Setup menu on the Elevation 1+ unit shows a Fast option and a value in mm/second/second. This option is the rate at which the unit will decelerate if it detects an internal fault such as "Overspeed" or "ENC1".

When using Vector to programme Elevation 1+ units this value is automatically set to the maximum deceleration rate, specified in the motor profile.