



How to set up NMEA output from a Trimble 750 \1000 to a X20

Requires cable part number ZTN67091



FM 750

FM 1000



2011

750

Connect cable ZNT67091 to
Port A or B




1000

Connect cable ZNT67091 to
Port A, B, C, or D





From main
Screen press
Settings






Press System






Press the
Advanced
tab






Select
NEMA Output
tab



2011


Select NEMA output port



2011

Select port that cable ZTN67091 is plugged into

When proper
Port is green
Select green
Check mark





Press the Baud
Rate tab



2011

Select Baud rate to match X20 monitor selected rate

Best choice
Usually is
38,400bps

Press green
Check mark





Your setup is
now complete
return to main
screen

Using red X
And left arrow
where the X
was

