






64	22nd floor - discoloration of elastomeric coating	Weather Damage	May 14, 2021, 3:52pm	Open
63	22nd floor - two small impact craters (?) on decorative stucco reveal	Weather Damage	May 14, 2021, 3:49pm	Open
62	22nd floor - large impact crater on decorative stucco reveal	Crack	May 14, 2021, 3:46pm	Open
61	21st floor - discoloration and boiling of elastomeric coating at horizontal expansion joint	Weather Damage	May 14, 2021, 3:41pm	Open
60	21st floor - minor discoloration of elastomeric coating around horizontal expansion joint	Weather Damage	May 14, 2021, 3:40pm	Open


21 - Crack

Apr 21, 2021 at 10:16am





No.	Summary	Type	Created	Lat,Lng	Status
21	7th floor - minor crack in stucco at window frame	Crack	May 14, 2021, 1:16pm	30.38893,-88.99492	Open











US ROOFING
SYSTEMS

