COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF SAFE DRINKING WATER

SERVICE LINE INVENTORY FORM

Inventory Response Summary information

PWS Name: Solebury School

PWSID: 1090030

NOTES: Information will autofill based on the responses in the Detailed Inventory. Record types marked "Inactive" are not included.

| Service Line Classification | | | |
|--|---|--------|------------|
| Service Line Classification | Definition | Number | Percentage |
| Lead | Any portion of the service line is known to be made of lead. | 0 | |
| Galvanized Requiring Replacement | A portion of the service line is galvanized and is downstream from: — a portion that was previously lead or is of unknown lead status — connectors that are lead or unknown | 0 | |
| Lead Status Unknown | The service line material is not known. There is not enough evidence to support material classification. | 0 | |
| Non-Lead | An evidence-based record, method, or technique has demonstrated that ALL portions of the service line are NOT lead or GRR. | 27 | 100% |
| TOTAL NUMBER OF ACTIVE S | ERVICE LINES ENTERED IN THE DETAILED INVENTORY | 27 | 100% |
| Service Line Classification | by School/Childcare Summary | | |
| | | Number | Percentage |
| Service Lines Connected to a Childcare facility: | | 0 | |
| | Lead | 0 | |
| | Galvanized Requiring Replacement | 0 | |
| | Lead Status Unknown | 0 | |
| | Non-Lead | 0 | |
| Service Lines Connected to an Elementary School: | | 0 | |
| | Lead | 0 | |
| | Galvanized Requiring Replacement | 0 | |
| | Lead Status Unknown | 0 | |
| | Non-Lead | 0 | |
| Service Lines Connected to an Secondary School: | | 17 | 100% |
| | Lead | 0 | |
| | Galvanized Requiring Replacement | 0 | |
| | Lead Status Unknown | 0 | |
| | Non-Lead | 17 | 100% |
| Lead Status Unknown Service Lines: | | 0 | |
| | Likely Lead | 0 | |
| | Unlikely Lead | 0 | |