


HISTORICAL EXTERIOR RESTORATIVE WORK, consisted of exterior restoration throughout the all facades, which included repairing deteriorated terracotta units utilizing a patching compound; selective replacement of damaged decorative terracotta with new architectural cast stone units; selective replacement of deteriorated masonry; installation of waterproofing membranes beneath select locations of replacement masonry; and selective replacement of deteriorated structural steel window lintels and a portion of the adjoining brickwork with new galvanized steel lintels and new brickwork, as well as rebuilding the damaged northeast corner of the building; rebuilding the brick and terracotta parapets; selective replacement and repointing of brick; selective sill replacement; selective terracotta replacement with GFRC or cast stone; exterior alterations at the roof, including replacement of the roofing membrane, the installation of control joints on the inside facing walls of the parapets; and cladding the bulkheads in stucco.

HISTORICAL ENTRANCE RESTORATION WORK, patch and repaint of the concrete planters flanking the primary entrance at the first floor to match parapet.







1100 GRAND CONCOURSE 2014-2019 (10-17a)

1100 GRAND CONCOURSE BRONX, NY 10462

LANDMARK: GRAND CONCOURSE HISTORIC DISTRICT



HISTORICAL WINDOW RESTORE,

including replacement of 726 white painted, straight-headed, one-over-one, double hung metal windows throughout all of the building facades with light brown painted double hung windows, including 30 arch-headed, six-over-six, wood windows at the second floor level; 63 straight-headed, one-over-one, metal windows at 11 vertical rows of small windows at courtyard, including 5 vertical rows at the street facing courtyard façade; and 633 straight-headed six-over-six metal windows at all of the remaining windows openings.

MVN ARCHITECT LLC