



DC Stick, Mig, Tig WELDER WITH CONTACTOR



DC WELDER WITH THERMOSTAT




Note: White wires can be connected in series with thermostat, remote control wire from Amphenol Socket, Stick-Tig switch, coil of contactor or other options.


MISSILE SWITCH COMBINATION

Can be used for bypassing ZRID device for additional welding processes if full OCV is required.


1 Connection of Power supply to the ZRID unit




2 Connection of control wires from welder to ZRID Unit



Reed Switch Connection



ENGINE DRIVEN MACHINES



NOTE: All ZRID units can be fitted with either a reed switch or a toroid ring