

-Site Benchmark Information-

(#1

Set Nail & Disk "LB 7623" in asphalt. Elevation: 157.21'

** #2


Set Nail & Disk "LB 7623" in concrete driveway. Elevation: 156.72

-Benchmark Information-

F.D.O.T. Network

Elevations are referenced to the Florida Department of Transportation Vertical Datum Network, North Trip, Base

(Elevations are based upon NAVD 88 Datum)



Field Date: 08-17-17	Date Completed: 08-21-17
Drawn By: GLG	File Number: IS-39853
C - Calculated C - Centerline CB - Concrete Block CM - Concrete Monument Conc Concrete D - Description DE - Drainage Easement Esmt Easement F.E.M.A Federal Emergency Management Agency FFE - Finished Floor Elevation Fnd Found IP - Iron Pipe L - Length (Arc) M - Measured N&D - Nail & Disk N.R Non-Radial ORB - Official Records Book P - Plat P.B Plat Book - D- Wood Fence	PC - Point of Curvature Pg Page Pl Planter P.O.B Point of Beginning P.O.L Point on Line PP - Power Pole PRM - Permanent Reference Monument PT - Point of Tangency R - Radius Rad Radius Rad Radial R&C - Rebar & Cap Rec Recovered Rtd Roofed Set - Set '%' Rebar & Rebar Cap "LB 7623" Typ Typical UE - Utility Easement WM - Water Meter WM - Vater Meter Δ - Delta (Central Angle) -O Chain Link Fence
-Notes-	

>Survey is Based upon the Legal Description Supplied by Client. >Abutting Properties Deeds have $\underline{\mathsf{NOT}}$ been Researched for Gaps, Overlaps and/or Hiatus. >Subject to any Easements and/or Restrictions of Record.

>Bearing Basis shown hereon, is Assumed and Based upon the Line Denoted with a "BB". >Building Ties are <u>NOT</u> to be used to reconstruct Property Lines.

>Fence Ownership is NOT determined. >Roof Overhangs, Underground Utilities and/or Footers have NOT been located UNLESS otherwise noted.

>Septic Tanks and/or Drainfield locations are approximate and MUST be verified by appropriate Utility Location Companies. >Use of This Survey for Purposes other than Intended, Without Written Verification, Will be at the User's Sole Risk and Without Liability to the Surveyor. Nothing Hereon shall be Construed to give ANY Rights or Benefits to Anyone Other than those Certified.

>Flood Zone Determination Shown Heron is Given as a Courtesy, and is Subject to Final Approval by F.E.M.A. This Determination may be affected by Flood Factors and/or other information NEITHER known by NOR given to this Surveying Company at the time of this Endeavor Ireland & Associates Surveying Inc. and the signing surveyor assume NO Liability for the Accuracy of this Determination.

I hereby Certify that this Boundary Survey of the above Described Property is True and Correct to the Best of my Knowledge and Belief as recently Surveyed under my Direction on the Date Shown, Based on Information furnished to Me as Noted and Conforms to the Standards of Practice for Land Surveying in the State of Florida in accordance with Chapter 5J-17,052 Florida Administrative Codes, Pursuant to Section 472,027 Florida Statutes.



Ireland & Associates Surveying, Inc 1301 S. International Parkway Suite 2001 Lake Mary, Florida 32746 www.irelandsurveying.com

Office-407.678.3366 Fax-407.320.8165

property appears to be located in zone X. This Property was found in Orange County, community number

JONATHAN BOYD

120179, dated 09/25/2009.

RANGE 28 EAST, THENCE RUN NORTH 89°10'38" EAST 322.33 FEET, THENCE RUN NORTH 00°57'39" WEST 160.00 FEET THENCE RUN SOUTH 89°20'38" WEST 322.33 FEET THENCE RUN SOUTH 00°57'39" EAST 160 FEET TO THE POINT OF 'BEGINNING OF THE PUBLIC RECORDS OF ORANGE COUNTY, FLORIDA. Flood Disclaimer: By performing a search with the local governing municipality or www.fema.gov, the