

Filing the tabs down.

SOME USERS MAY ENCOUNTER THE ISSUE OF NOT BEING ABLE TO HOOK THE SECOND PIECE/TAB AFTER TIGHTENING DOWN THEIR ROTOPAX TANK, THIS CAN HAPPEN DUE TO TOLERANCES BETWEEN ROTOPAX AND THE GORILLA CLAMP MANUFACTURING, THE GOOD NEWS IS THE GORILLA CLAMP HAS MANY ADJUSTMENTS THAT CAN BE MADE BY THE USERS TO FIT THEIR SETUP. PLEASE SEE BELOW FOR THE MODIFICATION TO THE CLAMP WHICH INVOLVES FILING DOWN THE TWO HOOKS TO A HEIGHT OF 1/4" OR WHAT'S NEEDED FOR YOUR SET UP. SOME TOUCH UP PAINT TO COVER THE EXPOSED METAL HELPS CORROSION. USUALLY THIS HEIGHT RESOLVES THE ISSUE.

IF THIS DOES NOT RESOLVE YOUR ISSUE PLEASE REACH OUT TO US VIA EMAIL AT [SUPPORT@GORILLACLAMP.COM](mailto:support@gorillaclamp.com)

WE CAN ALSO OFFER AN EXCHANGE OF A NEW CLAMP WITH THE MODIFICATION IF YOU ARE UNABLE TO MAKE THIS UPDATE AS LONG AS THE ORIGINAL CLAMP IS STILL IN AN UNMODIFIED STATE.

