FIRED UP KILNS
and pottery supplies

SHELF CARE GUIDE

NBSiC & SSiC shelves

Nitrogen bonded & sintered silicon carbide

WARNING **Moisture and thermal shock can shatter these shelves.**

01 Dry before firing

Ware must be bone dry.
Shelves must be completely dry.

02 Store dry and off the floor

Keep shelves in a dry area.
Avoid damp or humid storage.
Keep off floors to prevent water wicking.



03 CONTROL YOUR EARLY FIRING RATE

120°C/hour maximum

Until the kiln reaches 400°C.

This helps avoid thermal shock.