Configure SNMP on the reporting page. Set traps to v2c.

Configure all active inputs to at least use some form of “Notification” like “Relay”, “Light”, etc,. If left disabled, alarm OID will not turn 1 and NForm will not see the alarm status.