

2026 Crash Kings/Competition class

Any questions call: Justin Meyer-573-515-0313

General Driver Rules & Expectations

1. ALL RULES MUST BE FOLLOWED OR YOU WILL NOT RUN
2. Drivers must wear a seat belt, helmet, fire suit jacket and long pants while participating.
3. All drivers must attend the drivers' meeting.
4. You must run a roof sign.
5. Drivers are not allowed to drink alcohol before they participate. If found with alcohol in system you will not run, no exceptions.
6. All other Crash Kings event rules must be followed.

NO PAINTING OR UNDERCOATING THE FRAME. NO BUFFING OR GRINDING FRAMES. NO PAINTING ON THE INSIDE OF THE BODY OR SUSPENSION. IF THIS IS DONE THE CAR WILL NOT BE INSPECTED.

-Car building

-No distributor protectors allowed

-1 OEM bumper bracket per side or 1- 4x10x3/8 bumper bracket per side allowed.

-Fab bumpers are ok within Chrysler pointy.

-Lower cradle only with built mounts must have a rubber bushing.

-Cage 4point. Nothing bigger than 6" material, (may have taller side bars but must follow all other cages rules) must be 6" away from firewall and 6 inches off floor sheet metal. Cage can be welded or bolted in place. You are allowed 2-2x6x1/4 down tubes welded on each side (((Behind))) inside door seam, top of frame only, and cannot go through frame. Halo (rollover) bar can go to the top of frame but must be located in front of rear seat body mount hole.

-Transmission of choice. Steel bell and steel tail allowed.

-Any rear end allowed. Trailing arms may be braced or 2x3 box tubing

-Watts conversions are ok (no leaf conversions)

-Built tie rods allowed, OEM ball joints, a-arms may be changed and allowed (2) 2x4x1/8 straps per a-arm

-3/4 body bolts allowed but cant add any. Must be inside the frame and cant stack washers to pin frame. You must run at least 1" body spacers

-may have 2 3/8 x3 bars in front window

-Hoods may have 8 pieces of 1 in all thread. 2 may go through core support mounts. 6 can be welded or bolted to sheet metal or 6- 6x6x1/8 plates under the hood.

-Radiator guards allowed out of 1/8 only 4" over lap may be bolted or welded.

-2x2x1/4 cross member allowed with 1-3x3x1/4 angle iron 6" long per side to mount cross member

-03 cradles must bolt in factory mounting holes for factory cradle may change out aarms and spindles to direct bolt on parts.

-8 repair plates allowed. 6x6x1/8.