PROCEDURE FOR USING THE LWAD (Lone Worker Alert Device), LAXSON-R

1. TO TURN ON YOUR DEVICE

At the beginning of your shift:

Remove the device from the charger cable and press the side button until it vibrates. The blue light will flash to indicate that it is now powered.

2. THE DEVICE INDICATOR LIGHTS LEGEND

Blue light flashes = Device in operation
Green light flashes = Device is detected by the satellites outside
Red light flashes and vibration = SOS alert or Fall has been triggered
No light = The Device is off

To turn off the Device, press the side button until it vibrates. The blue or green light will turn off.

3. THE MULTIPLE WEAR OF THE DEVICE

With clip

Wrist bracelet

with velcro strap

4. IN CASE OF AN SOS EMERGENCY

In case of emergency, press the side button 3 times, a red light and a vibration will occur & an alert will be sent to the respondent.
If it is a false alarm, **press the button again twice to cancel the alert.**

5. DURING A FALL DETECTION

During a fall detection, the device screen around the R logo will turns red (like the SOS). and the alert will be sent to the responder. If it is a false alarm, **press 2 times on the side button to cancel the alert.**

6. CHARGING IMPORTANT

At the end of your shift or round:

. Connect the device to the charger cable magnet terminal on the side of the device.

When the Device is charging, it will turn itself off and the blue light will also turn off.

Occupational Health and Safety