ProHeat Air-Cooled Output Cables (195 404, 195 405 And 300 362)

1.   Safety Symbol Definitions

⚠	**DANGER!** – Indicates a hazardous situation which, if not avoided, will result in death or serious injury. The possible hazards are shown in the adjoining symbols or explained in the text.	📖	Have only trained and qualified persons install, operate, or service this unit. Read the safety information at the beginning of these instructions and in each section. Call your distributor if you do not understand the directions. For INDUCTION HEATING SAFETY and EMF information, read owner's manual(s).
⚠	Indicates a hazardous situation which, if not avoided, could result in death or serious injury. The possible hazards are shown in the adjoining symbols or explained in the text.	⚡	Beware of electric shock from wiring. Disconnect input power before installing this kit. Reinstall all panels and covers.
NOTICE ☞	Indicates statements not related to personal injury. Indicates special instructions.	👓	Wear safety glasses with side shields.

CALIFORNIA PROPOSITION 65 WARNINGS

Welding or cutting equipment produces fumes or gases which contain chemicals known to the State of California to cause birth defects and, in some cases, cancer. (California Health & Safety Code Section 25249.5 et seq.)

This product contains chemicals, including lead, known to the state of California to cause cancer, birth defects, or other reproductive harm. *Wash hands after use.*

2.   Tools Needed

3. Parts

Item No.	Part No.	Description (Qty)
1	253 841	Connector Shell (1)
2	254 886	Coupling Collar (1)
3	221 099	Strain Relief Clamp (2)
4	136 343	Screw K50 x 20 (2)
5	254 887	Connector Shell (2)
6	224 259	Strain Relief Socket Clamp (4)
7	228 296	Screw KA35x10 (4)
8	197 635	Warning Label (2)

Be sure to provide Model and Serial Number when ordering replacement parts.

804 324-A