



MUSASHI-21 MARK-1 TYPE:F

SEAM NO. SEAM LENGTH CYCLE SEWING サイクル縫い

1 2 3 4

SHIFT UP DOWN FLAP SHIFT SELECT

KNIFE メス使用 SHIFT STACKER スタックコー
CENTER センター PULL BACK 戻り止
TAB コーナー CARRIAGE STOP 車止

ERROR エラー
TOTAL カウンター
THREAD 7本
CENTER S センター前
CENTER E センター後
TAB S コーナー前
TAB E コーナー後

SHIFT UP DOWN
CENTER KNIFE DOWN
メス下降

OP
CARRIAGE 大降さ
ADVANCE 前進
RETURN 後進

START スタート
NEEDLE UP 針上
PULL ROD フロッド

EMERGENCY STOP 緊急停止
RESET リセット
POWER 電源

MUSASHI CORPORATION

Eagle AUTOMATIC POKER MUSASHI

AUTO POKETER
MACHINE NO. 7431

START
THREAD TRIMMER
RELEASE
ARM

if the machine
has burned out off
on changed Bobbins
etc

BEFORE THE WORK, HANGING BOBBINS AND NEEDLES
CLEANING etc, SWITCH OFF MAIN SWITCHES



LK-1920

HA

JUKI CORPORATION

Made in Japan

Mfg.No. 2L1VM01584

JUKI



LK-1920 HA

Program 52
1/2 x 2

PL-5410N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

PLNXE21278

WB



N

JUKI CP-130

ALM
OFF
1 2 3
A B C
V V V
D



N

+
A
-

+
B
-

+
C
-

+
D
-



R

+



0620

JUKI



JUKI 5410N-7
JUKI CORPORATION
Made in Japan
APL No.

WB

DDL-5550N-7

OKI CORPORATION

Made in Japan

Mfg No

WB



0703

1 A A
ABCBC
Y V I
0

N

+
A
-

+
B
-

+
C
-

+
D
-

>8

>6

SUKI

DDL-5550N-7

SUKI CORPORATION
Made in Japan
Mfg. No.

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WB




A B C
A B C D
A B C D E
A B C D E F

M N

M N

+ -
A B C D



JUKI CP-230

123

R

R

JUKI

1 2 3 4 5 6 7 8 9 10

DLN-5410N-7

WB

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

ELNKF28084

WB



JUKI



DLN-5410N-7
WB

DLN-54 NW-7

JUKI CORPORATION

Made in Japan

M. C. Co.

DLNWL

WB



JUKI CP-130

N

ALR
0FC
1A
ABC
Y-D

N

+

A

+

B

+

C

+

D

+

R

+

-

1/2

JUKI

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14

DLN-54 N-7

WB

LK-1920 HA

JUKI CORPORATION

Made in Japan

Mfg.No.

2111AH00554



JUKI



LK-1920 HA

JUKI CORPORATION
Made in Japan
Safety No.

53

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WB
203AL00495



JUKI

CAUTION
Moving parts may cause injury.
Operate with caution; do not touch moving parts before threading, changing bobbin and needle, cleaning, etc.

DLN-5410N-7

DLN-5410N-7

JIKI CORPORATION

Made in Japan

Mfg No.

DLN-XE 21422

WE



JUKI CP-130

JUKI

620

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

DLNWL20214

WB



JUKI CP-230

ALB7
OFCJ

M VI

ALB7
CD
AFBJ

I A A
ABCBC
V V I
D

B A A
C C N
D D B

M N

+
- A
+
- B
+
- C
+
- D

> <

[Blank display]

R

+
-

[Blank display]

R

+
-

JUKI

LH-1152-5

TOKYO JINKI

INDUSTRIAL CO. LTD.

4B



Back Tack Power
Start Z End

JUKI MC-110

JUKI

LH-1152-5

4B

28

LK-1852

TOKYO JUKI INDUSTRIAL CO., LTD.
MADE IN JAPAN

SUBCLASS 5



JUKI

LK-1000
MADE IN JAPAN

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

T L N X E 2 3 0 9 0

WB

JUKI



DLN-5410N-7
JUKI CORPORATION
Made in Japan

WB

13-24
25-3
37-

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

2R3W600001



0815

JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin
and needle, cleaning, etc.

DLN-5410N-7
JUKI CORPORATION
MADE IN JAPAN

DLN-5410N-7

JUKI CORPORATION

Made in Japan

WE

Mfg. No.

253 600012



JUKI CP-160



ALB1
D/CJ
ALB1
A/B
I A A
ABCBC
V V I
D
B A
C C N
O B

W N

+ + + +
- - - -



R +
-

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbins
and needle, cleaning etc.

0 1 2 3 4

DLN-5410N-7
JUKI CORPORATION

cial



FINEST QUALITY

Union Special

DLN-5410N 7

JUKI CORPORATION

Made in Japan

Mfg. No.

WB



DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

LENX 21773



ALB1
OFC
ALB1
CO
A[B]
I A A
ABCBC
Y V I
O
B A A
C C N
B B

M N
M N

+
A
-
+
B
-
+
C
-
+
D
-

✂ ✂

R +
-

R +
-

JUKI P-230

JUKI

DLN-5410N-7

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WE
2D3WM00007



DLN-5410N-7

JUKI CORPORATION

Made in Japan

WB

Mfg. No.

213WH000003



ALB1
DTCJ
ALB1
A[B]J
I A A
ABCBC
V Y I
D
B A A
C D N
C D B

JUKI CP-160

MN

MN

JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin
and needle, cleaning, etc.

DLN-5410N-7
JUKI CORPORATION



LK-1852
TOKYO JUKI INDUSTRIAL CO., LTD.
MADE IN JAPAN

SUBCLASS 5



20

LK-1852

JUKI CORPORATION
MADE IN JAPAN

SUBCLASS



JUKI

LK-1852
JUKI CORPORATION
MADE IN JAPAN

NUMC 1852

DLN-5410117

JUKI CORPORATION

Made in Japan

Mfg No

HL NXF 22957

WB



ALB1
OFC1
ALB1
CO
A/B1
I A A
ABCBC
V V I
D
DCA
C C B
D

M N
N N

+ A
- A
+ B
- B
+ C
- C
+ D
- D
✂ ✂

R +
- R +
-

JUKI CP-230

123

JUKI

0 1 2 3 4

DLN-5 10

WB

0819

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

2D31H00005



JUKI CP-160

JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin
and needle, cleaning etc.

DLN-5410N-7
JUKI CORPORATION

WILCOX & GIBBS

MADE IN U.S.A.

● TYPE 515-4-39

SPEC. 3X3

DEVICE



PEGASUS

WILCOX & GLENS
TYPE 515-4-39


WILCOX & GIBBS

MADE BY PEGASUS

TYPE 515-4-30

SPEC. 3X3

DEVICE



DLN-5410N-7

WATKINS CORPORATION

WB



JUKI

JUKI CP-130

N

A

B

C

D

✂

✂

R

DLN-5410N-7

WB

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WB
2D3WL00497

JUKI



DLN-5410N-7
JUKI CORPORATION
Made in Japan
Mfg. No. 2134100487



DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

DDLXC67753

WB



JUKI

JUKI CP-130

N

N

+

+

+

+

✂

✂

R

+

-

0
1
2
3
4

DDL-5550N-7

WB

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WB
2D3WL00500

JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin
and needle, cleaning etc.

DLN-5410N-7



A B 1
C D
A B J
I A A
A B C B C
V V J
D
B A A
D C C N
O B

W N

+ + + +
- - - -



+
-



1372346





1535490



MADE

CORPORATION

IN U.S.A.



1431151





1689529

STYLE
35800DN
MADE UNION SPECIAL IN U.S.A.
CORPORATION



1249677

DN

MADE MACHINE CO. U.S.A.



1473669

STYLE

35800 DN

MADE UNION SPECIAL
CORPORATION IN U.S.A.





34k4 variostop

LN-5410N-7

JUKI CORPORATION

Made in Japan

Fig. No.

LN-5410N-7



THE REECE

101-034-CT-CA-5/8-LE

CORPORATION



84

THE SINGER

OIL

3" SIDE
5/8" FROM INSIDE



LT

Union Special

GALKIN



28

LK-1852
TOKYO JUKI INDUSTRIAL CO., LTD.
MADE IN JAPAN

JUKI

28
LK-1852
TOKYO JUKI INDUSTRIAL CO., LTD.
MADE IN JAPAN



Union Special

63900

Type PS111

OFF

DLN-5410N-7

JUKI CORPORATION

Made in Japan

WE3

No.

203W600006

JUKI



DLN-5410N-7

JUKI CORPORATION

Made in Japan

JUKI CP-160

ALB
D/C
ALB
CO
A/D
I A A
ABCBC
V V
D
B A A
C C N
D B

MI
NN

+ + + +
- - - -

R

+

-



locked up
oct 26 2015
D. Black

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

WB



JUKI

DDL-5550N-7

JUKI CORPORATION
Made in Japan
Mfg. No.

WB







Union Special

Union Special



MADE IN U.S.A.



JUKI
Union Special



JUKI
Union Special



JUKI

Sewing Special

NEEDLE
TYPE
120
GBS



JUKI
Union Special

NEEDLE
TYPE
128
GBS

FS311S03-2H04/Z14

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA

CAUTION
WEAR SAFETY GLASSES. DO NOT TAMPER WITH SAFETY SHIELD. USE WITH RUT SHIELD MAY CAUSE AN INJURY.

LINK
Union Special

128GAS 44

NEEDLE
TYPE
128
GAS

UNION SPECIAL CORPORATION
MUNSTLEY, ILLINOIS, U.S.A.

CAUTION
KEEP



JUKI

Union Special

NEEDLE
TYPE
128
GAS




WILLCOX & gibbs

TYPE WS42-01A

SPEC 364

DEVICE UT5

MADE BY PEGASUS



WILCOX
& GIBBS

WILCOX & GIBBS
TYPE 10-A-1
SPEC 10-A
DATE 11-1-54
MADE BY WILLCOX

ES311S14-1M/CC2

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA

JUKI

Union Special

NEEDLE
TYPE
128
GBS

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS, U.S.A.

CAUTION

FS316Z01-2M48/Z4

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA

CAUTION
WEAR SAFETY GLASSES
AND PROTECTIVE EQUIPMENT
WHEN OPERATING THIS MACHINE
TO PREVENT INJURY FROM
MOVING PARTS.

NEEDLE
TYPE
128
GBS

F5316201-2M407/1
UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA

FS311S14-1MCC2

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA



on Spec

NEEDLE
TYPE
128
GBS

UNION
CORPORATION

FS311S14-1N/CC2

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA

CAUTION

WEAR SAFETY
GLASSES. DO NOT
TAMPER WITH
SAFETY SHIELD.
USE WITHOUT
SHIELD MAY CAUSE
AN INJURY.

JUKI
Union Special

NEEDLE
TYPE
128
GB5

CAUTION

willcox & gibbs

TYPE 401-02

SPEC. 100

DEVICE

MADE BY PEGASUS



Wg
iLLCOX
iBBS

Wg iLLCOX iBBS
1974

JK - 8569ADII-01GBX364/UT

JACK INDUSTRIAL
SEWING MACHINE



Mfg.No.

151082165-01

不要隨便拆除零件。



LK-1852

JUKI CORPORATION
Made in Japan

CLASS 5

JUKI

LK-1852

JUKI CORPORATION
MADE IN JAPAN

SUBCLASS 5

Eagle AUTO POCKETER

MACHINE, NO. 7061

RESET
ON
OFF
THREAD DETECTOR
TBD-202
MUSASHI CO

SHIFT UP DOWN
KNIFE X288
CENTER 10-9-8
TAB 3-4-5
SHIFT STACKEE
PULL BACK 18-1
CARRIAGE STOP 8R2
SHIFT
ZIPPER
CARRIAGE X812
ADVANCE 11-8
RETURN 1-8-8
START 20-4
NEEDLE UP 82
PULL ROD 78-0-4
EMERGENCY STOP
RESET 1/2VPP
POWER 8-8
MUSASHI CORPORATION

Engle
AUTOMATIC POCKET WELTING MACHINE
MUSASHI-25

START
THREAD
RELEASE
TAN

MODEL NUMBER
MACHINE NO. 77263

AMS-210E

JUKI CORPORATION

1510

Made in Japan

HL

Mfg. No. 2434400055



28

LK-1852

JUKI CORPORATION
Made in Japan

SUBCLASS

5

JUKI

LK-1852

JUKI CORPORATION
Made in Japan

SUBCLASS 5

28



JUKI

DLM-5200N

JUKI CORPORATION

Made in Japan

Mfg.No.

D
FLMAD 32422

JUKI



DLM-5200N
JUKI CORPORATION
Made in Japan
S/N No. 1000000000

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

111 W 68671

WB



JUKI

DDL-5550N-7

JUKI CORPORATION
Made in Japan
S/N: 1000000000

WB

CE

HIGHLEAD

GK0318-1

NO 0063768



HIGHLEAD

**COLLIER
EQUIPMENT**
www.sewtrain.com



REACH

PFAFF

KL. 337



734/02-900/51



Erz. Nr. 901-0997-006/001

Oberteil - Nr.

765253

PFAFF

PFAFF 11557
C 73470240/01
Ext. Nr. 11557/00000001
Oberst. Nr. 734702

FS311S03-2H04/Z14

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA



JUKI
Union Special



Union Special

16/4 TYPE 51



JK -T1790S-1

JACK INDUSTRIAL
SEWING MACHINE



ISO9001:2008

Mfg.No.

111280372



WB


LZ-2280-7

JUKI CORPORATION

Made in Japan

Mfg.No.

LZDXG16467



JUKI CP-130

ALB
DTC
L A A
ABCBC
X Z

N

A B C D

R

+

-

JUKI

15 1 2 125
140

LZ-2280-7

011

ES311603-2H04/Z14

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA

CAUTION
ALWAYS WEAR EYE PROTECTION
AND KEEP HANDS AWAY FROM
MOVING PARTS

1 R 0 0 A 5 0 4 4

CAUTION
WEAR SAFETY
GLASSES. DO NOT
DANGER WITH
SAFETY SHIELD.
USE WITHOUT
SHIELD MAY CAUSE
AN INJURY.

JUKI
Union Special



●	○	○	○	○	1	2
3	4	5	6	7	8	9
10	11	12	13	14	15	16
17	18	19	20	21	22	23
24	25	26	27	28	29	30

STYLE

51800 CBZ

Union Special®



TRADE MARKS

UNION SPECIAL CORPORATION
CHICAGO, ILLINOIS 60610

MADE IN U.S.A.



130GHS 144

Union Special

FS316Z01-2M48/Z3

UNION SPECIAL CORPORATION
HUNTLEY, ILLINOIS USA

1280AS-13

JUKI

Union Special

CAUTION



WEAR SAFETY
GLASSES. DO NOT
HANDLE WITH
SAFETY SHIELD
OFF. WITHOUT
SHIELD MAY CAUSE
EYE INJURY.

NEEDLE
TYPE
128
GBS

UNION SPECIAL CORPORATION
MUNSTER, INDIANA U.S.A.

CAUTION

DDL-5550-6

JUKI CORPORATION
Made in Japan

Mfg. No.

DDLEUF47123

WB



JUKI

JUKI
SC-180

1 2 3 4
10 11 12 13 14

DDL-5550-6

JUKI CORPORATION
Made in Japan

WB

DLM-5400N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

2D2XJ00263

JUKI





LK-1852

JANUS CORPORATION

MADE IN U.S.A.

SUBCLASS 5

JUKI

LK-1852

JUKI CORPORATION
Made in Japan

28

LK - 980

TOKYO JUKI INDUSTRIAL CO., LTD.

MADE IN JAPAN



JUKI
(212) 691-0470
CAMATRON
SEWING
MACHINE, INC.
42 WEST 24 STREET
NEW YORK, N.Y. 10011

LK-980
TOKYO JUKI INDUSTRIAL CO., LTD.
MADE IN JAPAN

42

COLEMAN CABLE • SEOPRENE 90 16-3 SLFW (III) 300V 60°C P-241-3-MSHA CSA 11.30713 • 16-3 SLFW (TBS) 60°C L-505C1 E73 WA

LK-1852

JUKI CORPORATION
Made in Japan

SUBCLASS 5

DAIKI

MADE IN JAPAN
SUBCLASS 5

LH-1152-5

JUKI CORPORATION
Made in Japan

Mfg. No.

R03794

4B

G

Gauge F



Back Tack
Start Z End
JUKI MC-110

1955 MR4

JUKI

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16

LH-1152-5
JUKI CORPORATION
Made in Japan

4B G
Gauge F

DDL-5550-6

JUKI CORPORATION

Made in Japan

Mfg. No.

Mfg. No.

367614

WB
WB



JUKI

NO
NO



JUKI
DDL-5550-6

1 2 3 4 5 6 7 8 9 10 11 12 13 14

DDL-5550-6

JUKI CORPORATION
Made in Japan

WB

LH-1152-7

JUKI CORPORATION

Made in Japan

Mfg.No.

LH0XB08640

WB

G

Gauge F

Mr Pak Bab
(Sunked?)
26 2017

Elka VARIOCONTROL 720

7 8

4 5

1 2

P E + -

LH-1152-7
JUKI CORPORATION
Made in Japan
MTG NO. 1102100110
WB G
Gauge F

DDL-5550-6

JUKI CORPORATION
Made in Japan

Mfg. No.

0111111529

WB



JUKI

71X1.19

DDL-5550-6

JUKI CORPORATION

WB

DDL-5550-6

JUKI-CORPORATION
Made in Japan


Mfg. No.

RE-7611

WB



JUKI



JUKI
BC-120



DDL-5550-6
JUKI-CORPORATION
Made in Japan

WB

DDL-5550N-7

IUKI CORPORATION

Made in Japan

Mfg. No.

HELXC76130

WB



JUKI

JUKI CP-130

N

ALR
DFC

1 1 1
A B C
V V V

N

+

+

+

+

>

>

R

+

+

-

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WB

DMN-5420N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

2DDYH000054



JUKI

DMN-5420N-7

JUKI CORPORATION

Made in JAPAN

Mfg. No.

PSR

TRADE-MARK REG.

"FUSE-IT"

Model No.

120001

Serial No.

12748

V.

220

Ø

1

Amps

17

Pat. No.

4,164,083

MADE IN U.S.A.




DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WB
243WG000009



JUKI CP-160

ALB1
D[C]
ALB1
A[B]
I A A
ABCBC
V V I
D
B C A
C C B
O B

11
11

+ + + +
- - - -

CAUTION
Making parts may cause injury.
Operate with safety device.
Turn off main switch before
threading, changing bobbin
and needle, cleaning, etc.

DLN-5410N-7

Size
339-C-102
440-102-102

DDL-8700-7

JUKI CORPORATION

Tokyo Japan

WB

Mfg.No.

AD0WF10239

Assembled in China



ALB7
D/C
ALB7
A/B
1A
ABCBC
V
D
B/A
C/C
D/B

MN
MN

JUKI CP-160

JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin
and needle, cleaning, etc.

DDL-8700-7
JUKI CORPORATION
Tokyo, Japan
Made in China

DDL-8700-7

JUKI CORPORATION

Tokyo Japan

Mfg No. 400VF10245

Assembled in China



ABCBC
V V J
D

B A
D C
C B

WN

+ + + +
- - - -

⚙️ ⚙️
✂️ ✂️

R

+
-

JUKI

⚠️ CAUTION
Moving parts may cause injury.
Operate with safety device.
Turn off main switch before
threading, changing bobbin
and needle, cleaning, etc.

1 2 3 4
1 2 3 4

DDL-8700-7

DLM-5200N

JUKI CORPORATION

Made in Japan

Mfg.No.

D
DLMZF28591

Service (customer)
Schedule (manufacturing)
Essee Apparel is committed to continual
improvement of quality related activities
devoted to achieving the requirements of ISO
9001-2000 standard, satisfying internal and
external customer needs, and supplying our
customers with the best quality for the best
price.



DLM-5200N
JULI CORPORATION
Made in Taiwan
Qty. No.

DMN-5420N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

JUKI



DMN-5420N-7
JUKI CORPORATION
Made in Japan
Mfg. No.

DLM-5400N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

2D2XK00142



JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin
and needle, cleaning etc.

DLM-5400N-7
JUKI CORPORATION

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

DDL5574275

WB



JUKI

DDL-5550N-7

WB

DMN-5420N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

2D5Y-100000



JUKI

DMN-5420N-7

DMN-5420N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

3050Y100633

JUKI CP-160



A B 1
D C 2
A B 1
C D 2
A B 1
C D 2
A B 1
C D 2
A B 1
C D 2

W W

N N



+ + + +
- - - -



R

+
-

JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin
and needle, cleaning etc.



DMN-5420N-7
JUKI CORPORATION







JUKI

ALB7
ofCJ
ALB7
CD
A7BJ
I A A
ABCBC
V V I
D
B A A
C C B
D

W N

W N

+
A
-

+
B
-

+
C
-

+
D
-

✂

✂

R

+

R

+

JUKI CP-230

DLN-5410W-7


WILLIAMS & GIBBS

MADE BY PEGASUS

TYPE 515-4-39

SPEC. 3X3

DEVICE



PEGASUS

MILLCOX O'NEILL
515-4-59

DDL-5550N-7


JUKI CORPORATION

Made in Japan

Mfg. No.

ELLXC70315

WB



JUKI

JUKI CP-100

DDL-5550N-7

DDL-5550N-7

JUKI CORPORATION

Made in Japan

WB



JUKI

DDL-5550N-7

JUKI CORPORATION
Made in Japan

WB

WILCOX & GIBBS

MADE BY PEGASUS

TYPE 515-4-51

SPEC. 5X5

DEVICE



DDL-8700-7

JUKI CORPORATION

Tokyo Japan

WB

Mfg. No.

4D3MF03T85

Assembled in China



ALB1
D/C
ALB1
A/B
I A A
ABCBC
V/D
B A
C C
D B

MN
MN

JUKI CP-100

16X231 16

JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing bobbin
and needle, cleaning etc.

DDL-8700-7

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WE
2D3W600004



JUKI CP-150

M

N

+ + + +
- - - -

CAUTION
Moving parts may cause injury.
Always use safety devices.
Turn off power switch before
servicing. Charge before
use. Handle carefully.

JUKI

0 1 2 3 4

DLN-5410N-7

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Part No.

WB



JUKI

DLN-5410N-7
JUKI CORPORATION
MADE IN JAPAN

WB

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

DDLWJ25192

WB



JUKI CP-130

JUKI

DDL-5550N-7

WB

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

DL-AC76126

WB

JUKI CP-130

AL07
07CJ

1 1 1
A A A
ABCBC
V V V
D

N

+ A -
+ B -
+ C -
+ D -

> <

R + -

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

SIZE 19 NEEDLE

JUKI

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14

DDL-5550N-7
JUKI CORPORATION
Made in Japan
Mfg. No.

WB

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WI: 203WL00501

ACCU-STOP LCD-790

STITCH & MESSAGE DISPLAY

P A B C D E F G

CONTROL KEYS

CLINTON INTERACTIVE WORKSTATION

Buttons: [Back], [Forward], [Stop], [Start], [Eject], [Reset]

JUKI

CAUTION

Moving parts may cause injury.

Operate with safety devices. Turn off main switch before threading, changing bobbin and needle, cleaning etc.

DLN-5410N-7

JUKI CORPORATION

MADE IN JAPAN

0 1 2 3 4

DLN-541-7

DUKE CORP

made in

DLN-XA20802

WB



MN

R

SUZUKI

Maxine 9/14/15
Bad Power pack
elec. problems
&



DLN-52 7

WB



8568-01GBX364/UT

JACK INDUSTRIAL
SEWING MACHINE



WT



ISO9001:2000

Mfg.No. 1003021291

警告

不要随便拆除零件。
请勿在机器下进行操作。

JACK JK-8568

JK 8568-01GBX364UT
JACK INDUSTRIAL
SEWING MACHINE
Mfg No. 225212

警告
不要隨意拆除零件。
在安全裝置下進行操作。
在更換、調整、拆卸及
修理等之前先將電源
切斷。

CAUTION
Never touch any parts
except with safety device.
Turn off main switch before
removing, changing, adjusting
and repairing.

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

FXC74284

WB

JUKI CP-130

N



1 2 3 4 5 6 7 8 9 0

N

+

+

+

+

✂

✂

R

+

-



JUKI



DDL-5550N-7

JUKI CORPORATION

Made in Japan

WB

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

DDL WH 78652

WB



JUKI

JUKI CP-200

DOL-5550W-7

DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

DLN-5410N-7

WB



JUKI CP-280

M M

M N

JUKI

DLN-5410N-7

WB

DDL-5550-6

JUKI CORPORATION
Made in Japan

Mfg. No.

387693

WB



DDL-8700-7

JUKI CORPORATION

Tokyo Japan

WB

Mfg.No. 1501E0229

Assembled in China



ALB7
D/CJ
ALB7
A/BJ
I A
ABCBC
V D
SA
C A
D C N B

W N

W N

+ + + +
- - - -



Atlanta Attachment Co
Sudden Service

JUKI

CAUTION
Moving parts may cause injury.
Do not touch safety device.
Turn off main switch before
inserting, changing, soldering
and making wiring etc.

DDL-8700-7
JUKI CORPORATION



Bottom

DDL-8700-7

JUKI CORPORATION

Tokyo Japan

Mfg.No.

4DQWF10243

mbled in China



JUKI CP-160

W N

W N

JUKI

CAUTION
Moving parts may cause injury.
Operate with safety devices.
Turn off main switch before
threading, changing foot, and needle, cleaning, etc.

DDL-8700-7

DDL-8700-7

JUKI CORPORATION

Tokyo Japan

Mfg No. 400MF10241

Assembled in China



JUKI



DDL-8700-7

DDL-8700-7

JUKI CORPORATION

Tokyo Japan

Mfg.No.

W/B
WDOVE10242

Assembled in China



Control panel of the Juki sewing machine. It includes a digital display, several buttons, and a small 'JUKI' logo. The panel is yellow and white.

Buttons and indicators include:

- ALB7
- DFC
- ALB7
- CD
- A7B7
- I A A
- ABCBC
- Y D
- B A A
- C C N
- D B

Buttons with symbols: +, -, and a small 'JUKI' logo.

16X231.185UK

JUKI

CAUTION

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

DDLX000335

WB

JUKI

JUKI CP-130

N

ALB
D/C

A
ABCBC
Y V I
S

N

A

B

C

D

✂

✂

≡

R

+

-

V

1 2 3 4

DDL-5550N-7

WB

 - 8569ADII-01GBX364/UT

JACK INDUSTRIAL
SEWING MACHINE

Mfg.No.

151175-4



警告

不要隨便拆除零件。
在安全公認前下進行操作



JACK

8569

JACK INDUSTRIAL
SEWING MACHINE



DDL-5550N-7


JUKI CORPORATION

Made in Japan

Mfg. No.

WB

JUKI



DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg.No.

WE



JUKI



DLN-5410N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

WE
2D3WG00011

JUKI

JUKI CP-900

AL07
UTC
AL07
CD
A70J
I A
ABCDC
D
BcA
D
CCCN
B

W N

W N

+ + + +
- - - -

⏮ ⏪ ⏩ ⏭

⏮ ⏪ ⏩ ⏭

R

+

-

CAUTION
Moving parts may cause injury.
Disconnect with auto device.
Turn off main switch before
threading, changing button
and needle, cleaning etc.

0 1 2 3 4

DLN-5410N-

Hand Power Part
Sewing Machine
1/2/2019

Quality Policy Statement
Toshiba Europe is committed to supplying a
quality product that meets or exceeds the
customer's needs and specifications in terms of:
Delivery (Product)
Performance (Product)
Reliability (Product)
Service (Customer)
Technical (Manufacturing)
Cost (Manufacturing)

DDL-5550N-7

JUKI CORPORATION

Made in Japan

Mfg. No.

DDL-XC75241

WB



N

JUKI CP-130

N

R

JUKI

DDL-5550N-7

JUKI CORPORATION

Made in Japan

500g Net

WB