Plant Service Record

SOCOTEC

Date: 24/8/2020		Fitter's name: CLEMENTS M. RANDALL	
Plant Item: DANDO 2500		Plant no: CT71	
Hour reading:		Last Service	

Description of work carried out	Time taken (hours)	Initials
2¼" PILLAR BEARING CRACKED TOP.		
REMOVED L. SPROCKET & REPLACED 2x PILLAR BEARINGS.	8HRS	PC.ML.
REPAIRED DAMAGED GUARD.		
TIDY UP		

Parts/materials used	Quantity
2¼" PILLAR BEARINGS	2.
1¼ - 12 DUREX SPROCKET.	1
CONSUMIBLES TO THE VALUE £40.	