Corner Edge Tool- How To

1. Turn the buckle with the prongs facing to the right.

2. Make a loop with one end of the strap, and thread the front prong through the loop.

3. Create another loop at the opposite end of the strap & thread the rear prong through the new loop.

1



2



3



*Note: push the buckle out to arm's length, hold down the bottom strap, and pull out excess strapping to make the next step easier.

4



4. Place the tool over the bottom strap.

5. Point handle of the Corner Edge Tool towards the buckle, and slide strapping through the strap slot in tool and the take up wheel.

5



6. Pull the handle towards you to tension the strap until the front prong is closed.


6







*Note: hold the rear of the base while tensioning.



7. Cut the strap with the Klever Kutter.

7



Watch Instructional Video

Remember to exercise caution when using any tool! Always work safely!

Order Now

BOSS Tiedowns & Strapping

936-867-4801
orders@boss-strapping.com