2001 Siemens Symphony Syngo, 1.5T

- 4 Channels
- Located: Oregon
- **Current Helium Level: 78.7%**
- SW: VA40
- Chiller Included: YES

Coils

BreastArray
CP_BodyArray
CP_Extremity
CP_FlexLarge
CP_FlexSmall
CP_NeckArray
CP_SpineArray
ShoulderArray

SoftwareOptions

Name	Version	Expirydays
Syngo General License	43.1	3650000
Application Suite/CORE Package	1.0	3650000
CORE Plus	1.0	3650000
Worklist	40.100	3650000
3D Usage License	40.100	3650000
3D MPR (Volume of Interest)	40.100	3650000
3D MIP	40.100	3650000
3D SSD	40.100	3650000
MPPS	1.0	3650000
Image Filter Software	1.1	3650000
syngo Remote Assist	1.0	3650000
USA License	1.0	3650000
1D/2D PACE	1.0	3650000
Advanced 3D	1.0	3650000
Advanced Turbo Package	1.0	3650000
Advanced Angio Package	1.0	3650000
CARE Bolus	1.0	3650000
Panoramic Table	1.0	3650000
Echo Planar Imaging	1.0	3650000
Spectroscopy: SVS	1.0	3650000
Advanced Cardiac Package	1.0	3650000
Argus Viewer	4.01	3650000
Argus Function	4.01	3650000
Spectroscopy: CSI	1.0	3650000
MR Spectroscopy Evaluation	1.0	3650000

DiskDb

Disk

Drive	DriveType	LogicalName	HostName	Manufacturer	CapacityMB	FreeSpaceMB
C:	Harddisk	Med_System	MRC22309	n.a.	270695	253900
D:	Harddisk	Med_Data	MRC22309	n.a.	284052	275522
E:	Harddisk	Med_Pixel	MRC22309	n.a.	286100	259356


SIEMENS
MAGNETOM

Omegacart


Electric Shock Hazard
Power Before Servicing Unit
SIEMENS
Schroff
DISCONNECT CABLES AT REAR BEFORE REMOVING.
CAUTION HEAVY
Attention:
Please drain
CCS
before transit!

Wharf Road EYNSHAM
Nr WITNEY
OXFORDSHIRE
UK OX29 4BP
WERNER
CAUTION

DOMESTIC COLD WATER
CHILLED WATER SUPPLY
CHILLED WATER RETURN
DOMESTIC COLD WATER
DOMESTIC COLD WATER
IF CHILLER FAILURE OCCURS:
1. ELECTRICALLY SHUT DOWN CHILLER AT PANEL
2. TURN OFF SUPPLY AND RETURN LINES (2 LEFT BLUE HANDLES)
3. TURN ON DRAIN VALVE (CENTER BRASS VALVE)
4. TURN ON WATER BY-PASS VALVE(LEFT BRASS VALVE)
Contact: American Heating (503) 239-4600
Keeler Plumbing (503) 887-3973