

1. Approving Civil Aviation Authority/Country:
United States

2.

AUTHORIZED RELEASE CERTIFICATE
FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
20-358

4. Organization Name and Address:

Air Prop Specialist
3671 Industrial Park Drive
Marianna, FL 32446

5. Work Order/Contract/Invoice Number:
20-358

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	Hartzell Propeller	HC-C2YK-1BF / F7666A-2	1	CH7936E	Overhauled

12. Remarks:

Overhauled propeller in accordance with Hartzell Manuals: 113B, 159, and 202A. All other current service information and Airworthiness Directives complied with as of this date. NOTICE: An Airworthiness Directive may apply to the installation of the propeller described hereon. The installer is responsible for ensuring complete compliance with any applicable installation Airworthiness Directive.

Propeller
Hub S/N - CH7936E
Blade # 1 - E61609
Blade # 2 - E61601


TSN	TSO
3725.65	0.00
3725.65	0.00
3725.65	0.00
3725.65	0.00

13a. Certifies the items identified above were manufactured in conformity to:

- Approved design data and are in a condition for safe operation.
- Non-approved design data specified in Block 12

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title, 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:
			IX4R274M
13d. Name (Typed or Printed):	13e. Date (dd/mm/yyyy):	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
		Christopher Giersberg	02 Mar 2020

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.


Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Blocks 13e and 14e do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the

March 2, 2020: HUB: HC-C2YK-1BF SN: CH7936E TT: 3725.65 TSO: 0.00
Overhauled propeller in accordance with Hartzell Manuals: 113, 159, and
202A. All current service information complied with as of this date.
NOTICE: An Airworthiness Directive may apply to the installation of the
propeller described hereon. The installer is responsible for ensuring
complete compliance with any applicable installation Airworthiness
Directive.

Maintenance Release (Overhaul)

The aircraft propeller or appliance identified above was serviced in accordance
with Regulations of the Federal Aviation Agency and is approved for return to
service. Pertinent details of the inspection are on file at this repair station under
Work Order Number 20-0358.

Signed  _____, for AIR PROP SPECIALISTS, INC.
Certificate Number 1X4R274M, 3671 Industrial Park Drive, Marianna, FL
32446