



FOUNDED 1862

# ABS

Certificate Number: 17-MQ3282785-B

ABS Port Office: Melbourne

Effective Date: 10 February 2017

Unless cancelled earlier, this certificate expires on: 09 February 2020

Service Provider's Address: 3/17 LINNMAX CRT, POINT COOK, VICTORIA-3030, AUSTRALIA

Service Provider's Website: [www.atlantisfiresafety.com](http://www.atlantisfiresafety.com)

For particulars regarding this recognition, see the ABS web site: [www.eagle.org](http://www.eagle.org)

## Certificate of Service Recognition

This is to Certify that

### ATLANTIS FIRE & SAFETY SERVICES PTY LTD

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

**Self Contained Breathing Apparatus Maintenance**

Choose an item.

Choose an item.

It is the responsibility of the Service Provider to employ, train, and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo identification and, if allowed, be listed on the company's web site (noted above). The products and models allowed to be serviced are to be listed on the company's web site. The ABS Office issuing this certificate is to be kept updated with changes to the management of the company, its employees, equipment and models on the authorization list and any changes made.

See enclosed Appendix for details regarding authorized personnel, and/or manufacturer authorizations, and/or subcontractors etc.

Md Mijanur Rahman, Surveyor





FOUNDED 1862

# ABS

Certificate Number: 17-MQ3282785-A

ABS Port Office: Melbourne

Effective Date: 10 February 2017

Unless cancelled earlier, this certificate expires on: 09 February 2020

Service Provider's Address: 3/17 LINNMAX CRT, POINT COOK, VICTORIA-3030, AUSTRALIA

Service Provider's Website: [www.atlantisfiresafety.com](http://www.atlantisfiresafety.com)

For particulars regarding this recognition, see the ABS web site: [www.caglc.org](http://www.caglc.org)

## Certificate of Service Recognition

This is to Certify that

### ATLANTIS FIRE & SAFETY SERVICES PTY LTD

having been audited by ABS and having given a satisfactory practical demonstration of the service listed below, is recognized by ABS as a Service Provider to provide services which ABS Surveyors may rely on to make decisions affecting classification or statutory surveys.

**Fire Extinguishing Systems Inspection/Maintenance**

Choose an item.

Choose an item.

It is the responsibility of the Service Provider to employ, train, and qualify persons in the service provided. If the service requires approval from manufacturers, the service provider is responsible to maintain contact with the manufacturer and maintain any service manuals up to date. The employees who will conduct the servicing are to have photo identification and, if allowed, be listed on the company's web site (noted above). The products and models allowed to be serviced are to be listed on the company's web site. The ABS Office issuing this certificate is to be kept updated with changes to the management of the company, its employees, equipment and models on the authorization list and any changes made.

See enclosed Appendix for details regarding authorized personnel, and/or manufacturer authorizations, and/or subcontractors etc.

\_\_\_\_\_  
Md Mijanur Rahman, Surveyor

