

BUICK

ASSEMBLY

INSTRUCTION

MANUAL

1967

- ◎ SPECIAL
- ◎ SPECIAL DELUXE
- ◎ SKYLARK
- ◎ SPORTWAGON

PART NO. 1379480

March 1, 1966

SUBJECT: 1967 BUICK MANUALS


Please find herewith the initial shipment of the Buick Assembly Instruction Manual.

It is important that you read the preface of the manual to become familiar with the manual contents.

You will note a recent change in revision symbols which appears in areas, reflects the latest change letter only.

When a subsequent change is made the existing symbols will be removed and new symbols bearing the latest change letter will be added.

Mr. Wm. C. Edgley authorized this change to provide rapid identification of each change and eliminate some of the cluttered appearance on the drawings.



O. H. Mundy
Sr. Contact Engineer

rlf



BUICK MOTOR DIVISION GENERAL MOTORS CORPORATION FLINT, MICHIGAN 48550

December 5, 1966

TO: All recipients of the Buick Assembly Instruction Manual

SUBJECT: 1968 DISTRIBUTION

In an effort to reduce the cost and eliminate waste, a survey of all recipients of the Buick Assembly Instruction Manual is being made.


Please review your present requirements and indicate your requirements for 1968.

We have no intention of depriving anyone of the manuals, but consideration should be given to reduce quantities wherever possible.

It has been brought to our attention that a considerable number of manuals are not being updated with the revisions filed in their respective sections.

It should be recognized that the basic reason for the Buick Assembly Instruction Manual is to furnish the Assembly Plants with the necessary Engineering Information to completely assemble the Buick Product.

Please make your requests by written memo to the writer. Make sure you have listed the names and correct address to whom they should be mailed. Request should be made at your earliest convenience. Your usual cooperation will be appreciated.


O. H. Mundy
Production Engineer
Buick Engineering Fact. #78

OHM:ng



1967 BUICK ASSEMBLY INSTRUCTION MANUAL
SPECIAL - SKYLARK 43000 - 44000 SERIES

Page 2

13. Omitted - See Section 11.

14. Bumpers.

Pages are numbered in the lower right corner title block to aid in filing.

For example, Page 0-1.0 will be filed the first page in Section "0" - Page 1-1.0 indicates Page 1 of Section 1. The page 2-1.0 indicates Section 2 Page 1, etc.

Note: When there is a conflict in the information the latest date of Buick Engineering Official Information will supersede.

To obtain the maximum benefit from the manual, it is imperative that revised and additional pages be filed in the proper section when received, and obsolete pages destroyed.

PART NUMBER-1379480

PAGE NUMBER-