

AFTER TAKE-OFF	
LANDING GEAR	UP
ANTI-ICE	AS REQD
SLATS/FLAPS (V2+25) +400'	CLEAN
STBY PUMP	AUTO
TAXI LIGHTS	OFF
IGNITORS	GRD START/AS RQRD

BEFORE LANDING	
GEAR	DOWN AND LOCKED
SLATS/FLAPS	SET
ANTISKID	CHECKED
IGNITORS/AIRBRAKES	AIR START/RETRACTED
AUTOPILOT/YD	DISENGAGED
ANTI-ICE	AS REQD

EMER EXIT LIGHT	OFF
TRANSPONDER	1200/STBY
NO SMOKING	OFF
BOOSTER PUMP 2	OFF
STBY HORIZON	CAGED
APU	SHUTDOWN
BUS TIE	FLIGHT NORMAL
BATT 1 & 2	OFF
GEN 1, 2 & 3	OFF
CHOCKS	AS RQRD
PARKING BRAKE	RELEASE
BATTERIES	DISCONNECTED
COVERS	ON

CLIMB FL-180	
ALTIMETERS	STANDARD/CHECKED
CABIN NOTICES (SIGNS)	AS RQRD
LANDING LIGHTS	OFF
PRESSURIZATION	CHECKED

AFTER LANDING	
ANTI-ICE	AS REQD
IGNITIONS	GRD START
PITOTS/WINDSHIELDS	OFF
LDG LIGHT	OFF
BUS TIE	TIED
APU	AS RQRD
RADAR	STBY
AIRBRAKES	IN/LIGHT OUT
FLAPS & SLATS	CLEAN
TRIMS	TAKE-OFF POSITION
TRANSPONDER	AS RQRD

QUICK TURN

CRUISE/DESCENT	
TREND MONITOR	LOG
PRESSURE CTL	SET/CHECKED
ANTI-ICE	AS RQRD
CABIN DOORS	OPEN
CABIN NOTICES	ON

PARKING BRAKE	SET
STBY PUMP	OFF
POWER LEVERS	CUTOFF
BOOSTPUMPS.	OFF AS RQRD
ANTI ICE	AS RQRD
SEAT BELT/NO SMOKING	OFF
CLOCKS	RESET
FMS	FUEL RESET
CB'S	CHECK
MX TEST PANEL	CHECK
ATIS/CLEARANCE	RECEIVED
RADIOS/FMS	PROGRAMMED
TAKEOFF DATA	SET
PRESSURIZATION	SET
FUEL QUANTITY	CKD/RESET

BELOW FL-180	
AOA	SET 1.3
ALTIMETERS	SET AND CHECKED
EXTERIOR LIGHTS	AS RQRD
NAV/FMS/BUGS/MINIMUMS	SET
APPROACH BRIEFING	COMPLETED

PARKING	
PARKING BRAKE	ON/ #2P BK LT ON
TAXI LIGHT	OFF
ANTICOLLISION	OFF
BOOSTER PUMP 1 & 3	OFF
HYD STBY PUMP	OFF
SEAT BELT SIGN	AS RQRD
DISPATCH	TEXTED

APPROACH	
NAV SOURCE/RADIOS	SET
ALTIMETERS	SET AND CHECKED
ST-BY PUMP	ON
FUEL X-BP PUMP	CLOSED
ANTI-ICE	AS REQUIRED
GO AROUND PROCEDURE	BRIEFED

PARKING-APU STOP	
FOS DATA/FMS PHOTO	RECORDED
IRS #1,#2,#3	OFF
LH AVIOINICS MASTER	OFF
RH AVIONICS MASTER	OFF

GWX1000# TAKE OFF SPDS	V1	VR/V2	VFR	VFTO	-SLATS/FLAPS 20
46,500	121	131	156	192	-SLATS/FLAPS 20
46,000	119	130	155	190	-SLATS/FLAPS 20
44,000	116	127	152	185	-SLATS/FLAPS 20
42,000	114	124	149	180	-SLATS/FLAPS 20
40,000	110	122	147	175	-SLATS/FLAPS 20
38,000	106	119	144	170	-SLATS/FLAPS 20
36,000	102	115	140	165	-SLATS/FLAPS 20
34,000	99	112	137	161	-SLATS/FLAPS 20
32,000	94	109	134	156	-SLATS/FLAPS 20

LANDING DATA

GWX1000	Vref
28	108
30	112
32	116
34	119
36	122
38	126
40	129
42	132
44	135
46	138