

SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

Structure Name: MEARS D 3

Reported By: Daniel Boyes

Date: July 3, 2019

Headgate	Latitude	Longitude
Location:	38.070167	-106.141115

Headgate Type: There is no headgate for this structure.

Headgate Condition:	A <input type="checkbox"/>	Diversion and Other Condition:	A <input type="checkbox"/>	Stream Miles from Saguache Creek Terminus (Point of Diversion):
	B <input type="checkbox"/>		B <input type="checkbox"/>	29.06 mi
	C <input type="checkbox"/>		C+ <input checked="" type="checkbox"/>	
	D <input type="checkbox"/>		D <input type="checkbox"/>	
	F <input type="checkbox"/>		F <input type="checkbox"/>	
	N/A <input checked="" type="checkbox"/>			

Repair(s) or Improvement(s) Currently Needed: No immediate repair needs were identified at the time of inspection.

Structure Description: This ditch is serviced by the Woodard Bros Ditch. The ditch crosses Saguache Creek just downstream of Hwy 285.

Comments: This ditch is a priority 76

Notes:

Estimated Range of Cost: Low

Pipeline inlet



Pipeline across Saguache Creek



Ditch downstream of flume



Channel looking upstream



SAGUACHE CREEK DIVERSION INFRASTRUCTURE INVENTORY

MEARS DITCH 3

PHOTO LOG

**Saguache Creek Stream
Management Plan**