


Set up



Slide parts A and B together. Slide joiner plate aligning index mark with the center of the 2 main pieces.




NOTE: do not remove this pin C.
This remains permanent.


Converting from left to right hand use.



Remove the center plate, scale, and post.
NOTE: post is hand tight only



Losen the 3 screw and slide the winch to the side and lock in place.



Flip part A and screw in post hand tight.

Note: pin C stays in place you never remove this.

Slide the draw scale in place and slip the joiner plate on.

Now slide part A into part B.



Align the index mark on the center of parts A and B and tighten in place.

slide the draw scale so it touches the side of the joiner plate.

Doing so will index the scale for measuring correct draw length.